BEFORE THE DIRECTOR DEPARTMENT OF CONSUMER AFFAIRS BUREAU OF AUTOMOTIVE REPAIR STATE OF CALIFORNIA

In the Matter of the Accusation Against:

EATON AUTO DIAGNOSTICS, INC. dba HIGH ST SMOG CHECK NICHOLAS YAKOUBOVSKY, President And Secretary ELENA YAKOUBOVSKY, Treasurer

Automotive Repair Dealer Registration
No. ARD 261712
Smog Check, Test Only, Station License
No. TC 261712

and

SALOKHIDDIN FAKHRIEV

Advanced Emission Specialist Technician License No. EA 630209

Respondents.

Case No. 79/12-50

OAH No. 2012020466

DECISION

The attached Proposed Decision of the Administrative Law Judge is hereby accepted and adopted by the Director of Consumer Affairs as the Decision in the above-entitled matter.

DATED: October 24, 2012

DOREATHEA JOHNSON
Deputy Director, Legal Affairs
Department of Consumer Affairs

BEFORE THE DEPARTMENT OF CONSUMER AFFAIRS FOR THE BUREAU OF AUTOMOTIVE REPAIR STATE OF CALIFORNIA

In the Matter of the Accusation Against:

EATON AUTO DIAGNOSTICS, INC., dba HIGH ST SMOG CHECK NICHOLAS YAKOUBOVSKY, President and Secretary ELENA YAKOUBOVSKY, Treasurer Automotive Repair Dealer Registration No. ARD 261712 Smog Check Test Only Station

and

License No. TC 261712,

SALOKHIDDIN FAKHRIEV Advanced Emission Specialist Technician License No. EA 630209

Respondents.

Case No. 79/12-50

OAH No. 2012020466

PROPOSED DECISION

Administrative Law Judge Jill Schlichtmann, State of California, Office of Administrative Hearings, heard this matter on September 4, 2012, in Oakland, California.

Deputy Attorney General Shana A. Bagley represented complainant Sherry Mehl, Chief of the Bureau of Automotive Repair.

William Ferreira, Attorney at Law, represented respondents. Nicholas Yakoubovsky and Salokhiddin Fakhriev were present throughout the administrative hearing.

The matter was submitted for decision on September 4, 2012.

FACTUAL FINDINGS

- 1. Sherry Mehl brought the accusation solely in her official capacity as the Chief of the Bureau of Automotive Repair (Bureau), Department of Consumer Affairs.
- 2. Eaton Auto Diagnostics, Inc., doing business as High St Smog Check (High St Smog Check) was registered as an automotive repair dealer (Reg. No. ARD 261712), on April 23, 2010. Respondent Nicholas Yakoubovsky (Yakoubovsky) is the president and secretary, and Elena Yakoubovsky is its treasurer. The registration is scheduled to expire on March 31, 2013, unless renewed.
- 3. High St Smog Check was licensed as a smog check/test only station (Lic. No. TC 261712) on April 26, 2010. The station license is scheduled to expire on March 31, 2013, unless renewed.
- 4. The Bureau issued Fakhriev an advanced emissions specialist license (Lic. No. EA 630209) on May 19, 2008. Fakhriev's license will expire on November 30, 2013, unless renewed.

Bureau Evidence

- 5. On November 30, 2010, a Bureau representative initiated an investigation of High St Smog Check and Fakhriev based on a review of information from the Bureau's Vehicle Information Database (VID). Information on each smog check inspection performed by a smog check station is transmitted electronically to the VID from the station's BAR-97 computer-based emissions system analyzer.
- 6. A properly performed smog check inspection has three parts: 1) a tailpipe emissions test; 2) a visual inspection of the emission control components; and 3) a functional test of certain components of the emissions system.

The functional test includes testing the On Board Diagnostics, generation II (OBD II) system on vehicles manufactured in 1996 or later. The technician is required to connect an interface cable from the BAR-97 analyzer to a Diagnostic Link Connector (DLC) located inside the vehicle. Through the DLC, the analyzer automatically retrieves information from the vehicle's onboard computer to determine if the vehicle's OBD II system is functioning properly. If the vehicle fails the OBD II test, it will fail the overall inspection.

The OBD II system continuously performs self-diagnostic tests on the vehicle's Power Train Control Module (PCM) and related sensors and actuators, to confirm that the PCM is able to properly control the operation of the engine and emissions control devices. These self-diagnostic tests are referred to as readiness monitors (monitors). Each monitor is designed to diagnose a specific system within the electronic engine and emission controls. If a malfunction is detected during the monitor operation, a diagnostic trouble code will be

stored in the PCM memory. Through the DLC, the analyzer determines if any diagnostic trouble codes are present in the PCM memory.

There are two types of diagnostic trouble codes, Type A codes and Type B codes. Type A codes indicate a significant malfunction that will illuminate the Malfunction Indicator Lamp (MIL), often referred to as the "check engine" light. The presence of a Type A code results in the vehicle failing the smog check inspection.

Type B codes ("pending codes") are for malfunctions that must be detected during at least two consecutive monitor cycles before the MIL will be illuminated. The first time the computer detects signals outside the expected parameters, a pending code is stored in the PCM memory. If this happens a second time, a hard code is generally stored and the MIL is illuminated. Pending codes for a vehicle are transmitted to the VID, but the analyzer does not reveal them to the smog check technician.

- 7. All OBD II diagnostic trouble codes are five digits long, with one letter followed by four numbers. PCM codes start with the letter P. Some codes are manufacturer specific, and other codes are generic. Codes for specific makes and models of vehicles are listed in the original equipment manufacturer's (OEM) service information and in the Alldata and Mitchell reference guides.
- 8. A Bureau representative conducted a detailed review of VID data for all smog inspections performed at High St Smog Check between May 2010 and June 30, 2011. The representative found that the 12 vehicles identified in the Table 1, all of which were tested by respondent Fakhriev, recorded diagnostic trouble codes during the OBD II tests which were not applicable to the vehicles being inspected. The Bureau representative concluded that Fakhriev performed the smog inspections on the vehicles using a different vehicle during the OBD II tests, a method known as "clean-plugging," resulting in the issuance of fraudulent certificates of compliance for the vehicles.

Clean-plugging is the use of the OBD II readiness monitor status and stored trouble code status of a passing vehicle for the purpose of illegally issuing a smog certificate to another vehicle that is not in compliance due to the presence of a stored diagnostic trouble code that indicates an emission control system or component failure. It is accomplished by connecting the interface cable from the BAR-97 analyzer to the DLC of another vehicle, to retrieve information from the passing vehicle. After entering vehicle information into the analyzer for the vehicle he wishes to certify, the technician can clean-plug by either performing a complete smog inspection on a different vehicle, or performing an incomplete smog inspection on the vehicle he wishes to certify and then plugging the interface cable from the BAR-97 analyzer into the DLC of a vehicle believed to have a properly functioning OBD II system.

TABLE 1

Vehicle	Date and Time of	Vehicle Certified	Certificate No.	Unsupported
No.	Inspection	& Vehicle Tested		Pending Code
1.	6/03/2010	2002 Chevrolet Venture	NU346373C	P1780
	17:32 to 17:40 hours	Lic. No. 5VEZ178		
2.	6/12/2010	1999 Suzuki Esteem	NU398749C	P0325
	10:50 to 10:56 hours	Lic. No. 6GMT520		
3.	7/15/2010	2000 Daewoo Lanos	NU898206C	P1298
	15:46 to 15:51 hours	Lic. No. 5DDC564		
4.	7/15/2010	1998 Nissan Maxima	NU898214C	P1298
	18:32 to 18:39 hours	Lic. No. 4ACH930		
5.	7/15/2010	1997 Buick LaSabre	NU898215C	P1298
	18:45 to 18:51 hours	Lic. No. ABM0470		
6.	7/19/2010	1996 Ford Thunderbird	NU930238C	P1298
	19:09 to 19:15 hours	Lic. No. 5WVP857		
7.	8/23/2010	1996 Mitsubishi Eclipse	NW380986C	P1768
	12:25 to 12:30 hours	No plates		
8.	8/28/2010	1997 GMC Suburban	NW448598C	P1738
	10:59 to 11:06 hours	Lic. No. 5JJT644		
9.	8/30/2010	2001 Dodge Stratus	NW489982C	P1298
	17:05 to 17:13 hours	Lic. No. 4SVX210		
10.	10/07/2010	1997 Ford F150	NY033482C	P0650
	17:54 to 18:20 hours	Lic. No. 5K50471		
11.	12/30/2010	2003 Ford Windstar	WR203843C	P0150
	14:39 to 14:46 hours	Lic. No. 5ANE584		
12.	4/05/2011	2000 Hyundai Accent	OC357043C	P0305
	17:13 to 17:18 hours	Lic. No. 6ESH595		

- 9. The three vehicles tested on July 15, 2010, and those tested on July 19, 2010, and August 30, 2010, all had the same inapplicable diagnostic trouble code.
- 10. On June 12, 2010, the Suzuki Esteem was inspected between 10:50 and 10:56 a.m., and a pending trouble code was recorded (P0325) which is not supported by that vehicle. The VID also reported that a 1999 Mercury automobile, which was inspected by Fakhriev at High St Smog Check at 10:58 a.m. on the same day, had the same diagnostic trouble code (P0325) stored in its onboard computer. The code was applicable to the Mercury automobile.
- 11. On August 28, 2010, a 2001 Honda was inspected by Fakhriev at 11:09 a.m., and a pending trouble code (P1738), which is applicable to the vehicle, was recorded. Vehicle No. 8, the GMC Suburban, was inspected between 10:59 and 11:06 a.m., and the same pending trouble code was recorded (P1738), however, that trouble code was not

supported by a GMC Suburban. The onboard computer for each vehicle reportedly inspected also had the same incomplete readiness monitors.

- 12. On December 30, 2010, Fakhriev performed a smog inspection on the Ford F150 at 2:39 p.m. Pending trouble codes of P0150 and P0300 were recorded during the inspection. Only the P0300 was supported by this Ford. At 2:50 p.m., on the same day, Fakhriev performed a smog inspection of a Mazda Minivan. The same pending trouble codes (P0300 and P0150) were recorded for the Mazda Minivan. Those trouble codes are both supported by the Mazda Minivan.
- 13. On April 5, 2011, when Fakhriev performed a smog inspection on the Hyundai Accent, a pending trouble code of (P0305) was recorded. Pending code P0305 indicates that a misfire has occurred on cylinder number five on the vehicle. However, a Hyundai Accent does not have five cylinders; it is a four-cylinder automobile.
- 14. David Lewis, a Senior Engineer who has worked for the Bureau for 28 years, testified at the hearing. He wrote the original electronic specifications and some code for the BAR-97 analyzer, and he is in charge of the unit that develops the technology for new smog check equipment. Lewis serves on the statewide network database committee, and develops new methods for smog check analyzers. Lewis manages the statewide network databases to ensure compliance with the air pollution standards in the state.

Lewis explained how the BAR-97 analyzer captures the OBD II fault codes and transmits that information to the VID. There is error checking between the analyzer and the vehicle's computer and error checking between the analyzer and the VID. Lewis stated that it is not possible for the analyzer to transmit a fault code for a different vehicle than the vehicle to which it is connected. If an error occurs, the analyzer will indicate that it cannot communicate with the vehicle's computer. If there is a problem with the onboard diagnostic system of the vehicle, it will not communicate with the BAR-97 analyzer and the vehicle will fail the test.

Lewis is very familiar with the system of OBD II diagnostic trouble codes. If a pending code is in a vehicle's computer, it will be in the OEM for the vehicle. The only way a code could be transmitted to the VID for a vehicle whose manufacturer has not listed the code in the OEM is by clean-plugging.

Bureau analysts and engineers search for anomalies in the VID data using automated data checks. If, for example, only one Honda automobile, of the millions tested, reports a particular diagnostic trouble code, the computer identifies that result as out of the ordinary and triggers an investigation. Lewis is aware of only a few instances in which there has been a software glitch in the smog check reporting system. The engineering team is constantly looking for glitches and they are fixed immediately when discovered.

Since a diagnostic trouble code reporting problem was discovered and corrected by the Bureau in 2004, the information obtained by the VID from the OBD II monitors and analyzers has been reliable. On occasion no code will be reported, but the Bureau has not seen any reports of a trouble code being reported on a vehicle that does not support that code. The analyzers are designed to shut down if there is an equipment failure of some sort; in that case, no certificate will be issued.

- 15. Lewis reviewed the investigation report prepared in this matter and determined that the 12 vehicles identified in Table 1 were clean-plugged. Lewis's opinions were credible and undisputed.
- 16. The evidence established that the 12 vehicles identified in the Table 1 were clean-plugged.
- 17. In order to protect against fraudulent smog inspections, some station owners conduct video surveillance of their employees. Other owners regularly review data for abnormalities. Some owners train their employees against committing fraudulent inspections. Once a technician is accused of fraudulent inspections, some owners immediately fire the technician and cooperate fully with the Bureau.

Costs

18. The Bureau has incurred \$12,754.76 in investigative costs, and \$7,540 in legal costs, for a total of \$20,294.76 in costs of investigation and enforcement. There was no challenge to the reasonableness of these costs.

Respondents' Evidence

- 19. Respondent Fakhriev testified at hearing. He denies having clean-plugged the 12 vehicles identified in Table 1, or any vehicles. Fakhriev has worked at High St Smog Check since 2008. His technician license has never been disciplined in the past, and he has never had consumer complaints filed against him.
- 20. Respondent Nicholas Yakoubovsky testified at hearing. Yakoubovsky purchased High St Smog Check in 2010. In February 2010, Yakoubovsky incorporated the business as Eaton Auto Diagnostics, Inc. He is the president and secretary of the corporation, which is in good standing.
- 21. In February 2011, Yakoubovsky obtained his smog technician license, after completing a six-month training course. Yakoubovsky's license has not been disciplined.
- 22. On a typical day, Fakhriev opens the business at 8:30 a.m. Yakoubovsky generally arrives at approximately 10:00 a.m. He completes paperwork and then leaves at about 2:00 p.m. Yakoubovsky performs smog check inspections when Fakhriev is at lunch or ill.

- 23. When Yakoubovsky first took over the business, he noticed that Fakhriev was warming up older cars extensively. He admonished him not to do so. He observed Fakhriev do it a few more times, but after further counseling, the conduct stopped. Yakoubovsky also observed that at times Fakhriev did not perform the visual portion of the smog inspection. Yakoubovsky counseled Fakhriev on this issue as well. Fakhriev has improved, but still sometimes forgets to perform the visual inspection.
- 24. Yakoubovsky states that he reviewed his calendar and emails to verify whether he was present at the station when any of the cars identified in Table 1 were inspected, but as far as he can determine, he was not present during those inspections. He normally does not work on Saturdays or late in the afternoon, when most of the inspections occurred.
- 25. Yakoubovsky had known Fakhriev for eight months when the accusation was filed. He had found him to be reliable and trustworthy with the business receipts. Yakoubovsky had heard that the prior owners of High St Smog Check would charge \$200 for a fraudulent smog check. Yakoubovsky states that Fakhriev never gave him an indication that he would cheat the system. If Yakoubovsky found out that the Bureau's data were correct, he would consider fining Fakhriev to be a just penalty.

LEGAL CONCLUSIONS

Cause for Discipline of Respondent High St Smog Check's License and Registration

1. It is the smog check station, not the technician, that issues a smog certificate. (Health & Saf. Code, § 44010.) The law is clear that as the licensee, respondent Eaton Auto Diagnostics, Inc., dba High St Smog Check, is responsible for any misconduct committed by its employee, Salokhiddin Fakhriev. (*California Assn. of Health Facilities v. Department of Health Services* (1997) 16 Cal.4th 284, 295-297 [licensee, if he elects to operate his business through employees, must be responsible to the licensing authority for their conduct in the exercise of his license.] See also, *Ford Dealers Assn. v. Department of Motor Vehicles* (1982) 32 Cal.3d 347, 360; *Rob-Mac, Inc. v. Department of Motor Vehicles* (1983) 148 Cal.App.3d 793; *Camacho v. Youde* (1979) 95 Cal.App.3d 161.)

Causes for Discipline

HIGH ST SMOG'S ARD REGISTRATION

2. First Cause for Discipline (Untrue or Misleading Statements): Cause for discipline of the automotive repair dealer registration issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check, exists pursuant to Business and Professions Code section 9884.7, subdivision (a)(1), for untrue or misleading statements made in the issuance of the electronic certificates of compliance nos. NU346373C, NU398749C, NU898206C, NU898214C, NU898215C, NU930238C, NW380986C, NW448598C, NW489982C, NY033482C, WR203843C, and OC357043C, certifying the certified vehicles were in compliance with

applicable laws and regulations, when in fact, the smog inspections was performed by using the clean-plugging method.

3. Second Cause for Discipline (Fraud): Cause for discipline of the automotive repair dealer registration issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check, exists pursuant to Business and Professions Code section 9884.7, subdivision (a)(4), for fraud associated with its inspections and the issuance of the electronic certificates of compliance nos. NU346373C, NU398749C, NU898206C, NU898214C, NU898215C, NU930238C, NW380986C, NW448598C, NW489982C, NY033482C, WR203843C, and OC357043C, without the performance of a bona fide smog inspection.

EATON AUTO DIAGNOSTICS' SMOG CHECK TEST ONLY STATION LICENSE

- 4. Third Cause for Discipline (Violations of the Motor Vehicle Inspection Program): Cause for discipline of the smog check test only station license issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check exists pursuant to Health and Safety Code section 44072.2, subdivision (a), in that in connection with its inspections and the issuance of the electronic certificates of compliance nos. NU346373C, NU398749C, NU898206C, NU898214C, NU898215C, NU930238C, NW380986C, NW448598C, NW489982C, NY033482C, WR203843C, and OC357043C, it violated the following provisions of the Health and Safety Code pertaining to the Motor Vehicle Inspection Program by:
 - a. Section 44012: failing to ensure that all emission control tests on the 12 vehicles identified in Table 1 were performed in accordance with Bureau procedures.
 - b. Section 44015: issuing electronic certificates of compliance for the 12 vehicles identified in Table 1, without ensuring that the vehicles were properly tested and inspected to determine if they were in compliance with Health and Safety Code section 44012.
- 5. Fourth Cause for Discipline (Failure to Comply with Motor Vehicle Inspection Program Regulations): Cause for discipline of the smog check test only station license issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check exists pursuant to Health and Safety Code section 44072.2, subdivision (c), in that in connection with its inspections and the issuance of the electronic certificates of compliance nos. NU346373C, NU398749C, NU898206C, NU898214C, NU898215C, NU930238C, NW380986C, NW448598C, NW489982C, NY033482C, WR203843C, and OC357043C, it violated the following provisions of California Code of Regulations, title 16, pertaining to the Motor Vehicle Inspection Program by:
 - a. Section 3340.35, subdivision (c): issuing electronic certificates of compliance for the 12 vehicles identified in Table 1 although the vehicles had not been inspected in accordance with section 3340.42.

- b. Section 3340.42: failing to conduct required smog tests on the 12 vehicles identified in Table 1, in accordance with the Bureau's specifications.
- 6. Fifth Cause for Discipline (Dishonesty, Fraud or Deceit): Cause for discipline of the smog check test only station license issued to Eaton Auto Diagnostics, Inc., dba High St Smog exists pursuant to Health and Safety Code section 44072.2, subdivision (d), for dishonesty, fraud or deceit because it inspected and issued the electronic certificates of compliance nos. NU346373C, NU398749C, NU898206C, NU898214C, NU898215C, NU930238C, NW380986C, NW448598C, NW489982C, NY033482C, WR203843C, and OC357043C in connection with the 12 vehicles identified in Table 1, without performing bona fide inspections of the emission control devices and systems on the vehicles.

ADVANCED EMISSION SPECIALIST TECHNICIAN FAKHRIEV'S LICENSE

- 7. Sixth Cause for Discipline (Violation of Motor Vehicle Inspection Program): Cause for discipline of the technician license issued to respondent Fakhriev exists pursuant to Health and Safety Code section 44072.2, subdivision (a), in that Fakhriev failed to comply with section 44012 of the Health and Safety Code in a material respect, in that he failed to perform the emission control tests on the 12 vehicles identified in Table 1 in accordance with Bureau procedures.
- 8. Seventh Cause for Discipline (Failure to Comply with Motor Vehicle Inspection Program Regulations): Cause for discipline of the technician license issued to Fakhriev exists pursuant to Health and Safety Code section 44072.2, subdivision (c), in that he failed to comply with provisions of California Code of Regulations, title 16, as follows:
 - a. Section 3340.30, subdivision (a): Fakhriev failed to inspect and test the 12 vehicles identified in Table 1, in accordance with Health and Safety Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
 - b. Section 3340.42: Fakhriev failed to inspect and test the 12 vehicles identified in Table 1 in accordance with Health and Safety Code section 44012.
 - c. Section 3340.42: Fakhriev failed to conduct the required smog tests on the 12 vehicles identified in Table 1, in accordance with the Bureau's specifications.
- 9. Eighth Cause for Discipline (Dishonesty, Fraud or Deceit): Cause for discipline of the technician license issued to Fakhriev exists pursuant to Health and Safety Code section 44072.2, subdivision (d), in that Fakhriev committed dishonest, fraudulent or deceitful acts whereby another is injured, in connection with the issuance of the certificates

of compliance for the 12 vehicles identified in Table 1 without performing bona fide inspections of the emission control devices and systems on the vehicles.

Penalty

- 10. The Bureau's guidelines for disciplinary penalties (Cal. Code Regs., tit. 16, § 3395.4) have been considered in reaching the determination of the appropriate penalty.
- 11. In light of the numerous acts of clean-plugging, protection of the public mandates the revocation of Fakhriev's advanced emission specialist technician license.
- 12. High St Smog Check's automotive repair dealer registration (No. ARD 261712) and its smog check, test only, station license (No. TC 261712) are also subject to discipline due to the misconduct by Fakhriev. Yakoubovsky's testimony that he was not present when the fraudulent certificates were issued does not relieve him from responsibility for the misconduct. During the months that the clean-plugging occurred, Yakoubovsky was attending a six-month training course to become a smog technician. He therefore was aware of the proper method of performing smog check inspections. At a minimum, as the new owner of a business, Yakoubovsky, should have been more vigilant in managing his employee. He did not know Fakhriev prior to taking over the business, but was aware that the previous owners of the business had sold fraudulent smog certificates to customers for \$200. Moreover, Yakoubovsky admits that Fakhriev often failed to conduct the visual portion of the inspection despite his counseling. In spite of the seriousness of the allegations, Yakoubovsky did not take immediate action to suspend or fire Fakhriev when he received the accusation. Instead, he allowed Fakhriev to continue working at High St Smog Check, challenged the Bureau's findings and supported Fakhriev's testimony that he did not clean-plug the vehicles. (Findings 17, 19 to 25.)

In the highly regulated field of smog inspections, a licensee must be watchful over his or her employees, and ready to discipline employees who are not following the rules. Yakoubovsky was aware that Fakhriev was employed by High St Smog Check while fraudulent smog checks occurred. In light of this knowledge, Yakoubovsky was not as vigilant as he should have been. Nor has he taken responsibility for the misconduct.

13. Given the egregious and repeated nature of the misconduct, revocation of the ARD registration and smog check, test only, station license issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check, is warranted.

Costs

14. Pursuant to Business and Professions Code section 125.3, the Bureau may request an administrative law judge to order a licensee found to have violated the licensing act to pay an amount that does not exceed the reasonable costs of investigation and enforcement. There was no objection to the reasonableness of the Bureau's costs of

\$20,294.76. The investigation required a detailed review of many records and references. The enforcement of the matter was complex. The costs are reasonable. (Finding 18.)

15. In Zuckerman v. State Board of Chiropractic Examiners (2002) 29 Cal.4th 32, the California Supreme Court set forth guidelines for determining whether costs should be assessed in the particular circumstances of each case. The Bureau must consider whether to do so will unfairly penalize the licensee who has committed misconduct, but who has used the hearing process to obtain a dismissal or a reduction in the severity of the discipline imposed, as well as whether the licensee will be financially able to pay the full costs of investigation and prosecution when it has conducted a disproportionately large investigation to prove that a licensee engaged in relatively innocuous misconduct. (*Id.*, at pp. 44-45.) Here, the misconduct committed was egregious and repetitive and the hearing process was not used to obtain a dismissal or reduction in the severity of the discipline imposed. No evidence of an inability to pay was submitted by respondents. There is no basis upon which to reduce the costs of investigation and enforcement of this matter.

ORDER

- 1. Advanced Emission Specialist Technician License No. EA 630209 issued to Salokhiddin Fakhriev is revoked.
- 2. Automotive Repair Dealer Registration No. ARD 261712 issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check, is revoked.
- 3. Smog Check Test Only Station License No. TC 261712 issued to Eaton Auto Diagnostics, Inc., dba High St Smog Check, is revoked.
- 4. Respondents Eaton Auto Diagnostics, Inc., dba High St Smog Check, and Salokhiddin Fakhriev, are jointly and severally liable, and ordered to pay the Director of Consumer Affairs the sum of \$20,294.76 as reimbursement for the reasonable costs of investigation and enforcement if this case, pursuant to Business and Professions Code section 125.3.

DATED: (1.24.12)

JIEL SCHLICHTMANN

Administrative Law Judge

Office of Administrative Hearings

1	Kamala D. Harris Attorney General of California	
2	Diann Sokoloff	
3	Supervising Deputy Attorney General SHANA A. BAGLEY	
4	Deputy Attorney General State Bar No. 169423	
	1515 Clay Street, 20th Floor	
5	P.O. Box 70550 Oakland, CA 94612-0550	
6	Telephone: (510) 622-2129 Facsimile: (510) 622-2270	
7	Attorneys for Complainant	
8	BEFORE T	
9	DEPARTMENT OF CON FOR THE BUREAU OF AUT	TOMOTIVE REPAIR
10	STATE OF CAL	IFORNIA
11		
12	In the Matter of the First Amended Accusation Against:	Case No. 79/12-50
13	EATON AUTO DIAGNOSTICS, INC., dba HIGH ST SMOG CHECK	FIRST AMENDED ACCUSATION
14	NICHOLAS YAKOUBOVSKY, PRESIDENT and SECRETARY	(Smog Check)
15	ELENA YAKOUBOVSKY, TREASURER	(Smog Check)
16	4321 San Leandro Street Oakland, CA 94601	
17	Mailing Address: 71 Wild Oak Lane	
18	Danville, CA 94506	
19	Automotive Repair Dealer Reg. No. ARD 261712	
	Smog Check, Test Only, Station License No. TC 261712	
20	and	
21	SALOKHIDDIN FAKHRIEV	
22	375 Colusa Avenue, #2 Kensington, CA 94707	
23		
24	Advanced Emission Specialist Technician License No. EA 630209	
25	Respondents.	
26		
27	<i>III!</i>	
28	///	
	1	

First Amended Accusation

PARTIES

1. Sherry Mehl ("Complainant") brings this First Amended Accusation solely in her official capacity as the Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer Affairs.

Eaton Auto Diagnostics, Inc. dba High St. Smog Check

- 2. On or about April 23, 2010, the Director of Consumer Affairs ("Director") issued Automotive Repair Dealer Registration Number ARD 261712 (hereinafter "registration") to Eaton Auto Diagnostics, Inc. ("Respondent Eaton"), doing business as High St Smog Check, with Nicholas Yakoubovsky as president and secretary and Elena Yakoubovsky as treasurer. Respondent's registration was in full force and effect at all times relevant to the charges brought herein and will expire on March 31, 2012, unless renewed.
- 3. On or about April 26, 2010, the Director issued Smog Check, Test Only, Station License Number TC 261712 (hereinafter "smog check station license") to Respondent Eaton. Respondent's smog check station license was in full force and effect at all times relevant to the charges brought herein and will expire on March 31, 2012, unless renewed.

Salokhiddin Fakhriev

4. On or about May 19, 2008, the Director issued Advanced Emissions Specialist Technician License Number EA 630209 (hereinafter "technician license") to Salokhiddin Fakhriev ("Respondent Fakhriev"). Respondent's technician license was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2013, unless renewed.

JURISDICTION

- 5. Business and Professions Code ("Bus. & Prof. Code") section 9884.7 provides that the Director may revoke an automotive repair dealer registration.
- 6. Bus. & Prof. Code section 9884.13 provides, in pertinent part, that the expiration of a valid registration shall not deprive the Director of jurisdiction to proceed with a disciplinary

proceeding against an automotive repair dealer or to render a decision temporarily or permanently invalidating (revoking or suspending) a registration.

- 7. Health and Safety Code ("Health & Saf. Code") section 44002 provides, in pertinent part, that the Director has all the powers and authority granted under the Automotive Repair Act for enforcing the Motor Vehicle Inspection Program.
- 8. Health & Saf. Code section 44072.6 provides, in pertinent part, that the expiration or suspension of a license by operation of law, or by order or decision of the Director of Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive the Director of jurisdiction to proceed with disciplinary action.

STATUTORY PROVISIONS

- 9. Bus. & Prof. Code section 9884.7 states, in pertinent part:
- (a) The director, where the automotive repair dealer cannot show there was a bona fide error, may deny, suspend, revoke or place on probation the registration of an automotive repair dealer for any of the following acts or omissions related to the conduct of the business of the automotive repair dealer, which are done by the automotive repair dealer or any automotive technician, employee, partner, officer, or member of the automotive repair dealer.
- (1) Making or authorizing in any manner or by any means whatever any statement written or oral which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading.
 - (4) Any other conduct that constitutes fraud.
- (c) Notwithstanding subdivision (b), the director may suspend, revoke or place on probation the registration for all places of business operated in this state by an automotive repair dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated and willful violations of this chapter, or regulations adopted pursuant to it.
- 10. Bus. & Prof. Code section 477 provides. in pertinent part, that "Board" includes "bureau," "commission," "committee," "department," "division," "examining committee." "program," and "agency." "License" includes certificate, registration or other means to engage in a business or profession regulated by the Bus. & Prof. Code.

]

diagnostic trouble codes (hereinafter "code") during the OBD II tests¹. The representative obtained information indicating that the codes were not applicable to the vehicles. The Bureau concluded that Respondent Fakhriev performed the smog inspections on the vehicles using a different vehicle during the OBD II tests, a method known as "clean plugging", ² resulting in the issuance of fraudulent certificates of compliance for the vehicles.

		H
	6	
	7	
	8	
	9	
1	0	
1	1	
1	2	
1	3	
1	4	
1	5	
1	6	
1	7	
1	8	
]	9	
_	_	

Date & Time of	Vehicle Certified	Certificate No.
Inspection		
1. 06/03/2010 17:32 – 17:40	2002 Chevrolet Venture FWD; License No. 5VEZ178	NU346373C
2. 06/12/2010 10:50 – 10:56	1999 Suzuki Esteem; License No. 6GMT520	NU398749C
3. 07/15/2010 15:46 – 15:51	2000 Daewoo Lanos; License No. 5DDC564	NU898206C
4. 07/15/2010 18:32- 18:39	1998 Nissan Maxima; License No. 4ACH930	NU898214C
5. 07/15/2010 18:45 – 18:51	1997 Buick LaSabre; License No. ABM0470	NU898215C
6. 07/19/2010 19:09 – 19:15	1996 Ford Thunderbird; License No. 5WVP857	NU930238C
7. 08/23/2010 12:25 – 12:30	1996 Mitsubishi Eclipse; no plates	NW380986C
8. 08/28/2010 10:59 – 11:06	1997 GMC Suburban: License No. 5.JJT644	NW448598C
9. 08/30/2010 17:05 – 17:13	2001 Dodge Stratus 4-DR; License No. 4SVX210	NW489982C
10. 10/07/2010 17:54 – 18:20	1997 Ford F150 regular cab short; License No. 5K50471	NY033482C
11. 12/30/2010 14:39 – 14:46	2003 Ford Windstar wagon; License No. 5ANE584	WR203843C

The On Board Diagnostics (OBD II) functional test is an automated function of the BAR-97 analyzer. During the OBD II functional test, the technician is required to connect an interface cable from the BAR-97 analyzer to a Diagnostic Link Connector (DLC) which is located inside the vehicle. Through the DLC, the BAR-97 analyzer automatically retrieves information from the vehicle's on-board computer about the status of the readiness indicators, trouble codes, and the MIL (malfunction indicator light). If the vehicle fails the OBD II functional test, it will fail the overall inspection.

² Clean-plugging is the use of the OBD II readiness monitor status and stored fault code (trouble code) status of a passing vehicle for the purpose of illegally issuing a smog certificate to another vehicle that is not in compliance due to a failure to complete the minimum number of self tests, known as monitors, or due to the presence of a stored fault code that indicates an emission control system or component failure.

1	Date & Time of Inspection	Vehicle Certified	Certificate No.
2	12. 04/05/2011	2000 Hyundai Accent/Brio; License No. 6ESH595	OC357043C
3	17:13 – 17:18		
4		FIRST CAUSE FOR DISCIPLINE	
5	(Untrue or Misleading Statements)		
6	15. Respondent Eaton's registration is subject to disciplinary action pursuant to Bus. &		
7	Prof. Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements		
8	which it knew or in the exercise of reasonable care should have known to be untrue or		
9	misleading, as follows:		
10	a. Respond	dent Eaton's technician, Respondent Fakhriev, certified	l under penalty of
11	perjury on the vehic	le inspection reports for vehicles 1 through 10, identifi	ed in paragraph 14
12	above ³ , that he performed the smog inspections on the vehicles in accordance with all Bureau		
13	requirements and that the vehicles had passed inspection and were in compliance with applicable		
14	laws and regulations. In fact, Respondent conducted the inspections on the vehicles using clean-		
15	plugging methods in that he substituted or used a different vehicle(s) during the OBD II		
16	functional tests in order to issue smog certificates of compliance for the vehicles, and did not test		
17	or inspect the vehicles as required by Health & Saf. Code section 44012.		
18	b. Respond	dent Eaton's technician, Respondent Fakhriev, certified	that vehicles 11 and
19	12, identified in par	agraph 14 above, had passed inspection and were in co	mpliance with
20	applicable laws and regulations. In fact, Respondent conducted the inspections on the vehicles		
21	using clean-plugging methods in that he substituted or used a different vehicle(s) during the OBD		
22	II functional tests in order to issue smog certificates of compliance for the vehicles, and did not		
23	test or inspect the vehicles as required by Health & Saf. Code section 44012.		
24	///		
25	///		
26	///		
27	³ On June 3,	2011, the representative made a field visit at Respondenvoices and vehicle inspection reports for vehicles 1 th	ent Eaton's facility and
28	obtained copies of f	m, orees and remote inspection reports for venicles 1 th	1005x1 101

SECOND CAUSE FOR DISCIPLINE

(Fraud)

16. Respondent Eaton's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that Respondent committed acts which constitute fraud by issuing electronic smog certificates of compliance for vehicles 1 through 12, identified in paragraph 14 above, without performing bona fide inspections of the emission control devices and systems on the vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

THIRD CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 17. Respondent Eaton's smog check station license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed to comply with the following sections of that Code:
- a. <u>Section 44012</u>: Respondent failed to ensure that the emission control tests on vehicles 1 through 12, identified in paragraph 14 above, were performed in accordance with procedures prescribed by the department.
- b. <u>Section 44015</u>: Respondent issued electronic smog certificates of compliance for vehicles 1 through 12, identified in paragraph 14 above, without ensuring that the vehicles were properly tested and inspected to determine if they were in compliance with Health & Saf. Code section 44012.

21 | ///

1

2

3

4

5

6

7

8

()

10

11

12

13

14

15

16

17

18

19

20

22 | 1//

23 | ///

24 | ///

25 | ///

26 ///

27 | ///

28 | ///

///

FOURTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 18. Respondent Eaton's smog check station license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2. subdivision (c), in that Respondent failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.35, subdivision (c)</u>: Respondent issued electronic smog certificates of compliance for vehicles 1 through 12, identified in paragraph 14 above, even though the vehicles had not been inspected in accordance with section 3340.42.
- b. <u>Section 3340.42</u>: Respondent failed to conduct the required smog tests on vehicles 1 through 12, identified in paragraph 14 above, in accordance with the Bureau's specifications.

FIFTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

19. Respondent Eaton's smog check station license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in that Respondent committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic smog certificates of compliance for vehicles 1 through 12, identified in paragraph 14 above, without performing bona fide inspections of the emission control devices and systems on the vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

SIXTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

20. Respondent Fakhriev's technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed to comply with section 44012 of that Code, as follows: Respondent failed to perform the emission control tests on vehicles 1 through 12, identified in paragraph 14 above. in accordance with procedures prescribed by the department.

SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant

to the Motor Vehicle Inspection Program)

- 21. Respondent Fakhriev's technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2. subdivision (c), in that Respondent failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.30, subdivision (a)</u>: Respondent failed to inspect and test vehicles 1 through 12, identified in paragraph 14 above, in accordance with Health & Saf. Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
- b. <u>Section 3340.42</u>: Respondent failed to conduct the required smog tests on vehicles 1 through 12, identified in paragraph 14 above, in accordance with the Bureau's specifications.

EIGHTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

22. Respondent Fakhriev's technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in that Respondent committed dishonest, fraudulent, or deceitful acts whereby another is injured by issuing electronic smog certificates of compliance for vehicles 1 through 12, identified in paragraph 14 above, without performing bona fide inspections of the emission control devices and systems on the vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

OTHER MATTERS

- 23. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the Director may suspend, revoke, or place on probation the registration for all places of business operated in this state by Respondent Eaton Auto Diagnostics, Inc., doing business as High St Smog Check, upon a finding that Respondent has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.
- 24. Pursuant to Health & Saf. Code section 44072.8, if Smog Check, Test Only, Station License Number TC 261712. issued to Respondent Eaton Auto Diagnostics, Inc., doing business

1	8. Taking such other and further action as deemed necessary and proper.
2	
3	DATED: 11312 SHERRY MEHL
4	Chief
5	Bureau of Automotive Repair Department of Consumer Affairs State of California
6	Complainant
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19 20	
21	
22	
23	
24	
25	
26	
27	
28	SF2011202651