-				
1				
2	Attorney General of California JANICE K. LACHMAN Supervising Deputy Attorney General KRISTINA T. JANSEN Deputy Attorney General State Bar No. 258229			
3				
4				
5	1300 I Street, Suite 125 P.O. Box 944255			
6	Sacramento, CA 94244-2550 Telephone: (916) 324-5403			
7	Facsimile: (916) 327-8643 Attorneys for Complainant			
8	BEFORE THE			
9	DEPARTMENT OF CONSUMER AFFAIRS FOR THE BUREAU OF AUTOMOTIVE REPAIR			
10	STATE OF CALIFORNIA			
11	1	77/15-12		
12		11/13/18		
13	BROOKS PERFORMANCE, dba BROOKS PERFORMANCE AND MACHINE CINDY BROOKS, PRES./TREAS. MITCHELL BROOKS, V.P./SECTY A C C U S A T I O N			
14				
15	5 3180 S. Parkway Drive Fresno, CA 93725			
16	Automotive Repair Dealer Reg. No. ARD 267691			
17	7 Respondent.			
18	8			
19	9 Complainant alleges:	Complainant alleges:		
20	<u>PARTIES</u>			
21	1. Patrick Dorais ("Complainant") brings this Accusation solely in his official capacity			
22	as the Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer Affairs.			
23	2. On or about January 11, 2012, the Director of Consumer Affairs ("Director") issued			
24	Automotive Repair Dealer Registration Number ARD 267691 to Brooks Performance			
25	5 ("Respondent"), doing business as Fresno Performance/Acc Engine, v	("Respondent"), doing business as Fresno Performance/Acc Engine, with Cindy Brooks as		
26	president and treasurer and Mitchell Brooks as vice president and secretary. On or about			
27	February 18, 2013, Respondent's business name was changed to Brooks Performance and			
28				
	1			

7. Code section 9884.9, subdivision (a), states, in pertinent part:

The automotive repair dealer shall give to the customer a written estimated price for labor and parts necessary for a specific job. No work shall be done and no charges shall accrue before authorization to proceed is obtained from the customer. No charge shall be made for work done or parts supplied in excess of the estimated price without the oral or written consent of the customer that shall be obtained at some time after it is determined that the estimated price is insufficient and before the work not estimated is done or the parts not estimated are supplied. Written consent or authorization for an increase in the original estimated price may be provided by electronic mail or facsimile transmission from the customer. The bureau may specify in regulation the procedures to be followed by an automotive repair dealer when an authorization or consent for an increase in the original estimated price is provided by electronic mail or facsimile transmission. If that consent is oral, the dealer shall make a notation on the work order of the date, time, name of person authorizing the additional repairs and telephone number called, if any, together with a specification of the additional parts and labor . . .

8. Code section 22, subdivision (a), states:

"Board" as used in any provision of this Code, refers to the board in which the administration of the provision is vested, and unless otherwise expressly provided, shall include "bureau," "commission," "committee," "department," "division," "examining committee," "program," and "agency."

- 9. Code section 477, subdivision (b), states, in pertinent part, that a "license" includes "registration" and "certificate."
- 10. California Code of Regulations, title 16, section ("Regulation") 3356 states, in pertinent part:
 - (a) All invoices for service and repair work performed, and parts supplied, as provided for in Section 9884.8 of the Business and Professions Code, shall comply with the following:
 - (1) The invoice shall show the automotive repair dealer's registration number and the corresponding business name and address as shown in the Bureau's records...
 - (2) The invoice shall separately list, describe and identify all of the following:
 - (A) All service and repair work performed, including all diagnostic and warranty work, and the price for each described service and repair.
 - (B) Each part supplied, in such a manner that the customer can understand what was purchased, and the price for each described part. The description of each part shall state whether the part was new, used, reconditioned, rebuilt, or an OEM crash part, or a non-OEM aftermarket crash part.
 - (C) The subtotal price for all service and repair work performed.

(D) The subtotal price for all parts supplied, not including sales tax . . .

11. Regulation 3373 states:

No automotive repair dealer or individual in charge shall, in filling out an estimate, invoice, or work order, or record required to be maintained by section 3340.15(f) of this chapter, withhold therefrom or insert therein any statement or information which will cause any such document to be false or misleading, or where the tendency or effect thereby would be to mislead or deceive customers, prospective customers, or the public.

COST RECOVERY

12. Code section 125.3 provides, in pertinent part, that a Board may request the administrative law judge to direct a licentiate found to have committed a violation or violations of the licensing act to pay a sum not to exceed the reasonable costs of the investigation and enforcement of the case.

CONSUMER COMPLAINT (K. S.): 1971 DODGE DUSTER

- 13. On or about March 12, 2012, K. S., who was in the United States Navy, took the engine from his 1971 Dodge Duster to Respondent's facility to have it rebuilt. In and between April and June 2012, K. S. paid the facility a total of \$2,710.40.
- 14. In or about September 2012, K. S. went on deployment. When K. S. returned, he contacted the facility to check on the status of the repairs. The facility would not return K. S.'s call(s). Later, K. S. went to the facility and found that it was closed.
 - 15. On or about June 25, 2013, K. S. filed a complaint with the Bureau.
- 16. On or about July 2, 2013, K. S. spoke with Mitchell Brooks and was informed that his engine had been taken to Allegiance Auto Machine ("Allegiance") in Fresno. K. S. went to Allegiance to pick up the engine. The engine had been disassembled, but it did not appear that any work had been performed. K. S. returned to Respondent's facility and was given all of the other engine parts except the flywheel.
- 17. On or about July 3, 2013, a Bureau representative met with K. S. and inspected the engine. There was no indication that any repairs had been performed on the unit.
- 18. On or about July 9, 2013, the representative went to the facility and met with Cindy and Mitchell Brooks. Mitchell Brooks ("M. Brooks") claimed that they did not start the work

until K. S. returned from deployment because they did not want the engine to sit and rust at the facility. M. Brooks also claimed that the repairs had been under-quoted by a former employee, that the work would now cost more than \$2,710.40, and that the Brooks did not have the money to start the engine rebuild.

19. On or about July 10, 2013, the representative returned to the facility and obtained copies of K. S.'s service file, including Service Order #181 dated March 13, 2012. The service order showed that K. S. had authorized the facility to tear down (disassemble) and inspect the engine for \$100. The representative recommended that the facility issue K. S. a refund of his \$2,610.40. M. Brooks again claimed that they did not have the money, and refused to issue K. S. a refund.

FIRST CAUSE FOR DISCIPLINE

(Fraud)

20. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that Respondent committed acts constituting fraud, as follows: After obtaining \$2,710.40 from K. S. for the rebuilding of the engine on his 1971 Dodge Duster, Respondent, through its automotive technicians, employees, or officers, including Mitchell and Cindy Brooks, failed to perform any of the work, with the exception of the teardown and inspection, failed to refund any portion of the \$2,710.40 to K. S., and misappropriated or diverted K. S.'s money.

SECOND CAUSE FOR DISCIPLINE

(Failure to Comply with the Code)

21. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent failed to comply with section 9884.9, subdivision (a), of that Code in a material respect, as follows: Respondent failed to document on Service Order #181 K. S.'s authorization for the \$2,610.40 in additional repairs, i.e., the rebuilding of the engine.

///

///

CONSUMER COMPLAINT (N. B.): 1992 FORD MUSTANG

- 22. In or about February 2011, N. B. took his 1992 Ford Mustang to Fresno Performance/Ace Engine and Machine ("Fresno Performance") to have a General Motors LS1 engine installed in the vehicle. The engine was to be machined to a size of 383 cubic inches with a manual transmission, turbo charger, and intercooler installed.
- While the vehicle was under repair at Fresno Performance, the owner sold the business to Cindy and Mitchell Brooks. The Brooks agreed to continue the work and to have it completed by August 6, 2012. N. B. made several payments to the Brooks and authorized them to sell the original seats on the vehicle for a credit of \$100. The Brooks did not finish the work by August 6, 2012 as promised. N. B. was informed that the engine installation had not been completed, the vehicle could not be driven, and the facility was closing.
 - 24. On or about June 26, 2013, N. B. filed a complaint with the Bureau.
- 25. On or about July 1, 2013, Bureau Representative R. G. inspected the vehicle and determined that Respondent Brooks Performance had built and installed a roll cage, and had installed the engine, transmission, front engine/cross member adapter for set up or mock up, the sub frame connectors and five lug wheel conversion. The engine compartment wiring harness and interior had also been removed.
- 26. On or about July 9, 2013, R. G. and Burcau Representative W. T. met with the Brooks at the Bureau's Fresno Field Office. The Brooks provided the representatives with copies of their repair records on the vehicle, including Service Order #251 dated May 21, 2012 and Invoice #590 dated February 14, 2013. The Brooks confirmed that the repairs had been started by the previous owner and that Brooks Performance had agreed to take over the work. The Brooks claimed that they were unable to continue working on the vehicle. R. G. asked the Brooks when they would be returning the vehicle and parts to N. B. and refunding his money. The Brooks claimed that they did not have N. B.'s money and were closing the facility. Later, the Brooks admitted that they placed all of their customers' money into a common fund, and took money paid by one customer and used or applied it toward the repair of a different customer's vehicle. The Brooks also used their customers' money to pay for the facility's general operations. The

representatives reviewed the repair records and found that N. B. had paid Brooks Performance approximately \$14,500. R. G. inspected the vehicle using Invoice #590 for comparison and found that Brooks Performance failed to perform approximately \$12,938.95 in repairs on the vehicle.

THIRD CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

- 27. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows:
- a. Respondent represented on the invoice that a custom wiring harness was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- b. Respondent represented on the invoice that hoses, oil, water, and miscellaneous parts (required for the engine operation) were supplied or installed on N. B.'s 1992 Ford Mustang. In fact, none of those parts were supplied or installed on the vehicle.
- c. Respondent represented on the invoice that a "Be Cool" radiator was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- d. Respondent represented on the invoice that a used electric fan was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- e. Respondent represented on the invoice that a flex-a-lite fan switch was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- f. Respondent represented on the invoice that GM performance sensors were supplied or installed on N. B.'s 1992 Ford Mustang. In fact, those parts were not supplied or installed on the vehicle.

///

- g. Respondent represented on the invoice that a Bosch fuel injector was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- h. Respondent represented on the invoice that a small block Chevy power steering pulley was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- i. Respondent represented on the invoice that a GM performance starter was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- j. Respondent represented on the invoice that used coil packs were supplied or installed on N. B.'s 1992 Ford Mustang. In fact, those parts were not supplied or installed on the vehicle.
- k. Respondent represented on the invoice that a thermostat was supplied or installed onN. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- Respondent represented on the invoice that a custom made throttle cable was supplied
 or installed on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the
 vehicle.
- m. Respondent represented on the invoice that a battery relocation kit was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, a battery relocation kit was not supplied or installed on the vehicle.
- n. Respondent represented on the invoice that a custom made fuel system was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, a custom made fuel system was not supplied or installed on the vehicle.
- o. Respondent represented on the invoice that a custom built exhaust system was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, a custom built exhaust system was not supplied or installed on the vehicle.
- p. Respondent represented on the invoice that a custom built intake system was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, a custom built intake system was not supplied or installed on the vehicle.

q. Respondent represented on the invoice that a Turbonetics Turbo kit for an LS1 Fox Conversion; i.e., turbo charger, was supplied or installed on N. B.'s 1992 Ford Mustang. In fact, a turbo charger was not been supplied or installed on the vehicle.

FOURTH CAUSE FOR DISCIPLINE

(Fraud)

- 28. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that Respondent committed acts constituting fraud, as follows:
- a. Respondent obtained payment from N. B. for supplying or installing a custom wiring harness on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- b. Respondent obtained payment from N. B. for supplying or installing hoses, oil, water, and miscellaneous parts (required for the engine operation) on N. B.'s 1992 Ford Mustang. In fact, none of those parts were supplied or installed on the vehicle.
- c. Respondent obtained payment from N. B. for supplying or installing a "Be Cool" radiator on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- d. Respondent obtained payment from N. B. for supplying or installing a used electric fan on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- e. Respondent obtained payment from N. B. for supplying or installing a flex-a-lite fan switch on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- f. Respondent obtained payment from N. B. for supplying or installing GM performance sensors on N. B.'s 1992 Ford Mustang. In fact, those parts were not supplied or installed on the vehicle.
- g. Respondent obtained payment from N. B. for supplying or installing a Bosch fuel injector on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.

-///

- h. Respondent obtained payment from N. B. for supplying or installing a small block Chevy power steering pulley on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- i. Respondent obtained payment from N. B. for supplying or installing a GM performance starter on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- j. Respondent obtained payment from N. B. for supplying or installing used coil packs on N. B.'s 1992 Ford Mustang. In fact, those parts were not supplied or installed on the vehicle.
- k. Respondent obtained payment from N. B. for supplying or installing a thermostat on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- l. Respondent obtained payment from N. B. for supplying or installing a custom made throttle cable on N. B.'s 1992 Ford Mustang. In fact, that part was not supplied or installed on the vehicle.
- m. Respondent obtained payment from N. B. for supplying or installing a battery relocation kit on N. B.'s 1992 Ford Mustang. In fact, a battery relocation kit was not supplied or installed on the vehicle.
- n. Respondent obtained payment from N. B. for supplying or installing a custom made fuel system on N. B.'s 1992 Ford Mustang. In fact, a custom made fuel system was not supplied or installed on the vehicle.
- o. Respondent obtained payment from N. B. for supplying or installing a custom built exhaust system on N. B.'s 1992 Ford Mustang. In fact, a custom built exhaust system was not supplied or installed on the vehicle.
- p. Respondent obtained payment from N. B. for supplying or installing a custom built intake system on N. B.'s 1992 Ford Mustang. In fact, a custom built intake system was not supplied or installed on the vehicle.
- q. Respondent obtained payment from N. B. for supplying or installing a Turbonetics

 Turbo kit for an LS1 Fox Conversion; i.e., turbo charger, on N. B.'s 1992 Ford Mustang. In fact,
 a turbo charger was not been supplied or installed on the vehicle.

FIFTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Code)

29. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent failed to comply with section 9884.9, subdivision (a), of that Code in a material respect, as follows: Respondent failed to specify on Service Order #251 the parts and/or labor that were included in the repairs described as "general service... install LS1 with customers new cross member" and "general service: custom wire harness".

SIXTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

- 30. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent failed to comply with Regulation 3356 in the following material respects:
- a. <u>Subdivision (a)(1)</u>: Respondent failed to show its automotive repair dealer registration number on the invoice or its correct business name (the business name was listed as Brooks Performance rather than Brooks Performance, doing business as Fresno Performance/Acc Engine).
- b. <u>Subdivision (a)(2)(A)</u>: Respondent failed to list, describe or identify on the invoice all service and repair work performed on N. B.'s 1992 Ford Mustang.
- c. <u>Subdivision (a)(2)(B)</u>: Respondent failed to state on the invoice whether the parts installed or supplied on N. B.'s 1992 Ford Mustang were new, used, reconditioned, or rebuilt.
- d. <u>Subdivisions (a)(2)(C) and (D)</u>: Respondent failed to show on the invoice the subtotal prices for all service and repair work performed and all parts supplied on N. B.'s 1992 Ford Mustang.

///

///

CONSUMER COMPLAINT (C. C.): 1979 CHEVROLET CAMARO

- 31. Complainant incorporates by reference as though fully set forth herein the allegations contained in paragraph 26 above.
- 32. In or about September 2013, C. C. filed a complaint with the Bureau, stating that he paid Respondent's facility \$10,000 to have the engine and transmission converted or rebuilt on his 1979 Chevrolet Camaro and that the facility failed to perform any of the work with the exception of "one dyno run". C. C. also stated that he picked up the vehicle when the facility went out of business and that they had failed to refund him any of his money. C. C. provided the Bureau with documentation showing that he paid the facility a total of \$9,500 between October 2012 and March 2013.
- 33. On or about October 2, 2013, Bureau Representative R. G. met with the Brooks. M. Brooks stated that the engine on C. C.'s 1979 Chevrolet Camaro was to be rebuilt and installed in another vehicle (a 2001 Chevrolet Camaro). M. Brooks claimed that C. C. signed over his 1999 Chevrolet Camaro to the Brooks in exchange for credit, and that the credit was to be applied towards other repairs. M. Brooks stated that C. C. later brought them the 2001 Chevrolet Camaro. M. Brooks admitted that they failed to perform all of the work on the vehicles and owed C. C. a refund.
- 34. On or about October 7, 2013, M. Brooks provided the Bureau with copies of their repair records on the vehicle, including Invoice #714 dated May 6, 2013, pertaining to repairs performed on the 1979 Chevrolet Camaro. The documents showed that C. C. was issued a credit of \$500 for the 1979 Chevrolet Camaro, that a total of \$3,196.47 in repairs had been performed on behalf of C. C., and that C. C. had a credit of \$4,635.29 remaining on his account.

SEVENTH CAUSE FOR DISCIPLINE

(Fraud)

35. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that Respondent committed acts constituting fraud, as follows: After obtaining \$9,500 from C. C. for the repair of his vehicles and issuing him a credit of \$500,

Respondent, through its automotive technicians, employees, or officers, including Mitchell and Cindy Brooks, failed to complete the work, failed to refund any portion of the \$4,635.29 to C. C.'s account, and misappropriated or diverted C. C.'s money.

EIGHTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

- 36. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent failed to comply with Regulation 3356 in the following material respects:
- a. <u>Subdivision (a)(1)</u>: Respondent failed to show its automotive repair dealer registration number on the invoice or its correct business name (the business name was listed as Brooks Performance rather than Brooks Performance, doing business as Brooks Performance and Machine).
- b. <u>Subdivision (a)(2)(A)</u>: Respondent failed to list, describe or identify on the invoice all service and repair work performed on the 1979 Chevrolet Camaro (Respondent listed the parts supplied on the vehicle, but not the related repairs).
- c. <u>Subdivision (a)(2)(B)</u>: Respondent failed to state on the invoice whether the parts supplied on the 1979 Chevrolet Camaro were new, used, reconditioned, or rebuilt.
- d. <u>Subdivisions (a)(2)(C) and (D)</u>: Respondent failed to show on the invoice the subtotal prices for all service and repair work performed and all parts supplied on the 1979 Chevrolet Camaro.

CONSUMER COMPLAINT (K. C.): 1997 PONTIAC TRANS AM

- 37. Complainant incorporates by reference as though fully set forth herein the allegations contained in paragraph 26 above.
- 38. On or about May 26, 2012, K. C., Jr., a United States Marine, took his 1997 Pontiac Trans Am to Respondent's facility to have the existing engine replaced with a custom built performance engine. K. C., Jr. was subsequently deployed.
- 39. In or about October 2013, K. C., Sr. filed a complaint with the Bureau, stating, in substance, as follows: K. C., Sr. and his son were co-owners of the vehicle. M. Brooks told

///

- K. C., Sr. and his son that it would cost over \$18,000 to perform the above work, and requested half of the money up front. K. C., Sr. and his son approved the estimate price and paid M. Brooks a total of \$10,000 in May 2012. In or about July 2013, K. C., Sr. went to the facility to make another payment. K. C., Sr. found the door locked and saw a note on the door, indicating that the facility's customers needed to retrieve their vehicles from the shop on July 11, 2013. Later, K. C., Sr. met with M. Brooks and asked him where the new engine and parts were for the vehicle. M. Brooks said, "I owe you and your son about \$15,000", or words to that effect. K. C., Sr. had the vehicle towed from the facility. The original engine was returned to K. C., Sr.; however, the oil pan, a valve cover, and one of the head bolts had been removed.
- 40. On or about November 6, 2013, Bureau Representative R. G. inspected the vehicle and found that the engine and all accessory drives had been removed in addition to the transmission and cooling system. K. C., Sr. provided R. G. with copies of various documents he had received from the facility, including Estimate #286 dated May 26, 2012, Invoice #636 dated March 12, 2013, and a handwritten noted dated July 18, 2013, signed by Cindy Brooks. The documents showed that between May 2012 and June 2013, K. C., Sr. and/or his son paid the facility a total of \$14,185.
- 41. On or about November 14, 2013, R. G. met with the Brooks and informed them that he had inspected the vehicle, and found that the engine, transmission, and all under hood components had been removed, but no other work had been performed. M. Brooks claimed that they had ordered most of the parts, including the cylinder heads, crankshaft, rods, and pistons, but diverted the parts to other vehicles since K. C., Jr. was on deployment. R. G. showed the Brooks the note identified in paragraph 40 above. The note indicated that the Brooks had deducted \$1,000 from K. C., Sr. and his son's account for the removal of the old engine, leaving a net credit of \$13,185. The Brooks agreed they owed K. C., Sr. and his son \$13,185. R. G. told the Brooks that based upon his inspection of the vehicle, he had determined that none of the repairs listed on the invoice had been performed and/or completed. The Brooks refused to refund K. C., Sr. and his son any money.

28 | ///

///

NINTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

42. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows:

Respondent represented on Invoice #636 that certain parts were supplied or installed on K. C., Sr.'s and K. C., Jr.'s 1997 Pontiac Trans Am, including, but not limited to, CNC heads, cylinder head studs, push rods, a Texas Speed Rumbler Bullet True Dual, a connecting rod, Texas Speed Long Tube LS1 headers, a front crank seal, a South Bend clutch, Manley Performance non-twist forgings, a water pump gasket, a rear main seal housing, a rear main seal, an oil pan gasket, 4 custom camshafts, an axle assembly, a cylinder head gasket, a cable driven throttle body, an exhaust manifold gasket, an oil pump, an intake manifold, and/or a valley cover gasket. In fact, none of those parts were supplied or installed on the vehicle.

TENTH CAUSE FOR DISCIPLINE

(Fraud)

- 43. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that Respondent committed acts constituting fraud, as follows:
- a. After obtaining \$14,185 from K. C., Sr. and/or K. C., Jr. for the installation of a custom built performance engine in their 1997 Pontiac Trans Am, Respondent, through its automotive technicians, employees, or officers, including Mitchell and Cindy Brooks, failed to complete the work, failed to refund K. C., Sr. and/or K. C., Jr. any portion of the \$13,185 remaining on their account, and misappropriated or diverted K. C., Sr.'s and/or K. C., Jr.'s money.
- b. Respondent's officers, Mitchell and Cindy Brooks, diverted parts that they had purchased for K. C., Sr.'s and K. C., Jr.'s 1997 Pontiac Trans Am to other consumers' vehicles, as set forth in paragraph 41 above.

///

 $/\!/\!/$

///

///

ELEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Code)

44. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent failed to comply with section 9884.9, subdivision (a), of that Code in a material respect, as follows: Respondent failed to specify on Estimate #286 the parts and/or labor that were included in the repairs described as "machine: machine pkg", "machine: engine balancing", "machine: engine assembly", and "4 custom camshaft intake design #3729 exhaust design #3732".

TWELFTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

- 45. Respondent is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent failed to comply with Regulation 3356 in the following material respects:
- a. <u>Subdivision (a)(1):</u> Respondent failed to show its automotive repair dealer registration number on the invoice or its correct business name (the business name was listed as Brooks Performance rather than Brooks Performance, doing business as Brooks Performance and Machine).
- b. <u>Subdivision (a)(2)(A)</u>: Respondent failed to list, describe or identify on the invoice all service and repair work performed on the 1997 Pontiac Trans Am.
- e. <u>Subdivision (a)(2)(B)</u>: Respondent failed to state on the invoice whether the parts supplied on the 1997 Pontiac Trans Am were new, used, reconditioned, or rebuilt.
- d. <u>Subdivisions (a)(2)(C) and (D)</u>: Respondent failed to show on the invoice the subtotal prices for all service and repair work performed and all parts supplied on the 1997 Pontiac Trans Am.

1	1
П	f)
1	11

OTHER MATTERS

46. Pursuant to Code section 9884.7, subdivision (c), the Director may suspend, revoke, or place on probation the registration for all places of business operated in this state by Respondent Brooks Performance, doing business as Brooks Performance and Machine, upon a finding that Respondent has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.

PRAYER

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of Consumer Affairs issue a decision:

- 1. Revoking or suspending Automotive Repair Dealer Registration Number ARD 267691, issued to Brooks Performance, doing business as Brooks Performance and Machine;
- 2. Ordering Brooks Performance, doing business as Brooks Performance and Machine, to pay the Director of Consumer Affairs the reasonable costs of the investigation and enforcement of this case, pursuant to Business and Professions Code section 125.3;
 - 3. Taking such other and further action as deemed necessary and proper.

DATED: Hugust 26, 2014

PATRICK DORAIS

Chief

Bureau of Automotive Repair
Department of Consumer Affairs

State of California Complainant

SA2014116092

2.7