

1 ROB BONTA  
Attorney General of California  
2 ARMANDO ZAMBRANO  
Supervising Deputy Attorney General  
3 KEVIN J. SCHETTIG  
Deputy Attorney General  
4 State Bar No. 234240  
300 So. Spring Street, Suite 1702  
5 Los Angeles, CA 90013  
Telephone: (213) 269-6272  
6 Facsimile: (916) 731-2126  
E-mail: Kevin.Schettig@doj.ca.gov  
7 *Attorneys for Complainant*

8 **BEFORE THE**  
9 **DEPARTMENT OF CONSUMER AFFAIRS**  
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**  
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 79/25-13743

13 **LA SMOG CHECK, CESAR AUGUSTO**  
14 **LARIOS, OWNER**  
2307 Whittier Blvd Unit C  
Los Angeles, CA 90023

**ACCUSATION**

15 **Automotive Repair Dealer Registration No.**  
16 **ARD 306077**  
**Smog Check, Test-Only, Station License No.**  
17 **TC 306077**

18 **and**

19 **HERNAN MOLINA LOPEZ**  
5134 Ithaca Ave  
Los Angeles, CA 90032

20 **Mailing Address:**  
21 **6046 Romaine St Apt 3**  
Los Angeles, CA 90038

22 **Smog Check Inspector License No. EO**  
23 **640564**

24 Respondents.

25  
26 ///

27 ///

28 ///

1 **PARTIES**

2 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as  
3 the Chief of the Bureau of Automotive Repair (Bureau), Department of Consumer Affairs.

4 2. On or about June 14, 2023, the Bureau issued Automotive Repair Dealer Registration  
5 Number ARD 306077 to Cesar Augusto Larios, dba LA Smog Check (Respondent LA Smog  
6 Check). The Automotive Repair Dealer Registration was in full force and effect at all times  
7 relevant to the charges brought herein and will expire on June 30, 2026, unless renewed.

8 3. On or about August 17, 2023, the Bureau issued Smog Check, Test-Only, Station  
9 License Number TC 306077 to Respondent LA Smog Check. The Smog Check, Test-Only,  
10 Station License expired on June 30, 2025, and has not been renewed.

11 4. On or about December 27, 2023, the Bureau issued STAR Station Certification to  
12 Respondent LA Smog Check. The STAR Station Certification was suspended on April 1, 2025  
13 and became inactive when the Smog Check, Test-Only, Station License expired on June 30, 2025.

14 5. On or about September 8, 2017, the Bureau issued Smog Check Inspector License  
15 Number EO 640564 to Hernan Molina Lopez (Respondent Lopez). The Smog Check Inspector  
16 License was in full force and effect at all times relevant to the charges brought herein but expired  
17 on April 30, 2025, and has not been renewed.

18 **OTHER LICENSES**

19 6. On or about April 14, 2015, the Bureau issued Smog Check Inspector License  
20 Number EO 634964 to Respondent Cesar Augusto Larios (Respondent Larios). The Smog Check  
21 Inspector License was in full force and effect at all times relevant to the charges brought herein  
22 and will expire on March 31, 2027, unless renewed.

23 7. On or about April 14, 2015, the Bureau issued Smog Check Repair Technician (EI)  
24 License Number 634964 to Respondent Larios. The Smog Check Repair Technician License  
25 expired on March 31, 2019, and has not been renewed.

26 8. On or about July 20, 2018, the Bureau issued Automotive Repair Dealer Registration  
27 Number ARD 291592 to Respondent Larios, dba Cesar Smog Check. The Automotive Repair  
28

1 Dealer Registration was in full force and effect at all times relevant to the charges brought herein  
2 and will expire on July 31, 2026, unless renewed.

3 9. On or about August 7, 2018, the Bureau issued Smog Check, Test-Only, Station  
4 License Number to Respondent Larios, dba Cesar Smog Check. The Smog Check, Test-Only,  
5 Station License was in full force and effect at all times relevant to the charges brought herein and  
6 will expire on July 31, 2026, unless renewed.

7 10. On or about December 31, 2018, the Bureau issued STAR Station Certification to  
8 Respondent Larios, dba Cesar Smog Check. The STAR Station Certification will remain active  
9 unless the Automotive Repair Dealer Registration and/or Smog Check, Test-Only, Station  
10 License is revoked, cancelled, becomes delinquent, or certification is suspended.

### 11 **JURISDICTION**

12 11. This Accusation is brought before the Director of the Department of Consumer  
13 Affairs (Director) for the Bureau, under the authority of the following laws.

14 12. Section 9884.7 of the Code provides that the Director may revoke an automotive  
15 repair dealer registration.

16 13. Section 9884.13 of the Code provides, in pertinent part, that the expiration of a valid  
17 registration shall not deprive the Director of jurisdiction to proceed with a disciplinary proceeding  
18 against an automotive repair dealer or to render a decision temporarily or permanently  
19 invalidating (suspending or revoking) a registration.

20 14. Health and Safety Code section 44002 provides, in pertinent part, that the Director  
21 has all the powers and authority granted under the Automotive Repair Act for enforcing the  
22 Motor Vehicle Inspection Program.

23 15. Health and Safety Code section 44072.6 provides, in pertinent part, that the expiration  
24 or suspension of a license by operation of law, or by order or decision of the Director of  
25 Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive the  
26 Director of jurisdiction to proceed with disciplinary action.

27 ///

28 ///

**STATUTORY PROVISIONS**

16. Section 9884.7 of the Code provides, in pertinent part:

(a) The director, if the automotive repair dealer cannot show there was a bona fide error, may deny, suspend, revoke, or place on probation the registration of an automotive repair dealer for any of the following acts or omissions related to the conduct of the business of the automotive repair dealer, which are done by the automotive repair dealer or any automotive technician, employee, partner, officer, or member of the automotive repair dealer:

(1) Making or authorizing in any manner or by any means whatever any statement written or oral which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading.

...

(4) Any other conduct that constitutes fraud.

...

(6) Failure in any material respect to comply with the provisions of this chapter or regulations adopted pursuant to it.

...

17. Section 9889.22 of the Code provides:

The willful making of any false statement or entry with regard to a material matter in any oath, affidavit, certificate of compliance or noncompliance, or application form which is required by this chapter or Chapter 5 (commencing with Section 44000) of Part 5 of Division 26 of the Health and Safety Code constitutes perjury and is punishable as provided in the Penal Code.

18. Health and Safety Code section 44012 provides:

The test at the smog check stations shall be performed in accordance with procedures prescribed by the department and may require loaded mode dynamometer testing in enhanced areas, two-speed idle testing, testing utilizing a vehicle's onboard diagnostic system, or other appropriate test procedures as determined by the department in consultation with the state board. The department shall implement testing using onboard diagnostic systems, in lieu of loaded mode dynamometer or two-speed idle testing, on model year 2000 and newer vehicles only, beginning no earlier than January 1, 2013, and on model-year 1996-99, inclusive, vehicles only, beginning no earlier than January 1, 2025. However, the department, in consultation with the state board, may prescribe alternative test procedures that include loaded mode dynamometer or two-speed idle testing for vehicles with onboard diagnostic systems that the department and the state board determine exhibit operational problems. The department shall ensure, as appropriate to the test method, the following:

(a) Emission control systems required by state and federal law are reducing excess emissions in accordance with the standards adopted pursuant to subdivisions (a) and (c) of Section 44013.

1 (b) Motor vehicles are preconditioned to ensure representative and stabilized  
operation of the vehicle's emission control system.

2 (c) For other than diesel-powered vehicles, the vehicle's exhaust emissions of  
3 hydrocarbons, carbon monoxide, carbon dioxide, and oxides of nitrogen in an idle  
4 mode or loaded mode are tested in accordance with procedures prescribed by the  
department. In determining how loaded mode and evaporative emissions testing shall  
5 be conducted, the department shall ensure that the emission reduction targets for the  
enhanced program are met.

6 (d) For other than diesel-powered vehicles, the vehicle's fuel evaporative  
7 system and crankcase ventilation system are tested to reduce any nonexhaust sources  
of volatile organic compound emissions, in accordance with procedures prescribed by  
the department.

8 (e) For diesel-powered vehicles, a visual inspection is made of emission control  
9 devices and the vehicle's exhaust emissions are tested in accordance with procedures  
prescribed by the department, that may include, but are not limited to, onboard  
10 diagnostic testing. The test may include testing of emissions of any or all of the  
pollutants specified in subdivision (c) and, upon the adoption of applicable standards,  
11 measurement of emissions of smoke or particulates, or both.

12 (f) A visual or functional check is made of emission control devices specified  
by the department, including the catalytic converter in those instances in which the  
13 department determines it to be necessary to meet the findings of Section 44001. The  
visual or functional check shall be performed in accordance with procedures  
14 prescribed by the department.

15 (g) A determination as to whether the motor vehicle complies with the emission  
standards for that vehicle's class and model-year as prescribed by the department.

16 (h) An analysis of pass and fail rates of vehicles subject to an onboard  
17 diagnostic test and a tailpipe test to assess whether any vehicles passing their onboard  
diagnostic test have, or would have, failed a tailpipe test, and whether any vehicles  
18 failing their onboard diagnostic test have or would have passed a tailpipe test.

19 (i) The test procedures may authorize smog check stations to refuse the testing  
20 of a vehicle that would be unsafe to test, or that cannot physically be inspected, as  
specified by the department by regulation. The refusal to test a vehicle for those  
21 reasons shall not excuse or exempt the vehicle from compliance with all applicable  
requirements of this chapter.

22 19. Health and Safety Code section 44015, subdivision (b), provides:

23 (b) If a vehicle meets the requirements of Section 44012, a smog check station  
24 licensed to issue certificates shall issue a certificate of compliance or a certificate of  
noncompliance.

25 20. Health and Safety Code section 44032 provides:

26 No person shall perform, for compensation, tests or repairs of emission control  
27 devices or systems of motor vehicles required by this chapter unless the person  
performing the test or repair is a qualified smog check technician and the test or  
28 repair is performed at a licensed smog check station. Qualified smog check  
technicians shall perform tests of emission control devices and systems in accordance

1 with Section 44012.

2 21. Health and Safety Code section 44059 provides:

3 The willful making of any false statement or entry with regard to a material  
4 matter in any oath, affidavit, certificate of compliance or noncompliance, or  
5 application form which is required by this chapter or Chapter 20.3 (commencing with  
6 Section 9880) of Division 3 of the Business and Professions Code, constitutes perjury  
7 and is punishable as provided in the Penal Code.

8 22. Health and Safety Code section 44072.2 provides, in pertinent part:

9 The director may suspend, revoke, or take other disciplinary action against a  
10 license as provided in this article if the licensee, or any partner, officer, or director  
11 thereof, does any of the following:

12 (a) Violates any section of this chapter and the regulations adopted pursuant to  
13 it, which related to the licensed activities.

14 ...

15 (c) Violates any of the regulations adopted by the director pursuant to this  
16 chapter.

17 (d) Commits any act involving dishonesty, fraud, or deceit whereby another is  
18 injured.

19 ...

20 23. Health and Safety Code section 44072.10, subdivision (c), provides:

21 (c) The department shall revoke the license of any smog check technician or  
22 station licensee who fraudulently certifies vehicles or participates in the fraudulent  
23 inspection of vehicles. A fraudulent inspection includes, but is not limited to, all of  
24 the following:

25 (1) Clean piping, clean plugging, clean glassing, clean tanking, or any other  
26 fraudulent inspection practice, as defined by the department.

27 (2) Tampering with a vehicle emission control system or test analyzer system.

28 (3) Tampering with a vehicle in a manner that would cause the vehicle to  
falsely pass or falsely fail an inspection.

### **REGULATORY PROVISIONS**

24 24. California Code of Regulations, title 16, section 3340.24, subdivision (c), states:

25 (c) The bureau may suspend or revoke the license of or pursue other legal  
26 action against a licensee, if the licensee falsely or fraudulently issues or obtains a  
27 certificate of compliance or a certificate of noncompliance.

1 25. California Code of Regulations, title 16, section 3340.30 provides, in pertinent part:

2 A licensed smog check inspector and/or repair technician shall comply with the  
3 following requirements at all times while licensed:

4 (a) Inspect, test and repair vehicles, as applicable, in accordance with section  
5 44012 of the Health and Safety Code, section 44035 of the Health and Safety Code,  
6 and section 3340.42 of this article.

7 ...

8 26. California Code of Regulations, title 16, section 3340.35 provides, subdivision (c),  
9 provides, in pertinent part:

10 (c) A licensed station shall issue a certificate of compliance or noncompliance  
11 to the owner or operator of any vehicle that has been inspected in accordance with the  
12 procedures specified in section 3340.42 of this article and has all the required  
13 emission control equipment and devices installed and functioning correctly. . .

14 27. California Code of Regulations, title 16, section 3340.41 provides, in pertinent part:

15 ...

16 (c) No person shall enter any vehicle identification information or emission  
17 control system identification data for any vehicle other than the one being tested into  
18 the EIS or OIS. Nor shall any person enter into the EIS or OIS any false information  
19 about the vehicle being tested.

20 ...

21 (h) No licensed station shall have in the approved testing area at any time any  
22 electronic device or software capable of simulating the OBD data stream from a  
23 vehicle or manipulating OBD VIN, calibration identification, calibration verification  
24 number, MIL-status, readiness, or diagnostic trouble codes collected from a vehicle  
25 during a Smog Check Inspection.

26 ...

27 28. California Code of Regulations, title 16, section 3340.42, sets forth specific emissions  
28 test methods and procedures which apply to all vehicles inspected in the State of California.

29 29. California Code of Regulations, title 16, section 3373, provides:

30 No automotive repair dealer or individual in charge shall, in filling out an  
31 estimate, invoice, or work order, or record required to be maintained by section  
32 3340.15(e) of this chapter, withhold therefrom or insert therein any statement or  
33 information which will cause any such document to be false or misleading, or where  
34 the tendency or effect thereby would be to mislead or deceive customers, prospective  
35 customers, or the public.

1 **COST RECOVERY**

2 30. Section 125.3 of the Code provides, in pertinent part, that the Board may request the  
3 administrative law judge to direct a licensee found to have committed a violation or violations of  
4 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and  
5 enforcement of the case, with failure of the licensee to comply subjecting the license to not being  
6 renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be  
7 included in a stipulated settlement.

8 **FACTUAL ALLEGATIONS**

9 31. Beginning March 9, 2015, California’s Smog Check Program was updated to require  
10 the use of an On-Board Diagnostic Inspection System (OIS). OIS is the Smog Check equipment  
11 required in all areas of the State when inspecting most model-year 2000 and newer gasoline and  
12 hybrid vehicles and most 1998 and newer diesel vehicles. The system consists of a certified Data  
13 Acquisition Device (DAD), computer, bar code scanner, and printer. The DAD is an On-Board  
14 Diagnostic (OBD) scan tool that, when requested by the California OIS software, retrieves OBD  
15 data from the vehicle. All OBD data that the vehicle indicates it supports is requested by the  
16 California OIS software and will be retrieved. The DAD connects between the OIS computer and  
17 the vehicle’s Data Link Connector (DLC). The California OIS software requires a continuous  
18 Internet connection when performing a Smog Check inspection and the OIS software  
19 communicates with Bureau’s central database through the Internet connection. The bar code  
20 scanner is used to input technician information, the vehicles identification number (VIN), and  
21 Department of Motor Vehicles (DMV) renewal information. The printer provides a Vehicle  
22 Inspection Report (VIR) containing inspection results for motorists and a Smog Check Certificate  
23 of Compliance number for passing vehicles.

24 32. Data retrieved and recorded during an OIS smog check includes the eVIN, which is  
25 the digitally stored VIN programmed into the vehicle’s Powertrain Control Module (PCM); the  
26 communication protocol, which is the manufacturer/vehicle specific language the PCM uses to  
27 relay information; and the number of Parameter Identifications (PIDs), which is the number of  
28 specific data values each PCM uses related to emissions controls.

1           33. During an OIS inspection, engine operating parameters are retrieved from the  
2 vehicle's OBD II system and recorded to the VID. This is accomplished during the functional  
3 portion of the OIS Smog Check inspection by plugging the DAD into the vehicle's DLC when  
4 prompted by the OIS analyzer screen prompt. Some of the parameters recorded are: (1) engine  
5 speed in revolutions per minute (RPM); (2) throttle position as measured by a throttle position  
6 sensor (TPS) mounted onto the throttle shaft, measured in a percentage of opening from 0% at  
7 idle and near or up to 100% at full throttle; (3) manifold absolute pressure as measured by a  
8 manifold absolute pressure sensor (MAP) connected to an intake manifold source, measured in  
9 kilo pascals (kpa). Typical readings for a normally aspirated vehicle are 0 kpa being absolute  
10 vacuum, 25kpa to 45kpa at idle, 101 kpa at full throttle, same as atmospheric pressure at sea  
11 level; and (4) mass air flow as measured by a mass air flow sensor (MAF) mounted in the  
12 engine's air intake tract, measured in grams per second (gps).

13           34. During normal engine operation at idle, engine speed is relatively steady around its  
14 target idle speed. With the engine idling, the TPS is steady and at or near 0%. The MAP and/or  
15 MAF readings are also steady. In order for the engine speed to increase, the throttle would have  
16 to be opened in order to increase airflow through the engine. The engine's management systems  
17 supply fuel and spark timing appropriate to any changes in throttle position and engine speed. An  
18 increase in throttle, measured by the TPS, which increases engine RPM, would result in  
19 corresponding increases in MAF, as well as a change in MAP. Stated another way, any  
20 movement in the throttle from the idle position will result in an increase of airflow through the  
21 engine with corresponding increases RPM and MAF along with changes in MAP.

22           35. During an OIS Smog Check inspection, along with other visual and functional  
23 inspections, there is an OBD II query portion of the inspection. The OBD II query is performed  
24 with the engine idling and, when requested by the OIS analyzer, and an elevated or increased  
25 engine speed. The increase in engine speed is performed by the inspector by stepping on the  
26 throttle pedal or manually opening the throttle, resulting in a corresponding increase in engine  
27 RPMs by allowing an increase in airflow into the engine.

28 ///

1           36. If the vehicle passes the visual, functional and tailpipe tests, it passes the overall  
2 inspection, and a Certificate of Compliance is issued and transmitted electronically to the VID.  
3 Each Certificate of Compliance has a unique control number so that it can be tracked to determine  
4 which Smog Check Station purchased the Certificate of Compliance and to which vehicle it was  
5 issued.

6           37. The VID contains registration data from DMV, plus emission standards, vehicle smog  
7 check inspections, smog check stations and technicians, and Certificates of Compliance. The  
8 VID receives the passing smog check results immediately following the inspection. During the  
9 vehicle registration process, the DMV accesses the VID to verify that the vehicle has been tested  
10 and certified. The Bureau can also access the VID to view test data on smog check inspections  
11 performed at any Smog Check Station, or search for, retrieve, and print a test record for a  
12 particular vehicle which has been tested. The EIS or OIS, depending on the test type, also prints a  
13 VIR, which is a physical record of the test results and shows the Certificate of Compliance  
14 number that was issued if the vehicle passed the smog inspection.

15           38. The smog check technician must sign the VIR under penalty of perjury to indicate  
16 that the inspection was done within Bureau guidelines. Smog Check Stations are required by law  
17 to maintain a copy of the VIR along with a copy of the repair invoice for three years. The  
18 consumer's VIR serves as a receipt and proof that the VID was updated, and a Certificate of  
19 Compliance was issued. Licensed Smog Check Technicians are the only persons authorized by  
20 the Bureau to perform official inspections. They are issued a personal access code and a license,  
21 which are used to gain access to the EIS and OIS to perform smog check inspections.  
22 Unauthorized use of another technician's access code or license is prohibited.

23           39. The Bureau has become aware of methods some Smog Check stations and Smog  
24 Check inspectors use to fraudulently issue smog certificates to vehicles that will not pass a Smog  
25 Check test on their own, or in some instances, are not even present during the time the test is  
26 performed. One method is known as "clean plugging." "Clean plugging" is a method by which  
27 another vehicle's properly functioning OBD II system, or another source such as defeat devices,  
28 are used to generate passing data readings or diagnostic information for the purpose of

1 fraudulently issuing smog certificates to vehicles that are not in smog compliance and or not  
2 present for testing. Defeat devices attempt to simulate engine operation during a Smog Check  
3 inspection by transmitting OBD II data to the VID which has been modified or replaced entirely  
4 for the purportedly inspected vehicle during the functional portion of the OIS inspection. The use  
5 of a defeat device during a Smog Check inspection is clean plugging and is strictly prohibited.

6 40. A Bureau representative investigated and reviewed OIS test data for the smog check  
7 inspection performed at LA Smog Check from December 2024 through March 2025. The  
8 investigation revealed that data related to certain vehicles certified by Respondents contained a  
9 pattern of vehicles being certified with improbable engine operating parameters not  
10 corresponding to normal engine operation, confirming the vehicles receiving smog certificates  
11 were not tested during the OBD II functional test. This constitutes clean plugging, as follows:

12 **Clean Plug # 1**

13 41. On or about December 3, 2024, a 2000 Toyota Celica GT VIN  
14 JTDDR32T3Y0038754, CA License 8XLA146, was tested and smog certificate UG440266C was  
15 issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

16 42. The Dynamic PID chart for the 2000 Toyota Celica GT shows that between time  
17 stamp 834 and 24925, the engine RPM is steady at around 750 RPM. During this time, the data  
18 shows that the throttle is fixed at 12.2% and the MAF is fixed at 0.39gps. After time stamp  
19 24925, the data shows the engine RPM is increased and held steady at around 2035 RPM. During  
20 the elevated engine RPM, the data shows the throttle drops and remains fixed at 10.6% while the  
21 MAF rises and is between 1.12gps and 1.61gps.

22 43. The steady idle and steady elevated engine RPM data along with the improbable  
23 throttle positions and MAF readings are not characteristic or expected for normal engine  
24 operation. The throttle positions and MAF readings are expected to be stable during the steady  
25 idle and subsequently raised during the elevated engine RPM. During the improbable readings,  
26 the throttle had data points during the elevated engine RPM which never increased past the  
27 highest data point at idle. Additionally, during the elevated engine RPM, the data shows an  
28 improbable inverse correlation between the throttle and MAF. The discrepancies in the OIS test

1 data prove the Data Acquisition Device (DAD) was not connected as required to the 2000 Toyota  
2 Celica GT being certified, causing the issuance of a fraudulent Smog Check Certificate of  
3 Compliance.

4 **Clean Plug # 2**

5 44. On or about December 21, 2024, a 2003 Ford F150 VIN 1FTRX17243NA92544, CA  
6 License 96241V1, was tested and smog certificate UI223166C was issued under the license of  
7 Smog Check Inspector EO 640564, Respondent Lopez.

8 45. The Dynamic PID chart for the 2003 Ford F150 shows that between time stamp 345  
9 and 20415, the engine RPM is steady at around 735 RPM. During this time, the data shows that  
10 the throttle is fixed at 18% and the MAF is fixed at 6.65gps. After time stamp 20415, the data  
11 shows the engine RPM is increased and stays elevated at no less than 1644 RPM. During the  
12 elevated engine RPM, the data shows the throttle drops from 17.6% to 14.1%, then rises to 18%,  
13 and the MAF rises from 5.68gps to 7.49gps and ultimately drops to 5.52gps.

14 46. The steady idle and elevated engine RPM data along with the improbable throttle  
15 positions and MAF readings are not characteristic or expected for normal engine operation. The  
16 throttle positions and MAF readings are expected to be stable during the steady idle and  
17 subsequently raised during the elevated engine RPM. During the improbable readings, the  
18 throttle and MAF had data points during the elevated engine RPM which were lower than data  
19 points at idle. The throttle data points during the elevated engine RPM never increased past the  
20 highest data point at idle. The discrepancies in the OIS test data prove the Data Acquisition  
21 Device (DAD) was not connected as required to the 2003 Ford F150 being certified, causing the  
22 issuance of a fraudulent Smog Check Certificate of Compliance.

23 **Clean Plug # 3**

24 47. On or about February 14, 2025, a 2003 Ford Focus SE Comfort VIN  
25 1FAFP34383W181559, CA License 6KYC250, was tested and smog certificate UI223187C was  
26 issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

27 48. The Dynamic PID chart for the 2003 Ford Focus SE Comfort shows that between  
28 time stamp 341 and 24908, the engine RPM is steady at around 750 RPM. During this time, the

1 data shows that the throttle is fixed at 16.1% and the MAF is fixed at 5.64gps. After time stamp  
2 24908, the data shows the engine RPM is increased and held steady at around 2000 RPM. During  
3 the elevated engine RPM, the data shows the throttle gradually drops from 15.3% to 12.5%, then  
4 rises to 13.7% and the MAF is fluctuating between 6.53gps and 7.58gps.

5 49. The steady idle and steady elevated engine RPM data along with the improbable  
6 throttle positions and MAF readings are not characteristic or expected for normal engine  
7 operation. The throttle positions and MAF readings are expected to be stable during the steady  
8 idle and subsequently raised and stable during the steady elevated engine RPM. During the  
9 improbable readings, the throttle had data points during the elevated engine RPM which never  
10 increased past the highest data point at idle. Additionally, during the elevated engine RPM, the  
11 data shows an improbable inverse correlation between the throttle and MAF. The discrepancies  
12 in the OIS test data prove the Data Acquisition Device (DAD) was not connected as required to  
13 the 2003 Ford Focus SE Comfort being certified, causing the issuance of a fraudulent Smog  
14 Check Certificate of Compliance.

15 **Clean Plug # 4**

16 50. On or about March 11, 2025, a 2001 Ford F150 VIN 1FTRX17L61NA63312, CA  
17 License 7D55636, was tested and smog certificate UK656314C was issued under the license of  
18 Smog Check Inspector EO 640564, Respondent Lopez.

19 51. The Dynamic PID chart for the 2001 Ford F150 shows that between time stamp 340  
20 and 21266, the engine RPM is steady at around 755 RPM. During this time, the data shows that  
21 the throttle is fixed at 17.6% and the MAF is fixed at 6.6gps. After time stamp 21266, the data  
22 shows the engine RPM is increased and stays elevated at no less than 1441 RPM. During the  
23 elevated engine RPM, the data shows the throttle rises from 12.5% to 17.6%, then drops to 16.5%  
24 and the MAF rises from 6.38gps to 7.46gps, then ultimately drops to 5.76gps.

25 52. The steady idle and steady elevated engine RPM data along with the improbable  
26 throttle positions and MAF readings are not characteristic or expected for normal engine  
27 operation. The throttle positions and MAF readings are expected to be stable during the steady  
28 idle and subsequently raised during the elevated engine RPM. During the improbable readings,

1 the throttle and MAF had data points during the elevated engine RPM which were lower than data  
2 points at idle. The throttle data points during the elevated engine RPM never increased past the  
3 highest data point at idle. The discrepancies in the OIS test data prove the Data Acquisition  
4 Device (DAD) was not connected as required to the 2001 Ford F150 being certified, causing the  
5 issuance of a fraudulent Smog Check Certificate of Compliance.

6 53. On or about September 19, 2024, a previous Smog Check inspection was performed  
7 on the 2001 Ford F150 at a different, unrelated Smog Check station. The Dynamic PID chart for  
8 the 2001 Ford F150 shows that between time stamp 63 and 23754, the engine RPM is steady at  
9 around 710 RPM. During this time, the data shows that the throttle is fixed at 17.6% opening and  
10 the MAF is stable between 5.59gps and 5.91gps. After time stamp 23754, the data shows the  
11 engine RPM is increased and held steady at around 1930 RPM. During the steady elevated  
12 engine RPM, the data shows that the throttle is fixed at 20.8% opening and the MAF is stable  
13 between 15.68gps and 16.26gps. The steady idle and steady elevated engine RPM data along  
14 with the associated throttle positions and MAF readings are characteristic and expected for  
15 normal engine operation.

16 **Clean Plug # 5**

17 54. On or about March 14, 2025, a 2005 Chevrolet Silverado C3500 VIN  
18 1GBJC34U05E324056, CA License 26524V2, was tested and smog certificate UK656324C was  
19 issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

20 55. The Dynamic PID chart for the 2005 Chevrolet Silverado C3500 shows that between  
21 time stamp 347 and 22893, the engine RPM is steady at around 575 RPM. During this time, the  
22 data shows that the throttle is fixed at 5.1%, the MAF is fixed at 4.67gps, and the MAP is fixed at  
23 32kPa. After time stamp 22893, the data shows the engine RPM is increased and held steady at  
24 around 1900 RPM. During this time, the data shows that the throttle is varying between 0.4% and  
25 3.5%, the MAF drops from 4.62gps to 3.25gps, then ultimately rises to 4.53gps, and the MAP is  
26 fluctuating between 33kPa and 43kPa.

27 56. The steady idle and steady elevated engine RPM data along with the improbable  
28 throttle positions, MAF readings, and MAP readings are not characteristic or expected for normal

1 engine operation. The throttle positions and MAF readings are expected to be stable during the  
2 steady idle and subsequently raised and stable during the steady elevated engine RPM. During  
3 the improbable readings, the throttle and MAF had data points during the elevated engine RPM  
4 which never increased past the highest data point at idle. The discrepancies in the OIS test data  
5 prove the Data Acquisition Device (DAD) was not connected as required to the 2005 Chevrolet  
6 Silverado C3500 being certified, causing the issuance of a fraudulent Smog Check Certificate of  
7 Compliance.

8 **Clean Plug # 6**

9 57. On or about March 20, 2025, a 2000 Ford Mustang GT VIN 1FAFP42XXYF109961,  
10 CA License 5PZS574, was tested and smog certificate UK656348C was issued under the license  
11 of Smog Check Inspector EO 640564, Respondent Lopez.

12 58. The Dynamic PID chart for the 2000 Ford Mustang GT shows that between time  
13 stamp 329 and 20627, the engine RPM is steady at around 700 RPM. During this time, the data  
14 shows that the throttle is fixed at 15.7% and the MAF is fixed at 5.01gps. After time stamp  
15 20627, the data shows the engine RPM is increased and held steady at around 1915 RPM. During  
16 the elevated engine RPM, the data shows the throttle is fluctuating between 12.5% and 15.7% and  
17 the MAF is fluctuating between 2.92gps and 5.01gps.

18 59. The steady idle and steady elevated engine RPM data along with the improbable  
19 throttle positions and MAF readings are not characteristic or expected for normal engine  
20 operation. The throttle positions and MAF readings are expected to be stable during the steady  
21 idle and subsequently raised and stable during the steady elevated engine RPM. During the  
22 improbable readings, the throttle and MAF had data points during the elevated engine RPM  
23 which never increased past the highest data point at idle. The discrepancies in the OIS test data  
24 prove the Data Acquisition Device (DAD) was not connected as required to the 2000 Ford  
25 Mustang GT being certified, causing the issuance of a fraudulent Smog Check Certificate of  
26 Compliance.

27 ///

28 ///

1           **Clean Plug # 7**

2           60. On or about March 29, 2025, a 2001 Chevrolet Suburban K1500 VIN  
3 3GNFK16T91G132531, CA License 9KVU188, was tested and smog certificate JD771137C was  
4 issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

5           61. The Dynamic PID chart for the 2001 Chevrolet Suburban K1500 shows that between  
6 time stamp 349 and 21269, the engine RPM is steady at around 540 RPM. During this time, the  
7 data shows that the throttle is fixed at 0%, the MAF is fixed at 4.49gps, and the MAP is fixed at  
8 33kPa. After time stamp 21269, the data shows the engine RPM is increased and held steady at  
9 around 1820 RPM. During this time, the data shows that the throttle is varying between 0% and  
10 5.1%, the MAF is varying between 2.9gps and 5.06gps, and the MAP drops from 44kPa to  
11 ultimately 35kPa, then rises to 39kPa.

12           62. The steady idle and steady elevated engine RPM data along with the improbable  
13 throttle positions, MAF readings, and MAP readings are not characteristic or expected for normal  
14 engine operation. The throttle positions and MAF readings are expected to be stable during the  
15 steady idle and subsequently raised and stable during the steady elevated engine RPM. During  
16 the improbable readings, the throttle and MAF had data points during the elevated engine RPM  
17 which were the same as or lower than data points at idle. The discrepancies in the OIS test data  
18 prove the Data Acquisition Device (DAD) was not connected as required to the 2001 Chevrolet  
19 Suburban K1500 being certified, causing the issuance of a fraudulent Smog Check Certificate of  
20 Compliance.

21           **Clean Plug # 8**

22           63. On or about March 30, 2025, a 2001 Ford Explorer Sport VIN  
23 1FMYU60E91UA60743, CA License 4VFS562, was tested and smog certificate JD771140C was  
24 issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

25           64. The Dynamic PID chart for the 2001 Ford Explorer Sport shows that between time  
26 stamp 342 and 19652, the engine RPM is steady at around 680 RPM. During this time, the data  
27 shows that the throttle is fixed at 20.4% and the MAF is fixed at 4.8gps. After time stamp 19652,  
28 the data shows the engine RPM is increased and held steady at around 1900 RPM. During the

1 elevated engine RPM, the data shows the throttle is fluctuating between 20.8% and 23.5% and the  
2 MAF is fluctuating between 3.31gps and 4.82gps.

3 65. The steady idle and steady elevated engine RPM data along with the improbable  
4 throttle positions and MAF readings are not characteristic or expected for normal engine  
5 operation. The throttle positions and MAF readings are expected to be stable during the steady  
6 idle and subsequently raised and stable during the steady elevated engine RPM. During the  
7 improbable readings, the MAF had data points during the elevated engine RPM which were lower  
8 than data points at idle. The discrepancies in the OIS test data prove the Data Acquisition Device  
9 (DAD) was not connected as required to the 2001 Ford Explorer Sport being certified, causing the  
10 issuance of a fraudulent Smog Check Certificate of Compliance.

11 66. On or about May 11, 2023, a previous Smog Check inspection was performed on the  
12 2001 Ford Explorer Sport at a different, unrelated Smog Check station. The Dynamic PID chart  
13 for 2001 Explorer Sport shows that between time stamp 40 and 17160, the engine RPM is steady  
14 at around 840 RPM. During this time, the data shows that the throttle is fixed at 20.4% opening  
15 and the MAF is stable between 5.49gps and 5.8gps. After time stamp 17160, the data shows the  
16 engine RPM is raised and increases at a steady rate ultimately reaching 2118 RPM. During the  
17 rising engine RPM, the data shows that the throttle also increases from 23.1% opening to 24.3%  
18 opening, and the MAF increases from 8.76gps to 13.99gps. Both the throttle and the MAF show  
19 a direct correlation, as expected, with the engine RPM. The steady idle and elevated, rising  
20 engine RPM data along with the associated throttle positions and MAF readings are characteristic  
21 and expected for normal engine operation.

22 **Clean Plug # 9**

23 67. On or about on March 31, 2025, a 2003 Ford Expedition XLT VIN  
24 1FMEU15W43LA78535, CA License 6EML541, was tested and smog certificate JD771145C  
25 was issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

26 68. The Dynamic PID chart for the 2003 Ford Expedition XLT shows that between time  
27 stamp 353 and 21065, the engine RPM is steady at around 705 RPM. During this time, the data  
28 shows that the throttle is fixed at 19.6% and the MAF is fixed at 7.64gps. After time stamp

1 21065, the data shows the engine RPM is increased and held steady at around 1870 RPM. During  
2 the elevated engine RPM, the data shows the throttle drops from 23.5% to 20%, then ultimately  
3 rises 22.4% and the MAF drops from 7.49gps to ultimately 5.28gps, then increases to ultimately  
4 7.32gps.

5 69. The steady idle and steady elevated engine RPM data along with the improbable  
6 throttle positions and MAF readings are not characteristic or expected for normal engine  
7 operation. The throttle positions and MAF readings are expected to be stable during the steady  
8 idle and subsequently raised and stable during the steady elevated engine RPM. During the  
9 improbable readings, the MAF had data points during the elevated engine RPM which never  
10 increased past the highest data point at idle. The discrepancies in the OIS test data prove the Data  
11 Acquisition Device (DAD) was not connected as required to the 2003 Ford Expedition XLT  
12 being certified, causing the issuance of a fraudulent Smog Check Certificate of Compliance.

13 **Clean Plug # 10**

14 70. On or about March 31, 2025, a 2004 GMC Savana Cutaway G3500, VIN  
15 1GDGG31V841913798, CA License 82573P3, was tested and smog certificate JD771146C was  
16 issued under the license of Smog Check Inspector EO 640564, Respondent Lopez.

17 71. The Dynamic PID chart for the 2004 GMC Savana Cutaway G3500 shows that  
18 between time stamp 347 and 28076, the engine RPM is steady at around 625 RPM. During this  
19 time, the data shows that the throttle is fixed at 0%, the MAF is fixed at 3.79gps, and the MAP is  
20 fixed at 34kPa. After time stamp 28076, the data shows the engine RPM is increased and stays  
21 elevated at no less than 1398 RPM. During this time, the data shows that the throttle is drops  
22 from 3.9% and 0.4%, the MAF rises from 2.99gps to 4.3%gps and ultimately drops to 3.52gps,  
23 and the MAP rises from 34kPa to ultimately 45kPa, then drops to 35kPa.

24 72. The steady idle and elevated engine RPM data along with the improbable throttle  
25 positions, MAF readings, and MAP readings are not characteristic or expected for normal engine  
26 operation. The throttle positions and MAF readings are expected to be stable during the steady  
27 idle and subsequently raised during the elevated engine RPM. During the improbable readings,  
28 the data shows the throttle and RPM had an inverse correlation, also the MAF had a data point

1 during the elevated engine RPM which was lower than data points at idle. The discrepancies in  
2 the OIS test data prove the Data Acquisition Device (DAD) was not connected as required to the  
3 2004 GMC Cutaway G3500 being certified, causing the issuance of a fraudulent Smog Check  
4 Certificate of Compliance.

5 73. On or about March 1, 2023, a previous Smog Check inspection was performed on the  
6 2004 GMC Savana Cutaway G3500 at a different, unrelated Smog Check station. The Dynamic  
7 PID chart for the 2004 GMC Savana Cutaway G3500 shows that between time stamp 48 and  
8 19730, the engine RPM is steady at around 550 RPM. During this time, the data shows that the  
9 throttle is fixed at 0% opening, the MAF is stable between 3.28gps and 3.35gps and the MAP is  
10 fixed at 34kPa. After time stamp 19730, the data shows the engine RPM is increased and held  
11 steady at around 1580 RPM. During the elevated engine RPM, the data shows that the throttle is  
12 fixed at 8.6% opening, the MAF is stable between 10.92gps and 11.01gps, and the MAP is  
13 between 25kPa and 26kPa. The steady idle and elevated engine RPM data along with the  
14 associated throttle positions, MAF, and MAP readings are characteristic and expected for normal  
15 engine operation.

#### 16 **FIRST CAUSE FOR DISCIPLINE**

#### 17 **(Untrue or Misleading Statements – Respondent LA Smog Check)**

18 74. Respondent LA Smog Check's Automotive Repair Dealer Registration is subject to  
19 disciplinary action under Code section 9884.7, subdivision (a)(1), in that, with respect to the  
20 vehicles identified above, Respondent LA Smog Check made or authorized statements which they  
21 knew, or in the exercise of reasonable care should have known to be untrue or misleading, as  
22 follows: Respondent LA Smog Check certified that these vehicles had passed inspection and  
23 were in compliance with applicable laws and regulations, when in fact, Respondent LA Smog  
24 Check conducted the inspections on the vehicles using the clean plugging method in order to  
25 issue smog certificates of compliance for the vehicles. Complainant refers to, and by this  
26 reference incorporates, the allegations set forth above in paragraphs 41-73, as though fully set  
27 forth herein.

28 ///

1 **SECOND CAUSE FOR DISCIPLINE**

2 **(Fraud – Respondent LA Smog Check)**

3 75. Respondent LA Smog Check’s Automotive Repair Dealer Registration is subject to  
4 disciplinary action under Code section 9884.7, subdivision (a)(4), in that, with respect to the  
5 vehicles identified above, Respondent LA Smog Check committed acts which constitute fraud by  
6 issuing electronic smog certificates of compliance for these vehicles without performing bona  
7 fide inspections of the emissions control devices and systems on those vehicles, thereby depriving  
8 the People of the State of California of the protection afforded by the Motor Vehicle Inspection  
9 Program. Complainant refers to, and by this reference incorporates, the allegations set forth  
10 above in paragraphs 41-73, as though fully set forth herein.

11 **THIRD CAUSE FOR DISCIPLINE**

12 **(Material Violation of Automotive Repair Act – Respondent LA Smog Check)**

13 76. Respondent LA Smog Check’s Automotive Repair Dealer Registration is subject to  
14 disciplinary action under Code section 9884.7, subdivision (a)(6), in that, with respect to the  
15 vehicles identified above, Respondent LA Smog Check failed in a material respect to comply  
16 with the provisions of this chapter or regulations adopted pursuant to it by issuing electronic smog  
17 certificates of compliance for these vehicles without performing bona fide inspections of the  
18 emissions control devices and systems on those vehicles, thereby depriving the People of the  
19 State of California of the protection afforded by the Motor Vehicle Inspection Program.  
20 Complainant refers to, and by this reference incorporates, the allegations set forth above in  
21 paragraphs 41-73, as though fully set forth herein.

22 **FOURTH CAUSE FOR DISCIPLINE**

23 **(Violations of the Motor Vehicle Inspection Program – Respondent LA Smog Check)**

24 77. Respondent LA Smog Check’s Smog Check, Test-Only, Station License is subject to  
25 disciplinary action under Health and Safety Code section 44072.2, subdivision (a), in that, with  
26 respect to the vehicles identified above, Respondent LA Smog Check failed to comply with the  
27 following sections of the Health and Safety Code:

28 ///

1 a. **Section 44012:** Respondent LA Smog Check failed to ensure that the emission  
2 control tests were performed on the vehicles in accordance with procedures prescribed by the  
3 Bureau.

4 b. **Section 44015, subdivision (b):** Respondent LA Smog Check issued electronic  
5 smog certificates of compliance for the vehicles without ensuring that the vehicles were properly  
6 tested and inspected to determine if they were in compliance with Health and Safety Code section  
7 44012.

8 c. **Section 44059:** Respondent LA Smog Check willfully made false entries for the  
9 electronic smog certificates of compliance for the vehicles by certifying that the vehicles had  
10 been inspected as required when, in fact, they had not.

11 Complainant refers to, and by this reference incorporates, the allegations set forth above in  
12 paragraphs 41-73, as though fully set forth herein.

13 **FIFTH CAUSE FOR DISCIPLINE**

14 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection**  
15 **Program – Respondent LA Smog Check)**

16 78. Respondent LA Smog Check's Smog Check, Test-Only, Station License is subject to  
17 disciplinary action under Health and Safety Code section 44072.2, subdivision (c), in that, with  
18 respect to the vehicles identified above, Respondent LA Smog Check failed to comply with  
19 provisions of the California Code of Regulations, title 16, as follows:

20 a. **Section 3340.24, subdivision (c):** Respondent LA Smog Check issued false or  
21 fraudulent certificates of compliance for the vehicles.

22 b. **Section 3340.35, subdivision (c):** Respondent LA Smog Check issued electronic  
23 smog certificates of compliance for the vehicles even though the vehicles had not been inspected  
24 in accordance with section 3340.42 of the California Code of Regulations, title 16.

25 c. **Section 3340.41, subdivision (c):** Respondent LA Smog Check knowingly entered  
26 false information into the emissions inspection system for the vehicles.

27 d. **Section 3340.42:** Respondent LA Smog Check failed to ensure that the required  
28 smog tests were conducted on the vehicles in accordance with the Bureau's specifications.

1 e. **Section 3373:** Respondent LA Smog Check withheld or inserted statements or  
2 information in an estimate, invoice, work order, or record required to be maintained by California  
3 Code of Regulations, title 16, section 3340.15, subdivision (e), which caused the document to be  
4 false or misleading for the vehicles.

5 Complainant refers to, and by this reference incorporates, the allegations set forth above in  
6 paragraphs 41-73, as though fully set forth herein.

7 **SIXTH CAUSE FOR DISCIPLINE**

8 **(Dishonesty, Fraud, or Deceit – Respondent LA Smog Check)**

9 79. Respondent LA Smog Check’s Smog Check, Test-Only, Station License is subject to  
10 disciplinary action under Health and Safety Code section 44072.2, subdivision (d), in conjunction  
11 with Health and Safety Code section 44072.10, subdivision (c), in that, with respect to the  
12 vehicles identified above, Respondent LA Smog Check committed dishonest, fraudulent, or  
13 deceitful acts whereby another was injured by issuing electronic smog certificates of compliance  
14 for the vehicles without performing bona fide inspections of the emission control devices and  
15 systems on those vehicles, thereby depriving the People of the State of California of the  
16 protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this  
17 reference incorporates, the allegations set forth above in paragraphs 41-73, as though fully set  
18 forth herein.

19 **SEVENTH CAUSE FOR DISCIPLINE**

20 **(Violations of the Motor Vehicle Inspection Program – Respondent Lopez)**

21 80. Respondent Lopez’s Smog Check Inspector License is subject to disciplinary action  
22 under Health and Safety Code section 44072.2, subdivision (a), in that, with respect to the  
23 vehicles identified above, Respondent Lopez violated the following Health and Safety Code  
24 sections:

25 a. **Section 44012, subdivision (a):** Respondent Lopez failed to determine that all  
26 emission control devices and systems required by law were installed and functioning correctly on  
27 the vehicles in accordance with test procedures prescribed by the Bureau.

28 ///



1 **NINTH CAUSE FOR DISCIPLINE**

2 **(Dishonesty, Fraud, or Deceit – Respondent Lopez)**

3 82. Respondent Lopez’s Smog Check Inspector License is subject to disciplinary  
4 action under Health and Safety Code section 44072.2, subdivision (d), in conjunction with  
5 Health and Safety Code section 44072.10, subdivision (c), in that, with respect to the vehicles  
6 identified above, Respondent Lopez committed acts involving dishonesty, fraud, or deceit  
7 when he issued electronic smog certificates of compliance for the vehicles without performing  
8 bona fide inspections of the emission control devices and systems on those vehicles, thereby  
9 depriving the People of the State of California of the protection afforded by the Motor Vehicle  
10 Inspection Program. Complainant refers to, and by this reference incorporates, the allegations  
11 set forth above in paragraphs 41-73, as though fully set forth herein.

12 **OTHER MATTERS**

13 83. Pursuant to Business and Professions Code section 9884.7, subdivision (c), the  
14 Director may suspend, revoke, or place on probation the registration for all places of business  
15 operated in this state by Respondent Cesar Augusto Larios upon a finding that he has, or is,  
16 engaged in a course of repeated and willful violations of the laws and regulations pertaining to an  
17 automotive repair dealer.

18 84. Pursuant to Health and Safety Code section 44072.8, if Smog Check, Test-Only,  
19 Station License Number TC 306077, issued to Respondent Cesar Augusto Larios, dba LA Smog  
20 Check, is revoked or suspended following a hearing under this article, any additional license  
21 issued under Chapter 5 of Part 5 of Division 26 of the Health and Safety Code in the name of said  
22 licensee may be likewise revoked or suspended by the Director.

23 85. Pursuant to Health and Safety Code section 44072.8, if Smog Check Inspector  
24 License Number EO 640564, issued to Respondent Hernan Molina Lopez is revoked or  
25 suspended following a hearing under this article, any additional license issued under Chapter 5 of  
26 Part 5 of Division 26 of the Health and Safety Code in the name of said licensee may be likewise  
27 revoked or suspended by the Director.

28 ///

**PRAYER**

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of the Department of Consumer Affairs issue a decision:

- 1. Revoking or suspending Automotive Repair Dealer Registration Number ARD 306077, issued to Cesar Augusto Larios, dba LA Smog Check;
  - 2. Revoking or suspending Smog Check, Test-Only, Station License Number TC 306077, issued to Cesar Augusto Larios, dba LA Smog Check;
  - 3. Revoking or suspending Smog Check Inspector License Number EO 640564, issued to Hernan Molina Lopez;
  - 4. Revoking or suspending any other automotive repair dealer registration issued to Cesar Augusto Larios;
  - 5. Revoking or suspending any additional license issued under Chapter 5, Part 5 of Division 26 of the Health and Safety Code in the name of Cesar Augusto Larios;
  - 6. Revoking or suspending any additional license issued under Chapter 5, Part 5 of Division 26 of the Health and Safety Code in the name of Hernan Molina Lopez;
  - 7. Ordering Cesar Augusto Larios and Hernan Molina Lopez to pay the Bureau of Automotive Repair the reasonable costs of the investigation and enforcement of this case, pursuant to Business and Professions Code section 125.3 and if placed on probation, the costs of probation monitoring;
- and,
- 8. Taking such other and further action as deemed necessary and proper.

DATED: As of Digital Signature Date

\_\_\_\_\_  
PATRICK DORAIS  
Chief  
Bureau of Automotive Repair  
Department of Consumer Affairs  
State of California  
*Complainant*

LA2025604109/68008194