

1 EDMUND G. BROWN JR., Attorney General
of the State of California
2 ALFREDO TERRAZAS
Senior Assistant Attorney General
3 LINDA K. SCHNEIDER, State Bar No. 101336
Supervising Deputy Attorney General
4 California Department of Justice
110 West "A" Street, Suite 1100
5 San Diego, CA 92101
6 P.O. Box 85266
San Diego, CA 92186-5266
7 Telephone: (619) 645-3037
Facsimile: (619) 645-2061
8
9 Attorneys for Complainant

10 **BEFORE THE**
11 **DEPARTMENT OF CONSUMER AFFAIRS**
12 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
13 **STATE OF CALIFORNIA**

14 In the Matter of the Accusation Against:

Case No. 79/08-23

15 CALIFORNIA SMOG CERTIFICATION, INC.
JOHN PATRICK DEVIN, PRESIDENT
16 1655 Broadway, Suite 1
Chula Vista, CA 91911

A C C U S A T I O N

(S M O G C H E C K)

17 Automotive Repair Dealer Registration No. AD 221240
Smog Check, Test Only, Station License No. TD 221240,

18 KARL DUER ROBSON
P.O. Box 433192
19 San Diego, CA 92143

20 Advanced Emission Specialist Technician License
No. EA 085454,

21 LOREN THOMAS WILSON
P.O. Box 86487
22 San Diego, CA 92138

23 Advanced Emission Specialist Technician License
24 No. EA 137341,

25
26 ///

27 ///

28 ///

1 JESSE SMOG STATION
JESUS BENITO ZUNIGA,
2 a.k.a. JESUS B. ZUNIGA, OWNER
2446 Main Street, #R
3 Chula Vista, CA 91911

4 Automotive Repair Dealer Registration No. AE 160498
Smog Check Station License No. RE 160498,

5 JESUS B. ZUNIGA
6 524 Center
Chula Vista, CA 91910

7
8 Advanced Emission Specialist Technician License
No. EA 304458,

9 CALIFORNIA SMOG CERTIFICATION, INC.
JOHN PATRICK DEVIN, PRESIDENT
10 11 3rd Avenue, Suite A
Chula Vista, CA 91910

11
12 Automotive Repair Dealer Registration No. AF 216533
Smog Check, Test Only, Station License No. TF 216533,

13 JEREMIAH EDGAR RIVERA
302 Island Avenue, #208
14 San Diego, CA 92101

15 Advanced Emission Specialist Technician License
No. EA 148756,

16 JAIME GARCIA
17 517 Sacramento Avenue
Spring Valley, CA 91977

18 Advanced Emission Specialist Technician License
19 No. EA 143159,

20 and

21 DIEGO SALVADO DELGADO
100 Woodlawn Avenue, Space 112
22 Chula Vista, CA 91910

23 Advanced Emission Specialist Technician License No.
EA 148105

24 Respondents.

25
26
27 ///

28 ///

1 Complainant alleges:

2 **PARTIES**

3 1. Sherry Mehl ("Complainant") brings this Accusation solely in her official
4 capacity as the Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer
5 Affairs.

6 **Automotive Repair Dealer Registration No. AD 221240**

7 2. On or about April 26, 2002, the Director of Consumer Affairs ("Director")
8 issued Automotive Repair Dealer Registration Number AD 221240 to California Smog
9 Certification, Inc. ("Respondent California Smog Certification"), with John Patrick Devin as
10 president. Respondent California Smog Certification's automotive repair dealer registration was
11 in full force and effect at all times relevant to the charges brought herein and will expire on April
12 30, 2008, unless renewed.

13 **Smog Check, Test Only, Station License No. TD 221240**

14 3. On or about May 3, 2002, the Director issued Smog Check, Test Only^{1/},
15 Station License Number TD 221240 to Respondent California Smog Certification. Respondent's
16 smog check station license was in full force and effect at all times relevant to the charges brought
17 herein and will expire on April 30, 2008, unless renewed.

18 **Advanced Emission Specialist Technician License No. EA 085454**

19 4. In or about 1997, the Director issued Advanced Emission Specialist
20 Technician License Number EA 085454 to Karl Duer Robson ("Respondent Robson").
21 Respondent's advanced emission specialist technician license was in full force and effect at all

22 ///

23 _____
24 1. Test only facilities are licensed smog check stations, that by law, are only allowed to test vehicles; they
25 cannot repair them. Any needed repairs must be performed at either a smog check station designated as a test-and-
26 repair facility or a "gold shield" station. Test-and-repair stations are licensed by the state to provide smog check
27 tests and repairs to most vehicles. Under current law, test-and-repair stations are prohibited from certifying
28 repaired "gross polluters" or vehicles that have been directed to test-only stations for inspection. Only test-only
stations and gold shield stations are able to certify repaired gross polluter vehicles.

Pursuant to Health and Safety Code section 39032.5, "gross polluter" means a vehicle with excess
hydrocarbon, carbon monoxide, or oxides of nitrogen (NOX) emissions as established by the department in
consultation with the state board.

1 times relevant to the charges brought herein and will expire on September 30, 2008, unless
2 renewed.

3 **Advanced Emission Specialist Technician License No. EA 137341**

4 5. In or about 1997, the Director issued Advanced Emission Specialist
5 Technician License Number EA 137341 to Loren Thomas Wilson ("Respondent Wilson").
6 Respondent's advanced emission specialist technician license was in full force and effect at all
7 times relevant to the charges brought herein and will expire on January 31, 2009, unless renewed.

8 **Automotive Repair Dealer Registration No. AE 160498**

9 6. On or about May 14, 1991, the Director issued Automotive Repair Dealer
10 Registration Number AE 160498 to Jesus Benito Zuniga, also known as Jesus B. Zuniga
11 ("Respondent Zuniga"), owner of Jesse Smog Station. Respondent's automotive repair dealer
12 registration was in full force and effect at all times relevant to the charges brought herein and will
13 expire on May 31, 2008, unless renewed.

14 **Smog Check Station License No. RE 160498**

15 7. On or about July 12, 1991, the Director issued Smog Check Station
16 License Number RE 160498 to Respondent Zuniga.² Respondent's smog check station license
17 was in full force and effect at all times relevant to the charges brought herein and will expire on
18 May 31, 2008, unless renewed.

19 **Advanced Emission Specialist Technician License No. EA 304458**

20 8. In or about 1996, the Director issued Advanced Emission Specialist
21 Technician License Number EA 304458 to Respondent Zuniga. Respondent's advanced
22 emission specialist technician license was in full force and effect at all times relevant to the
23 charges brought herein and will expire on March 31, 2009, unless renewed.

24 **Automotive Repair Dealer Registration No. AF 216533**

25 9. On or about June 29, 2001, the Director issued Automotive Repair Dealer
26 Registration Number AF 216533 to Respondent California Smog Certification, with John Devin

27
28

2. Respondent Zuniga's smog check station is a licensed test-and-repair facility.

1 as president. Respondent California Smog Certification's automotive repair dealer registration
2 was in full force and effect at all times relevant to the charges brought herein and will expire on
3 June 30, 2008, unless renewed.

4 **Smog Check, Test Only, Station License No. TF 216533**

5 10. On or about July 6, 2001, the Director issued Smog Check, Test Only,
6 Station License Number TF 216533 to Respondent California Smog Certification. Respondent's
7 smog check station license was in full force and effect at all times relevant to the charges brought
8 herein and will expire on June 30, 2008, unless renewed.

9 **Advanced Emission Specialist Technician License No. EA 148756**

10 11. On or about June 7, 2004, the Director issued Advanced Emission
11 Specialist Technician License Number EA 148756 to Jeremiah Edgar Rivera ("Respondent
12 Rivera"). Respondent's advanced emission specialist technician license was in full force and
13 effect at all times relevant to the charges brought herein and will expire on September 30, 2008,
14 unless renewed.

15 **Advanced Emission Specialist Technician License No. EA 143159**

16 12. On or about October 24, 2000, the Director issued Advanced Emission
17 Specialist Technician License Number EA 143159 to Jaime Garcia ("Respondent Garcia").
18 Respondent's advanced emission specialist technician license was in full force and effect at all
19 times relevant to the charges brought herein and will expire on August 31, 2008, unless renewed.

20 **Advanced Emission Specialist Technician License No. EA 148105**

21 13. On or about December 12, 2003, the Director issued Advanced Emission
22 Specialist Technician License Number EA 148105 to Diego Salvado Delgado ("Respondent
23 Delgado"). Respondent's advanced emission specialist technician license was in full force and
24 effect at all times relevant to the charges brought herein and will expire on September 30, 2007,
25 unless renewed.

26 ///

27 ///

28 ///

[illegible]2
3

4
5
6
7

8
9
0

- 1
- 2
- 3
- 4

5

6

7
3
9
0

2

1

4

5

11

1

1 (6) Failure in any material respect to comply with the provisions of this
2 chapter or regulations adopted pursuant to it.

3 (7) Any willful departure from or disregard of accepted trade standards for
4 good and workmanlike repair in any material respect, which is prejudicial to
5 another without consent of the owner or his or her duly authorized representative.

6

7 (c) Notwithstanding subdivision (b), the director may refuse to
8 validate, or may invalidate temporarily or permanently, the registration
9 for all places of business operated in this state by an automotive repair
10 dealer upon a finding that the automotive repair dealer has, or is, engaged
11 in a course of repeated and willful violations of this chapter, or regulations
12 adopted pursuant to it.

13 19. Bus. & Prof. Code section 9884.8 states, in pertinent part:

14 All work done by an automotive repair dealer, including all warranty
15 work, shall be recorded on an invoice and shall describe all service work done
16 and parts supplied. Service work and parts shall be listed separately on the
17 invoice, which shall also state separately the subtotal prices for service work
18 and for parts, not including sales tax, and shall state separately the sales tax,
19 if any, applicable to each . . . One copy shall be given to the customer
20 and one copy shall be retained by the automotive repair dealer.

21 20. Bus. & Prof. Code section 9884.9, subdivision (a), states, in pertinent part:

22 The automotive repair dealer shall give to the customer a written estimated
23 price for labor and parts necessary for a specific job. No work shall be done and
24 no charges shall accrue before authorization to proceed is obtained from the
25 customer. No charge shall be made for work done or parts supplied in excess of
26 the estimated price without the oral or written consent of the customer that shall
27 be obtained at some time after it is determined that the estimated price is
28 insufficient and before the work not estimated is done or the parts not estimated
are supplied. Written consent or authorization for an increase in the original
estimated price may be provided by electronic mail or facsimile transmission from
the customer. The bureau may specify in regulation the procedures to be followed
by an automotive repair dealer when an authorization or consent for an increase in
the original estimated price is provided by electronic mail or facsimile
transmission. If that consent is oral, the dealer shall make a notation on the work
order of the date, time, name of person authorizing the additional repairs and
telephone number called, if any, together with a specification of the additional
parts and labor . . .

24 21. Bus. & Prof. Code section 477 provides, in pertinent part, that "Board"
25 includes "bureau," "commission," "committee," "department," "division," "examining
26 committee," "program," and "agency." "License" includes certificate, registration or other means
27 to engage in a business or profession regulated by the Bus. & Prof. Code.

28 ///

22. Health & Saf. Code section 44072.2 states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

(a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health and Saf. Code § 44000, et seq.)] and the regulations adopted pursuant to it, which related to the licensed activities.

• • • •

(c) Violates any of the regulations adopted by the director pursuant to this chapter.

(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured . . .

Cost Recovery

23. Bus. & Prof. Code section 125.3 provides, in pertinent part, that a Board may request the administrative law judge to direct a licensee found to have committed a violation or violations of the licensing act to pay a sum not to exceed the reasonable costs of the investigation and enforcement of the case.

RESPONDENT CALIFORNIA SMOG

CERTIFICATION'S 1655 BROADWAY FACILITY

UNDERCOVER OPERATION #1: 1988 TOYOTA PICKUP TRUCK

24. On August 4, 2005, an undercover operator with the Bureau (hereinafter "the operator") took the Bureau's 1988 Toyota pickup truck to Respondent California Smog Certification's facility located at 1655 Broadway, Suite 1, Chula Vista, California (hereinafter "1655 Broadway facility"). A defective #2 vacuum switch had been installed in the Bureau-documented vehicle, causing the vehicle's exhaust tailpipe emissions to exceed the gross polluter limits. The operator met with Respondent's service writer, "Cynthia", and requested a smog inspection on the vehicle. The operator completed and signed a work order/invoice, but did not receive a copy of the document or a written estimate for the inspection.

25. After the inspection was completed, one of Respondent's technicians told the operator that the vehicle failed the inspection because the carburetor was passing too much fuel, that the engine could not burn all of the fuel, and that the emissions had high levels of "CO"

1 (carbon monoxide). Cynthia gave the operator a document titled "Station List May 20, 2005",
2 a list of test and repair facilities in the area that could repair the emissions problem on the
3 vehicle.^{3/} The operator paid Cynthia \$49.95 in cash and received a final invoice, the station list,
4 and a vehicle inspection report ("VIR"). The VIR indicated that the vehicle failed the smog
5 inspection as a gross polluter. Before the operator left the facility, Cynthia approached him and
6 suggested that he take the vehicle to shop number 18 on the station list, Jesse Smog Station.

7 26. At approximately 0950 hours that same day, the operator took the vehicle
8 to Respondent Zuniga's (hereinafter "Zuniga") facility, Jesse Smog Station, and met with one of
9 Zuniga's employees. The operator asked the employee if they could repair the smog check
10 failure problem. The employee opened the hood of the vehicle and Zuniga looked into the
11 engine compartment. The operator completed and signed a work order/invoice, but did not
12 receive a copy of the document or a written estimate. The employee told the operator that the
13 vehicle only needed an adjustment and that the repair work would cost \$50, which the operator
14 authorized. The operator observed Zuniga remove the air cleaner lid and air filter from the
15 engine compartment, then observed Zuniga perform a smog inspection on the vehicle. After the
16 inspection was completed, the employee told the operator that the vehicle was ready and that the
17 operator should return to California Smog Certification. The operator paid the employee \$50 in
18 cash and received two copies of Invoice No. 64237 and a VIR dated August 4, 2005, for a pretest
19 (unofficial) inspection on the vehicle. The employee told the operator that the air cleaner lid and
20 air filter were inside the vehicle.

21 27. Later that same day, Bureau Representative John Nelson ("Nelson")
22 inspected the vehicle and found that the defective #2 vacuum switch was still in place. Nelson
23 performed an acceleration simulation mode (ASM) smog check inspection on the vehicle. The
24 vehicle failed the inspection for the disconnected vacuum hose, excessive CO and HC

25 ///

26
27
28 3. Health & Saf. Code section 44014.5, subdivision (c), states, in pertinent part, that "[t]he department shall
provide for the distribution to consumers by test-only facilities of a list, compiled by region, of smog check
stations licensed to make repairs of vehicular emission control systems"

1 (hydrocarbons) tailpipe emissions, a disconnected PCV (positive crankcase ventilation) system,
2 and missing TAC (thermostatic air cleaner) unit.

3 28. On August 5, 2005, the operator returned the vehicle to the 1655
4 Broadway facility and met with Cynthia. The air cleaner lid and air filter, removed by Zuniga,
5 were still lying on the seat of the vehicle. Cynthia informed the operator that he only needed a
6 smog retest on the vehicle. The operator completed and signed a work order/invoice, but did not
7 receive a copy of the document or a written estimate. After the smog inspection was completed,
8 the operator paid Cynthia \$8.25 in cash for the smog certificate and received copies of a final
9 invoice and a VIR dated August 5, 2005, initialed or signed by Respondent Robson. That same
10 day, electronic smog Certificate of Compliance #FW989927C was issued for the vehicle.

11 29. On August 11, 2005, Nelson reinspected the vehicle and found that the
12 defective #2 vacuum switch was still in place. Nelson performed a smog check inspection on the
13 vehicle. The vehicle failed the inspection for the disconnected vacuum hose, excessive CO and
14 HC tailpipe emissions, a disconnected PCV system, and the missing TAC unit.

15 **FIRST CAUSE FOR DISCIPLINE**

16 **(Untrue or Misleading Statements)**

17 30. Respondent California Smog Certification's automotive repair dealer
18 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
19 subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the
20 exercise of reasonable care should have known to be untrue or misleading, as follows:
21 Respondent California Smog Certification's technician, Respondent Robson, certified under
22 penalty of perjury on the VIR dated August 5, 2005, that the Bureau's 1988 Toyota pickup truck
23 had passed inspection and was in compliance with applicable laws and regulations. In fact, the
24 #2 vacuum switch was defective, the CO and HC tailpipe emissions were excessive, the PCV
25 system was disconnected, and the TAC unit was missing. As such, the vehicle would not pass
26 the inspection required by Health & Saf. Code section 44012.

27 ///

28 ///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

SECOND CAUSE FOR DISCIPLINE

(Failure to Provide Copy of Signed Document)

31. Respondent California Smog Certification's automotive repair dealer registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(3), in that on or about August 4, 2005, and August 5, 2005, Respondent's service writer failed to give the undercover operator copies of the work orders/invoices, identified in paragraphs 24 and 28 above, as soon as the operator signed the documents.

THIRD CAUSE FOR DISCIPLINE

(Fraud)

32. Respondent California Smog Certification's automotive repair dealer registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that it committed an act which constitutes fraud, as follows: Respondent issued an electronic smog certificate of compliance for the Bureau's 1988 Toyota pickup truck without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

FOURTH CAUSE FOR DISCIPLINE

(Violations of the Bus. & Prof. Code)

33. Respondent California Smog Certification's automotive repair dealer registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that on or about August 4, 2005, and August 5, 2005, Respondent failed to comply with section 9884.9, subdivision (a), of that Code. Respondent's service writer failed to provide the undercover operator with written estimates for parts and/or labor necessary for a specific job.

///
///
///
///

1 **FIFTH CAUSE FOR DISCIPLINE**

2 **(Violations of the Motor Vehicle Inspection Program)**

3 34. Respondent California Smog Certification's smog check station license is
4 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
5 that Respondent failed to comply with the following sections of that Code:

- 6 a. **Section 44012:** Respondent California Smog Certification's technician,
7 Respondent Robson, failed to perform the emission control tests on the
8 Bureau's 1988 Toyota pickup truck in accordance with procedures
9 prescribed by the department.
- 10 b. **Section 44015:** Respondent California Smog Certification issued an
11 electronic smog certificate of compliance for the Bureau's 1988 Toyota
12 pickup truck without properly testing and inspecting the vehicle to
13 determine if it was in compliance with Health & Saf. Code section 44012.
- 14 c. **Section 44033, subdivision (c):** Respondent's employee/service writer
15 failed to provide the undercover operator with written estimates for parts
16 and/or labor necessary for a specific job.

17 **SIXTH CAUSE FOR DISCIPLINE**

18 **(Failure to Comply with Regulations Pursuant**
19 **to the Motor Vehicle Inspection Program)**

20 35. Respondent California Smog Certification's smog check station license is
21 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
22 that Respondent failed to comply with the provisions of California Code of Regulations, title 16,
23 as follows:

- 24 a. **Section 3340.24, subdivision (c):** Respondent California Smog
25 Certification falsely or fraudulently issued an electronic smog certificate of
26 compliance for the Bureau's 1988 Toyota pickup truck.
- 27 b. **Section 3340.35, subdivision (c):** Respondent California Smog
28 Certification issued an electronic smog certificate of compliance for the

1 Bureau's 1988 Toyota pickup truck even though the vehicle had not been
2 inspected in accordance with Health & Saf. Code section 3340.42.

- 3 c. **3340.41, subdivision (c):** Respondent California Smog Certification's
4 technician, Respondent Robson, knowingly entered into the emissions
5 inspection system false information about the Bureau's 1988 Toyota
6 pickup truck.
- 7 d. **Section 3340.42:** Respondent California Smog Certification's
8 technician, Respondent Robson, failed to conduct the required smog tests
9 on the Bureau's 1988 Toyota pickup truck in accordance with the Bureau's
10 specifications.

11 **SEVENTH CAUSE FOR DISCIPLINE**

12 **(Dishonesty, Fraud or Deceit)**

13 36. Respondent California Smog Certification's smog check station license is
14 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
15 that Respondent committed a dishonest, fraudulent or deceitful act whereby another is injured by
16 issuing an electronic smog certificate of compliance for the Bureau's 1988 Toyota pickup truck
17 without performing a bona fide inspection of the emission control devices and systems on the
18 vehicle, thereby depriving the People of the State of California of the protection afforded by the
19 Motor Vehicle Inspection Program.

20 **EIGHTH CAUSE FOR DISCIPLINE**

21 **(Violations of the Motor Vehicle Inspection Program)**

22 37. Respondent Robson's advanced emission specialist technician license is
23 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
24 that he failed to comply with provisions of that Code as follows:

- 25 a. **Section 44012:** Respondent failed to perform the emission control tests
26 on the Bureau's 1988 Toyota pickup truck in accordance with procedures
27 prescribed by the department.

28 ///

- 1 b. **Section 44059:** Respondent willfully made false entries on the VIR
2 dated August 5, 2005, as set forth in paragraph 30 above, resulting in the
3 issuance of an electronic smog certificate of compliance for the Bureau's
4 1988 Toyota pickup truck.

5 **NINTH CAUSE FOR DISCIPLINE**

6 **(Failure to Comply with Regulations Pursuant**
7 **to the Motor Vehicle Inspection Program)**

8 38. Respondent Robson's advanced emission specialist technician license is
9 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
10 that Respondent failed to comply with provisions of California Code of Regulations, title 16, as
11 follows:

- 12 a. **Section 3340.24, subdivision (c):** Respondent falsely or fraudulently
13 issued an electronic smog certificate of compliance for the Bureau's
14 1988 Toyota pickup truck.
15 b. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
16 the Bureau's 1988 Toyota pickup truck in accordance with Health & Saf.
17 Code sections 44012 and 44035, and California Code of Regulations, title
18 16, section 3340.42.
19 c. **3340.41, subdivision (c):** Respondent knowingly entered into the
20 emissions inspection system false information about the Bureau's 1988
21 Toyota pickup truck.
22 d. **Section 3340.42:** Respondent failed to conduct the required smog tests on
23 the Bureau's 1988 Toyota pickup truck in accordance with the Bureau's
24 specifications.

25 **TENTH CAUSE FOR DISCIPLINE**

26 **(Dishonesty, Fraud or Deceit)**

27 39. Respondent Robson's advanced emission specialist technician license is
28 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in

1 that he committed a dishonest, fraudulent or deceitful act whereby another is injured by issuing
2 an electronic smog certificate of compliance for the Bureau's 1988 Toyota pickup truck without
3 performing a bona fide inspection of the emission control devices and systems on the vehicle,
4 thereby depriving the People of the State of California of the protection afforded by the Motor
5 Vehicle Inspection Program.

6 **ELEVENTH CAUSE FOR DISCIPLINE**

7 **(Untrue or Misleading Statements)**

8 40. Respondent Zuniga's automotive repair dealer registration is subject to
9 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that
10 Respondent made or authorized statements which he knew, or in the exercise of reasonable care,
11 should have known to be untrue or misleading, as follows:

12 a. Respondent certified under penalty of perjury on the VIR dated August 4,
13 2005, that the Bureau's 1988 Toyota pickup truck had passed the pretest inspection and was in
14 compliance with applicable laws and regulations. In fact, the #2 vacuum switch on the vehicle
15 was defective, the CO and HC exhaust tailpipe emissions were excessive, the PCV system was
16 disconnected, and the TAC unit was missing.

17 b. Respondent represented on Invoice No. 64237 that the carburetor on the
18 Bureau's 1988 Toyota pickup truck had been adjusted when, in fact, that repair was not
19 performed on the vehicle.

20 **TWELFTH CAUSE FOR DISCIPLINE**

21 **(Failure to Provide Copy of Signed Document)**

22 41. Respondent Zuniga's automotive repair dealer registration is subject to
23 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(3), in that on or
24 about August 4, 2005, Respondent's employee failed to give the undercover operator a copy of
25 the work order/invoice, identified in paragraph 26 above, as soon as the operator signed the
26 document.

27 ///

28 ///

1 **THIRTEENTH CAUSE FOR DISCIPLINE**

2 **(Fraud)**

3 42. Respondent Zuniga's automotive repair dealer registration is subject to
4 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that
5 Respondent committed an act which constitutes fraud. Respondent charged and obtained
6 payment from the undercover operator for adjusting the carburetor on the Bureau's 1988 Toyota
7 pickup truck when, in fact, that repair was not performed on the vehicle.

8 **FOURTEENTH CAUSE FOR DISCIPLINE**

9 **(Departure From Trade Standards)**

10 43. Respondent Zuniga's automotive repair dealer registration is subject to
11 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(7), in that
12 Respondent willfully departed from or disregarded accepted trade standards for good and
13 workmanlike repair without the consent of the owner or the owner's duly authorized
14 representative, in the following material respects: Respondent failed to properly diagnose and
15 repair the defect in the emissions control system on the Bureau's 1988 Toyota pickup truck.
16 Respondent determined that the carburetor needed adjustment in order to reduce the emissions on
17 the vehicle. In fact, the #2 vacuum switch was defective, causing excessive CO and HC tailpipe
18 emissions. Further, the only repair needed for the vehicle to pass an ASM smog inspection was
19 the replacement of the defective switch, which Respondent failed to perform.

20 **FIFTEENTH CAUSE FOR DISCIPLINE**

21 **(Violations of the Bus. & Prof. Code)**

22 44. Respondent Zuniga's automotive repair dealer registration is subject to
23 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that on or
24 about August 4, 2005, Respondent failed to comply with section 9884.9, subdivision (a), of that
25 Code. Respondent's employee failed to provide the undercover operator with a written estimate
26 for parts and/or labor necessary for a specific job.

27 ///

28 ///

1 **SIXTEENTH CAUSE FOR DISCIPLINE**

2 **(Violations of the Motor Vehicle Inspection Program)**

3 45. Respondent Zuniga's smog check station license is subject to disciplinary
4 action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed
5 to comply with the following sections of that Code:

- 6 a. **Section 44012:** Respondent failed to perform the emission control tests
7 on the Bureau's 1988 Toyota pickup truck in accordance with procedures
8 prescribed by the department.
- 9 b. **Section 44016:** Respondent failed to perform the repairs on the Bureau's
10 1988 Toyota pickup truck in accordance with established specifications
11 and procedures.
- 12 c. **Section 44033, subdivision (c):** Respondent's employee failed to provide
13 the undercover operator with a written estimate for parts and/or labor
14 necessary for a specific job.

15 **SEVENTEENTH CAUSE FOR DISCIPLINE**

16 **(Failure to Comply with Regulations Pursuant
17 to the Motor Vehicle Inspection Program)**

18 46. Respondent Zuniga's smog check station license is subject to disciplinary
19 action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed
20 to comply with the following sections of California Code of Regulations, title 16:

- 21 a. **Section 3340.41, subdivision (d):** Respondent failed to perform the
22 repairs on the Bureau's 1988 Toyota pickup truck in accordance with
23 established specifications and procedures.
- 24 b. **3340.41, subdivision (c):** Respondent knowingly entered into the
25 emissions inspection system false information about the Bureau's 1988
26 Toyota pickup truck.

27 ///

28 ///

- 1 c. **Section 3340.42:** Respondent failed to conduct the required smog tests on
2 the Bureau's 1988 Toyota pickup truck in accordance with the Bureau's
3 specifications.

4 **EIGHTEENTH CAUSE FOR DISCIPLINE**

5 **(Dishonesty, Fraud or Deceit)**

6 47. Respondent Zuniga's smog check station license is subject to disciplinary
7 action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in that Respondent
8 committed a dishonest, fraudulent or deceitful act whereby another is injured by charging and
9 obtaining payment from the undercover operator for adjusting the carburetor on the Bureau's
10 1988 Toyota pickup truck when, in fact, that repair was not performed on the vehicle.

11 **NINETEENTH CAUSE FOR DISCIPLINE**

12 **(Violations of the Motor Vehicle Inspection Program)**

13 48. Respondent Zuniga's advanced emission specialist technician license is
14 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
15 that he failed to comply with provisions of that Code as follows:

- 16 a. **Section 44012:** Respondent failed to perform the emission control tests
17 on the Bureau's 1988 Toyota pickup truck in accordance with procedures
18 prescribed by the department.
19 b. **Section 44059:** Respondent willfully made false entries on the VIR
20 dated August 4, 2005, as set forth in subparagraph 40 (a) above.

21 **TWENTIETH CAUSE FOR DISCIPLINE**

22 **(Failure to Comply with Regulations Pursuant
23 to the Motor Vehicle Inspection Program)**

24 49. Respondent Zuniga's advanced emission specialist technician license is
25 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in

26 ///

27 ///

28 ///

1 that Respondent failed to comply with provisions of California Code of Regulations, title 16, as
2 follows:

- 3 a. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
4 the Bureau's 1988 Toyota pickup truck in accordance with Health & Saf.
5 Code sections 44012 and 44035, and California Code of Regulations, title
6 16, section 3340.42.
- 7 b. **Section 3340.42:** Respondent failed to conduct the required smog tests on
8 the Bureau's 1988 Toyota pickup truck in accordance with the Bureau's
9 specifications.

10 **UNDERCOVER OPERATION #2: 1992 CHEVROLET S10 PICKUP TRUCK**

11 50. On September 20, 2005, an undercover operator with the Bureau
12 (hereinafter "the operator") took the Bureau's 1992 Chevrolet S10 pickup truck to Respondent
13 California Smog Certification's 1655 Broadway facility. A defective coolant temperature sensor
14 ("CTS") had been installed in the Bureau-documented vehicle, causing the vehicle's exhaust
15 tailpipe emissions to exceed the gross polluter limits. The operator met with Respondent's
16 service writer and requested a smog inspection. The operator completed and signed a work
17 order/invoice, but did not receive a copy of the document or a written estimate for the inspection.
18 After the smog inspection was completed, the service writer told the operator that the vehicle
19 failed the inspection. The operator paid the service writer \$49.75 in cash and received a final
20 invoice, VIR, and station list.

21 51. At approximately 1335 hours that same day, the operator took the vehicle
22 to Zuniga's facility, Jesse Smog Station. The operator told Zuniga that the vehicle needed smog
23 repairs. Zuniga's employee, "Roberto", checked the vehicle and looked under the hood. Roberto
24 told the operator to buy a coolant sensor and he would install it in the vehicle.

25 52. On September 21, 2005, Bureau Representative Paul Stump ("Stump")
26 inspected the vehicle. Stump found that the defective CTS was still in place; however, the sensor
27 had been disturbed and the top part of the sensor had been separated from the lower part. Stump
28 installed a new CTS in the engine.

1 53. On September 26, 2005, the operator returned the vehicle to Jesse Smog
2 Station and told Zuniga that her boyfriend replaced the CTS. Zuniga asked the operator if she
3 needed him to check the vehicle so that it would pass a smog inspection. The operator
4 authorized Zuniga to perform the smog inspection. The operator completed and signed a work
5 order/invoice, but did not receive a copy of the document or a written estimate. Roberto told the
6 operator that they needed to fix the timing (ignition timing), which would cost \$80. The operator
7 authorized the repair and while waiting at the facility, observed Zuniga perform a smog
8 inspection on the vehicle. After the inspection was completed, the operator paid Roberto \$80 in
9 cash and received copies of two invoices numbered 64924 and a VIR dated September 26, 2005,
10 for a pretest inspection. The VIR indicated that the vehicle passed the pretest inspection and that
11 the ignition timing was checked and passed the inspection at 10 degrees before top dead center
12 ("BTDC"). The operator asked Zuniga what he had done to the vehicle. Zuniga told the operator
13 that he replaced a hose and "the smog went down." Roberto told the operator that she should
14 return to California Smog Certification.

15 54. On September 27, 2005, Stump reinspected the vehicle and found that the
16 ignition timing test had not been performed, or performed properly, the thermostatic air cleaner
17 ("ACL") cover was incorrectly installed, allowing fresh air to enter the throttle body without
18 going through the ACL snorkel; and the vacuum hose to the hot air door actuator had been
19 notched (the notch was deep enough to allow a vacuum leak at the hose). Stump performed an
20 ASM smog check inspection on the vehicle. The vehicle failed the visual portion of the
21 inspection due to the modified ACL.

22 55. On October 4, 2005, the operator returned the vehicle to Respondent
23 California Smog Certification's 1655 Broadway facility and requested a smog inspection. The
24 catalytic converter on the vehicle had been gutted (all of the catalyst material had been removed
25 from the emission control component), causing the vehicle's exhaust tailpipe emissions to exceed
26 the gross polluter limits. The operator completed and signed a work order/invoice which was
27 given to her by the service writer, but did not receive a copy of the document or a written
28 estimate. After the smog inspection was completed, the service writer told the operator that the

1 vehicle failed the inspection. The operator did not receive an invoice or VIR for the smog
2 inspection performed that day.

3 **TWENTY-FIRST CAUSE FOR DISCIPLINE**

4 **(Failure to Provide Copy of Signed Document)**

5 56. Respondent California Smog Certification's automotive repair dealer
6 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
7 subdivision (a)(3), in that on or about September 20, 2005, and October 4, 2005, Respondent's
8 service writer failed to give the undercover operator copies of the work orders/invoices,
9 identified in paragraphs 50 and 55 above, as soon as the operator signed the documents.

10 **TWENTY-SECOND CAUSE FOR DISCIPLINE**

11 **(Violations of the Bus. & Prof. Code)**

12 57. Respondent California Smog Certification's automotive repair dealer
13 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
14 subdivision (a)(6), in that Respondent failed to comply with provisions of that Code, as follows:

- 15 a. **Section 9884.8:** On or about October 4, 2005, Respondent failed to
16 provide the undercover operator with an invoice listing all service work
17 performed and/or parts supplied on the Bureau's 1992 Chevrolet S10
18 pickup truck.
- 19 b. **Section 9884.9, subdivision (a):** On or about September 20, 2005, and
20 October 4, 2005, Respondent's service writer failed to provide the
21 undercover operator with written estimates for parts and/or labor
22 necessary for a specific job.

23 **TWENTY-THIRD CAUSE FOR DISCIPLINE**

24 **(Violations of the Motor Vehicle Inspection Program)**

25 58. Respondent California Smog Certification's smog check station license is
26 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
27 that Respondent failed to comply with section 44033, subdivision (c), of that Code, as follows:
28 On or about September 20, 2005, and October 4, 2005, Respondent's service writer failed to

1 provide the undercover operator with written estimates for parts and/or labor necessary for a
2 specific job.

3 **TWENTY-FOURTH CAUSE FOR DISCIPLINE**

4 **(Failure to Comply with Regulations Pursuant
5 to the Motor Vehicle Inspection Program)**

6 59. Respondent California Smog Certification's smog check station license is
7 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
8 that on or about October 4, 2005, Respondent failed to comply with California Code of
9 Regulations, title 16, section 3340.41, subdivision (a), by failing to provide the undercover
10 operator with a copy of the VIR following the smog inspection on the Bureau's 1992 Chevrolet
11 S10 pickup truck.

12 **TWENTY-FIFTH CAUSE FOR DISCIPLINE**

13 **(Untrue or Misleading Statements)**

14 60. Respondent Zuniga's automotive repair dealer registration is subject to
15 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that
16 Respondent made or authorized statements which he knew, or in the exercise of reasonable care,
17 should have known to be untrue or misleading, as follows:

18 a. Respondent certified under penalty of perjury on the VIR dated September
19 26, 2005, that he performed the pretest inspection on the Bureau's 1992 Chevrolet S10 pickup
20 truck in accordance with all Bureau requirements. In fact, Respondent failed to perform, or
21 properly perform, the functional ignition timing check on the vehicle in that he failed to
22 disconnect the wire timing connector during the test.

23 b. Respondent certified under penalty of perjury on the VIR dated September
24 26, 2005, that the Bureau's 1992 Chevrolet S10 pickup truck had passed the visual portion of the
25 smog inspection. In fact, the ACL cover was incorrectly installed, allowing fresh air to enter the
26 throttle body without going through the ACL snorkel, and the vacuum hose to the hot air door
27 actuator had been notched (the notch was deep enough to allow a vacuum leak at the hose).

28 ///

1 **TWENTY-SIXTH CAUSE FOR DISCIPLINE**

2 **(Failure to Provide Copy of Signed Document)**

3 61. Respondent Zuniga's automotive repair dealer registration is subject to
4 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(3), in that on or
5 about September 26, 2005, Respondent failed to give the undercover operator a copy of the work
6 order/invoice, identified in paragraph 53 above, as soon as the operator signed the document.

7 **TWENTY-SEVENTH CAUSE FOR DISCIPLINE**

8 **(Violations of the Bus. & Prof. Code)**

9 62. Respondent Zuniga's automotive repair dealer registration is subject to
10 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that
11 Respondent failed to comply with provisions of that Code, as follows:

12 a. **Section 9884.8:**

- 13 1. On or about September 20, 2005, Respondent failed to provide the
14 undercover operator with an invoice listing all service work
15 performed on the Bureau's 1992 Chevrolet S10 pickup truck, i.e.,
16 the diagnosis of the emissions failure on the vehicle.
- 17 2. Respondent failed to record on Invoice No. 64924 all service work
18 performed and/or parts supplied on the Bureau's 1992 Chevrolet
19 S10 pickup truck, including the adjustment of the ignition timing
20 and the replacement of the vacuum hose.

- 21 b. **Section 9884.9, subdivision (a):** On or about September 20, 2005, and
22 September 26, 2005, Respondent failed to provide the undercover operator
23 with written estimates for parts and/or labor necessary for a specific job.

24 ///

25 ///

26 ///

27 ///

28 ///

1 **TWENTY-EIGHTH CAUSE FOR DISCIPLINE**

2 **(Violations of the Motor Vehicle Inspection Program)**

3 63. Respondent Zuniga's smog check station license is subject to disciplinary
4 action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed
5 to comply with the following sections of that Code:

- 6 a. **Section 44012:** Respondent failed to perform the emission control tests
7 on the Bureau's 1992 Chevrolet S10 pickup truck in accordance with
8 procedures prescribed by the department.
9 b. **Section 44033, subdivision (c):** On or about September 20, 2005, and
10 September 26, 2005, Respondent failed to provide the undercover operator
11 with written estimates for parts and/or labor necessary for a specific job.

12 **TWENTY-NINTH CAUSE FOR DISCIPLINE**

13 **(Failure to Comply with Regulations Pursuant**
14 **to the Motor Vehicle Inspection Program)**

15 64. Respondent Zuniga's smog check station license is subject to disciplinary
16 action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed
17 to comply with the following sections of California Code of Regulations, title 16:

- 18 a. **3340.41, subdivision (c):** Respondent knowingly entered into the
19 emissions inspection system false information about the Bureau's 1992
20 Chevrolet S10 pickup truck.
21 b. **Section 3340.42:** Respondent failed to conduct the required smog tests on
22 the Bureau's 1992 Chevrolet S10 pickup truck in accordance with the
23 Bureau's specifications.

24 ///

25 ///

26 ///

27 ///

28 ///

1 **UNDERCOVER OPERATION #3: 1988 CHEVROLET CAPRICE**

2 67. On March 22, 2006, an undercover operator with the Bureau (hereinafter
3 "the operator") took the Bureau's 1988 Chevrolet Caprice to Respondent California Smog
4 Certification's 1655 Broadway facility. The throttle positioning sensor ("TPS") ground circuit
5 wire at the engine control module (on-board computer) of the Bureau-documented vehicle had
6 been disconnected, causing the vehicle's exhaust tailpipe emissions to exceed the gross polluter
7 limits. Further, a defective bulb had been installed in the "service engine soon" light
8 (Malfunction Indicator Lamp or "MIL"), preventing the MIL from operating. The operator met
9 with Respondent's service writer, "Cynthia", and completed and signed a work order/invoice for
10 a smog inspection on the vehicle. Cynthia did not provide the operator with a copy of the work
11 order/invoice or a written estimate.

12 68. After the inspection was completed, one of Respondent's employees told
13 the operator that the vehicle failed the inspection and that some work needed to be performed on
14 the vehicle so that it would pass the smog inspection. The operator paid \$49.75 in cash and was
15 given copies of a final invoice and a VIR.

16 69. At approximately 0935 hours that same day, the operator took the vehicle
17 to Respondent Zuniga's facility, Jesse Smog Station, and requested smog repairs on the vehicle.
18 A facility employee checked the vehicle and told the operator that there were problems with the
19 carburetor. The employee stated that he could get the vehicle to pass the smog inspection and
20 that he would only charge the operator \$80. The operator authorized the repairs on the vehicle,
21 but did not receive a work order or estimate for the repairs. After the repairs were completed, the
22 operator signed and received a copy of Invoice No. 67224 and paid the facility employee \$100 in
23 cash. The operator also received a copy of a VIR dated March 22, 2006, for a pretest inspection
24 on the vehicle. The VIR indicated that Respondent Zuniga performed the pretest inspection.

25 70. On March 23, 2006, Bureau Representative John Nelson ("Nelson")
26 inspected the vehicle. Nelson found that the defective bulb in the MIL had been replaced, but
27 that the TPS ground circuit wire to the computer was still disconnected. Nelson also found that
28 the hot air tube to the thermostatic air cleaner ("TAC") was disconnected, that a jumper wire with

1 a test light had been connected to the mixture control solenoid ("M/C") dwell connector, with the
2 other end connected to a ground, and that the vacuum hose to the early fuel evaporation valve
3 ("EFE") was disconnected. Nelson performed an ASM smog check inspection on the vehicle.
4 The vehicle passed the emission test, but failed the visual inspection portion of the smog test due
5 to the disconnected vacuum hose, modified sensor wiring, and disconnected TAC. The vehicle
6 also failed the functional portion of the test because the MIL remained illuminated during the
7 test.

8 71. On March 24, 2006, the operator returned the vehicle to Respondent
9 California Smog Certification's 1655 Broadway facility. The operator met with Respondent's
10 employee, Virgil Wayne White ("White"), and requested a smog inspection. White provided the
11 operator with a work order/invoice, which the operator completed and signed. White did not
12 give the operator a copy of the work order/invoice or a written estimate for the inspection. After
13 the inspection was completed, the operator paid Cynthia \$8.25 in cash for the smog certificate
14 and received copies of an invoice and a VIR dated March 24, 2006, signed or initialed by
15 Respondent Wilson. That same day, electronic smog Certificate of Compliance #GC553940C
16 was issued for the vehicle.

17 72. On March 30, 2006, Nelson reinspected the vehicle and found that the
18 TPS ground circuit wire to the computer, the TAC hose, and the vacuum hose to the EFE valve
19 were still disconnected and that the jumper wire with the test light was still connected to the M/C
20 and grounded. Nelson also found that the vacuum hose to the exhaust gas recirculation ("EGR")
21 valve, the electric solenoid to the EGR valve, and the evaporative hose to the carburetor float
22 bowl vent were disconnected. Nelson performed an ASM smog check inspection on the vehicle.
23 The vehicle failed the test for excessive exhaust emissions, the disconnected EGR valve, TAC,
24 vacuum hoses, and carburetor float bowl vent, and the modified wiring to the sensors.

25 **THIRTY-SECOND CAUSE FOR DISCIPLINE**

26 **(Untrue or Misleading Statements)**

27 73. Respondent California Smog Certification's automotive repair dealer
28 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,

1 subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the
2 exercise of reasonable care should have known to be untrue or misleading, as follows:
3 Respondent California Smog Certification's technician, Respondent Wilson, certified under
4 penalty of perjury on the VIR dated March 24, 2006, that the Bureau's 1988 Chevrolet Caprice
5 had passed inspection and was in compliance with applicable laws and regulations. In fact,
6 the TPS ground circuit wire to the computer, the hot air tube to the TAC, the vacuum hose to the
7 EFE, the vacuum hose to the EGR valve, the electric solenoid to the EGR valve, and the
8 evaporative hose to the carburetor float bowl vent were disconnected. Further, a jumper wire
9 with a test light had been connected to the M/C dwell connector and grounded. As such, the
10 vehicle would not pass the inspection required by Health & Saf. Code section 44012.

11 **THIRTY-THIRD CAUSE FOR DISCIPLINE**

12 **(Failure to Provide Copy of Signed Document)**

13 74. Respondent California Smog Certification's automotive repair dealer
14 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
15 subdivision (a)(3), in that on or about March 22, 2006, and March 24, 2006, Respondent's
16 employees failed to give the undercover operator copies of the work orders/invoices, identified in
17 paragraphs 67 and 71 above, as soon as the operator signed the documents.

18 **THIRTY-FOURTH CAUSE FOR DISCIPLINE**

19 **(Fraud)**

20 75. Respondent California Smog Certification's automotive repair dealer
21 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
22 subdivision (a)(4), in that it committed an act which constitutes fraud, as follows: Respondent
23 issued an electronic smog certificate of compliance for the Bureau's 1988 Chevrolet Caprice
24 without performing a bona fide inspection of the emission control devices and systems on the
25 vehicle, thereby depriving the People of the State of California of the protection afforded by the
26 Motor Vehicle Inspection Program.

27 ///

28 ///

1 **THIRTY-FIFTH CAUSE FOR DISCIPLINE**

2 **(Violations of the Bus. & Prof. Code)**

3 76. Respondent California Smog Certification's automotive repair dealer
4 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
5 subdivision (a)(6), in that on or about March 22, 2006, and March 24, 2006, Respondent failed to
6 comply with section 9884.9, subdivision (a), of that Code. Respondent's employees failed to
7 provide the undercover operator with written estimates for parts and/or labor necessary for a
8 specific job.

9 **THIRTY-SIXTH CAUSE FOR DISCIPLINE**

10 **(Violations of the Motor Vehicle Inspection Program)**

11 77. Respondent California Smog Certification's smog check station license is
12 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
13 that Respondent failed to comply with the following sections of that Code:

- 14 a. **Section 44012:** Respondent California Smog Certification's technician,
15 Respondent Wilson, failed to perform the emission control tests on the
16 Bureau's 1988 Chevrolet Caprice in accordance with procedures
17 prescribed by the department.
- 18 b. **Section 44015:** Respondent California Smog Certification issued an
19 electronic smog certificate of compliance for the Bureau's 1988 Chevrolet
20 Caprice without properly testing and inspecting the vehicle to determine if
21 it was in compliance with Health & Saf. Code section 44012.
- 22 c. **Section 44033, subdivision (c):** On or about March 22, 2006, and March
23 24, 2006, Respondent's employees failed to provide the undercover
24 operator with written estimates for parts and/or labor necessary for a
25 specific job.

26 ///

27 ///

28 ///

1 **THIRTY-SEVENTH CAUSE FOR DISCIPLINE**

2 **(Failure to Comply with Regulations Pursuant**
3 **to the Motor Vehicle Inspection Program)**

4 78. Respondent California Smog Certification's smog check station license is
5 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
6 that Respondent failed to comply with the provisions of California Code of Regulations, title 16,
7 as follows:

- 8 a. **Section 3340.24, subdivision (c):** Respondent California Smog
9 Certification falsely or fraudulently issued an electronic smog certificate of
10 compliance for the Bureau's 1988 Chevrolet Caprice.
- 11 b. **Section 3340.35, subdivision (c):** Respondent California Smog
12 Certification issued an electronic smog certificate of compliance for the
13 Bureau's 1988 Chevrolet Caprice even though the vehicle had not been
14 inspected in accordance with Health & Saf. Code section 3340.42.
- 15 c. **3340.41, subdivision (c):** Respondent California Smog Certification's
16 technician, Respondent Wilson, knowingly entered into the emissions
17 inspection system false information about the Bureau's 1988 Chevrolet
18 Caprice.
- 19 d. **Section 3340.42:** Respondent California Smog Certification's
20 technician, Respondent Wilson, failed to conduct the required smog tests
21 on the Bureau's 1988 Chevrolet Caprice in accordance with the Bureau's
22 specifications.

23 **THIRTY-EIGHTH CAUSE FOR DISCIPLINE**

24 **(Dishonesty, Fraud or Deceit)**

25 79. Respondent California Smog Certification's smog check station license is
26 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
27 that Respondent committed a dishonest, fraudulent or deceitful act whereby another is injured by
28 issuing an electronic smog certificate of compliance for the Bureau's 1988 Chevrolet Caprice

1 without performing a bona fide inspection of the emission control devices and systems on the
2 vehicle, thereby depriving the People of the State of California of the protection afforded by the
3 Motor Vehicle Inspection Program.

4 **THIRTY-NINTH CAUSE FOR DISCIPLINE**

5 **(Violations of the Motor Vehicle Inspection Program)**

6 80. Respondent Wilson's advanced emission specialist technician license is
7 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
8 that he failed to comply with provisions of that Code as follows:

- 9 a. **Section 44012:** Respondent failed to perform the emission control tests
10 on the Bureau's 1988 Chevrolet Caprice in accordance with procedures
11 prescribed by the department.
12 b. **Section 44059:** Respondent willfully made false entries on the VIR
13 dated March 24, 2006, as set forth in paragraph 73 above, resulting in the
14 issuance of an electronic smog certificate of compliance for the Bureau's
15 1988 Chevrolet Caprice.

16 **FORTIETH CAUSE FOR DISCIPLINE**

17 **(Failure to Comply with Regulations Pursuant
18 to the Motor Vehicle Inspection Program)**

19 81. Respondent Wilson's advanced emission specialist technician license is
20 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
21 that Respondent failed to comply with provisions of California Code of Regulations, title 16, as
22 follows:

- 23 a. **Section 3340.24, subdivision (c):** Respondent falsely or fraudulently
24 issued an electronic smog certificate of compliance for the Bureau's
25 1988 Chevrolet Caprice.
26 b. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
27 the Bureau's 1988 Chevrolet Caprice in accordance with Health & Saf.

28 ///

Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.

- c. **3340.41, subdivision (c)**: Respondent knowingly entered into the emissions inspection system false information about the Bureau's 1988 Chevrolet Caprice.
- d. **Section 3340.42**: Respondent failed to conduct the required smog tests on the Bureau's 1988 Chevrolet Caprice in accordance with the Bureau's specifications.

FORTY-FIRST CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

82. Respondent Wilson's advanced emission specialist technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in that he committed a dishonest, fraudulent or deceitful act whereby another is injured by issuing an electronic smog certificate of compliance for the Bureau's 1988 Chevrolet Caprice without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

FORTY-SECOND CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

83. Respondent Zuniga's automotive repair dealer registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements which he knew, or in the exercise of reasonable care, should have known to be untrue or misleading, as follows: Respondent certified under penalty of perjury on the VIR dated March 22, 2006, that the Bureau's 1988 Chevrolet Caprice had passed the pretest inspection and was in compliance with applicable laws and regulations. In fact, the TPS ground circuit wire to the computer, the hot air tube to the TAC, and the vacuum hose to the EFE were disconnected. Further, a jumper wire with a test light had been connected to the M/C dwell connector and grounded.

1 **FORTY-THIRD CAUSE FOR DISCIPLINE**

2 **(Departure From Trade Standards)**

3 84. Respondent Zuniga's automotive repair dealer registration is subject to
4 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(7), in that
5 Respondent willfully departed from or disregarded accepted trade standards for good and
6 workmanlike repair without the consent of the owner or the owner's duly authorized
7 representative, in the following material respects:

8 a. Respondent failed to diagnose, or properly diagnose the defect in the
9 emissions control system on the Bureau's 1988 Chevrolet Caprice in that Respondent failed to
10 determine that the TPS ground circuit wire at the engine control module was disconnected.
11 Further, Respondent failed to repair the defect in the emissions control system by reestablishing
12 ground for the TPS circuit at the engine control module.

13 b. Respondent illegally modified the emissions control system on the
14 Bureau's 1988 Chevrolet Caprice by disconnecting the hot air tube to the TAC and the vacuum
15 hose to the EFE. Further, Respondent connected a jumper wire with a test light to the M/C dwell
16 connector and grounded the wire.

17 **FORTY-FOURTH CAUSE FOR DISCIPLINE**

18 **(Violations of the Bus. & Prof. Code)**

19 85. Respondent Zuniga's automotive repair dealer registration is subject to
20 disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that
21 Respondent failed to comply with provisions of that Code, as follows:

22 a. **Section 9884.8:** Respondent failed to record on Invoice No. 67224 all
23 service work performed and/or parts supplied on the Bureau's 1988
24 Chevrolet Caprice.

25 b. **Section 9884.9, subdivision (a):** Respondent failed to provide the
26 undercover operator with a written estimate for parts and/or labor
27 necessary for a specific job.

28 ///

1 **FORTY-FIFTH CAUSE FOR DISCIPLINE**

2 **(Violations of the Motor Vehicle Inspection Program)**

3 86. Respondent Zuniga's smog check station license is subject to disciplinary
4 action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed
5 to comply with the following sections of that Code:

- 6 a. **Section 44012:** Respondent failed to perform the emission control tests
7 on the Bureau's 1988 Chevrolet Caprice in accordance with procedures
8 prescribed by the department.
- 9 b. **Section 44016:** Respondent failed to perform the repairs on the Bureau's
10 1988 Chevrolet Caprice in accordance with established specifications
11 and procedures.
- 12 c. **Section 44033, subdivision (c):** Respondent's employee failed to provide
13 the undercover operator with a written estimate for parts and/or labor
14 necessary for a specific job.

15 **FORTY-SIXTH CAUSE FOR DISCIPLINE**

16 **(Failure to Comply with Regulations Pursuant**
17 **to the Motor Vehicle Inspection Program)**

18 87. Respondent Zuniga's smog check station license is subject to disciplinary
19 action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed
20 to comply with the following sections of California Code of Regulations, title 16:

- 21 a. **Section 3340.41, subdivision (d):** Respondent failed to perform the
22 repairs on the Bureau's 1988 Chevrolet Caprice in accordance with
23 established specifications and procedures.
- 24 b. **3340.41, subdivision (c):** Respondent knowingly entered into the
25 emissions inspection system false information about the Bureau's 1988
26 Chevrolet Caprice.

27 ///

28 ///

- 1 c. **Section 3340.42:** Respondent failed to conduct the required smog tests on
2 the Bureau's 1988 Chevrolet Caprice in accordance with the Bureau's
3 specifications.

4 **FORTY-SEVENTH CAUSE FOR DISCIPLINE**

5 **(Violations of the Motor Vehicle Inspection Program)**

6 88. Respondent Zuniga's advanced emission specialist technician license is
7 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
8 that he failed to comply with provisions of that Code as follows:

- 9 a. **Section 44012:** Respondent failed to perform the emission control tests
10 on the Bureau's 1988 Chevrolet Caprice in accordance with procedures
11 prescribed by the department.
12 b. **Section 44059:** Respondent willfully made false entries on the VIR
13 dated March 22, 2006, as set forth in paragraph 83 above.

14 **FORTY-EIGHTH CAUSE FOR DISCIPLINE**

15 **(Failure to Comply with Regulations Pursuant
16 to the Motor Vehicle Inspection Program)**

17 89. Respondent Zuniga's advanced emission specialist technician license is
18 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
19 that Respondent failed to comply with provisions of California Code of Regulations, title 16, as
20 follows:

- 21 a. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
22 the Bureau's 1988 Chevrolet Caprice in accordance with Health & Saf.
23 Code sections 44012 and 44035, and California Code of Regulations, title
24 16, section 3340.42.
25 b. **Section 3340.42:** Respondent failed to conduct the required smog tests on
26 the Bureau's 1988 Chevrolet Caprice in accordance with the Bureau's
27 specifications.

28 ///

**RESPONDENT CALIFORNIA SMOG
CERTIFICATION'S 11 3RD AVENUE FACILITY**

UNDERCOVER OPERATION #1: 1986 CHEVROLET MONTE CARLO

90. On August 8, 2005, an undercover operator with the Bureau, using the alias "Nancy Cruz" (hereinafter "the operator"), took the Bureau's 1986 Chevrolet Monte Carlo to Respondent California Smog Certification's facility located at 11 3rd Avenue, Suite A, Chula Vista, California (hereinafter "11 3rd Avenue facility"). A defective emissions coolant temperature sensor had been installed in the Bureau-documented vehicle, causing the vehicle's exhaust tailpipe emissions to exceed the gross polluter limits. Further, a faulty bulb had been installed in the MIL socket in the dash panel, preventing the MIL from functioning. The operator requested a smog inspection on the vehicle and signed and received a copy of a written estimate. After the inspection was completed, the operator was informed that the vehicle failed the inspection. The operator paid \$49.75 in cash for the inspection and received copies of an invoice and a VIR dated August 8, 2005, signed or initialed by Respondent Rivera.

91. On August 16, 2005, Bureau Representative Daniel Woods ("Woods") inspected the vehicle and found that the gas (fuel) cap had not been tested, the ignition timing had not been tested, or properly tested, and the MIL still was not functioning.

92. On August 22, 2005, the operator took the vehicle to Highland Mobil Service Station ("Highland Mobil"), a test and repair facility located at 2945 Highland Avenue, National City, California. That same day, Highland Mobile's employee, Ricardo, told the operator that the vehicle needed a new coolant temperature sensor, which the operator authorized. The operator paid Highland Mobil \$133.99 in cash for the repairs and received an invoice and a VIR. The VIR indicated that the vehicle passed a pre-test smog inspection.

93. On September 13, 2005, Woods inspected the vehicle and found that the defective coolant temperature sensor had been replaced, which corrected the vehicle's emissions failure.

94. On September 29, 2005, another undercover operator with the Bureau, using the alias "Brenda Cruz" (hereinafter "the operator"), took the vehicle to Respondent

1 California Smog Certification's 11 3rd Avenue facility. A defective emissions coolant
2 temperature sensor had been installed in the vehicle, causing the exhaust tailpipe emissions to
3 exceed the gross polluter limits. Further, a faulty bulb had been installed in the MIL socket in the
4 dash panel, preventing the MIL from functioning. The operator told a female service writer that
5 she was there for her sister and that the vehicle had failed a smog test, but had been repaired.
6 The operator requested a smog re-test on the vehicle and signed and received a copy of a written
7 estimate. After the smog inspection was completed, the operator was informed that the vehicle
8 passed the inspection. The operator paid \$8.25 in cash for the smog certificate and received
9 copies of an invoice and a VIR dated September 29, 2005, signed or initialed by Respondent
10 Garcia. That same day, electronic smog Certificate of Compliance #FY422301C was issued for
11 the vehicle.

12 95. On October 31, 2005, Woods performed an ASM smog check inspection
13 on the vehicle. The vehicle failed the emissions test as a gross polluter. Woods inspected the
14 vehicle and found that the MIL still was not functioning, the defective coolant temperature sensor
15 was still in place, and the fuel cap had not been tested.

16 **FORTY-NINTH CAUSE FOR DISCIPLINE**

17 **(Untrue or Misleading Statements)**

18 96. Respondent California Smog Certification's automotive repair dealer
19 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
20 subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the
21 exercise of reasonable care should have known to be untrue or misleading, as follows:

22 a. Respondent California Smog Certification's technician, Respondent
23 Rivera, certified under penalty of perjury on the VIR dated August 8, 2005, that he performed the
24 smog inspection on the Bureau's 1986 Chevrolet Monte Carlo in accordance with all Bureau
25 requirements. In fact, Respondent Rivera failed to perform the functional fuel cap integrity test
26 and failed to perform, or properly perform, the functional ignition timing test on the vehicle.

27 b. Respondent California Smog Certification's technician, Respondent
28 Rivera, certified under penalty of perjury on the VIR dated August 8, 2005, that the information

1 listed on the VIR was true and correct and that the Bureau's 1986 Chevrolet Monte Carlo had
2 passed the functional check portion of the smog inspection. In fact, the MIL was not functioning
3 at the time the vehicle was taken to the 11rd Avenue facility on the above date and as such, the
4 vehicle would not pass the inspection required by Health & Saf. Code section 44012.

5 c. Respondent California Smog Certification's technician, Respondent
6 Garcia, certified under penalty of perjury on the VIR dated September 29, 2005, that the Bureau's
7 1986 Chevrolet Monte Carlo had passed inspection and was in compliance with applicable laws
8 and regulations. In fact, the MIL was not functioning, the emissions coolant temperature sensor
9 was defective, and the exhaust tailpipe emissions were in excess of the gross polluter limits at the
10 time the vehicle was taken to the 11rd Avenue facility on the above date. As such, the vehicle
11 would not pass the inspection required by Health & Saf. Code section 44012.

12 d. Respondent California Smog Certification's technician, Respondent
13 Garcia, certified under penalty of perjury on the VIR dated September 29, 2005, that he
14 performed the smog inspection on the Bureau's 1986 Chevrolet Monte Carlo in accordance with
15 all Bureau requirements. In fact, Respondent Garcia failed to perform the functional fuel cap
16 integrity test on the vehicle.

17 **FIFTIETH CAUSE FOR DISCIPLINE**

18 **(Fraud)**

19 97. Respondent California Smog Certification's automotive repair dealer
20 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
21 subdivision (a)(4), in that it committed an act which constitutes fraud, as follows: Respondent
22 issued an electronic smog certificate of compliance for the Bureau's 1986 Chevrolet Monte Carlo
23 without performing a bona fide inspection of the emission control devices and systems on the
24 vehicle, thereby depriving the People of the State of California of the protection afforded by the
25 Motor Vehicle Inspection Program.

26 ///

27 ///

28 ///

1 **FIFTY-FIRST CAUSE FOR DISCIPLINE**

2 **(Violations of the Motor Vehicle Inspection Program)**

3 98. Respondent California Smog Certification's smog check station license is
4 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
5 that Respondent failed to comply with the following sections of that Code:

- 6 a. **Section 44012:** Respondent California Smog Certification's technicians,
7 Respondents Rivera and Garcia, failed to perform the emission control
8 tests on the Bureau's 1986 Chevrolet Monte Carlo in accordance with
9 procedures prescribed by the department.
- 10 b. **Section 44015:** Respondent California Smog Certification issued an
11 electronic smog certificate of compliance for the Bureau's 1986 Chevrolet
12 Monte Carlo without properly testing and inspecting the vehicle to
13 determine if it was in compliance with Health & Saf. Code section 44012.

14 **FIFTY-SECOND CAUSE FOR DISCIPLINE**

15 **(Failure to Comply with Regulations Pursuant**
16 **to the Motor Vehicle Inspection Program)**

17 99. Respondent California Smog Certification's smog check station license is
18 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
19 that Respondent failed to comply with the provisions of California Code of Regulations, title 16,
20 as follows:

- 21 a. **Section 3340.24, subdivision (c):** Respondent California Smog
22 Certification falsely or fraudulently issued an electronic smog certificate of
23 compliance for the Bureau's 1986 Chevrolet Monte Carlo.
- 24 b. **Section 3340.35, subdivision (c):** Respondent California Smog
25 Certification issued an electronic smog certificate of compliance for the
26 Bureau's 1986 Chevrolet Monte Carlo even though the vehicle had not
27 been inspected in accordance with Health & Saf. Code section 3340.42.

28 ///

- 1 c. **3340.41, subdivision (c):** Respondent California Smog
2 Certification's technicians, Respondents Rivera and Garcia, knowingly
3 entered into the emissions inspection system false information about the
4 Bureau's 1986 Chevrolet Monte Carlo.

5 **FIFTY-THIRD CAUSE FOR DISCIPLINE**

6 **(Dishonesty, Fraud or Deceit)**

7 100. Respondent California Smog Certification's smog check station license is
8 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
9 that Respondent committed a dishonest, fraudulent or deceitful act whereby another is injured by
10 issuing an electronic smog certificate of compliance for the Bureau's 1986 Chevrolet Monte
11 Carlo without performing a bona fide inspection of the emission control devices and systems on
12 the vehicle, thereby depriving the People of the State of California of the protection afforded by
13 the Motor Vehicle Inspection Program.

14 **FIFTY-FOURTH CAUSE FOR DISCIPLINE**

15 **(Violations of the Motor Vehicle Inspection Program)**

16 101. Respondent Rivera's advanced emission specialist technician license is
17 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
18 that on or about August 8, 2005, he failed to comply with provisions of that Code as follows:

- 19 a. **Section 44012:** Respondent failed to perform the emission control tests
20 on the Bureau's 1986 Chevrolet Monte Carlo in accordance with
21 procedures prescribed by the department.
22 b. **Section 44059:** Respondent willfully made false entries on the VIR dated
23 dated August 8, 2005, as set forth in subparagraphs 96 (a) and (b) above.

24 **FIFTY-FIFTH CAUSE FOR DISCIPLINE**

25 **(Failure to Comply with Regulations Pursuant
26 to the Motor Vehicle Inspection Program)**

27 102. Respondent Rivera's advanced emission specialist technician license is
28 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in

1 that on or about August 8, 2005, Respondent failed to comply with provisions of California Code
2 of Regulations, title 16, as follows:

- 3 a. **Section 3340.30, subdivision (a):** Respondent failed to inspect
4 and test the Bureau's 1986 Chevrolet Monte Carlo in accordance with
5 Health & Saf. Code sections 44012 and 44035, and California Code of
6 Regulations, title 16, section 3340.42.
- 7 b. **3340.41, subdivision (c):** Respondent knowingly entered into the
8 emissions inspection system false information about the Bureau's 1986
9 Chevrolet Monte Carlo.
- 10 c. **Section 3340.42:** Respondent failed to conduct the required smog tests on
11 the Bureau's 1986 Chevrolet Monte Carlo in accordance with the Bureau's
12 specifications.

13 **FIFTY-SIXTH CAUSE FOR DISCIPLINE**

14 **(Violations of the Motor Vehicle Inspection Program)**

15 103. Respondent Garcia's advanced emission specialist technician license is
16 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
17 that on or about September 29, 2005, he failed to comply with provisions of that Code as
18 follows:

- 19 a. **Section 44012:** Respondent failed to perform the emission control tests
20 on the Bureau's 1986 Chevrolet Monte Carlo in accordance with
21 procedures prescribed by the department.
- 22 b. **Section 44059:** Respondent willfully made false entries on the VIR dated
23 September 29, 2005, as set forth in subparagraphs 96 (c) and (d) above,
24 resulting in the issuance of an electronic smog certificate of compliance
25 for the Bureau's 1986 Chevrolet Monte Carlo.

26 ///

27 ///

28 ///

1 **FIFTY-SEVENTH CAUSE FOR DISCIPLINE**

2 **(Failure to Comply with Regulations Pursuant**
3 **to the Motor Vehicle Inspection Program)**

4 104. Respondent Garcia's advanced emission specialist technician license is
5 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
6 that on or about September 29, 2005, Respondent failed to comply with provisions of California
7 Code of Regulations, title 16, as follows:

- 8 a. **Section 3340.24, subdivision (c):** Respondent falsely or fraudulently
9 issued an electronic smog certificate of compliance for the Bureau's 1986
10 Chevrolet Monte Carlo.
- 11 b. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
12 the Bureau's 1986 Chevrolet Monte Carlo in accordance with Health &
13 Saf. Code sections 44012 and 44035, and California Code of Regulations,
14 title 16, section 3340.42.
- 15 c. **3340.41, subdivision (c):** Respondent knowingly entered into the
16 emissions inspection system false information about the Bureau's 1986
17 Chevrolet Monte Carlo.
- 18 d. **Section 3340.42:** Respondent failed to conduct the required smog tests on
19 the Bureau's 1986 Chevrolet Monte Carlo in accordance with the Bureau's
20 specifications.

21 **FIFTY-EIGHTH CAUSE FOR DISCIPLINE**

22 **(Dishonesty, Fraud or Deceit)**

23 105. Respondent Garcia's advanced emission specialist technician license is
24 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
25 that on or about September 29, 2005, he committed a dishonest, fraudulent or deceitful act
26 whereby another is injured by issuing an electronic smog certificate of compliance for the
27 Bureau's 1986 Chevrolet Monte Carlo without performing a bona fide inspection of the emission

28 ///

1 control devices and systems on the vehicle, thereby depriving the People of the State of
2 California of the protection afforded by the Motor Vehicle Inspection Program.

3 **UNDERCOVER OPERATION #2: 1984 BUICK REGAL**

4 106. On December 28, 2005, an undercover operator with the Bureau, using the
5 alias "Heather Rios" (hereinafter "the operator"), took the Bureau's 1984 Buick Regal to
6 Respondent California Smog Certification's 11 3rd Avenue facility. The fuel control wire from
7 the engine control module ("ECM") to the mixture control solenoid in the carburetor on the
8 Bureau-documented vehicle had been damaged, causing the vehicle's exhaust tailpipe emissions
9 to exceed the gross polluter limits and the MIL to remain illuminated, indicating a problem with
10 the emission control systems. The operator signed and received a copy of a written estimate for a
11 smog inspection on the vehicle, which had been given to her by Respondent's service writer.
12 After the inspection was completed, the service writer told the operator that the vehicle failed the
13 inspection and that the check engine light had a blown fuse and needed replacement. The
14 operator paid \$49.75 in cash and received a copy of an invoice and VIR.

15 107. On February 15, 2006, another undercover operator with the Bureau, using
16 the alias "Felix Rios" (hereinafter "the operator"), took the vehicle to Highland Mobil. The
17 operator told one of the technicians that the vehicle had failed a smog inspection and that he
18 needed to have the vehicle checked. The operator signed and received a copy of a written
19 estimate, totaling \$78, to diagnose the cause of the emissions failure. At approximately 1203
20 hours that same day, the operator received a telephone call from the technician. The technician
21 told the operator that there were problems with the computer and carburetor on the vehicle and
22 gave the operator a verbal estimate of \$152 to replace the computer, which the operator
23 authorized. After the repairs were completed, the operator paid \$222.16 in cash and received
24 copies of an invoice and VIR for a pretest inspection on the vehicle. The VIR indicated that the
25 vehicle passed the pretest inspection.

26 108. On February 17, 2006, Bureau Representative Daniell Rogers inspected
27 the vehicle and found that the damaged fuel control wire from the ECM to the mixture control
28 solenoid had been repaired and the MIL bulb had been replaced.

1 109. On March 27, 2006, a third undercover operator, using the alias "Maria
2 Rios" (hereinafter "operator"), took the vehicle to Respondent California Smog Certification's
3 11 3rd Avenue facility. The mixture control ("M/C") solenoid on the vehicle had been damaged,
4 causing the vehicle's exhaust tailpipe emissions to exceed the gross polluter limits and the MIL
5 to remain illuminated, indicating a problem with the emission control systems. The operator met
6 with Respondent's service writer and requested a smog re-test on the vehicle. The operator did
7 not receive an estimate for the re-test inspection. A short while later, the service writer told the
8 operator that the vehicle had passed the inspection. The operator signed a work order for the
9 inspection, but was not provided with a copy of the document. The operator paid \$8.25 for the
10 smog certificate and received copies of an invoice and a VIR dated March 27, 2006, signed or
11 initialed by Respondent Delgado. That same day, electronic smog Certificate of Compliance
12 #GC644240C was issued for the vehicle.

13 110. On March 27, 2006, Rogers performed an ASM smog check inspection on
14 the vehicle. The vehicle failed the emissions test as a gross polluter, failed the functional MIL
15 test (the MIL was illuminated during the test), and failed the visual portion of the inspection due
16 to a missing gas (fuel) cap.

17 **FIFTY-NINTH CAUSE FOR DISCIPLINE**

18 **(Untrue or Misleading Statements)**

19 111. Respondent California Smog Certification's automotive repair dealer
20 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
21 subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the
22 exercise of reasonable care should have known to be untrue or misleading, as follows:
23 Respondent California Smog Certification's technician, Respondent Delgado, certified under
24 penalty of perjury on the VIR dated March 27, 2006, that the Bureau's 1984 Buick Regal had
25 passed inspection and was in compliance with applicable laws and regulations. In fact, the
26 M/C solenoid in the carburetor was defective, the exhaust tailpipe emissions were in excess of
27 the gross polluter limits, the MIL was still illuminated on the vehicle, and the fuel cap was

28 ///

1 missing. As such, the vehicle would not pass the inspection required by Health & Saf. Code
2 section 44012.

3 **SIXTIETH CAUSE FOR DISCIPLINE**

4 **(Failure to Provide Copy of Signed Document)**

5 112. Respondent California Smog Certification's automotive repair dealer
6 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
7 subdivision (a)(3), in that on or about March 27, 2006, Respondent's service writer failed to give
8 the undercover operator a copy of the work order, identified in paragraph 109 above, as soon as
9 the operator signed the document.

10 **SIXTY-FIRST CAUSE FOR DISCIPLINE**

11 **(Fraud)**

12 113. Respondent California Smog Certification's automotive repair dealer
13 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
14 subdivision (a)(4), in that it committed an act which constitutes fraud, as follows: Respondent
15 issued an electronic smog certificate of compliance for the Bureau's 1984 Buick Regal without
16 performing a bona fide inspection of the emission control devices and systems on the vehicle,
17 thereby depriving the People of the State of California of the protection afforded by the Motor
18 Vehicle Inspection Program.

19 **SIXTY-SECOND CAUSE FOR DISCIPLINE**

20 **(Violations of the Bus. & Prof. Code)**

21 114. Respondent California Smog Certification's automotive repair dealer
22 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
23 subdivision (a)(6), in that on or about March 27, 2006, Respondent failed to comply with section
24 9884.9, subdivision (a), of that Code. Respondent's service writer failed to provide the
25 undercover operator with a written estimate for parts and/or labor necessary for a specific job.

26 ///

27 ///

28 ///

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28

2

3
4
5

- 6
7
8
9
10
11
12
13

14

15

16

17
18
19
20

- 21
22
23
24
25
26
27

28

- 1 c. **3340.41, subdivision (c):** Respondent California Smog Certification's
2 technician, Respondent Delgado, knowingly entered into the emissions
3 inspection system false information about the Bureau's 1984 Buick Regal.

4 **SIXTY-FIFTH CAUSE FOR DISCIPLINE**

5 **(Dishonesty, Fraud or Deceit)**

6 117. Respondent California Smog Certification's smog check station license is
7 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
8 that Respondent committed a dishonest, fraudulent or deceitful act whereby another is injured by
9 issuing an electronic smog certificate of compliance for the Bureau's 1984 Buick Regal without
10 performing a bona fide inspection of the emission control devices and systems on the vehicle,
11 thereby depriving the People of the State of California of the protection afforded by the Motor
12 Vehicle Inspection Program.

13 **SIXTY-SIXTH CAUSE FOR DISCIPLINE**

14 **(Violations of the Motor Vehicle Inspection Program)**

15 118. Respondent Delgado's advanced emission specialist technician license is
16 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
17 that he failed to comply with provisions of that Code, as follows:

- 18 a. **Section 44012:** Respondent failed to perform the emission control tests
19 on the Bureau's 1984 Buick Regal in accordance with procedures
20 prescribed by the department.
21 b. **Section 44059:** Respondent willfully made false entries on the VIR dated
22 dated March 27, 2006, as set forth in paragraph 111 above, resulting in the
23 issuance of a fraudulent certificate of compliance for the vehicle.

24 **SIXTY-SEVENTH CAUSE FOR DISCIPLINE**

25 **(Failure to Comply with Regulations Pursuant
26 to the Motor Vehicle Inspection Program)**

27 119. Respondent Delgado's advanced emission specialist technician license is
28 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in

1 that Respondent failed to comply with provisions of California Code of Regulations, title 16, as
2 follows:

- 3 a. **Section 3340.24, subdivision (c):** Respondent falsely or fraudulently
4 issued an electronic smog certificate of compliance for the Bureau's
5 1984 Buick Regal.
- 6 b. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
7 the Bureau's 1984 Buick Regal in accordance with Health & Saf. Code
8 sections 44012 and 44035, and California Code of Regulations, title 16,
9 section 3340.42.
- 10 c. **3340.41, subdivision (c):** Respondent knowingly entered into the
11 emissions inspection system false information about the Bureau's 1984
12 Buick Regal.
- 13 d. **Section 3340.42:** Respondent failed to conduct the required smog tests on
14 the Bureau's 1984 Buick Regal in accordance with the Bureau's
15 specifications.

16 **SIXTY-EIGHTH CAUSE FOR DISCIPLINE**

17 **(Dishonesty, Fraud or Deceit)**

18 120. Respondent Delgado's advanced emission specialist technician license is
19 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
20 that he committed a dishonest, fraudulent or deceitful act whereby another is injured by issuing
21 an electronic smog certificate of compliance for the Bureau's 1984 Buick Regal without
22 performing a bona fide inspection of the emission control devices and systems on the
23 vehicle, thereby depriving the People of the State of California of the protection afforded by the
24 Motor Vehicle Inspection Program.

25 ///

26 ///

27 ///

28 ///

1 **UNDERCOVER OPERATION #3: 1992 TOYOTA COROLLA**

2 121. On April 27, 2006, an undercover operator with the Bureau (hereinafter
3 "operator"), took the Bureau's 1992 Toyota Corolla to Respondent California Smog
4 Certification's 11 3rd Avenue facility. The signal hose to the VSV plug, a solenoid vacuum
5 valve used by the electronic control unit to control the EGR system, was routed to the wrong port
6 on the Bureau-documented vehicle, preventing the EGR valve from functioning. Further, the
7 oxygen sensor ground was switched with the oxygen sensor signal wire in the wire harness
8 connector. Both defects caused the vehicle's exhaust tailpipe emissions to exceed the gross
9 polluter limits. There were no other problems with the emission control systems on the vehicle
10 and the ignition timing was set to manufacturer's specifications (10 degrees before top dead
11 center). The operator requested a smog inspection on the vehicle. Respondent's service writer
12 had the operator complete and sign a work order for the inspection, but did not provide the
13 operator with a copy of the work order or a written estimate. After a while, the service writer
14 told the operator that the smog test would take more time because they needed to "reheat" the
15 vehicle.

16 122. After the inspection was completed, the operator paid \$58 in cash and
17 received copies of Invoice No. 343821 and a VIR signed or initialed by Respondent Delgado.
18 That same day, electronic smog Certificate of Compliance #GD440987C was issued for the
19 vehicle.

20 123. On April 27, 2006, Bureau Representative Robert Badham ("Badham")
21 reviewed the invoice and VIR. Badham noticed that the VIR indicated that the engine size on the
22 Bureau's vehicle was 2.2 liters when, in fact, the vehicle is equipped with a 1.6 liter engine.
23 Further, both the invoice and VIR referred to the vehicle as a "Camry" rather than a "Corolla".⁴
24 Badham also noticed that the engine RPM readings on the VIR were 2501 and 2384, indicating
25 that the vehicle was tested in first and second gears instead of "drive".

26 _____
27 4. The fact that the engine size was entered into the emission inspection system as 2.2 liter rather, than 1.6
28 liter as indicated on the under-hood label, may have lowered the maximum allowable limit for NOX by
approximately 35 PPM (parts per million).

1 124. On April 28, 2006, Badham performed a smog check inspection on the
2 vehicle. The vehicle failed the functional MIL test, the functional ignition timing test, and the
3 emissions test due to high NOX. Badham found that Respondent California Smog Certification
4 had adjusted the ignition timing on the vehicle^{5/} and that the ignition timing had not been
5 adjusted to manufacturer's specifications.

6 **SIXTY-NINTH CAUSE FOR DISCIPLINE**

7 **(Untrue or Misleading Statements)**

8 125. Respondent California Smog Certification's automotive repair dealer
9 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
10 subdivision (a)(1), in that Respondent made or authorized statements which it knew or in the
11 exercise of reasonable care should have known to be untrue or misleading, as follows:

12 a. Respondent California Smog Certification's technician, Respondent
13 Delgado, certified under penalty of perjury on the VIR that the Bureau's 1992 Toyota Corolla
14 had passed inspection and was in compliance with applicable laws and regulations. In fact, the
15 ignition timing on the vehicle was not adjusted to manufacturer's specifications. The ignition
16 timing had been adjusted or set to 5 degrees BTDC when the manufacturer's specifications are
17 10 degrees BDTC. Further, the MIL was illuminated, indicating a problem with the vehicle's
18 emissions system, and the NOX tailpipe emissions were in excess of the maximum allowable
19 limit. As such, the vehicle would not pass the inspection required by Health & Saf. Code section
20 44012.

21 b. Respondent California Smog Certification's technician, Respondent
22 Delgado, certified under penalty of perjury on the VIR that the ignition timing on the Bureau's

23 ///

24 _____
25 5. Health & Saf. Code section 44014.5, subdivision (b), states: "The repair of vehicles at test-only facilities
26 shall be prohibited, except that the minor repair of components damaged by station personnel during inspection at
27 the station, any minor repair that is necessary for the safe operation of a vehicle while at a station, or other minor
repairs, such as the reconnection of hoses or vacuum lines, may be undertaken at no charge to the vehicle owner or
operator if authorized in advance in writing by the department."

28 California Code of Regulations, title 16, section 3340.16, subdivision (d), states: "A smog check test-
only station shall not engage in any automotive repair work".

1 1992 Toyota Corolla was 10 degrees BTDC when, in fact, the ignition timing had been set to 5
2 degrees BTDC, as set forth in subparagraph (a) above.

3 c. Respondent California Smog Certification's technician, Respondent
4 Delgado, certified under penalty of perjury on the VIR that he performed the smog inspection on
5 the Bureau's 1992 Toyota Corolla in accordance with all Bureau requirements. In fact, Delgado
6 failed to start the inspection with the automatic transmission in drive (or overdrive if the RPM
7 exceeds 3000 RPM).

8 d. Respondent California Smog Certification's technician, Respondent
9 Delgado, certified under penalty of perjury on the VIR that the information listed on the VIR was
10 true and correct and that the Bureau's vehicle was a 1992 Toyota Camry with a 2.2 liter engine.
11 In fact, the vehicle was a 1992 Toyota *Corolla* with a 1.6 liter engine.

12 **SEVENTIETH CAUSE FOR DISCIPLINE**

13 **(Failure to Provide Copy of Signed Document)**

14 126. Respondent California Smog Certification's automotive repair dealer
15 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
16 subdivision (a)(3), in that Respondent's service writer failed to give the undercover operator a
17 copy of the work order as soon as the operator signed the document.

18 **SEVENTY-FIRST CAUSE FOR DISCIPLINE**

19 **(Fraud)**

20 127. Respondent California Smog Certification's automotive repair dealer
21 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
22 subdivision (a)(4), in that it committed an act which constitutes fraud, as follows: Respondent
23 issued an electronic smog certificate of compliance for the Bureau's 1992 Toyota Corolla
24 without performing a bona fide inspection of the emission control devices and systems on the
25 vehicle, thereby depriving the People of the State of California of the protection afforded by the
26 Motor Vehicle Inspection Program.

27 ///

28 ///

1 **SEVENTY-SECOND CAUSE FOR DISCIPLINE**

2 **(Violations of the Bus. & Prof. Code)**

3 128. Respondent California Smog Certification's automotive repair dealer
4 registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7,
5 subdivision (a)(6), in that Respondent failed to comply with section 9884.9, subdivision (a), of
6 that Code. Respondent's service writer failed to provide the undercover operator with a written
7 estimate for parts and/or labor necessary for a specific job.

8 **SEVENTY-THIRD CAUSE FOR DISCIPLINE**

9 **(Violations of the Motor Vehicle Inspection Program)**

10 129. Respondent California Smog Certification's smog check station license is
11 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
12 that Respondent failed to comply with the following sections of that Code:

- 13 a. **Section 44012:** Respondent California Smog Certification's technician,
14 Respondent Delgado, failed to perform the emission control tests on the
15 Bureau's 1992 Toyota Corolla in accordance with procedures prescribed
16 by the department.
- 17 b. **44014.5, subdivision (b):** Respondent California Smog Certification
18 repaired the Bureau's 1992 Toyota Corolla by adjusting the ignition
19 timing on the vehicle, as set forth in paragraph 124 above, when, in fact,
20 Respondent was not legally authorized to repair the vehicle as it is
21 licensed as a test only facility.
- 22 c. **Section 44015:** Respondent California Smog Certification issued an
23 electronic smog certificate of compliance for the Bureau's 1992 Toyota
24 Corolla without properly testing and inspecting the vehicle to determine if
25 it was in compliance with Health & Saf. Code section 44012.

26 ///

27 ///

28 ///

1 **SEVENTY-FOURTH CAUSE FOR DISCIPLINE**

2 **(Failure to Comply with Regulations Pursuant**
3 **to the Motor Vehicle Inspection Program)**

4 130. Respondent California Smog Certification's smog check station license is
5 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
6 that Respondent failed to comply with the provisions of California Code of Regulations, title 16,
7 as follows:

- 8 a. **Section 3340.16, subdivision (d):** Respondent California Smog
9 Certification engaged in automotive repair work by adjusting the ignition
10 timing on the Bureau's 1992 Toyota Corolla, as set forth in paragraph 124
11 above, when, in fact, Respondent was not legally authorized to repair the
12 vehicle as it is licensed as a test only facility.
- 13 b. **Section 3340.24, subdivision (c):** Respondent California Smog
14 Certification falsely or fraudulently issued an electronic smog certificate of
15 compliance for the Bureau's 1992 Toyota Corolla.
- 16 c. **Section 3340.35, subdivision (c):** Respondent California Smog
17 Certification issued an electronic smog certificate of compliance for the
18 Bureau's 1992 Toyota Corolla even though the vehicle had not been
19 inspected in accordance with Health & Saf. Code section 3340.42.
- 20 d. **3340.41, subdivision (c):** Respondent California Smog Certification's
21 technician, Respondent Delgado, knowingly entered into the emissions
22 inspection system false information about the Bureau's 1992 Toyota
23 Corolla.

24 **SEVENTY-FIFTH CAUSE FOR DISCIPLINE**

25 **(Dishonesty, Fraud or Deceit)**

26 131. Respondent California Smog Certification's smog check station license is
27 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
28 that Respondent committed a dishonest, fraudulent or deceitful act whereby another is injured by

1 issuing an electronic smog certificate of compliance for the Bureau's 1992 Toyota Corolla
2 without performing a bona fide inspection of the emission control devices and systems on the
3 vehicle, thereby depriving the People of the State of California of the protection afforded by the
4 Motor Vehicle Inspection Program.

5 **SEVENTY-SIXTH CAUSE FOR DISCIPLINE**

6 **(Violations of the Motor Vehicle Inspection Program)**

7 132. Respondent Delgado's advanced emission specialist technician license is
8 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in
9 that he failed to comply with provisions of that Code, as follows:

- 10 a. **Section 44012:** Respondent failed to perform the emission control tests
11 on the Bureau's 1992 Toyota Corolla in accordance with procedures
12 prescribed by the department.
13 b. **Section 44059:** Respondent willfully made false entries on the VIR, as set
14 forth in paragraph 125 above, resulting in the issuance of a fraudulent
15 certificate of compliance for the vehicle.

16 **SEVENTY-SEVENTH CAUSE FOR DISCIPLINE**

17 **(Failure to Comply with Regulations Pursuant
18 to the Motor Vehicle Inspection Program)**

19 133. Respondent Delgado's advanced emission specialist technician license is
20 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in
21 that Respondent failed to comply with provisions of California Code of Regulations, title 16, as
22 follows:

- 23 a. **Section 3340.24, subdivision (c):** Respondent falsely or fraudulently
24 issued an electronic smog certificate of compliance for the Bureau's
25 1992 Toyota Corolla.
26 b. **Section 3340.30, subdivision (a):** Respondent failed to inspect and test
27 the Bureau's 1992 Toyota Corolla in accordance with Health & Saf. Code

28 ///

1 sections 44012 and 44035, and California Code of Regulations, title 16,
2 section 3340.42.

- 3 c. **3340.41, subdivision (c):** Respondent knowingly entered into the
4 emissions inspection system false information about the Bureau's 1992
5 Toyota Corolla.
- 6 d. **Section 3340.42:** Respondent failed to conduct the required smog tests on
7 the Bureau's 1992 Toyota Corolla in accordance with the Bureau's
8 specifications.

9 **SEVENTY-EIGHTH CAUSE FOR DISCIPLINE**

10 **(Dishonesty, Fraud or Deceit)**

11 134. Respondent Delgado's advanced emission specialist technician license is
12 subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in
13 that he committed a dishonest, fraudulent or deceitful act whereby another is injured by issuing
14 an electronic smog certificate of compliance for the Bureau's 1992 Toyota Corolla without
15 performing a bona fide inspection of the emission control devices and systems on the
16 vehicle, thereby depriving the People of the State of California of the protection afforded by the
17 Motor Vehicle Inspection Program.

18 **OTHER MATTERS**

19 135. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the
20 Director may refuse to validate, or may invalidate temporarily or permanently, the registrations
21 for all places of business operated in this state by Respondent California Smog Certification, Inc.
22 upon a finding that said Respondent has, or is, engaged in a course of repeated and willful
23 violations of the laws and regulations pertaining to an automotive repair dealer.

24 136. Pursuant to Health & Saf. Code section 44072.8, if Smog Check, Test
25 Only, Station License Number TD 221240, issued to Respondent California Smog Certification
26 Inc., is revoked or suspended, any additional license issued under this chapter in the name of said
27 licensee may be likewise revoked or suspended by the Director.

28 ///

1 137. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission
2 Specialist Technician License Number EA 085454, issued to Karl Duer Robson, is revoked or
3 suspended, any additional license issued under this chapter in the name of said licensee may be
4 likewise revoked or suspended by the Director.

5 138. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission
6 Specialist Technician License Number EA 137341, issued to Loren Thomas Wilson, is revoked
7 or suspended, any additional license issued under this chapter in the name of said licensee may
8 be likewise revoked or suspended by the Director.

9 139. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the
10 Director may refuse to validate, or may invalidate temporarily or permanently, the registrations
11 for all places of business operated in this state by Respondent Jesus Benito Zuniga, also known
12 as Jesus B. Zuniga, owner of Jesse Smog Station, upon a finding that said Respondent has, or is,
13 engaged in a course of repeated and willful violations of the laws and regulations pertaining to an
14 automotive repair dealer.

15 140. Pursuant to Health & Saf. Code section 44072.8, if Smog Check, Test
16 Only, Station License Number RE 160498, issued to Respondent Jesus Benito Zuniga, also
17 known as Jesus B. Zuniga, owner of Jesse Smog Station, is revoked or suspended, any additional
18 license issued under this chapter in the name of said licensee may be likewise revoked or
19 suspended by the Director.

20 141. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission
21 Specialist Technician License Number EA 304458, issued to Jesus Benito Zuniga, also known as
22 Jesus B. Zuniga, is revoked or suspended, any additional license issued under this chapter in the
23 name of said licensee may be likewise revoked or suspended by the Director.

24 142. Pursuant to Health & Saf. Code section 44072.8, if Smog Check, Test
25 Only, Station License Number TF 216533, issued to Respondent California Smog Certification,
26 Inc., is revoked or suspended, any additional license issued under this chapter in the name of said
27 licensee may be likewise revoked or suspended by the Director.

28 ///

143. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 148756, issued to Jeremiah Edgar Rivera, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the Director.

144. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 143159, issued to Jaime Garcia, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the Director.

145. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 148105, issued to Diego Salvado Delgado, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the Director.

PRAAYER

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of Consumer Affairs issue a decision:

1. Temporarily or permanently invalidating Automotive Repair Dealer
Registration Number AD 221240, issued to California Smog Certification, Inc.;

2. Temporarily or permanently invalidating any other automotive repair dealer registration issued in the name of California Smog Certification, Inc., including, but not limited to, Automotive Repair Dealer Registration Number AF 216533;

3. Revoking or suspending Smog Check, Test Only, Station License Number TD 221240, issued to California Smog Certification, Inc.;

4. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name of California Smog Certification, Inc., including, but not limited to, Smog Check, Test Only, Station License Number TF 216533;

5. Revoking or suspending Advanced Emission Specialist Technician License Number EA 085454, issued to Karl Duer Robson;

///

1 6. Revoking or suspending any additional license issued under Chapter 5 of
2 the Health and Safety Code in the name of Karl Duer Robson;

3 7. Revoking or suspending Advanced Emission Specialist Technician
4 License Number EA 137341, issued to Loren Thomas Wilson;

5 8. Revoking or suspending any additional license issued under Chapter 5 of
6 the Health and Safety Code in the name of Loren Thomas Wilson;

7 9. Temporarily or permanently invalidating Automotive Repair Dealer
8 Registration Number AE 160498, issued to Jesus Benito Zuniga, also known as Jesus B. Zuniga,
9 owner of Jesse Smog Station;

10 10. Temporarily or permanently invalidating any other automotive repair
11 dealer registration issued to Jesus Benito Zuniga, also known as Jesus B. Zuniga;

12 11. Revoking or suspending Smog Check Station License Number
13 RE 160498, issued to Jesus Benito Zuniga, also known as Jesus B. Zuniga, owner of Jesse Smog
14 Station;

15 12. Revoking or suspending Advanced Emission Specialist Technician
16 License Number EA 304458, issued to Jesus Benito Zuniga, also known as Jesus B. Zuniga;

17 13. Revoking or suspending any additional license issued under Chapter 5 of
18 the Health and Safety Code in the name of Jesus Benito Zuniga, also known as Jesus B. Zuniga;

19 14. Temporarily or permanently invalidating Automotive Repair Dealer
20 Registration Number AF 216533, issued to California Smog Certification, Inc.;

21 15. Temporarily or permanently invalidating any other automotive repair
22 dealer registration issued in the name of California Smog Certification, Inc., including, but not
23 limited to, Automotive Repair Dealer Registration Number AD 221240;

24 16. Revoking or suspending Advanced Emission Specialist Technician
25 License Number EA 148756, issued to Jeremiah Edgar Rivera;

26 17. Revoking or suspending any additional license issued under Chapter 5 of
27 the Health and Safety Code in the name of Jeremiah Edgar Rivera;

28 ///

1 18. Revoking or suspending Advanced Emission Specialist Technician
2 License Number EA 143159, issued to Jaime Garcia;

3 19. Revoking or suspending any additional license issued under Chapter 5 of
4 the Health and Safety Code in the name of Jaime Garcia;

5 20. Revoking or suspending Advanced Emission Specialist Technician
6 License Number EA 148105, issued to Diego Salvado Delgado;

7 21. Revoking or suspending any additional license issued under Chapter 5 of
8 the Health and Safety Code in the name of Diego Salvado Delgado;

9 22. Ordering Respondents California Smog Certification, Inc., Karl Duer
10 Robson, Loren Thomas Wilson, Jesus Benito Zuniga, also known as Jesus B. Zuniga,
11 individually, and as owner of Jesse Smog Station, Jeremiah Edgar Rivera, Jaime Garcia, and/or
12 Diego Salvado Delgado, to pay the Bureau of Automotive Repair the reasonable costs of the
13 investigation and enforcement of this case, pursuant to Business and Professions Code section
14 125.3;

15 23. Taking such other and further action as deemed necessary and proper.

16
17 DATED: 9-26-07

18
19 
20 SHERRY MEHL
21 Chief
22 Bureau of Automotive Repair
23 Department of Consumer Affairs
24 State of California

25
26
27 Complainant
28