1	ROB BONTA	
2	Attorney General of California THOMAS L. RINALDI	
3	Supervising Deputy Attorney General M. TRAVIS PEERY	
4	Deputy Attorney General State Bar No. 261887	
5	300 So. Spring Street, Suite 1702 Los Angeles, CA 90013	
6	Telephone: (213) 269-6309 Facsimile: (916) 731-2126	
7	E-mail: Travis.Peery@doj.ca.gov Attorneys for Complainant	
8	BEFORE THE	
9	DEPARTMENT OF CONSUMER AFFAIRS FOR THE BUREAU OF AUTOMOTIVE REPAIR	
10	STATE OF CALIFORNIA	
11		
12	In the Matter of the Accusation Against:	Case No. 79/25-3073
13	LEONARDO VELASCO GARCIA DBA CHUY SMOG CHECK	ACCUSATION
14	2070 W Slauson Ave Los Angeles, CA 90047	
15	Automotive Repair Dealer Registration No. ARD 295165	
16	Smog Check Test Only Station License No. TC 295165	
17	WILLIAM ANTONIO HERNANDEZ	
18	5018 ½ S Harvard Blvd Los Angeles, CA 90026	
19	Smog Check Inspector License No.	
20	EO 641783	
21	and	
22	KEVIN EDGARDO LEZAMA 817 W 55 th St	
23	Los Angeles, CA 90037	
24	Smog Check Inspector License No EO 637795	
25	Respondents.	
26		
27		
28		1
	(LEONARDO VELASCO GARCIA DBA CHUY SMOG CHECK, WILLIAM ANTONIO HERNANDEZ, and KEVIN EDGARDO LEZAMA) ACCUSATION	

KEVIN EDGARDO LEZAMA) ACCUSATION

PARTIES

- 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as the Chief of the Bureau of Automotive Repair (Bureau), Department of Consumer Affairs.
- 2. On or about August 16, 2019, the Bureau issued Automotive Repair Dealer Registration Number ARD 295165 to Leonardo Velasco Garcia dba Chuy Smog Check (Respondent Garcia). The Automotive Repair Dealer Registration was in full force and effect at all times relevant to the charges brought herein and will expire on August 31, 2025, unless renewed.
- 3. On or about October 28, 2019, the Bureau issued Smog Check Test Only Station License Number TC 295165 to Respondent Garcia. The Smog Check Test Only Station License was in full force and effect at all times relevant to the charges brought herein and will expire on August 31, 2025, unless renewed.
- 4. On or about March 13, 2020, the Bureau certified Chuy Smog Check as a STAR station. The certification was suspended on January 29, 2025.
- 5. On or about March 18, 2019, the Bureau issued Smog Check Inspector License Number EO 641783 to William Antonio Hernandez (Respondent Hernandez). The Smog Check Inspector License was in full force and effect at all times relevant to the charges brought herein and will expire on December 31, 2026, unless renewed.
- 6. On or about January 28, 2015, the Bureau issued Smog Check Inspector License Number EO 637795 to Kevin Edgardo Lezama (Respondent Lezama). The Smog Check Inspector License was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2026, unless renewed.

JURISDICTION

- 7. This Accusation is brought before the Director of the Department of Consumer Affairs (Director) for the Bureau of Automotive Repair, under the authority of the following laws.
- 8. Business and Professions Code (Bus. & Prof. Code) section 118, subdivision (b), provides that suspension, expiration, surrender, or cancellation of a license shall not deprive the

dynamometer. The vehicle's drive wheels are placed on rollers, and the vehicle is driven to simulate driving conditions while the emissions are sampled by the EIS.

- 29. In Basic areas of the State, or depending on a vehicle's configuration, a similar test called a Two Speed Idle test is performed, but instead of applying a load to the vehicle's drive wheels with a dynamometer, the EIS measures the emissions of HC, CO, O², and CO² at idle as well as 2500 revolutions per minute (rpm).
- 30. In the visual portion of a smog check, the technician inspects the emission control components to verify that the required emission control devices are present and properly connected.
- 31. An On-Board Diagnostics (OBD II) functional test is also performed on most 1996 to 1999 model year vehicles. The EIS retrieves information through the Diagnostic Link Connector (DLC) from the vehicle's on-board computer about its ability to communicate, the status of the I/M readiness monitors and the MIL light command. The I/M readiness monitors tell whether or not the OBD II system has run a sufficient number of self-tests on the vehicle's emission and engine control systems. A failure of one or more of the OBD II functional criteria, depending on model year, will result in the vehicle failing its smog check inspection. In addition to reporting the outcome of the OBD II functional test, the smog check inspection results also show Diagnostic Trouble Codes (DTC) if there are any in the vehicle's on-board computer memory.
- 32. The inspector enters the results of the visual and functional inspections into the EIS. The EIS unit makes the determination whether or not the vehicle passes the inspection based on the results of the tailpipe, visual and functional tests.
- 33. The EIS is connected by internet connection to Bureau's Vehicle Information

 Database (VID). If the vehicle passes the visual, functional and tailpipe tests, it passes the overall inspection. A Certificate of Compliance is issued and transmitted electronically to the VID.

 Additionally, all data gathered during a Smog Check inspection, regardless of the type of inspection, is transmitted to and retained in the VID.
- 34. Beginning March 9, 2015, California's Smog Check Program was updated to require the use of an On-Board Diagnostic Inspection System (BAR-OIS). BAR-OIS is the smog check

equipment required in all areas of the State when inspecting most model-year 2000 and newer gasoline and hybrid vehicles. The system consists of a certified Data Acquisition Device (DAD), computer, bar code scanner, and printer. The DAD is an OBD scan tool that, when requested by the BAR-OIS software, retrieves OBD data from the vehicle. All OBD data that the vehicle indicates it supports is requested by the BAR-OIS software and will be retrieved. The DAD connects between the BAR-OIS computer and the vehicle's DLC. The bar code scanner is used to input inspector information, the vehicle identification number (VIN), and Department of Motor Vehicles renewal information. The printer provides a Vehicle Inspection Report (VIR) containing inspection results for motorists and a Smog Check Certificate of Compliance number for passing vehicles.

- 35. During an OIS inspection, engine operating parameters are retrieved from the vehicle's OBD II system and recorded to the VID. This is accomplished during the functional portion of the OIS Smog Check inspection by plugging the DAD into the vehicle's DLC when prompted by the OIS analyzer screen prompt. Some of the parameters recorded are:
 - Engine speed in revolutions per minute (RPM)
- Throttle position as measured by a throttle position sensor (TPS) mounted onto the throttle shaft. Measured in a percentage of opening from 0% at idle and near or up to 100% at full throttle.
- Manifold absolute pressure as measured by a manifold air pressure sensor (MAP) connected to an intake manifold source, measured in kilo pascals (kpa). Typical readings for a normally aspirated vehicle as follows: 0 kpa being absolute vacuum, 25 to 45 kpa at idle, 101 kpa at full throttle, same as atmospheric pressure at sea level.
- Mass air flow as measured by a mass air flow sensor (MAF) mounted in the engine's air intake tract. Measured in grams per second (gps).
- Ignition timing is set by the vehicle PCM based on engine speed and load, and is measured in degrees Before Top Dead Center (BTDC).

Not all vehicles include both MAP and MAF parameters. Many vehicles will have either MAP or MAF parameters separately.

- 36. During normal engine operation at idle, engine speed is relatively steady around its target idle speed. With the engine idling, the TPS is steady and at or near 0%. The MAP and/or MAF readings are also steady. For the engine speed to increase, the throttle would have to be opened in order to increase airflow through the engine. The engine's management systems supply fuel and spark timing appropriate to any changes in throttle position and engine speed. An increase in throttle, measured by the TPS, which increases engine RPM, would result in a corresponding increase in MAF as well as a change in MAP. Any movement in the throttle from the idle position will result in an increase of airflow through the engine with corresponding increases RPM and MAF along with changes in MAP.
- 37. During an OIS Smog Check inspection, along with other visual and functional inspections, there is an OBD II query portion of the inspection. The OBD II query is performed with the engine idling and, when requested by the OIS analyzer, and an elevated or increased engine speed. The increase in engine speed is performed by the inspector by stepping on the throttle pedal or manually opening the throttle resulting in a corresponding increase in engine RPMs by allowing an increase in airflow into the engine.
- 38. The Bureau has become aware of methods that some Smog Check stations and Smog Check inspectors use to fraudulently issue smog certificates to vehicles that may not pass a smog check test on their own, or in some instances, are not even present during the time the test is performed. "Clean plugging" is a method by which another vehicle's OBD II system, or another source such as defeat devices, are used to generate passing data readings or diagnostic information for the purpose of fraudulently issuing smog certificates to vehicles that are not in smog compliance, and or not present for testing. Defeat devices attempt to simulate engine operation during a smog check inspection by transmitting OBD II data to the VID which has been modified or replaced entirely for the purportedly inspected vehicle during the functional portion of the OIS inspection.

26 | ///

27 | //

28 | //

FACTUAL ALLEGATIONS

39. On or about February 18, 2025, a Bureau Representative conducted a detailed review of the VID data for Smog Check inspections performed at Chuy Smog Check which showed a pattern of vehicles being certified with engine operating parameters that did not correspond to normal engine operation, confirming the vehicles receiving smog certifications were not tested during the OBD II functional test, which constitutes clean plugging. The Bureau's review of the smog check activities at Chuy Smog Check confirmed ten (10) Smog Check Certificates of Compliance were fraudulently issued by Chuy Smog Check to vehicles that were inspected by Respondents Hernandez and Lezama.

Fraudulent Inspection Number 1 – 2002 Acura RSX Type-S

40. OIS Test Data for Chuy Smog Check indicated that on July 28, 2023, a 2002 Acura RSX Type-S, VIN #JH4DC53022C008246 (2002 RSX Type-S), was tested and Smog Certificate of Compliance #TK733642C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that between time stamps 851 and 34355, the engine RPM is steady at around 750 RPM. During this time, the data show that the throttle is fixed at 9.4% opening and the MAP is fixed at 100kpa. Between time stamp 35233 and 38806, the engine RPM is increased then held steady at around 1700 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 9.4% opening and the MAP continues to stay fixed at 100kpa. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position and fixed MAP readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2002 RSX Type-S during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Fraudulent Inspection Number 2 – 2005 Nissan Altima SE

41. OIS Test Data for Chuy Smog Check indicated that on September 16, 2023, a 2005 Nissan Altima SE, CA license #5TPT198, VIN #1N4BL11D15C376290 (2005 Altima SE), was tested and smog certificate #TM889945C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that between time

stamps 983 and 22987, the engine RPM is steady at around 700 RPM. During this time, the data show that the throttle is fixed at 1.6% opening and the MAF is fixed at 0.9gps. Between time stamp 23983 and 31017, the engine RPM is increased then held steady at around 1480 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 1.6% opening and the MAF continues to stay fixed at 0.9gps. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position and fixed MAF readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2005 Altima SE during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Fraudulent Inspection Number 3 – 2000 Jeep Wrangler / TJ SE

42. OIS Test Data for Chuy Smog Check indicated that on October 13, 2023, a 2000 Jeep Wrangler / TJ SE, VIN #1J4FA29P8YP705130 (2000 Wrangler / TJ SE), was tested and smog certificate #IX046820C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that between time stamps 956 and 31776, the engine RPM is steady at around 875 RPM. During this time, the data show that the throttle is fixed at 0.0% opening and the MAF is fixed at 4.49gps. Between time stamp 32768 and 36752, the engine RPM is increased then held steady at around 1640 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 0.0% opening and the MAF continues to stay fixed at 4.49gps. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position and fixed MAF readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2000 Wrangler / TJ SE during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Fraudulent Inspection Number 4 – 2001 Nissan Maxima GXE

43. OIS Test Data for Chuy Smog Check indicated that on October 14, 2023, a 2001
Nissan Maxima GXE, CA license #7JJP824, VIN #JN1CA31DX1T818528 (2001 Maxima GXE),
was tested and smog certificate #IX046827C was issued by Chuy Smog Check, under
Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that

between time stamps 964 and 26756 engine speed is steady at around 650 RPM. During this time, the data show that the throttle is fixed at 0.0% opening and the MAF is fixed at 3.96gps. Between time stamp 27764 and 32709, the engine RPM is increased and held steady at around 1500 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 0.0% opening and the MAF continues to stay fixed at 3.96gps. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position and fixed MAF readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2001 Maxima GXE during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Fraudulent Inspection Number 5 – 2007 BMW 335I

44. OIS Test Data for Chuy Smog Check indicated that on November 14, 2023, a 2007 BMW 335I, CA license #7ELG758, VIN #WBAVB73587PA86062 (2007 335I), was tested and smog certificate #TO838623C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that between time stamps 827 and 27763, the engine RPM is steady at around 835 RPM. During this time, the data show that the throttle is fixed at 17.3% opening and the MAP is fixed at 99kpa. Between time stamp 28623 and 45976, the engine RPM is increased and held steady at around 1725 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 17.3% opening and the MAP continues to stay fixed at 99kpa. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position and fixed MAP readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2007 335I during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Fraudulent Inspections Number 6 – 2004 Nissan Armada SE

45. OIS Test Data for Chuy Smog Check indicated that on November 15, 2023, a 2004 Nissan Armada SE, CA license #5HKA588, VIN #5N1AA08A44N724955 (2004 Armada SE), was tested and smog certificate #TO838632C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that

between time stamps 968 and 22759, the engine RPM is steady at around 680 RPM. During this time, the data show that the throttle is fixed at 0.4% opening and the MAF is fixed at 5.28gps. Between time stamp 23746 and 25716, the engine RPM is increased then held steady at around 1850 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 0.4% opening and the MAF continues to stay fixed at 5.28gps. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position and fixed MAF readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2004 Armada SE during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Fraudulent Inspection Number 7 – 2002 Subaru Impreza WRX

46. OIS Test Data for Chuy Smog Check indicated that on December 6, 2023, a 2002 Subaru Impreza WRX, CA license #5NQK408, VIN #JF1GD29672G516670 (2002 Impreza WRX), was tested and smog certificate #IX656141C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that between time stamps 949 and 25001, the engine RPM is steady at around 900 RPM. During this time, the data show that the throttle is at 0.0% opening, the MAF is at 2.76gps, and the MAP is fixed at 32kpa. Between time stamp 26004 and 29029, the data show that the engine RPM is increased then held steady at around 2075 RPM. During the steady elevated engine RPM, the data shows that the throttle continues to stay fixed at 0.0% opening, the MAF continues to stay fixed at 2.76gps, and the MAP continues to stay fixed at 32kpa. The steady idle and steady elevated engine RPMs along with the associated fixed throttle position, and fixed MAF and MAP readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2002 Impreza WRX during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

. . .

6 ///

27 || //

28 | ///

5

7 8

9

1112

1314

15

16

17

18

19

2021

22

23

2425

26

27

28

Clean Plug Number 8 – 2002 Ford F150

OIS Test Data for Chuy Smog Check indicated that on August 24, 2024, a 2002 Ford F150, CA license #7A48988, VIN #1FTRF17252NC09520 (2002 F150), was tested and smog certificate #JB024672C was issued by Chuy Smog Check, under Respondent Lezama's Smog Check Inspector License. The OIS Test Data also show that between time stamps 350 and 28825, the engine RPM is steady at around 850 RPM. During this time, the data show that the throttle is fixed at 18.4% opening and the MAF makes four drops from 5.8pgs to 4.06gps. After time stamp 28825, the engine RPM is increased and then held at around 2480 RPM. During this elevated engine RPM, the data show that the throttle increases from 23.9% opening to 24.7% opening, drops to 23.1% opening, then increases to 23.5% opening. The MAF increases from 12.25gps to 17.85gps, drops to 14.47gps, increases to 16.89gps, drops to 14.2gps, drops to 10.19gps, increases up to 13.73gps, drops to 11.61gps, then increases to 13.57gps. The steady idle and steady elevated engine RPMs along with the associated varying throttle positions and fluctuating MAF readings are not characteristic or expected for normal engine operation. The throttle position and MAF readings are expected to be stable at idle and at the elevated engine RPM. These discrepancies confirm that the OIS DAD was not connected to the 2002 Ford F150 during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Clean Plug Number 9 – 2004 BMW 325I

48. OIS Test Data for Chuy Smog Check indicated that on October 16, 2024, a 2004 BMW 325I, CA license #5JIT423, VIN #WBAET37444NJ44132 (2004 325I), was tested and smog certificate #UE593789C was issued by Chuy Smog Check, under Respondent Hernandez's Smog Check Inspector License. The OIS Test Data also show that between time stamps 858 and 21246, the engine RPM is steady at around 800 RPM. During this time, the data show that the throttle is fixed at 9.8% opening and the MAF is fixed at 0.0gps. Between time stamp 22143 and 27506, the engine RPM is increased then held steady at around 1525 RPM. During the steady elevated engine RPM, the data show that the throttle continues to stay fixed at 9.8% opening and the MAF continues to stay fixed at 0.0gps. The steady idle and steady elevated engine RPMs

28

along with the associated fixed throttle position and fixed MAF readings are not characteristic or expected for normal engine operation. These discrepancies confirm that the OIS DAD was not connected to the 2004 325I during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Clean Plug Number 10 – 2005 Honda Accord LX

49. OIS Test Data for Chuy Smog Check indicated that on October 30, 2024, a 2005 Honda Accord LX, CA license #7PMF306, VIN #JHMCM56435C006758 (2005 Accord LX), was tested and smog certificate #UE983018C was issued by Chuy Smog Check, under Respondent Lezama's Smog Check Inspector License. The OIS Test Data also show that between time stamps 859 and 21114, the engine RPM is steady at around 800 RPM. During this time, the data show that the throttle is at 9.4%, the MAF drops from 4.93gps to 2.76gps, and the MAP increases from 25kpa to 34kpa. After time stamp 21197, the engine RPM is increased then held steady at around 2100 RPM. During the elevated engine RPM, the data show that the throttle is 13.7%, the MAF drops from 8.39gps to 4.24gps, and the MAP increases from 23kpa to 25kpa. The steady idle and steady elevated engine RPMs along with the associated throttle positions and improbable MAF and MAP readings are not characteristic or expected for normal engine operation. The MAF and MAP readings are expected to be stable at idle and at the elevated engine RPM. These discrepancies confirm that the OIS DAD was not connected to the 2005 Accord LX during the certification process as required, thereby confirming this as a fraudulent inspection by way of Clean Plugging.

Respondent Garcia

FIRST CAUSE FOR DISCIPLINE

(Untrue of Misleading Statements)

50. Respondent Garcia's Automotive Repair Dealer Registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that he made statements which were known to be untrue or misleading or, which by exercise of reasonable care should have been known to be untrue or misleading, by issuing electronic smog certificates of compliance for the ten (10) vehicles set forth in paragraphs 40-49 above, certifying that those

vehicles were in compliance with applicable laws and regulations when, in fact, those vehicles had not been so inspected. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 39-49, above, as though set forth fully herein.

SECOND CAUSE FOR DISCIPLINE

(Fraud)

51. Respondent Garcia's Automotive Repair Dealer Registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that he committed acts that constitute fraud by issuing electronic certificates of compliance to the ten (10) vehicles set forth in paragraphs 40-49, above, without performing bone fide inspections of the emission control devices and systems on those vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 39-49, above, as though set forth fully herein.

THIRD CAUSE FOR DISCIPLINE

(Material Violation of Automotive Repair Act)

52. Respondent Garcia's Automotive Repair Dealer Registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that he failed in a material respect to comply with the provisions of this chapter or regulations adopted pursuant to it when he issued electronic certificates of compliance for the ten (10) vehicles set forth in paragraphs 40-49, above, without performing bona fide inspections of the emission control devices and systems on those vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 39-49, above, as though set forth fully herein.

- c. <u>Section 3340.35, subdivision (c)</u>: Respondent issued electronic smog certificates of compliance for the ten (10) vehicles identified in paragraphs 40-49, above, even though those vehicles had not been inspected in accordance with section 3340.42.
- d. <u>Section 3340.42</u>: Respondent failed to ensure that the smog inspections conducted on the ten (10) vehicles identified in paragraphs 40-49 above, were done in accordance with the Bureau's specifications.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 39-49, above, as though set forth fully herein.

SIXTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

55. Respondent Garcia's Smog Check Test Only Station License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health & Saf. Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts whereby another was injured by issuing electronic smog certificates of compliance for the ten (10) vehicles described in paragraphs 40-49, above, without performing bona fide inspections of the emission control devices and systems on those vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 39-49, above, as though set forth fully herein.

Respondent Hernandez

SEVENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 56. Respondent Hernandez's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that he failed to comply with the following sections of that code:
- a. <u>Section 44032</u>: Respondent failed to perform tests of emission control devices and systems of the eight (8) vehicles identified in paragraphs 40-46 and 48, above, in accordance with Health & Saf. Code section 44012.

b. <u>Section 44015, subdivision (b)</u>: Respondent caused electronic smog certificates of compliance to be issued for the eight (8) vehicles identified in paragraphs 40-46 and 48, above, without ensuring that they were properly tested and inspected to determine if they were in compliance with Health & Saf. Code section 44012.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 40-46 and 48, above, as though set forth fully herein.

EIGHTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 57. Respondent Hernandez's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that he failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent falsely or fraudulently issued electronic smog certificates of compliance for the eight (8) vehicles identified in paragraphs 40-46 and 48, above.
- b. <u>Section 3340.30, subdivision (a)</u>: Respondent failed to inspect and test the eight (8) vehicles identified in paragraphs 40-46 and 48, above, in accordance with Health & Saf. Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
- c. <u>Section 3340.41, subdivision (c)</u>: Respondent knowingly entered false information into the emissions inspection system for the eight (8) vehicles identified in paragraphs 40-46 and 48, above.
- d. <u>Section 3340.42</u>: Respondent failed to ensure that the smog inspections conducted on the eight (8) vehicles identified in paragraphs 40-46 and 48, above, were done in accordance with the Bureau's specifications.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 40-46 and 48, above, as though set forth fully herein.

///

28 | ///

NINTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

58. Respondent Hernandez's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health & Saf. Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts whereby another was injured by issuing electronic smog certificates of compliance for the eight (8) vehicles identified in paragraphs 40-46 and 48, above, without performing bona fide inspections of the emission control devices and systems on those vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 40-46 and 48, above, as though set forth fully herein.

Respondent Lezama

TENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 59. Respondent Lezama's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that he failed to comply with the following sections of that code:
- a. <u>Section 44032</u>: Respondent failed to perform tests of emission control devices and systems of the two (2) vehicles identified in paragraphs 47 and 49, above, in accordance with Health & Saf. Code section 44012.
- b. <u>Section 44015, subdivision (b)</u>: Respondent caused electronic smog certificates of compliance to be issued for the two (2) vehicles identified in paragraphs 47 and 49, above, without ensuring that they were properly tested and inspected to determine if they were in compliance with Health & Saf. Code section 44012.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 47 and 49, above, as though set forth fully herein.

7 || ///

28 | ///

ELEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant

to the Motor Vehicle Inspection Program)

- 60. Respondent Lezama's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that he failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent falsely or fraudulently issued electronic smog certificates of compliance for the two (2) vehicles identified in paragraphs 47 and 49, above.
- b. <u>Section 3340.30, subdivision (a)</u>: Respondent failed to inspect and test the two (2) vehicles identified in paragraphs 47 and 49, above, in accordance with Health & Saf. Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
- c. <u>Section 3340.41, subdivision (c)</u>: Respondent knowingly entered false information into the emissions inspection system for the two (2) vehicles identified in paragraphs 47 and 49, above.
- d. <u>Section 3340.42</u>: Respondent failed to ensure that the smog inspections conducted on the two (2) vehicles identified in paragraphs 47 and 49, above, were done in accordance with the Bureau's specifications.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 47 and 49, above, as though set forth fully herein.

TWELFTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

61. Respondent Lezama's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health & Saf. Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts whereby another was injured by issuing electronic smog certificates of compliance for the two (2) vehicles identified in paragraphs 47 and 49, above, without performing bona fide inspections of the emission control devices and systems on those vehicles, thereby depriving the

People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 47 and 49, above, as though set forth fully herein.

OTHER MATTERS

- 62. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the Director may suspend, revoke, or place on probation the registration for all places of business operated in this state by Respondent Garcia, upon a finding that he has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.
- 63. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Test Only Station License No. TC 295165, issued to Respondent Garcia, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Saf. Code in the name of said licensee may be likewise revoked or suspended by the director.
- 64. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Inspector License No. EO 641783, issued to Respondent Hernandez, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Saf. Code in the name of said licensee may be likewise revoked or suspended by the director.
- 65. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Inspector License No. EO 637795, issued to Respondent Lezama, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Saf. Code in the name of said licensee may be likewise revoked or suspended by the director.

PRAYER

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of the Department of Consumer Affairs issue a decision:

- Revoking or suspending Automotive Repair Dealer Registration Number ARD
 295165, issued to Leonardo Velasco Garcia dba Chuy Smog Check;
- 2. Revoking or suspending any other automotive repair dealer registration issued to Leonardo Velasco Garcia;