

1 ROB BONTA
Attorney General of California
2 NANCY A. KAISER
Supervising Deputy Attorney General
3 MICHAEL BROWN
Deputy Attorney General
4 State Bar No. 231237
300 So. Spring Street, Suite 1702
5 Los Angeles, CA 90013
Telephone: (213) 269-6308
6 Facsimile: (916) 731-2126
E-mail: MichaelB.Brown@doj.ca.gov
7 *Attorneys for Complainant*

8 **BEFORE THE**
9 **DEPARTMENT OF CONSUMER AFFAIRS**
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No.79/25-21964

13 **JOSE ANTONIO RENDEROS-OWNER**
14 **DBA AZUR SMOG CHECK**
15 **4815 S Figueroa Street**
16 **Los Angeles, CA 90037**
17 **Automotive Repair Dealer Registration No.**
18 **ARD 297712**
19 **Smog Check, Test-Only, Station License No.**
20 **TC 297712**

ACCUSATION

21 **and**

22 **JOSE ANTONIO RENDEROS**
23 **3420 S Bronson Avenue**
24 **Los Angeles, CA 90018**
25 **Smog Check Station Inspector No.**
26 **EO 644890**

27 Respondents

28 **PARTIES**

1. Patrick Dorais (“Complainant”) brings this Accusation solely in his official capacity as the Chief of the Bureau of Automotive Repair (“Bureau”), Department of Consumer Affairs.

///

///

///

1 **Jose Antonio Renderos-Owner dba Azur Smog Check**

2 **Automotive Repair Dealer Registration**

3 2. On or about July 30, 2020, the Bureau issued Automotive Repair Dealer Registration
4 Number ARD 297712 to Jose Antonio Renderos-Owner dba Azur Smog Check (“Respondent
5 Azur Smog”). The Automotive Repair Dealer Registration was in full force and effect at all times
6 relevant to the charges brought herein and will expire on July 31, 2026, unless renewed.

7 **Smog Check, Test-Only, Station License**

8 3. On or about May 2, 2022, the Bureau issued Smog Check, Test-Only, Station License
9 Number TC 297712 to Respondent Azur Smog. The Smog Check, Test-Only, Station License
10 was in full force and effect at all times relevant to the charges brought herein and will expire on
11 July 31, 2026, unless renewed.

12 **STAR Station Certification**

13 4. Respondent Azur Smog is also certified as a STAR Station. The certification was
14 issued on or about October 31, 2023, and was suspended on October 29, 2024.

15 **. Jose Antonio Renderos**

16 **Smog Check Inspector License**

17 5. On or about March 11, 2024, the Bureau issued Smog Check Inspector License
18 Number EO 644890 to Jose Antonio Renderos (“Respondent Renderos”). The Smog Check
19 Inspector License was in full force and effect at all times relevant to the charges brought herein
20 and will expire on February 28, 2026, unless renewed.

21 **JURISDICTION**

22 6. Business and Professions Code (“Code”) section 9884.7 provides that the Director
23 may revoke an automotive repair dealer registration.

24 7. Section 9884.13 of the Code provides, in pertinent part, that the expiration of a valid
25 registration shall not deprive the director or chief of jurisdiction to proceed with a disciplinary
26 proceeding against an automotive repair dealer or to render a decision invalidating a registration
27 temporarily or permanently.

28 ///

1 testing using onboard diagnostic systems, in lieu of loaded mode dynamometer or
2 two-speed idle testing, on model year 2000 and newer vehicles only, beginning no
3 earlier than January 1, 2013, and on model-year 1996-99, inclusive, vehicles only,
4 beginning no earlier than January 1, 2025. However, the department, in consultation
5 with the state board, may prescribe alternative test procedures that include loaded
6 mode dynamometer or two-speed idle testing for vehicles with onboard diagnostic
7 systems that the department and the state board determine exhibit operational
8 problems. The department shall ensure, as appropriate to the test method, the
9 following:

10 (a) Emission control systems required by state and federal law are reducing
11 excess emissions in accordance with the standards adopted pursuant to subdivisions
12 (a) and (c) of Section 44013.

13 (b) Motor vehicles are preconditioned to ensure representative and stabilized
14 operation of the vehicle's emission control system.

15 (c) For other than diesel-powered vehicles, the vehicle's exhaust emissions of
16 hydrocarbons, carbon monoxide, carbon dioxide, and oxides of nitrogen in an idle
17 mode or loaded mode are tested in accordance with procedures prescribed by the
18 department. In determining how loaded mode and evaporative emissions testing shall
19 be conducted, the department shall ensure that the emission reduction targets for the
20 enhanced program are met.

21 (d) For other than diesel-powered vehicles, the vehicle's fuel evaporative
22 system and crankcase ventilation system are tested to reduce any nonexhaust sources
23 of volatile organic compound emissions, in accordance with procedures prescribed by
24 the department.

25 (e) For diesel-powered vehicles, a visual inspection is made of emission
26 control devices and the vehicle's exhaust emissions are tested in accordance with
27 procedures prescribed by the department, that may include, but are not limited to,
28 onboard diagnostic testing. The test may include testing of emissions of any or all of
the pollutants specified in subdivision (c) and, upon the adoption of applicable
standards, measurement of emissions of smoke or particulates, or both.

(f) A visual or functional check is made of emission control devices specified
by the department, including the catalytic converter in those instances in which the
department determines it to be necessary to meet the findings of [Section 44001](#). The
visual or functional check shall be performed in accordance with procedures
prescribed by the department.

(g) A determination as to whether the motor vehicle complies with the
emission standards for that vehicle's class and model-year as prescribed by the
department.

(h) An analysis of pass and fail rates of vehicles subject to an onboard
diagnostic test and a tailpipe test to assess whether any vehicles passing their onboard
diagnostic test have, or would have, failed a tailpipe test, and whether any vehicles
failing their onboard diagnostic test have or would have passed a tailpipe test.

(i) The test procedures may authorize smog check stations to refuse the testing
of a vehicle that would be unsafe to test, or that cannot physically be inspected, as
specified by the department by regulation. The refusal to test a vehicle for those
reasons shall not excuse or exempt the vehicle from compliance with all applicable
requirements of this chapter.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

12. Section 44015 of the Health and Safety Code states:

....

(b) If a vehicle meets the requirements of Section 44012, a smog check station licensed to issue certificates shall issue a certificate of compliance or a certificate of noncompliance.

13. Section 44032 of the Health and Safety Code states:

No person shall perform, for compensation, tests or repairs of emission control devices or systems of motor vehicles required by this chapter unless the person performing the test or repair is a qualified smog check technician and the test or repair is performed at a licensed smog check station. Qualified smog check technicians shall perform tests of emission control devices and systems in accordance with Section 44012.

14. Section 44059 of the Health and Safety Code states:

The willful making of any false statement or entry with regard to a material matter in any oath, affidavit, certificate of compliance or noncompliance, or application form which is required by this chapter or Chapter 20.3 (commencing with Section 9880) of Division 3 of the Business and Professions Code, constitutes perjury and is punishable as provided in the Penal Code.

15. Section 44072.2 of the Health and Safety Code states:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

(a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health and Saf. Code, “ 44000, et seq.)] and the regulations adopted pursuant to it, which related to the licensed activities.

....

(c) Violates any of the regulations adopted by the director pursuant to this chapter.

(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

16. Section 44072.8 of the Health and Safety Code states:

When a license has been revoked or suspended following a hearing under this article, any additional license issued under this chapter in the name of the licensee may be likewise revoked or suspended by the director.

///
///
///

1 17. Section 44072.10 of the Health and Safety Code, subdivision (c) states:

2 (c) The department shall revoke the license of any smog check technician or
3 station licensee who fraudulently certifies vehicles or participates in the fraudulent
4 inspection of vehicles. A fraudulent inspection includes, but is not limited to, all of
5 the following:

6 (1) Clean piping, clean plugging, clean glassing, clean tanking, or any other
7 fraudulent inspection practice, as defined by the department.

8 (2) Tampering with a vehicle emission control system or test analyzer system.

9 (3) Tampering with a vehicle in a manner that would cause the vehicle to
10 falsely pass or falsely fail an inspection.

11 (4) Intentional or willful violation of this chapter or any regulation, standard, or
12 procedure of the department implementing this chapter.

13 **REGULATORY PROVISIONS**

14 18. California Code of Regulations, title 16, section 3340.24, states:

15

16 (c) The bureau may suspend or revoke the license of or pursue other legal
17 action against a licensee, if the licensee falsely or fraudulently issues or obtains a
18 certificate of compliance or a certificate of noncompliance.

19 19. California Code of Regulations, title 16, section 3340.30, states:

20 A licensed smog check inspector and/or repair technician shall comply with the
21 following requirements at all times while licensed:.

22 (a) Inspect, test and repair vehicles, as applicable, in accordance with section
23 44012 of the Health and Safety Code, section 44035 of the Health and
24 Safety Code, and section 3340.42 of this article..

25 20. California Code of Regulations, title 16, section 3340.35 states:

26 (c) A licensed station shall issue a certificate of compliance or noncompliance
27 to the owner or operator of any vehicle that has been inspected in accordance with the
28 procedures specified in section 3340.42 of this article and has all the required
emission control equipment and devices installed and functioning correctly.

29 21. California Code of Regulations, title 16, section 3340.41 states:

30

31 (c) No person shall enter any vehicle identification information or emission
32 control system identification data for any vehicle other than the one being tested into
33 the EIS or OIS. Nor shall any person enter into the EIS or OIS any false information

1 about the vehicle being tested.

2 22. California Code of Regulations, title 16, section 3340.42, states:

3 Smog check inspection methods are prescribed in the Smog Check Manual,
4 referenced by section 3340.45.

5 (a) All vehicles subject to a smog check inspection, shall receive one of the
6 following test methods:

7 (1) A loaded-mode test shall be the test method used to inspect 1976 - 1999
8 model-year vehicle, except diesel-powered, registered in the enhanced program areas
9 of the state. The loaded-mode test shall measure hydrocarbon, carbon monoxide,
10 carbon dioxide and oxides of nitrogen emissions, as contained in the bureau's
11 specifications referenced in subsection (a) of Section 3340.17 of this article. The
12 loaded-mode test shall use Acceleration Simulation Mode (ASM) test equipment,
13 including a chassis dynamometer, certified by the bureau.

14 On and after March 31, 2010, exhaust emissions from a vehicle subject to this
15 inspection shall be measured and compared to the emissions standards shown in the
16 Vehicle Look-up Table (VLT) Row Specific Emissions Standards (Cutpoints) Table,
17 dated March 2010, which is hereby incorporated by reference. If the emissions
18 standards for a specific vehicle are not included in this table then the exhaust
19 emissions shall be compared to the emissions standards set forth in TABLE I or
20 TABLE II, as applicable. A vehicle passes the loaded-mode test if all of its measured
21 emissions are less than or equal to the applicable emission standards specified in the
22 applicable table.

23 (2) A two-speed idle mode test shall be the test method used to inspect 1976 -
24 1999 model-year vehicles, except diesel-powered, registered in all program areas of
25 the state, except in those areas of the state where the enhanced program has been
26 implemented. The two-speed idle mode test shall measure hydrocarbon, carbon
27 monoxide and carbon dioxide emissions at high RPM and again at idle RPM, as
28 contained in the bureau's specifications referenced in subsection (a) of Section
3340.17 of this article. Exhaust emissions from a vehicle subject to this inspection
shall be measured and compared to the emission standards set forth in this section and
as shown in TABLE III. A vehicle passes the two-speed idle mode test if all of its
measured emissions are less than or equal to the applicable emissions standards
specified in Table III.

(3) An OBD-focused test, shall be the test method used to inspect gasoline-
powered vehicles 2000 model-year and newer, and diesel-powered vehicles 1998
model-year and newer. The OBD test failure criteria are specified in section
3340.42.2.

(b) In addition to subsection (a), all vehicles subject to the smog check program
shall receive the following:

(1) A visual inspection of emission control components and systems to verify
the vehicle's emission control systems are properly installed.

(2) A functional inspection of emission control systems as specified in the
Smog Check Manual, referenced by section 3340.45, which may include an OBD
test, to verify their proper operation.

1 (c) The bureau may require any combination of the inspection methods in
sections (a) and (b) under any of the following circumstances:

2 (1) Vehicles that the department randomly selects pursuant to Health and Safety
3 Code section 44014.7 as a means of identifying potential operational problems with
vehicle OBD systems.

4 (2) Vehicles identified by the bureau as being operationally or physically
5 incompatible with inspection equipment.

6 (3) Vehicles with OBD systems that have demonstrated operational problems.

7 (d) Pursuant to section 39032.5 of the Health and Safety Code, gross polluter
standards are as follows:

8 (1) A gross polluter means a vehicle with excess hydrocarbon, carbon
9 monoxide, or oxides of nitrogen emissions pursuant to the gross polluter emissions
standards included in the tables described in subsection (a), as applicable.

10 (2) Vehicles with emission levels exceeding the emission standards for gross
11 polluters during an initial inspection will be considered gross polluters and the
provisions pertaining to gross polluting vehicles will apply, including, but not limited
12 to, sections 44014.5, 44015, and 44081 of the Health and Safety Code.

13 (3) A gross polluting vehicle shall not be passed or issued a certificate of
14 compliance until the vehicle's emissions are reduced to or below the applicable
emissions standards for the vehicle included in the tables described in subsection (a),
15 as applicable. However, the provisions described in section 44017 of the Health and
Safety Code may apply.

16 (4) This subsection applies in all program areas statewide to vehicles requiring
inspection pursuant to sections 44005 and 44011 of the Health and Safety Code.

17 23. California Code of Regulations, title 16, section 3373, states:

18 No automotive repair dealer or individual in charge shall, in filling out an
19 estimate, invoice, or work order, or record required to be maintained by section
20 3340.15(f) of this chapter, withhold therefrom or insert therein any statement or
information which will cause any such document to be false or misleading, or where
21 the tendency or effect thereby would be to mislead or deceive customers, prospective
customers, or the public.

22 COST RECOVERY

23 24. Section 125.3 of the Code provides, in pertinent part, that the Board may request the
24 administrative law judge to direct a licensee found to have committed a violation or violations of
25 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
26 enforcement of the case, with failure of the licensee to comply subjecting the license to not being
27 renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be
28 included in a stipulated settlement.

1 **FACTUAL ALLEGATIONS**

2 25. During the course of regular duties, a Bureau Representative accessed the Vehicle
3 Information Database (“VID”) and reviewed Smog Check data transmitted from Respondent
4 Azur Smog. Additionally, the Bureau Representative accessed the VID and produced copies of
5 the BAR OIS Test Details and Certificate Sales.

6 26. During a Board Diagnostic Inspection System inspection (“OIS”), engine operating
7 parameters are retrieved from the vehicle’s OBD II system and recorded to the VID. This is
8 accomplished during the functional portion of the OIS Smog Check Inspection by plugging the
9 Data Acquisition Device (“DAD”) into the vehicle’s Diagnostic Link Connector (“DLC”) when
10 prompted by the OIS analyzer screen prompt. Some of the parameters recorded are:

- 11 • Engine speed in revolutions per minute (“RPM”).
- 12 • The throttle position is measured by a throttle position sensor (“TPS”) mounted onto
13 the throttle shaft. It is measured in a percentage of opening from 0% at idle and near
14 or up to 100% at full throttle.
- 15 • Manifold absolute pressure as measured by a manifold air pressure sensor (“MAP”) connected to an intake manifold source, measured in kilo pascals (“kpa”). Typical readings for a normally aspirated vehicle undergoing Smog Check inspection are as follows: 25 kPa to 45 kPa at idle, with a subsequent decrease as the RPM is raised.
- 16 • Mass airflow as measured by a mass air flow sensor (“MAF”) mounted in the engine’s air intake tract and measured in grams per second (“grams/sec”).

17 27. During normal engine operation at idle, the engine speed is relatively steady around
18 its target idle speed. With the engine idling, the TPS is steady and at or near 0%. The MAP
19 and/or MAF readings are also steady. In order for the engine speed to increase, the throttle would
20 have to be opened in order to increase airflow through the engine. The engine’s management
21 systems supply fuel and spark timing appropriate to any changes in throttle position and engine
22 speed. An increase in throttle, measured by the TPS, which increases engine RPM, would result
23 in a corresponding increase in MAF as well as a decrease in MAP.

24 28. During an OIS Smog Check Inspection, along with other visual and functional
25 inspections, there is an OBD II query portion of the inspection. The OBD II query is performed
26 with the engine idling and, when requested by the OIS analyzer, at an elevated or increased
27 engine speed. The increase in engine speed is performed by the smog check inspector by
28

1 stepping on the throttle pedal or manually opening the throttle, resulting in a corresponding
2 increase in engine RPMs by allowing an increase in airflow into the engine.

3 29. The Bureau Representative conducted a detailed review of the VID data for the Smog
4 Check inspections performed at Respondent Azur Smog's facility. The review showed a pattern
5 of vehicles being certified with engine operating parameters not corresponding to normal engine
6 operation, that confirmed the vehicles that received smog certificates were not tested during the
7 OBD II functional test, which constituted clean piping¹. The Bureau Representative's
8 comprehensive review confirmed that ten (10) Smog Check Certificates of Compliance were
9 fraudulently issued to vehicles by Respondents Azur Smog and Renderos.

10 **Fraudulent Inspection No. 1-2005 Toyota RAV4**

11 30. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
12 The review showed that on or about April 29, 2024, a 2005 Toyota RAV4 was tested, and
13 Certificate of Compliance Number TW326138C was issued by Respondents Azur Smog and
14 Respondent Renderos.

15 31. The Dynamic PID charts and data for the 2005 Toyota RAV4 showed that between
16 timestamps 146 and 22034, the engine RPM was steady at around 615 RPM. During this time,
17 the data showed that the throttle was fixed at 15.7% opening and the MAF was fixed at 2.25
18 grams/sec. After timestamp 22389, the engine RPM was increased and then held steady at around
19 1480 RPM. During this time, the data showed that the throttle was fluctuating erratically between
20 12.5% opening and 17.6% opening, and the MAF dropped from 1.93 grams/sec to 0.7 grams/sec,
21 rose to 0.9 grams/sec, dropped to 0.67 grams/sec, then eventually rose to 2.03 grams/sec.

22 32. The steady idle and steady elevated engine RPMs, along with the improbable throttle
23 positions and MAF readings, were not characteristic or expected for normal engine operation.
24 The throttle positions and MAF readings were expected to be stable at idle and at the elevated
25 engine RPM, not drop and rise unexpectedly and/or fluctuate. Additionally, the throttle positions

26 _____
27 ¹ "Clean piping" is sampling the (clean) tailpipe emissions and/or the RPM readings of another vehicle for
28 the purpose of illegally issuing smog certifications to vehicles that are not in compliance or are not present in the
smog check area during the time of the certification.

1 and MAF readings were expected to rise with the increase in engine RPM, not decrease to values
2 less than idle readings. The discrepancies in the OIS Test Data proved that the OIS DAD was not
3 connected to the 2005 Toyota RAV 4 being certified, which caused the issuance of a fraudulent
4 Smog Check Certificate of Compliance.

5 **Fraudulent Inspection No. 2-2000 Ford F150**

6 33. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
7 The review showed that on or about May 1, 2024, a 2000 Ford F150 was tested, and Certificate of
8 Compliance Number TW522212C was issued by Respondents Azur Smog and Respondent
9 Renderos.

10 34. The Dynamic PID charts and data for the 2000 Ford F150 showed that between
11 timestamps 21 and 20855, the engine RPM was steady at around 690 RPM. During this time, the
12 data showed that the throttle was fixed at 18.4% opening and the MAF was fixed at 4.8
13 grams/sec. After timestamp 21194, the engine RPM was increased and then held steady at around
14 1670 RPM. During this time, the data showed that the throttle was fluctuating between 14.1%
15 opening and 18% opening, and the MAF was fluctuating erratically between 3.06 grams/sec and
16 4.96 grams/sec.

17 35. The steady idle and steady elevated engine RPM data, along with the improbable
18 throttle positions and MAF readings, were not characteristic or expected for normal engine
19 operation. The throttle positions and MAF readings were expected to be stable at idle and at the
20 elevated engine RPM, not fluctuate. Additionally, the throttle positions and MAF readings were
21 expected to rise with the increase in engine RPM, not decrease to values less than idle readings.
22 The discrepancies in the OIS Test Data proved that the OIS DAD was not connected to the 2000
23 Ford F150 certified, which caused the issuance of a fraudulent Smog Check Certificate of
24 Compliance.

25 **Fraudulent Inspection No. 3-2002 Nissan Pathfinder LE**

26 36. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
27 The review showed that on or about May 2, 2024, a 2002 Nissan Pathfinder LE was tested, and
28

1 Certificate of Compliance Number TW522223C was issued by Respondents Azur Smog and
2 Respondent Renderos.

3 37. The Dynamic PID charts and data for the 2002 Nissan Pathfinder LE showed that
4 between timestamps 185 and 18993, the engine RPM was steady at around 750 RPM. During
5 this time, the data showed that the throttle was fixed at 0% opening and the MAF was fixed at
6 2.97 grams/sec. After timestamp 19371, the engine RPM was increased and then held steady at
7 around 1670 RPM. During this time, the data showed that the throttle dropped from 4.7%
8 opening to 0% opening, rose back to 4.7% opening, then eventually dropped to 0.8% opening,
9 and the MAF dropped from 5 grams/sec to 3.89 grams/sec, rose to 4.98 grams/sec, then dropped
10 to 3.81 grams/sec.

11 38. The steady idle and steady elevated engine RPMs, along with the improbable throttle
12 positions and MAF readings, were not characteristic or expected for normal engine operation.
13 The throttle positions and MAF readings were expected to be stable at idle and at the elevated
14 engine RPM, not drop and rise unexpectedly. Additionally, the throttle positions were expected
15 to rise with the increase in engine RPM, not decrease to values equal to idle readings. The
16 discrepancies in the OIS Test Data proved that the OIS DAD was not connected to the 2002
17 Nissan Pathfinder LE being certified, which caused the issuance of a fraudulent Smog Check
18 Certificate of Compliance.

19 **Fraudulent Inspection No. 4-2000 Honda Civic EX**

20 39. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
21 The review showed that on or about May 2, 2024, a 2000 Honda Civic EX was tested, and
22 Certificate of Compliance Number TW522226C was issued by Respondents Azur Smog and
23 Respondent Renderos.

24 40. The Dynamic PID charts and data for the 2000 Honda Civic EX showed that between
25 timestamps 125 and 17917, the engine RPM was steady at around 710 RPM. During this time,
26 the data showed that the throttle was fixed at 9% opening and the MAP was fixed at 24 kPa.
27 After timestamp 18255, the engine RPM was increased and then held at around 1740 RPM.
28 During this time, the data showed that the throttle rose from 7.8% opening to 9.4% opening,

1 dropped to 7.1% opening, then rose to 10.6% opening, and the MAP was fluctuating between 17
2 kPa and 29 kPa.

3 41. The steady idle and steady elevated engine RPMs, along with the improbable throttle
4 positions and MAP readings, were not characteristic or expected for normal engine operation.
5 The throttle position and MAP readings were expected to be stable at idle and at the higher engine
6 RPM, not drop and rise unexpectedly and/or fluctuate. Additionally, the throttle position was
7 expected to rise with the increase in engine RPM, not decrease to values less than idle readings.
8 The discrepancies in the OIS Test Data proved that the OIS DAD was not connected to the 2000
9 Honda Civic EX being certified, which caused the issuance of a fraudulent Smog Check
10 Certificate of Compliance.

11 **Fraudulent Inspection No. 5-2003 Toyota Corolla CE**

12 42. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
13 The review showed that on or about May 7, 2024, a 2003 Toyota Corolla CE was tested, and
14 Certificate of Compliance Number TW522247C was issued by Respondents Azur Smog and
15 Respondent Renderos.

16 43. The Dynamic PID charts and data for the 2003 Toyota Corolla CE showed that
17 between timestamps 139 and 18281, the engine RPM was steady at around 715 RPM. During
18 this time, the data showed that the throttle was fixed at 10.2% opening and the MAF was fixed at
19 1.75 gams/sec. After timestamp 18629, the engine RPM was increased and held steady at around
20 1735 RPM. During this time, the data showed that the throttle rose from 8.2% opening to 11%
21 opening, dropped to 6.3% opening, then eventually rose to 8.6% opening, and the MAF
22 eventually dropped from 2.22 grams/sec to 0.82 grams/sec, rose to 2.05 grams/sec, then dropped
23 to 0.26 grams/sec.

24 44. The steady idle and steady elevated engine RPMs, along with the improbable throttle
25 positions and MAF readings, were not characteristic or expected for normal engine operation.
26 The throttle position and MAF readings are expected to be stable at idle and at the higher engine
27 RPM, not drop and rise unexpectedly. Additionally, the throttle positions and MAF readings
28 were expected to rise with the increase in engine RPM, not decrease to values less than idle

1 readings. The discrepancies in the OIS Test Data proved that the OIS DAD was not connected to
2 the 2003 Toyota Corolla CE being certified, which caused the issuance of a fraudulent Smog
3 Check Certificate of Compliance.

4 **Fraudulent Inspection No. 6-2003 GMC Yukon**

5 45. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
6 The review showed that on or about May 8, 2024, a 2003 GMC Yukon was tested, and Certificate
7 of Compliance Number TW692761C was issued by Respondents Azur Smog and Respondent
8 Renderos.

9 46. The Dynamic PID charts and data for the 2003 GMC Yukon showed that between
10 timestamps 388 and 19045, the engine RPM was steady at around 590 RPM. During this time,
11 the data showed that the throttle was fixed at 1.2% opening, the MAP was fixed at 37 kPa, and
12 the MAF was fixed at 4.85 grams/sec. After timestamp 19403, the engine RPM was increased
13 and then held steady at around 1755 RPM. During this time, the data showed that the throttle
14 rose from 0% opening to 3.1% opening, then eventually dropped to a fixed 0.4% opening, the
15 MAP dropped from 37 kPa to 34 kPa, then eventually rose to 46 kPa, and the MAF was
16 fluctuating between 3.32 grams/sec and 4.67 grams/sec.

17 47. The steady idle and steady elevated engine RPMs, along with the improbable throttle
18 positions, MAP, and MAF readings, were not characteristic or expected for normal engine
19 operation. The throttle position, MAP, and MAF readings were expected to be stable at idle and
20 at the higher engine RPM, not drop and rise unexpectedly, and/or fluctuate. Additionally, the
21 throttle positions and MAF readings were expected to rise with the increase in engine RPM, not
22 decrease to values less than idle readings. The discrepancies in the OIS Test Data proved that the
23 OIS DAD was not connected to the 2003 GMC Yukon being certified, which caused the issuance
24 of a fraudulent Smog Check Certificate of Compliance.

25 **Fraudulent Inspection No. 7-2001 Honda Accord LX**

26 48. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
27 The review showed that on or about May 14, 2024, a 2001 Honda Accord LX was tested, and
28

1 Certificate of Compliance Number TW692786C was issued by Respondents Azur Smog and
2 Respondent Renderos.

3 49. The Dynamic PID charts and data for the 2001 Honda Accord LX showed that
4 between timestamps 141 and 19305, the engine RPM was steady at around 735 RPM. During
5 this time, the data showed that the throttle was fixed at 9.8% opening and the MAP was fixed at
6 25 kPa. After timestamp 19646, the engine RPM was increased, then eventually held at no less
7 than 1346 RPM. During this time, the data showed that the throttle dropped from 7.5% opening
8 to 6.3% opening, rose to 9% opening, dropped to 7.8% opening, then rose to 9.4% opening, and
9 the MAP dropped from 20 kPa to 19 kPa, eventually rose to 28 kPa, then eventually dropped to
10 16 kPa.

11 50. The steady idle and steady elevated engine RPMs, along with the improbable throttle
12 positions and MAP readings, were not characteristic or expected for normal engine operation.
13 The throttle positions and MAP readings were expected to be stable at idle and at the elevated
14 engine RPM, not drop and rise unexpectedly. Additionally, the throttle positions were expected
15 to rise with the increase in engine RPM, not decrease to values less than idle readings. The
16 discrepancies in the OIS Test Data proved that the OIS DAD was not connected to the 2001
17 Honda Accord LX being certified, which caused the issuance of a fraudulent Smog Check
18 Certificate of Compliance.

19 **Fraudulent Inspection No. 8-2004 Honda Accord EX**

20 51. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
21 The review showed that on or about November 9, 2024, a 2004 Honda Accord EX was tested,
22 and Certificate of Compliance Number JB478126C was issued by Respondents Azur Smog and
23 Respondent Renderos.

24 52. The Dynamic PID charts and data for the 2004 Honda Accord EX showed that
25 between timestamps 107 and 18336, the engine RPM was steady at around 800 RPM. During
26 this time, the data showed that the throttle was varying between 9.4% opening and 9.8% opening,
27 the MAP was fixed at 23 kPa, rose to a fixed 24 kPa, then dropped back to 23 kPa, and the MAF
28 was varying between 2.15 grams/sec, and 2.2 grams/sec. After timestamp 18611, the engine

1 RPM was increased and then held steady at around 2200 RPM. During this time, the data showed
2 that the throttle was fixed at 12.9% opening, the MAP dropped from 23 kPa to 22 kPa, then rose
3 back to a fixed 23 kPa, and the MAF was varying between 6.29 grams/sec and 6.45 grams/sec.

4 53. The steady idle and elevated engine RPMs, along with the improbable MAP readings,
5 were not characteristic or expected for normal engine operation. The MAP readings were
6 expected to decrease with the increase in engine RPM, not increase back to values equal to idle
7 readings. The discrepancies in the OIS Test Data proved that the OIS DAD was not connected to
8 the 2004 Honda Accord EX being certified, which caused the issuance of a fraudulent Smog
9 Check Certificate of Compliance.

10 **Fraudulent Inspection No. 9-2002 Honda CR-V LX**

11 54. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
12 The review showed that on or about November 9, 2024, a 2002 Honda CR-V LX was tested, and
13 Certificate of Compliance Number JB478130C was issued by Respondents Azur Smog and
14 Respondent Renderos.

15 55. The Dynamic PID charts and data for the 2002 Honda CR-V LX showed that between
16 timestamps 124 and 20827, the engine RPM was steady at around 690 RPM. During this time,
17 the data showed that the throttle was fluctuating erratically between 8.2% opening and 11.8%
18 opening, and the MAP was fluctuating erratically between 16 kPa and 29 kPa. After timestamp
19 21163, the data showed the engine RPM was increased and then held at around 1689 RPM.
20 During this time, the data showed that the throttle rose from 8.6% opening to 10.6% opening,
21 dropped to 9.4% opening, rose to 11.8% opening, then dropped to 6.3% opening, and the MAP
22 was fluctuating between as 19 kPa and 29 kPa.

23 56. The steady idle and elevated engine RPMs along improbable throttle positions and
24 MAP readings were not characteristic or expected for normal engine operation. The throttle
25 positions and MAP readings were expected to be stable at idle and at the elevated engine RPM,
26 not drop and rise unexpectedly and/or fluctuate. Additionally, the throttle position readings were
27 expected to rise with the increase in engine RPM, not decrease to values less than idle readings.
28 The discrepancies in the OIS Test Data proved that the OIS DAD was not connected to the 2002

1 Honda CR-V LX being certified, which caused the issuance of a fraudulent Smog Check
2 Certificate of Compliance.

3 **Fraudulent Inspection No. 10-2004 Ford Mustang Cobra SVT**

4 57. A Bureau Representative reviewed the OIS Test Data for Respondent Azur Smog.
5 The review showed that on or about October 18, 2025, a 2004 Ford Mustang Cobra SVT was
6 tested, and Certificate of Compliance Number JF425012C was issued by Respondents Azur Smog
7 and Respondent Renderos.

8 58. The Dynamic PID charts and data for the 2004 Ford Mustang Cobra SVT showed that
9 between timestamps 36 and 18369, the engine RPM was steady at around 770 RPM. During this
10 time, the data showed that the throttle was fixed at 19.2% opening and the MAF was fixed at 1.1
11 gams/sec. After timestamp 18597, the engine RPM was increased and then held at no less than
12 1582 RPM. During this time, the data showed that the throttle continued to stay fixed at 19.2%
13 opening and the MAF continued to stay fixed at 1.1 gams/sec.

14 59. The steady idle and steady elevated engine RPMs, along with the improbable throttle
15 positions and MAF readings, were not characteristic or expected for normal engine operation.
16 The throttle positions and MAF readings were expected to rise with the increase in engine RPM,
17 not remain fixed with no changes. The discrepancies in the OIS Test Data proved that the OIS
18 DAD was not connected to the 2004 Ford Mustang Cobra SVT being certified, which caused the
19 issuance of a fraudulent Smog Check Certificate of Compliance.

20 **FIRST CAUSE FOR DISCIPLINE**

21 **(Untrue or Misleading Statements)**

22 60. Respondent Azur Smog's Automotive Repair Registration is subject to discipline
23 pursuant to Code section 9884.7, subdivision (a)(1) and California Code of Regulations, title 16,
24 section 3373, in that between April 29, 2024, through October 18, 2025, Respondent Azur Smog
25 made or authorized statements which he knew or in the exercise of reasonable care should have
26 known to be untrue or misleading, as follows: Respondent Azur Smog certified that vehicles 1
27 through 10, set forth above, had passed inspection and were in compliance with applicable laws
28 and regulations. Respondent Azur Smog conducted the inspections on the vehicles using the

1 clean plugging method by substituting or using different vehicles or another source during the
2 OBD II functional tests to issue smog check certificates of compliance for the ten (10) vehicles
3 and did not test or inspect the ten (10) vehicles as required by Health and Safety Code section
4 44012. Complainant refers to, and by this reference incorporates, the allegations set forth above
5 in paragraphs 25 through 59, as though fully set forth.

6 **SECOND CAUSE FOR DISCIPLINE**

7 **(Fraud)**

8 61. Respondent Azur Smog’s Automotive Repair Registration is subject to discipline
9 pursuant to Code section 9884.7, subdivision (a)(4), in that between April 29, 2024, through
10 October 18, 2025, Respondent Azur Smog committed acts that constitute fraud by issuing
11 electronic smog check certificates of compliance for vehicles 1 through 10, set forth above,
12 without performing bona fide inspections of the emission control devices and systems on those
13 vehicles, thereby depriving the People of the State of California of the protection afforded by the
14 Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the
15 allegations set forth above in paragraphs 25 through 59, as though fully set forth.

16 **THIRD CAUSE FOR DISCIPLINE**

17 **(Material Violation of Automotive Repair Act)**

18 62. Respondent Azur Smog’s Automotive Repair Registration is subject to disciplinary
19 action under Code section 9884.7, subdivision (a)(6), in that between April 29, 2024, through
20 October 18, 2025, regarding vehicles 1 through 10, set forth above, Respondent Azur Smog failed
21 in a material respect to comply with the provisions of this chapter or regulations adopted pursuant
22 to it by issuing electronic smog check certificates of compliance for the ten (10) vehicles without
23 performing bona fide inspections of the emissions control devices and systems on those vehicles,
24 thereby depriving the People of the State of California of the protection afforded by the Motor
25 Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the
26 allegations set forth above in paragraphs 25 through 59, as though fully set forth.

27 ///

28 ///

1 **FOURTH CAUSE FOR DISCIPLINE**

2 **(Failure to Comply with the Motor Vehicle Inspection Program)**

3 63. Respondent Azur Smog’s Smog Check, Test-Only Station License is subject to
4 discipline pursuant to Health and Safety Code section 44072.2, subdivision (a), in that between
5 April 29, 2024, through October 18, 2025, regarding vehicles 1 through 10, set forth above,
6 Respondent Azur Smog failed to comply with the following sections of that Code:

7 a. **Section 44012:** Respondent Azur Smog failed to ensure that the emission control tests
8 were performed on vehicles 1 through 10, in accordance with procedures prescribed by the
9 department.

10 b. **Section 44015, subdivision (b):** Respondent Azur Smog issued electronic smog check
11 certificates of compliance for vehicles 1 through 10, without ensuring that the vehicles were
12 properly tested and inspected to determine if they were in compliance with Health and Safety
13 Code section 44012.

14 c. **Section 44059:** Respondent Azur Smog willfully made false entries for the electronic
15 smog check certificates of compliance by certifying that those vehicles had been inspected as
16 required when, in fact, they had not.

17 Complainant refers to, and by this reference incorporates, the allegations set forth above in
18 paragraphs 25 through 59, as though fully set forth.

19 **FIFTH CAUSE FOR DISCIPLINE**

20 **(Failure to Comply with Regulations Pursuant to the**
21 **Motor Vehicle Inspection Program)**

22 64. Respondent Azur Smog’s Smog Check, Test-Only Station License is subject to
23 discipline pursuant to Health and Safety Code section 44072.2, subdivision (c), in that between
24 April 29, 2024, through October 18, 2025, regarding vehicles 1 through 10, set forth above,
25 Respondent Azur Smog failed to comply with provisions of California Code of Regulations, title
26 16, as follows:

27 a. **Section 3340.24, subdivision (c):** Respondent Azur Smog falsely or fraudulently issued
28 electronic smog check certificates of compliance for those vehicles without performing bona fide

1 inspections of the emission control devices and systems on the vehicles as required by Health and
2 Safety Code section 44012.

3 b. **Section 3340.35, subdivision (c)**: Respondent Azur Smog issued electronic smog check
4 certificates of compliance even though those vehicles had not been inspected in accordance with
5 section 3340.42 of that Code.

6 c. **Section 3340.41, subdivision (c)**: Respondent Azur Smog knowingly entered false
7 information into the emissions inspection system for the ten (10) vehicles identified above.

8 d. **Section 3340.42**: Respondent Azur Smog failed to conduct the required smog check
9 tests and inspections on those vehicles in accordance with the Bureau's specifications.

10 Complainant refers to, and by this reference incorporates, the allegations set forth above in
11 paragraphs 25 through 59, as though fully set forth.

12 **SIXTH CAUSE FOR DISCIPLINE**

13 **(Dishonesty, Fraud or Deceit)**

14 65. Respondent Azur Smog's Smog Check, Test-Only Station License is subject to
15 discipline pursuant to Health and Safety Code sections 44072.2, subdivision (d) in conjunction
16 with 44072.10, subdivision (c), in that between April 29, 2024, through October 18, 2025,
17 regarding vehicles 1 through 10, set forth above, Respondent Azur Smog committed acts
18 involving dishonesty, fraud or deceit whereby another was injured by issuing electronic smog
19 check certificates of compliance for those vehicles without performing bona fide inspections of
20 the emission control devices and systems on the vehicles, thereby depriving the People of the
21 State of California of the protection afforded by the Motor Vehicle Inspection Program.

22 Complainant refers to, and by this reference incorporates, the allegations set forth above in
23 paragraphs 25 through 59, as though fully set forth.

24 **SEVENTH CAUSE FOR DISCIPLINE**

25 **(Violations of the Motor Vehicle Inspection Program – Respondent Renderos)**

26 66. Respondent Renderos' Smog Check Inspector License is subject to disciplinary action
27 under Health and Safety Code section 44072.2, subdivision (a), in that between April 29, 2024,
28

1 through October 18, 2025, regarding vehicles 1 through 10, set forth above, Respondent Renderos
2 violated the following Health and Safety Code sections:

3 a. **Section 44012, subdivision (a):** Respondent Renderos failed to determine that all
4 emission control devices and systems required by law were installed and functioning correctly on
5 the vehicles identified above in accordance with test procedures prescribed by the Bureau.

6 b. **Section 44012, subdivision (f):** Respondent Renderos failed to perform emission
7 control tests on the vehicles identified above in accordance with procedures prescribed by the
8 Bureau.

9 c. **Section 44032:** Respondent Renderos failed to perform tests of the emission control
10 devices and systems on the vehicles identified above in accordance with section 44012 of the
11 Health and Safety Code, in that the vehicles had been clean plugged.

12 d. **Section 44059:** Respondent Renderos willfully made false entries for the electronic
13 smog check certificates of compliance by certifying that the vehicles identified above had been
14 inspected as required when, in fact, they had not.

15 Complainant refers to, and by this reference incorporates, the allegations set forth above in
16 paragraphs 25 through 59, as though fully set forth.

17 **EIGHTH CAUSE FOR DISCIPLINE**

18 **(Failure to Comply with Regulations Pursuant to the**
19 **Motor Vehicle Inspection Program – Respondent Renderos)**

20 67. Respondent Renderos' Smog Check Inspector License is subject to discipline
21 pursuant to Health and Safety Code section 44072.2, subdivision (c), in that between April 29,
22 2024, through October 18, 2025, regarding vehicles 1 through 10, set forth above, Respondent
23 Renderos failed to comply with provisions of California Code of Regulations, title 16, as follows:

24 a. **Section 3340.24, subdivision (c):** Respondent Renderos falsely or fraudulently issued
25 electronic smog check certificates of compliance without performing bona fide inspections of the
26 emission control devices and systems on those vehicles as required by Health and Safety Code
27 section 44012.

28 ///

1 is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Div 26 of the
2 Health and Safety Code in the name of said licensee may be likewise revoked or suspended by the
3 director.

4 71. Pursuant to Health and Safety Code section 44072.8, if Smog Check Inspector
5 License No. EO 644890, issued to Jose Antonio Renderos, is revoked or suspended, any
6 additional license issued under Chapter 5 of Part 5 of Div 26 of the Health and Safety Code in the
7 name of said licensee may be likewise revoked or suspended by the director.

8 **PRAYER**

9 WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged,
10 and that following the hearing, the Director of the Department of Consumer Affairs issue a
11 decision:

- 12 1. Revoking or suspending Automotive Repair Dealer Registration Number ARD
13 297712, issued to Jose Antonio Renderos-Owner dba Azur Smog Check;
- 14 2. Revoking, suspending, or placing on probation any other automotive repair dealer
15 registration issued in the name of Jose Antonio Renderos;
- 16 3. Revoking or suspending Smog Check, Test-Only, Station License Number TC
17 297712 issued to Jose Antonio Renderos-Owner dba Azur Smog Check;
- 18 4. Revoking or suspending Smog Check Inspector License Number EO 644890, issued
19 to Jose Antonio Renderos;
- 20 5. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
21 Division 26 of the Health and Safety Code in the name of Jose Antonio Renderos;
- 22 6. Ordering Jose Antonio Renderos to pay the Bureau of Automotive Repair the
23 reasonable costs of the investigation and enforcement of this case, pursuant to Business and
24 Professions Code section 125.3, and if placed on probation, the costs of probation monitoring;

25 and,

26 ///

27 ///

28 ///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

7. Taking such other and further action as deemed necessary and proper.

DATED: As of Digital Signature Date

PATRICK DORAIS
Chief
Bureau of Automotive Repair
Department of Consumer Affairs
State of California
Complainant

LA2026600439
Accusation.docx