

1 ROB BONTA
Attorney General of California
2 ERIN M. SUNSERI
Supervising Deputy Attorney General
3 GREGORY J. SALUTE
Supervising Deputy Attorney General
4 State Bar No. 164015
600 West Broadway, Suite 1800
5 San Diego, CA 92101
Telephone: (619) 738-9431
6 Facsimile: (916) 732-7920
E-mail: Gregory.Salute@doj.ca.gov
7 *Attorneys for Complainant*

8 **BEFORE THE**
9 **DEPARTMENT OF CONSUMER AFFAIRS**
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

11 In the Matter of the Accusation Against:

Case No. **79/25-2733**

12 **MOHAMMED ALMAGHAZACHI d.b.a.**
13 **BEST SMOG STATION 2**
14 **1139 Third Ave**
15 **Chula Vista, CA 91911**

OAH No.

ACCUSATION

16 **Automotive Repair Dealer Registration No.**
17 **ARD 305522; Smog Check Station License**
18 **No. TC 305522**

19 **-and-**

20 **JAFAR NASER ALSALEH**
21 **24905 Pine Creek Loop**
22 **Corona, CA 92883**

23 **Smog Check Inspector License No. EO**
24 **639476, Smog Check Repair Technician**
25 **Number EI 639476**

26 Respondents.

27 **PARTIES**

28 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as the Chief of the Bureau of Automotive Repair, Department of Consumer Affairs.

2. On or about April 12, 2023, Bureau of Automotive Repair issued Automotive Repair Dealer Registration Number ARD 305522 to Mohammed Almaghazachi, dba Best Smog Station

1 2 (Respondent Best Smog Station). The Automotive Repair Dealer Registration was in full force
2 and effect at all times relevant to the charges brought herein and will expire on April 30, 2026,
3 unless renewed.

4 3. On or about April 28, 2023, Bureau of Automotive Repair issued Smog Check, Test-
5 Only, Station License Number TC 305522 to Mohammed Almaghazachi, dba Best Smog Station
6 2. The Smog Check, Test-Only, station license was in full force and effect at all times relevant to
7 the charges brought herein and will expire on April 30, 2026, unless renewed.

8 4. Respondent is also certified as a STAR Station. The certification was issued on July
9 24, 2023, and will remain active unless the ARD registration and/or Smog Check Station license
10 is revoked, canceled, licenses become delinquent, or the certification is suspended.

11 5. On or about July 18, 2016, Bureau of Automotive Repair issued Smog Check
12 Inspector License Number EO 639476 to Jafar Naser Alsaleh (Respondent Alsaleh). The Smog
13 Check Inspector License expired on July 31, 2024, and has not been renewed.

14 6. On or about November 7, 2018, Bureau of Automotive Repair issued Smog Check
15 Repair Technician License Number EI 639476 to Jafar Naser Alsaleh. The Smog Check Repair
16 Technician License expired on July 31, 2022, and has not been renewed.

17 **JURISDICTION**

18 7. This Accusation is brought before the Director of the Department of Consumer
19 Affairs (“Director”) for the Bureau, under the authority of the following laws.

20 8. Section 9884.7 of the Business and Professions Code¹ provides that the Director may
21 revoke an ARD registration.

22 9. Section 9884.13 of the Code provides, in pertinent part, that the expiration of a valid
23 registration shall not deprive the director or chief of jurisdiction to proceed with a disciplinary
24 proceeding against an automotive repair dealer or to render a decision invalidating a registration
25 temporarily or permanently.

26
27
28 ¹ All statutory references herein shall be to the Business and Professions Code unless
specifically stated otherwise.

1 14. Section 44072.10 of the Health and Safety Code states, in pertinent part:

2 . . .

3 (c) The department shall revoke the license of any smog check technician or
4 station license who fraudulently certifies vehicles or participates in the fraudulent
5 inspection of vehicles. A fraudulent inspection includes, but is not limited to, all of
6 the following:

7 (1) Clean piping, as defined by the department. . . .

8 (4) Intentional or willful violation of this chapter or any regulation, standard, or
9 procedure of the department implementing this chapter. . . .”

10 **REGULATORY PROVISIONS**

11 15. California Code of Regulations, title 16, section 3340.24, subdivision (c), states:

12 The bureau may suspend or revoke the license of or pursue other legal action
13 against a licensee, if the licensee falsely or fraudulently issues or obtains a certificate
14 of compliance or a certificate of noncompliance.

15 16. California Code of Regulations, title 16, section 3340.30, states:

16 A smog check technician shall comply with the following requirements at all
17 times while licensed.

18 (a) A licensed technician shall inspect, test and repair vehicles in accordance
19 with section 44012 of the Health and Safety Code, section 44035 of the Health and
20 Safety Code, and section 3340.42 of this article. . . .”

21 17. California Code of Regulations, title 16, section 3340.35, states, in pertinent part:

22

23 (c) A licensed station shall issue a certificate of compliance or noncompliance
24 to the owner or operator of any vehicle that has been inspected in accordance with the
25 procedures specified in section 3340.42 of this article and has all the required
26 emission control equipment and devices installed and functioning correctly. . . .

27 18. California Code of Regulations, title 16, section 3340.42, sets forth specific emissions
28 test methods and procedures which apply to all vehicles inspected in the State of California.

COST RECOVERY

19 19. Section 125.3 of the Code provides, in pertinent part, that the Board may request the
20 administrative law judge to direct a licentiate found to have committed a violation or violations of
21 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
22 enforcement of the case, with failure of the licentiate to comply subjecting the license to not being
23

1 renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be
2 included in a stipulated settlement.

3 **VID DATA REVIEW**

4 20. Beginning March 9, 2015, California's Smog Check Program was updated to require
5 the use of an On-Board Diagnostic Inspection System ("OIS"). OIS is the Smog Check
6 equipment required in all areas of the State when inspecting most model-year 2000 and newer
7 gasoline and hybrid vehicles and most 1998 and newer diesel vehicles. The system consists of a
8 certified Data Acquisition Device ("DAD"), computer, bar code scanner, and printer. The DAD
9 is an On Board Diagnostic ("OBD") scan tool that, when requested by the California OIS
10 software, retrieves OBD data from the vehicle. All OBD data that the vehicle indicates it
11 supports is requested by the California OIS software and will be retrieved. The DAD connects
12 between the OIS computer and the vehicle's DLC. The California OIS software requires a
13 continuous Internet connection when performing a Smog Check inspection and the OIS software
14 communicates with BAR's central database through the Internet connection. The bar code
15 scanner is used to input technician information, the vehicles identification number ("VIN"), and
16 DMV renewal information. The printer provides a Vehicle Inspection Report ("VIR") containing
17 inspection results for motorists and a Smog Check Certificate of Compliance number for passing
18 vehicles.

19 21. Data retrieved and recorded during an OIS smog check includes; the eVIN, which is
20 the digitally stored VIN programmed into the vehicle's Powertrain Control Module ("PCM"); the
21 communication protocol, which is the manufacturer/vehicle specific language the PCM uses to
22 relay information; and the number of Parameter Identifications ("PIDs"), which is the number of
23 specific data values each PCM uses related to emissions controls.

24 22. During an OIS inspection, engine operating parameters are retrieved from the
25 vehicle's OBD II system and recorded to the VID. This is accomplished during the functional
26 portion of the OIS Smog Check inspection by plugging the DAD into the vehicle's DLC when
27 prompted by the OIS analyzer screen prompt. Some of the parameters recorded are:

- 28 • Engine speed in revolutions per minute (RPM)

1 • Throttle position as measured by a throttle position sensor (TPS) mounted onto
2 the throttle shaft. Measured in a percentage of opening from 0% at idle and near
3 or up to 100% at full throttle.

4 • Manifold absolute pressure as measured by a manifold air pressure sensor (MAP)
5 connected to an intake manifold source, measured in kilo pascals (kpa). Typical
6 readings for a normally aspirated vehicle as follows: 0 kpa being absolute vacuum,
7 25kpa to 45kpa at idle, 101 kpa at full throttle, same as atmospheric pressure at
8 sea level.

9 • Mass air flow as measured by a mass air flow sensor (MAF) mounted in the
10 engine's air intake tract. Measured in grams per second (gps).²

11 • Ignition timing is set by the vehicle PCM based on engine speed and load, and is
12 measured in degrees Before Top Dead Center (BTDC).

13 23. During normal engine operation at idle, engine speed is relatively steady around its
14 target idle speed. With the engine idling, the TPS is steady and at or near 0%. The MAP and/or
15 MAF readings are also steady. For the engine speed to increase, the throttle would have to be
16 opened to increase airflow through the engine. The engine's management systems supply fuel and
17 spark timing appropriate to any changes in throttle position and engine speed. An increase in
18 throttle, measured by the TPS, which increases engine RPM, would result in corresponding
19 increases in MAF as well as a change in MAP. Stated another way, any movement in the throttle
20 from the idle position will result in an increase of airflow through the engine with corresponding
21 increases RPM and/or MAF along with changes in MAP.

22 24. During an OIS Smog Check inspection, along with other visual and functional
23 inspections, there is an OBD II query portion of the inspection. The OBD II query is performed
24 with the engine idling and, when requested by the OIS analyzer, and an elevated or increased
25 engine speed.

27 ² Not all vehicles include both MAP and MAF parameters. Many vehicles will have either
28 MAP or MAF parameters separately.

1 25. If the vehicle passes the visual, functional and tailpipe tests, it passes the overall
2 inspection, and a Certificate of Compliance is issued and transmitted electronically to the Vehicle
3 Information Database (“VID”). These Certificates of Compliance are purchased in blocks of fifty
4 (50) through the EIS or OIS from the VID, using a pre-arranged electronic bank account debit
5 system or by check, via mail, from Bureau Headquarters in Sacramento. Each Certificate of
6 Compliance has a unique control number so that it can be tracked to determine which Smog
7 Check Station purchased the Certificate of Compliance and to which vehicle it was issued.

8 26. The VID contains registration data from Department of Motor Vehicles (“DMV”)
9 plus emission standards, vehicle smog check inspections, smog check stations and technicians,
10 and Certificates of Compliance. The VID receives the passing smog check results immediately
11 following the inspection. During the vehicle registration process, the DMV accesses the VID to
12 verify that the vehicle has been tested and certified. The Bureau can also access the VID to view
13 test data on smog check inspections performed at any Smog Check Station, or search for, retrieve,
14 and print a test record for a particular vehicle which has been tested. The EIS or OIS, depending
15 on the test type, also prints a Vehicle Inspection Report (“VIR”), which is a physical record of the
16 test results and shows the Certificate of Compliance number that was issued if the vehicle passed
17 the smog inspection.

18 27. The smog check technician must sign the VIR under penalty of perjury to indicate
19 that the inspection was done within Bureau guidelines. Smog Check Stations are required by law
20 to maintain a copy of the VIR along with a copy of the repair invoice for three years. The
21 consumer’s VIR serves as a receipt and proof that the VID was updated, and a Certificate of
22 Compliance was issued. Licensed Smog Check Technicians are the only persons authorized by
23 the Bureau to perform official inspections. They are issued a personal access code and a license,
24 which are used to gain access to the EIS and OIS to perform smog check inspections.
25 Unauthorized use of another technician’s access code or license is prohibited.

26 28. Respondents have engaged in numerous acts or omissions constituting violations of
27 the Automotive Repair Act (Business and Professions Code section 9880 *et seq.*) and Motor
28 Vehicle Inspection Program (Health and Safety Code section 44000 *et seq.*) through their practice

1 of “clean plugging.”³ Respondent’s OIS Test Data available on the State database indicates that
2 Respondents are involved in fraudulent smog inspection activities. A Bureau representative
3 initiated an investigation based on information transmitted to the VID for smog check inspections
4 performed by Respondents. The investigation revealed that the data related to certain vehicles
5 certified by Respondents contained a pattern of unmistakable discrepancies between the
6 information transmitted during the inspections and documented information known about the
7 vehicles at issue. Specifically, the representative compared the data received from the certified
8 vehicles to data from vehicles of the same year, make, and model and determined that the data
9 from at least ten (10) of the certified vehicles were fraudulently tested by Respondents during the
10 smog inspection using the “clean plugging” method as follows:

11 **Clean Plug #1**

12 29. Bureau program representative Hector Barraza (Barraza) reviewed the OIS Test Data
13 for Best Smog Station 2. The review shows that on January 30, 2024, a 2002 Dodge Ram 1500,
14 VIN # 1D7HA18Z92J164410, CA License # 6V13135 was tested and smog certificate #
15 TS014786C was issued under Jafar Naser Alsaleh’s Smog Check Inspector License #EO 639476.

16 30. The Dynamic PID chart for the 2002 Dodge Ram 1500 shows that between time
17 stamp 363 and 17679, the engine RPM is steady at around 580 RPM. During this time, the data
18 shows that the throttle is fluctuating between 8.2% opening and 11.8% opening, and the MAP is
19 fluctuating between 33kPa and 41kPa. After time stamp 17679, the data shows the engine RPM is
20 increased and stays elevated at no less than 1558 RPM. During the elevated engine RPM, the data
21 shows the throttle is fluctuating between 6.7% opening to 11.8% opening, and the MAP is
22 fluctuating between 33kPa and 43kPa.

23 31. The steady idle and elevated engine RPM data along with the improbable throttle
24 positions and fluctuating MAP readings are not characteristic or expected for normal engine
25 operation. The throttle positions and MAP readings are expected to be stable during the steady

26 ³ “Clean plugging” refers to the use of another vehicle’s properly functioning On Board
27 Diagnostic, generation II, (OBD II) system, or another source, to generate passing diagnostic
28 readings for the purpose of issuing fraudulent smog Certificates of Compliance to vehicles that
are not in smog compliance and/or not present for testing.

1 idle, not fluctuating erratically. Subsequently, the throttle is expected to rise during the elevated
2 engine RPM. During the improbable readings, the throttle had data points during the elevated
3 engine RPM which were lower than data points at idle. The throttle data points during the
4 elevated engine RPM never increased past the highest data point at idle. The discrepancies in the
5 OIS test data prove the Data Acquisition Device (DAD) was not connected as required to the
6 2002 Dodge Ram 1500 being certified, causing the issuance of a fraudulent Smog Check
7 Certificate of Compliance.

8 **Clean Plug #2**

9 32. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
10 on February 26, 2024, a 2004 Chevrolet Express G3500, VIN # 1GBJG31U241179391, CA
11 License # 7K58857 was tested and smog certificate # TS541598C was issued under Jafar Naser
12 Alsaleh's Smog Check Inspector License #EO 639476.

13 33. The Dynamic PID chart for the 2004 Chevrolet Express G3500 shows that between
14 time stamp 330 and 19149, the engine RPM is steady at around 555 RPM. During this time, the
15 data shows that the throttle is fluctuating between 2.7% opening and 4.3% opening, the MAF is
16 fluctuating between 5.3gps and 7.01gps, and the MAP is fluctuating between 32kPa and 44kPa.
17 After time stamp 19149, the data shows the engine RPM is increased and stays elevated at no less
18 than 1476 RPM. During the elevated engine RPM, the data shows the throttle is fluctuating
19 between 0% opening to 4.3% opening, the MAF is fluctuating between 6.58gps and 7.46gps, and
20 the MAP is fluctuating between 33kPa and 45kPa.

21 34. The steady idle and elevated engine RPM data along with the improbable throttle
22 positions, MAF readings and fluctuating MAP readings are not characteristic or expected for
23 normal engine operation. The throttle positions, MAF and MAP readings are expected to be
24 stable during the steady idle, not fluctuating erratically. Subsequently, the throttle and MAF are
25 expected to rise during the elevated engine RPM. During the improbable readings, the throttle and
26 MAF had data points during the elevated engine RPM which were lower than data points at idle.
27 The throttle data points during the elevated engine RPM never increased past the highest data
28 point at idle.

1 35. The discrepancies in the OIS test data prove the Data Acquisition Device (DAD) was
2 not connected as required to the 2004 Chevrolet Express G3500 being certified, causing the
3 issuance of a fraudulent Smog Check Certificate of Compliance.

4 **Clean Plug #3**

5 36. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
6 on March 13, 2024, a 2002 Toyota Sienna CE, VIN # 4T3ZF19C62U451294, CA License #
7 5GAU348 was tested and smog certificate # IZ425988C was issued under Jafar Naser Alsaleh's
8 Smog Check Inspector License #EO 639476.

9 37. The Dynamic PID chart for the 2002 Toyota Sienna CE shows that between time
10 stamp 870 and 23112, the engine RPM is steady at around 640 RPM. During this time, the data
11 shows that the throttle is fixed at 9.4% opening while the MAF drops from 4.21gps to 3.07gps.
12 After time stamp 23112, the data shows the engine RPM is increased and stays elevated at no less
13 than 1480 RPM. During the elevated engine RPM, the data shows the throttle drops to a fixed
14 8.6% opening, and the MAF is between 2.96gps and 3.18gps.

15 38. The steady idle and elevated engine RPM data along with the improbable throttle
16 positions and MAF readings are not characteristic or expected for normal engine operation. The
17 throttle positions and MAF readings are expected to be stable during the steady idle and
18 subsequently raised during the elevated engine RPM. During the improbable readings, the throttle
19 and MAF had lower data points during the elevated engine RPM than data points at idle. The
20 throttle and MAF data points during the elevated engine RPM never increased past the highest
21 data point at idle. The discrepancies in the OIS test data prove the Data Acquisition Device
22 (DAD) was not connected as required to the 2002 Toyota Sienna CE being certified causing the
23 issuance of a fraudulent Smog Check Certificate of Compliance.

24 **Clean Plug #4**

25 39. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
26 on March 23, 2024, a 2003 Toyota Corolla CE, VIN # 1NXBR32E23Z163864, CA License #
27 6DYK522 was tested and smog certificate # TU489709C was issued under Jafar Naser Alsaleh's
28 Smog Check Inspector License #EO 639476.

1 40. The Dynamic PID charts and data for the 2003 Toyota Corolla CE shows that
2 between time stamp 850 and 20721, the engine RPM is steady at around 710 RPM. During this
3 time, the data shows that the throttle is fixed at 11.4% opening while the MAF rises from 0.27gps
4 to 2.01gps. After time stamp 20721, the data shows the engine RPM is increased and stays
5 elevated at no less than 1544 RPM. During the elevated engine RPM, the data shows the throttle
6 drops from 11.8% to 9.4% opening and the MAF is between 1.82gps to 2.16gps.

7 41. The steady idle and elevated engine RPM data along with the improbable throttle
8 positions and MAF readings are not characteristic or expected for normal engine operation. The
9 throttle positions and MAF readings are expected to be stable during the steady idle and
10 subsequently raised during the elevated engine RPM. During the improbable readings, the throttle
11 and MAF had a lower data point during the elevated engine RPM than the highest data point at
12 idle. Additionally, during the elevated engine RPM, the data shows an improbable inverse
13 correlation between the throttle and MAF. The discrepancies in the OIS test data prove the Data
14 Acquisition Device (DAD) was not connected as required to the 2003 Toyota Corolla CE being
15 certified, causing the issuance of a fraudulent Smog Check Certificate of Compliance.

16 **Prior Inspection**

17 42. On February 23, 2022, a previous Smog Check inspection was performed on the 2003
18 Toyota Corolla CE at a different, unrelated Smog Check station. The Dynamic PID chart for the
19 2003 Toyota Corolla shows that between time stamp 839 and 24345, the engine RPM is steady at
20 around 720 RPM. During this time, the data shows that the throttle is at 11% opening and the
21 MAF is stable between 1.78gps and 1.79gps. After time stamp 24345, the data shows the engine
22 RPM is increased and held steady at around 2250 RPM.

23 43. During the elevated engine RPM, the data shows that the throttle is at a fixed 13.7%,
24 and the MAF is stable between 5.45gps and 5.5gps. The steady idle and steady elevated engine
25 RPM data along with the associated throttle positions and subsequent MAF readings are
26 characteristic and expected for normal engine operation.

27 ///

28 ///

1 **Clean Plug #5**

2 44. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
3 on April 4, 2024, a 2000 Toyota Tundra Access Cab, VIN # 5TBRT3415YS064426, CA License
4 # 6F57400 was tested and smog certificate # TU934454C was issued under Jafar Naser Alsaleh’s
5 Smog Check Inspector License #EO 639476.

6 45. The Dynamic PID chart for the 2000 Toyota Tundra Access Cab shows that between
7 time stamp 813 and 21482, the engine RPM is steady at around 660 RPM. During this time, the
8 data shows that the throttle increases from 14.5% and 18% opening, while the MAF drops from
9 7.19gps to 6.63gps. After time stamp 21482, the data shows the engine RPM is increased and
10 stays elevated at no less than 1816 RPM. During the elevated engine RPM, the data shows that
11 the throttle is between 12.9% and 18% opening, and the MAF is between 6.46gps and 6.79gps.

12 46. The steady idle and elevated engine RPM data along with the improbable throttle
13 positions and MAF readings are not characteristic or expected for normal engine operation. The
14 throttle positions and MAF readings are expected to be stable during the steady idle and
15 subsequently raised during the elevated engine RPM. During the improbable readings, the throttle
16 and MAF had lower data points during the elevated engine RPM than data points at idle. The
17 throttle and MAF data points during the elevated engine RPM never increased past the highest
18 data point at idle. The discrepancies in the OIS test data prove the Data Acquisition Device
19 (DAD) was not connected as required to the 2000 Toyota Tundra Access Cab being certified,
20 causing the issuance of a fraudulent Smog Check Certificate of Compliance.

21 **Clean Plug #6**

22 47. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
23 on April 27, 2024, a 2001 Toyota Sienna LE, VIN # 4T3ZF13C71U405769, CA License #
24 8DUB055 was tested and smog certificate # TW616552C was issued under Jafar Naser Alsaleh’s
25 Smog Check Inspector License #EO 639476.

26 48. The Dynamic PID chart for the 2001 Toyota Sienna LE shows that between time
27 stamp 845 and 21416, the engine RPM is steady at around 660 RPM. During this time, the data
28 shows that the throttle drops from 11.4% to 9% opening and the MAF is between 3.71gps and

1 3.92gps. After time stamp 21416, the data shows the engine RPM is increased and stays elevated
2 at no less than 1454 RPM. During the elevated engine RPM, the data shows the throttle is varying
3 between 7.5% and 9% opening and the MAF is varying between 4.11gps and 5.04gps.

4 49. The steady idle and elevated engine RPM data along with the improbable throttle
5 positions and MAF readings are not characteristic or expected for normal engine operation. The
6 throttle positions and MAF readings are expected to be stable during the steady idle and
7 subsequently raised during the elevated engine RPM. During the improbable readings, the throttle
8 had data points during the elevated engine RPM which were lower than data points at idle. The
9 throttle data points during the elevated engine RPM never increased past the highest data point at
10 idle.

11 50. The discrepancies in the OIS test data prove the Data Acquisition Device (DAD) was
12 not connected as required to the 2001 Toyota Sienna LE being certified, causing the issuance of a
13 fraudulent Smog Check Certificate of Compliance.

14 **Clean Plug #7**

15 51. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
16 on April 27, 2024, a 2000 Toyota Tundra Access Cab Limited, VIN # 5TBRT3818YS060722
17 License # 6G54193 was tested and smog certificate # TW616553C was issued under Jafar Naser
18 Alsaleh's Smog Check Inspector License #EO 639476.

19 52. The Dynamic PID chart for the 2000 Toyota Tundra Access Cab Limited shows that
20 between time stamp 841 and 19611, the engine RPM is steady at around 670 RPM. During this
21 time, the data shows that the throttle drops from 16.9% to 16.1% opening, and the MAF is drops
22 from 5.72gps to 5.29gps. After time stamp 19611, the data shows the engine RPM is increased
23 and stays elevated at no less than 1357 RPM. During the elevated engine RPM, the data shows
24 that the throttle drops from 16.1% to 14.5% opening, and the MAF is between 7.58gps and
25 7.59gps.

26 53. The steady idle and elevated engine RPM data along with the improbable throttle
27 positions and MAF readings are not characteristic or expected for normal engine operation. The
28 throttle positions and MAF readings are expected to be stable during the steady idle and

1 subsequently raised during the elevated engine RPM. During the improbable readings, the throttle
2 had lower data points during the elevated engine RPM than data points at idle. The throttle data
3 points during the elevated engine RPM never increased past the highest data point at idle. The
4 discrepancies in the OIS test data prove the Data Acquisition Device (DAD) was not connected as
5 required to the 2000 Toyota Tundra Access Cab Limited being certified, causing the issuance of a
6 fraudulent Smog Check Certificate of Compliance.

7 **Clean Plug #8**

8 54. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
9 on May 1, 2024, a 2006 Chevrolet Silverado C2500 Heavy Duty, VIN # 1GCHC24U16E210895,
10 CA License # 8C30551 was tested and smog certificate # TW616585C was issued under Jafar
11 Naser Alsaleh's Smog Check Inspector License #EO 639476.

12 55. The Dynamic PID Chart for the 2006 Chevrolet Silverado C2500 Heavy Duty shows
13 that between time stamp 342 and 17259, the engine RPM is steady at around 545 RPM. During
14 this time, the data shows that the throttle is fluctuating between 8.6% and 11% opening, the MAF
15 is fluctuating between 5.36gps and 6.88gps, and the MAP is fluctuating between 35kPa and
16 46kPa. After time stamp 17259, the data shows the engine RPM is increased and stays elevated at
17 no less than 1406 RPM. During this time, the data shows that the throttle is fluctuating between
18 7.1% and 11% opening, the MAF is fluctuating between 5.34gps and 6.1gps, and the MAP is
19 fluctuating between 36kPa and 46kPa.

20 56. The steady idle and elevated engine RPM data along with the improbable throttle
21 positions, MAF readings and fluctuating MAP readings are not characteristic or expected for
22 normal engine operation. The throttle positions, MAF and MAP readings are expected to be
23 stable during the steady idle, not fluctuating erratically. Subsequently, the throttle position and
24 MAF readings are expected to rise during the elevated engine RPM. During the improbable
25 readings, the throttle and MAF had lower data points during the elevated engine RPM than data
26 points at idle. The MAF data points during the elevated engine RPM never increased past the
27 highest data point at idle. The discrepancies in the OIS test data prove the Data Acquisition
28

1 Device (DAD) was not connected as required to the 2006 Chevrolet Silverado C2500 Heavy Duty
2 being certified, causing the issuance of a fraudulent Smog Check Certificate of Compliance.

3 **Clean Plug #9**

4 57. Barraza reviewed the OIS Test Data for Best Smog Station 2. The review shows that
5 on May 2, 2024, a 2003 GMC Safari XT, VIN # 1GKDM19X83B513215, License # 5CTY750
6 was tested and smog certificate # TW586520C was issued under Jafar Naser Alsaleh's Smog
7 Check Inspector License #EO 639476.

8 58. The Dynamic PID chart for the 2003 GMC Safari XT shows that between time stamp
9 423 and 17660, the engine RPM is steady at around 650 RPM. During this time, the data shows
10 that the throttle is fluctuating between 0.4% and 5.5% opening, the MAF is fluctuating between
11 7.17gps and 7.55gps, and the MAP is varying between 32kPa and 44kPa. After time stamp
12 17660, the data shows the engine RPM is increased and stays elevated at no less than 1263 RPM.
13 During the elevated engine RPM, the data shows the throttle is fluctuating between 0% and 4.7%
14 opening, the MAF is varying between 6.43gps and 6.73gps, and the MAP is fluctuating between
15 34kPa and 46kPa.

16 59. The steady idle and elevated engine RPM data along with the improbable throttle
17 positions, MAF readings and fluctuating MAP readings are not characteristic or expected for
18 normal engine operation. The throttle positions, MAF and MAP readings are expected to be
19 stable during the steady idle, not fluctuating. Subsequently, the throttle and MAF are expected to
20 rise during the elevated engine RPM. During the improbable readings, the throttle and MAF had
21 data points during the elevated engine RPM which were lower than data points at idle. The
22 throttle and MAF data points during the elevated engine RPM never increased past the highest
23 data point at idle.

24 60. The discrepancies in the OIS test data prove the Data Acquisition Device (DAD) was
25 not connected as required to the 2003 GMC Safari XT being certified, causing the issuance of a
26 fraudulent Smog Check Certificate of Compliance.

27 ///

28 ///

1 conducted the inspections on those vehicles using the clean plugging method in order to issue
2 smog certificates of compliance, and did not test or inspect the vehicles as required by Health and
3 Safety Code section 44012.

4 **SECOND CAUSE FOR DISCIPLINE**

5 **(Fraud - Respondent Best Smog Station)**

6 65. Respondent Best Smog Station's registration is subject to disciplinary action pursuant
7 to section 9884.7, subdivision (a)(4), in that Respondent Best Smog Station 's employees
8 committed acts which constitute fraud by issuing electronic certificates of compliance for the
9 vehicles set forth above in paragraphs 29-63, without performing bona fide inspections of the
10 emission control devices and systems on those vehicles, thereby depriving the People of the State
11 of California of the protection afforded by the Motor Vehicle Inspection Program.

12 **THIRD CAUSE FOR DISCIPLINE**

13 **(Failure to Comply with the Motor Vehicle Inspection Program –**
14 **Respondent Best Smog Station)**

15 66. Respondent Best Smog Station 's smog station license is subject to disciplinary action
16 pursuant to Health and Safety Code section 44072.2, subdivision (a), in conjunction with Health
17 and Safety Code section 44072.10 subdivision (c), in that regarding the vehicles set forth above in
18 paragraphs 29-63, Respondents failed to comply with the following sections of the Health and
19 Safety Code:

20 (a) **Section 44012**: Respondent Best Smog Station's employees failed to ensure that the
21 emission control tests were performed on the vehicles, in accordance with procedures prescribed
22 by the department.

23 (b) **Section 44015**: Respondent Best Smog Station's employees issued electronic
24 certificates of compliance for the vehicles, without ensuring that the vehicles were properly tested
25 and inspected to determine if they were in compliance with Health and Safety Code section
26 44012.

27 ///

28 ///

1 **FOURTH CAUSE FOR DISCIPLINE**

2 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program -**
3 **Respondent Best Smog Station)**

4 67. Respondent Best Smog Station’s smog station license is subject to disciplinary action
5 pursuant to Health and Safety Code section 44072.2, subdivision (c), in that regarding the
6 vehicles set forth above in paragraphs 29-63, Respondents failed to comply with the following
7 provisions of the California Code of Regulations, Title 16, as follows:

8 (a) **Section 3340.35, subdivision (c)**: Respondent Best Smog Station ’s employees
9 issued electronic certificates of compliance even though those vehicles had not been inspected in
10 accordance with section 3340.42, Title 16, of the California Code of Regulations.

11 (b) **Section 3340.42**: Respondent Best Smog Station ’s employees failed to conduct the
12 required smog tests and inspections on those vehicles in accordance with the Bureau’s
13 specifications.

14 **FIFTH CAUSE FOR DISCIPLINE**

15 **(Dishonesty, Fraud or Deceit - Respondent Best Smog Station)**

16 68. Respondent Best Smog Station’s smog station license is subject to disciplinary action
17 pursuant to Health and Safety Code section 44072.2, subdivision (d), in conjunction with Health
18 and Safety Code section 44072.10 subdivision (c), in that regarding the vehicles set forth above in
19 paragraphs 29-63, Respondents employees committed acts involving dishonesty, fraud or deceit
20 whereby another was injured by issuing electronic certificates of compliance for those vehicles
21 without performing bona fide inspections of the emission control devices and systems on the
22 vehicles, thereby depriving the People of the State of California of the protection afforded by the
23 Motor Vehicle Inspection Program.

24 **SIXTH CAUSE FOR DISCIPLINE**

25 **(Violations of the Motor Vehicle Inspection Program – Respondent Alsaleh)**

26 69. Respondent Alsaleh’s smog check inspector license and smog check repair technician
27 license are subject to discipline pursuant to Health and Safety Code section 44072.2, subdivision
28 (a), in that regarding the vehicles set forth above in paragraphs 29-63, Respondent Alsaleh failed

1 to comply with section 44012 of the Health and Safety Code in a material respect, as follows:
2 Respondent Alsaleh failed to perform the emission control tests on those vehicles in accordance
3 with procedures prescribed by the department.

4 **SEVENTH CAUSE FOR DISCIPLINE**

5 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program –**
6 **Respondent Alsaleh)**

7 70. Respondent Alsaleh’s smog check inspector license and smog check repair technician
8 license are subject to discipline pursuant to Health and Safety Code section 44072.2, subdivision
9 (c), in that regarding the vehicles set forth above in paragraphs 29-63, Respondent Alsaleh failed
10 to comply with provisions of the California Code of Regulations, title 16, as follows:

11 (a) **Section 3340.30, subdivision (a)**: Respondent Alsaleh failed to inspect and test those
12 vehicles in accordance with Health and Safety Code section 44012.

13 (b) **Section 3340.41, subdivision (c)**: Respondent Alsaleh entered false information into
14 the EIS.

15 (c) **Section 3340.42**: Respondent Alsaleh failed to conduct the required smog tests and
16 inspections on those vehicles in accordance with the Bureau’s specifications.

17 **EIGHTH CAUSE FOR DISCIPLINE**

18 **(Dishonesty, Fraud or Deceit - Respondent Alsaleh)**

19 71. Respondent Alsaleh’s smog check inspector license and smog check repair technician
20 license are subject to discipline pursuant to Health and Safety Code section 44072.2, subdivision
21 (d), in conjunction with Health and Safety Code section 44072.10 subdivision (c), in that
22 regarding the vehicles set forth above in paragraphs 29-63, Respondent Alsaleh committed acts
23 involving dishonesty, fraud or deceit whereby another was injured by issuing electronic
24 certificates of compliance for those vehicles without performing bona fide inspections of the
25 emission control devices and systems on the vehicles., thereby depriving the People of the State
26 of California of the protection afforded by the Motor Vehicle Inspection Program.

27 ///

28 ///

OTHER MATTERS

72. Pursuant to Business & Professions Code section 9884.7, subdivision (c), the Director may suspend, revoke, or place on probation the registration for all places of business operated in this State by Respondent Best Smog Station upon a finding that Respondent Best Smog Station has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.

73. Pursuant to Health & Safety Code section 44072.8, if Smog Check, Test Only Station License Number TC 305522 issued to Respondent Best Smog Station is revoked or suspended following a hearing under this article, any additional license issued under Chapter 5, Part 5, Division 26 in the name of said licensee may be likewise revoked or suspended by the Director.

74. Pursuant to Health & Safety Code section 44072.8, if Smog Check Inspector License Number EO 639476, and/or Smog Check Repair Technician License Number EI 639476 issued to Respondent Alsaleh, is revoked or suspended following a hearing under this article, any additional license issued under Chapter 5, Part 5, Division 26 in the name of said licensee may be likewise revoked or suspended by the Director.

PRAYER

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of the Department of Consumer Affairs issue a decision:

1. Revoking or suspending Automotive Repair Dealer Registration Number ARD 305522, issued to Mohammed Almaghazachi, dba Best Smog Station 2;
2. Revoking or suspending any other Automotive Repair Dealer Registration issued to Respondent Mohammed Almaghazachi;
3. Revoking or suspending Smog Check, Test-Only, Station License Number TC 305522, issued to Mohammed Almaghazachi, dba Best Smog Station 2;
4. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health and Safety Code in the name of Respondent Mohammed Almaghazachi;

1 5. Revoking or suspending Smog Check Inspector License Number EO 639476, issued
2 to Jafar Naser Alsaleh;

3 6. Revoking or suspending Smog Check Repair Technician License Number EI 639476,
4 issued to Jafar Naser Alsaleh;

5 7. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
6 Division 26 of the Health and Safety Code in the name of Respondent Jafar Naser Alsaleh;

7 8. Ordering Mohammed Almaghazachi and Jafar Naser Alsaleh to pay the Bureau of
8 Automotive Repair the reasonable costs of the investigation and enforcement of this case,
9 pursuant to Business and Professions Code section 125.3 and if placed on probation, the costs of
10 probation monitoring; and,

11 9. Taking such other and further action as deemed necessary and proper.

13 DATED: As of Digital Signature Date

PATRICK DORAIS
Chief
Bureau of Automotive Repair
Department of Consumer Affairs
State of California
Complainant

17
18 SD2025801811
19 85155955.docx

20
21
22
23
24
25
26
27
28