

1 ROB BONTA
Attorney General of California
2 THOMAS L. RINALDI
Supervising Deputy Attorney General
3 VIVIAN CHO
Deputy Attorney General
4 State Bar No. 293773
300 So. Spring Street, Suite 1702
5 Los Angeles, CA 90013
Telephone: (213) 269-6603
6 Facsimile: (916) 731-2126
E-mail: Vivian.Cho@doj.ca.gov
7 *Attorneys for Complainant*

8 **BEFORE THE**
9 **DEPARTMENT OF CONSUMER AFFAIRS**
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 79/25-16693

13 **DAVID GERARDO RAMIREZ, DBA LOS**
14 **SMOGGERS SMOG CHECK**

ACCUSATION

10076 Cedar Ave Unit B
14 Bloomington, CA 92316

15 Automotive Repair Dealer Registration No.
ARD 305845
16 Smog Check, Test-Only, Station No.
TC 305845

17 **ZEFERINO PERALTA JR**

18 615 E Belmont St Apt A
19 Ontario, CA 91761

20 Smog Check Inspector No. EO 643740

21 Respondents.

22
23
24 **PARTIES**

25 1. Patrick Dorais (“Complainant”) brings this Accusation solely in his official capacity
26 as the Chief of the Bureau of Automotive Repair, Department of Consumer Affairs.

27 2. On or about May 16, 2023, the Bureau of Automotive Repair (“Bureau”) issued
28 Automotive Repair Dealer Registration Number ARD 305845 to David Gerardo Ramirez

1 (“Respondent Ramirez”) doing business as Los Smoggers Smog Check. The Automotive Repair
2 Dealer Registration was in full force and effect at all times relevant to the charges brought herein
3 and will expire on May 31, 2026, unless renewed.

4 3. On or about June 29, 2023, the Bureau issued Smog Check, Test-Only, Station
5 License Number TC 305845 to Respondent Ramirez doing business as Los Smoggers Smog
6 Check. The Smog Check, Test-Only, Station License was in full force and effect at all times
7 relevant to the charges brought herein and will expire on May 31, 2026, unless renewed.

8 4. On or about June 24, 2022, the Bureau issued Smog Check Inspector License Number
9 EO 643740 to Zeferino Peralta Jr. (“Respondent Peralta”). The Smog Check Inspector License
10 was in full force and effect at all times relevant to the charges brought herein and will expire on
11 February 28, 2026, unless renewed.

12 **JURISDICTION**

13 5. This Accusation is brought before the Director of the Department of Consumer
14 Affairs (“Director”) for the Bureau under the authority of the following laws.

15 6. Business and Professions Code section 118, subdivision (b), provides that the
16 suspension, expiration, surrender, or cancellation of a license shall not deprive the Director of
17 jurisdiction to proceed with a disciplinary action during the period within which the license may
18 be renewed, restored, reissued or reinstated.

19 7. Business and Professions Code section 477 provides, in pertinent part, that “Board”
20 includes “bureau,” “commission,” “committee,” “department,” “division,” “examining
21 committee,” “program,” and “agency.” “License” includes certificate, registration or other means
22 to engage in a business or profession regulated by the Business and Professions Code.

23 8. Business and Professions Code section 9884.13 provides, in pertinent part, that the
24 expiration of a valid registration shall not deprive the Director of jurisdiction to proceed with a
25 disciplinary proceeding against an automotive repair dealer or to render a decision temporarily or
26 permanently invalidating (suspending or revoking) a registration.

27 ///

28 ///

...

(e) For purposes of this section, “fraud” includes, but is not limited to, violations of this chapter involving misrepresentations and all of the following:

(1) Any act or omission that is included within the definition of either “actual fraud” or “constructive fraud,” as those terms are defined in Sections 1572 and 1573 of the Civil Code.

(2) A misrepresentation in any manner, whether intentionally false or due to gross negligence, of a material fact.

(3) A promise or representation not made honestly and in good faith.

(4) An intentional failure to disclose a material fact.

(5) Any act in violation of Section 484 of the Penal Code.

12. Health and Safety Code section 44012 provides:

The test at the smog check stations shall be performed in accordance with procedures prescribed by the department and may require loaded mode dynamometer testing in enhanced areas, two-speed idle testing, testing utilizing a vehicle's onboard diagnostic system, or other appropriate test procedures as determined by the department in consultation with the state board. The department shall implement testing using onboard diagnostic systems, in lieu of loaded mode dynamometer or two-speed idle testing, on model year 2000 and newer vehicles only, beginning no earlier than January 1, 2013. However, the department, in consultation with the state board, may prescribe alternative test procedures that include loaded mode dynamometer or two-speed idle testing for vehicles with onboard diagnostic systems

that the department and the state board determine exhibit operational problems. The department shall ensure, as appropriate to the test method, the following:

(a) Emission control systems required by state and federal law are reducing excess emissions in accordance with the standards adopted pursuant to subdivisions (a) and (c) of Section 44013.

(b) Motor vehicles are preconditioned to ensure representative and stabilized operation of the vehicle's emission control system.

(c) For other than diesel-powered vehicles, the vehicle's exhaust emissions of hydrocarbons, carbon monoxide, carbon dioxide, and oxides of nitrogen in an idle mode or loaded mode are tested in accordance with procedures prescribed by the department. In determining how loaded mode and evaporative emissions testing shall be conducted, the department shall ensure that the emission reduction targets for the enhanced program are met.

(d) For other than diesel-powered vehicles, the vehicle's fuel evaporative system and crankcase ventilation system are tested to reduce any nonexhaust sources of volatile organic compound emissions, in accordance with procedures prescribed by the department.

1 (e) For diesel-powered vehicles, a visual inspection is made of emission
2 control devices and the vehicle's exhaust emissions are tested in accordance with
3 procedures prescribed by the department, that may include, but are not limited
4 to, onboard diagnostic testing. The test may include testing of emissions of any or all
5 of the pollutants specified in subdivision (c) and, upon the adoption of applicable
6 standards, measurement of emissions of smoke or particulates, or both.

7 (f) A visual or functional check is made of emission control devices specified
8 by the department, including the catalytic converter in those instances in which the
9 department determines it to be necessary to meet the findings of Section 44001. The
10 visual or functional check shall be performed in accordance with procedures
11 prescribed by the department.

12 (g) A determination as to whether the motor vehicle complies with the
13 emission standards for that vehicle's class and model-year as prescribed by the
14 department.

15 (h) An analysis of pass and fail rates of vehicles subject to an onboard
16 diagnostic test and a tailpipe test to assess whether any vehicles passing their
17 onboard diagnostic test have, or would have, failed a tailpipe test, and whether any
18 vehicles failing their onboard diagnostic test have or would have passed a tailpipe
19 test.

20 (i) The test procedures may authorize smog check stations to refuse the
21 testing of a vehicle that would be unsafe to test, or that cannot physically be
22 inspected, as specified by the department by regulation. The refusal to test a vehicle
23 for those reasons shall not excuse or exempt the vehicle from compliance with all
24 applicable requirements of this chapter.

25 13. Health and Safety Code section 44014, subdivision (a), provides:

26 Except as otherwise provided in this chapter, the testing and repair portion of
27 the program shall be conducted by smog check stations licensed by the department,
28 and by smog check technicians who have qualified pursuant to this chapter.

14. Health and Safety Code section 44015, subdivision (b), provides:

If a vehicle meets the requirements of Section 44012, a smog check station
licensed to issue certificates shall issue a certificate of compliance or a certificate of
noncompliance.

15. Health and Safety Code section 44032 provides:

No person shall perform, for compensation, tests or repairs of emission control
devices or systems of motor vehicles required by this chapter unless the person
performing the test or repair is a qualified smog check technician and the test or
repair is performed at a licensed smog check station. Qualified technicians shall
perform tests of emission control devices and systems in accordance with Section
44012.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

16. Health and Safety Code section 44059 provides:

The willful making of any false statement or entry with regard to a material matter in any oath, affidavit, certificate of compliance or noncompliance, or application form which is required by this chapter or Chapter 20.3 (commencing with Section 9880) of Division 3 of the Business and Professions Code, constitutes perjury and is punishable as provided in the Penal Code.

17. Health and Safety Code section 44072.2 states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

(a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health and Saf. Code, “ 44000, et seq.)] and the regulations adopted pursuant to it, which related to the licensed activities.

...

(c) Violates any of the regulations adopted by the director pursuant to this chapter.

(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

...

(h) Violates or attempts to violate the provisions of this chapter relating to the particular activity for which he or she is licensed.

18. Health & Safety Code section 44072.10 states, in pertinent part:

...

(c) The department shall revoke the license of any smog check technician or station licensee who fraudulently certifies vehicles or participates in the fraudulent inspection of vehicles. A fraudulent inspection includes, but is not limited to, all of the following:

(1) Clean piping, clean plugging, clean glassing, clean tanking, or any other fraudulent inspection practice, as defined by the department.

(2) Tampering with a vehicle emission control system or test analyzer system.

(3) Tampering with a vehicle in a manner that would cause the vehicle to falsely pass or falsely fail an inspection.

(4) Intentional or willful violation of this chapter or any regulation, standard, or procedure of the department implementing this chapter.

1 19. Health and Safety Code section 44072.8 states that “[w]hen a license has been
2 revoked or suspended following a hearing under this article, any additional license issued under
3 this chapter in the name of the licensee may be likewise revoked or suspended by the director.”

4 **REGULATORY PROVISIONS**

5 20. California Code of Regulations, title 16, section 3340.24, subdivision (c), states that
6 the Bureau “may suspend or revoke the license of or pursue other legal action against a licensee,
7 if the licensee falsely or fraudulently issues or obtains a certificate of compliance or a certificate
8 of noncompliance.”

9 21. California Code of Regulations, title 16, section 3340.30, states, in pertinent part:

10 A smog check technician shall comply with the following requirements at all
11 times while licensed.

12 (a) A licensed technician shall inspect, test and repair vehicles in accordance
13 with section 44012 of the Health and Safety Code, section 44035 of the Health and
14 Safety Code, and section 3340.42 of this article.

15 ...

16 22. California Code of Regulations, title 16, section 3340.35, subdivision (c), states that a
17 licensed smog check station “shall issue a certificate of compliance or noncompliance to the
18 owner or operator of any vehicle that has been inspected in accordance with the procedures
19 specified in section 3340.42 of this article and has all the required emission control equipment
20 and devices installed and functioning correctly.”

21 23. California Code of Regulations, title 16, section 3340.41, states, in pertinent part:

22 ...

23 (b) No person shall enter any access or qualification number other than as
24 authorized by the Bureau into the EIS or OIS, nor in any way tamper with the EIS or
25 OIS.

26 (c) No person shall enter any vehicle identification information or emission
27 control system identification data for any vehicle other than the one being tested into
28 the EIS or OIS. Nor shall any person enter into the EIS or OIS any false information
about the vehicle being tested.

///

///

1 24. California Code of Regulations, title 16, section 3340.42, states:

2 Smog check inspection methods are prescribed in the Smog Check Manual,
3 referenced by section 3340.45.

4 (a) All vehicles subject to a smog check inspection, shall receive one of the
5 following test methods:

6 (1) A loaded-mode test shall be the test method used to inspect 1976-1999
7 model-year vehicle, except diesel-powered, registered in the enhanced program areas
8 of the state. The loaded-mode test shall measure hydrocarbon, carbon monoxide,
9 carbon dioxide and oxides of nitrogen emissions, as contained in the bureau's
10 specifications referenced in subsection (a) of Section 3340.17 of this article. The
11 loaded-mode test shall use Acceleration Simulation Mode (ASM) test equipment,
12 including a chassis dynamometer, certified by the bureau.

13 On and after March 31, 2010, exhaust emissions from a vehicle subject to
14 this inspection shall be measured and compared to the emissions standards shown in
15 the Vehicle Look-up Table (VLT) Row Specific Emissions Standards (Cutpoints)
16 Table, dated March 2010, which is hereby incorporated by reference. If the emissions
17 standards for a specific vehicle are not included in this table then the exhaust
18 emissions shall be compared to the emissions standards set forth in TABLE I or
19 TABLE II, as applicable. A vehicle passes the loaded-mode test if all of its measured
20 emissions are less than or equal to the applicable emission standards specified in the
21 applicable table.

22 (2) A two-speed idle mode test shall be the test method used to inspect
23 1976-1999 model-year vehicles, except diesel-powered, registered in all program
24 areas of the state, except in those areas of the state where the enhanced program has
25 been implemented. The two-speed idle mode test shall measure hydrocarbon, carbon
26 monoxide and carbon dioxide emissions at high RPM and again at idle RPM, as
27 contained in the bureau's specifications referenced in subsection (a) of Section
28 3340.17 of this article. Exhaust emissions from a vehicle subject to this inspection
shall be measured and compared to the emission standards set forth in this section and
as shown in TABLE III. A vehicle passes the two-speed idle mode test if all of its
measured emissions are less than or equal to the applicable emissions standards
specified in Table III.

(3) An OBD-focused test, shall be the test method used to inspect gasoline-
powered vehicles 2000 model-year and newer, and diesel-powered vehicles 1998
model-year and newer. The OBD test failure criteria are specified in section
3340.42.2.

(b) In addition to subsection (a), all vehicles subject to the smog check
program shall receive the following:

(1) A visual inspection of emission control components and systems to
verify the vehicle's emission control systems are properly installed.

1 (2) A functional inspection of emission control systems as specified in the
2 Smog Check Manual, referenced by section 3340.45, which may include an OBD
test, to verify their proper operation.

3 (c) The bureau may require any combination of the inspection methods in
4 sections (a) and (b) under any of the following circumstances:

5 (1) Vehicles that the department randomly selects pursuant to Health and
6 Safety Code section 44014.7 as a means of identifying potential operational
problems with vehicle OBD systems.

7 (2) Vehicles identified by the bureau as being operationally or physically
8 incompatible with inspection equipment.

9 (3) Vehicles with OBD systems that have demonstrated operational
problems.

10 (d) Pursuant to section 39032.5 of the Health and Safety Code, gross polluter
11 standards are as follows:

12 (1) A gross polluter means a vehicle with excess hydrocarbon, carbon
13 monoxide, or oxides of nitrogen emissions pursuant to the gross polluter emissions
standards included in the tables described in subsection (a), as applicable.

14 (2) Vehicles with emission levels exceeding the emission standards for
15 gross polluters during an initial inspection will be considered gross polluters and the
provisions pertaining to gross polluting vehicles will apply, including, but not
16 limited to, sections 44014.5, 44015, and 44081 of the Health and Safety Code.

17 (3) A gross polluting vehicle shall not be passed or issued a certificate of
18 compliance until the vehicle's emissions are reduced to or below the applicable
emissions standards for the vehicle included in the tables described in subsection (a),
19 as applicable. However, the provisions described in section 44017 of the Health and
Safety Code may apply.

20 (4) This subsection applies in all program areas statewide to vehicles
21 requiring inspection pursuant to sections 44005 and 44011 of the Health and Safety
Code.

22 25. California Code of Regulations, title 16, section 3340.45, states:

23 All Smog Check inspections shall be performed in accordance with
24 requirements and procedures prescribed in the Smog Check Manual, dated January
2021, which is hereby incorporated by reference.

25 26. California Code of Regulations, title 16, section 3373 states:

26 No automotive repair dealer or individual in charge shall, in filling out an
27 estimate, invoice, or work order, or record required to be maintained by section
3340.15(e) of this chapter, withhold therefrom or insert therein any statement or
28 information which will cause any such document to be false or misleading, or where

1 the tendency or effect thereby would be to mislead or deceive customers, prospective
2 customers, or the public.

3 **COST RECOVERY**

4 27. Business and Professions Code section 125.3 provides, in pertinent part, that a Board
5 may request the administrative law judge to direct a licentiate found to have committed a
6 violation or violations of the licensing act to pay a sum not to exceed the reasonable costs of the
7 investigation and enforcement of the case.

8 **CALIFORNIA'S SMOG CHECK PROGRAM**

9 28. California's Smog Check Program requires most vehicles in the State to undergo a
10 smog check inspection every two years when renewing their registration and when the vehicle's
11 title is transferred. The Smog Check Program is designed and intended to reduce air pollution by
12 identifying and requiring the repair of polluting motor vehicles.

13 29. A smog check inspection in certain Enhanced areas of the State is an Acceleration
14 Simulation Mode (ASM) test performed using an Emission Inspection System (EIS), also known
15 as a BAR 97. This is a computer based five-gas analyzer that measures Hydrocarbons (HC),
16 Carbon Monoxide (CO), Oxides of Nitrogen (NO_x), Carbon Dioxide (CO₂) and Oxygen (O₂). The
17 first part of the test is a loaded mode test of the vehicle's tailpipe emissions on a dynamometer.
18 The vehicle's drive wheels are placed on rollers and the vehicle is driven to simulate driving
19 conditions while the emissions are sampled by the EIS.

20 30. In Basic areas of the State, or depending on a vehicle's configuration, a similar test
21 called a Two Speed Idle test is performed, but instead of applying a load to the vehicle's drive
22 wheels with a dynamometer, the EIS measures the emissions of HC, CO, O₂, and CO₂ at idle as
23 well as 2500 revolutions per minute (rpm).

24 31. In the visual portion of a smog check, the technician inspects the emission control
25 components to verify that the required emission control devices are present and properly
26 connected.

27 32. An On-Board Diagnostics (OBD II) functional test is also performed on most 1996 to
28 1999 model year vehicles. The EIS retrieves information through the Diagnostic Link Connector
from the vehicle's on-board computer about its ability to communicate, the status of the I/M

1 readiness monitors and the MIL light command. The I/M readiness monitors tell whether or not
2 the OBD II system has run a sufficient number of self-tests on the vehicle's emission and engine
3 control systems. A failure of one or more of the OBD II functional criteria, depending on model
4 year, will result in the vehicle failing its smog check inspection. In addition to reporting the
5 outcome of the OBD II functional test, the smog check inspection results also show Diagnostic
6 Trouble Codes if there are any in the vehicle's on-board computer memory.

7 33. The inspector enters the results of the visual and functional inspections into the EIS.
8 The EIS unit makes the determination whether or not the vehicle passes the inspection based on
9 the results of the tailpipe, visual, and functional tests.

10 34. The EIS is connected by internet connection to Bureau's Vehicle Information
11 Database (VID). If the vehicle passes the visual, functional and tailpipe tests, it passes the overall
12 inspection. A Certificate of Compliance is issued and transmitted electronically to the VID.

13 35. Beginning March 9, 2015, California's Smog Check Program was updated to require
14 the use of an On-Board Diagnostic Inspection System (BAR-OIS). BAR-OIS is the smog check
15 equipment required in all areas of the State when inspecting most model-year 2000 and newer
16 gasoline and hybrid vehicles. The system consists of a certified Data Acquisition Device,
17 computer, bar code scanner, and printer. The Data Acquisition Device is an OBD scan tool that,
18 when requested by the BAR-OIS software, retrieves OBD data from the vehicle. All OBD data
19 that the vehicle indicates it supports is requested by the BAR-OIS software and will be retrieved.
20 The Data Acquisition Device connects between the BAR-OIS computer and the vehicle's
21 diagnostic link connector. The bar code scanner is used to input inspector information, the
22 vehicle identification number (VIN), and Department of Motor Vehicles renewal information.
23 The printer provides a Vehicle Inspection Report (VIR) containing inspection results for
24 motorists and a Smog Check Certificate of Compliance number for passing vehicles.

25 36. During an OIS inspection, engine operating parameters (PIDs) are retrieved from the
26 vehicle's OBD II system and recorded to the VID. This is accomplished during the functional
27 portion of the OIS Smog Check inspection by plugging the Data Acquisition Device into the
28

1 vehicle's diagnostic link connector when prompted by the OIS analyzer screen prompt. Some of
2 the parameters recorded are:

- 3 • Engine speed in revolutions per minute (RPM)
- 4 • Throttle position as measured by a throttle position sensor (TPS) mounted onto the
5 throttle shaft. Measured in a percentage of opening from 0% at idle and near or up to 100% at full
6 throttle.
- 7 • Manifold absolute pressure as measured by a manifold air pressure sensor (MAP)
8 connected to an intake manifold source, measured in kilo pascals (kpa). Typical readings for a
9 normally aspirated vehicle as follows: 0 kpa being absolute vacuum, 25 to 45 kpa at idle, 101 kpa
10 at full throttle, same as atmospheric pressure at sea level.
- 11 • Mass air flow as measured by a mass air flow sensor (MAF) mounted in the engine's
12 air intake tract. Measured in grams per second (gps).
- 13 • Ignition timing is when the spark plug is ignited in relation to the position of the
14 engine's moving pistons. It is measured in degrees before top dead center (BTDC). The ignition
15 timing will constantly change based on engine operating conditions such as RPM, engine load,
16 and throttle position.

17 37. During normal engine operation at idle, engine speed is relatively steady around its
18 target idle speed. With the engine idling, the TPS is steady and at or near 0%. The MAP and/or
19 MAF readings are also steady. For the engine speed to increase, the throttle would have to be
20 opened in order to increase airflow through the engine. The engine's management systems
21 supply fuel and spark timing appropriate to any changes in throttle position and engine speed.
22 An increase in throttle, measured by the TPS, which increases engine RPM, would result in a
23 corresponding increases in MAF as well as a change in MAP. Any movement in the throttle from
24 the idle position will result in an increase of airflow through the engine with corresponding
25 increases RPM and MAF along with changes in MAP.

26 38. During an OIS Smog Check inspection, along with other visual and functional
27 inspections, there is an OBD II query portion of the inspection. The OBD II query is performed
28 with the engine idling and, when requested by the OIS analyzer, and an elevated or increased

1 engine speed. The increase in engine speed is performed by the inspector by stepping on the
2 throttle pedal or manually opening the throttle resulting in a corresponding increase in engine
3 RPMs by allowing an increase in airflow into the engine.

4 39. The Bureau has become aware of methods that some Smog Check stations and Smog
5 Check inspectors use to fraudulently issue smog certificates to vehicles that may not pass a smog
6 check test on their own, or in some instances, are not even present during the time the test is
7 performed. “Clean plugging” is a method by which another vehicle’s OBD II system, or another
8 source such as defeat devices, are used to generate passing data readings or diagnostic
9 information for the purpose of fraudulently issuing smog certificates to vehicles that are not in
10 smog compliance, and or not present for testing. Defeat devices attempt to simulate engine
11 operation during a smog check inspection by transmitting OBD II data to the VID which has been
12 modified or replaced entirely for the purportedly inspected vehicle during the functional portion
13 of the OIS inspection.

14 **SEPTEMBER 18, 2025 VID DATA REVIEW**

15 40. On or around September 18, 2025, a Bureau Representative conducted a detailed
16 review of the VID data for smog check inspections performed at Los Smoggers Smog Check,
17 which showed a pattern of vehicles being certified with engine operating parameters that did not
18 correspond to normal engine operation. The Bureau’s review of the smog check activities at Los
19 Smoggers Smog Check confirmed 10 smog check Certificates of Compliance were fraudulently
20 issued to vehicles after inspections performed at Los Smoggers Smog Check.

21 **Clean Plug Number 1 – 2001 Ford F350 SRW Super Duty**

22 41. OIS Test data for Los Smoggers indicated that on November 29, 2024, a 2001 Ford
23 F 350 SRW Super Duty, 1FTSW30S71ED18938, License Plate 6V24162, was tested and
24 Smog Certificate of Compliance #UG698921C was issued by Los Smoggers Smog
25 Check under Respondent Peralta’s Smog Check Inspector License #EO 643740.

26 42. The OBD Data (Dynamic) and Dynamic Data Charts for the 2001 Ford F350 SRW
27 Super Duty shows that between time stamp 83 and 17664, the engine RPM is steady at around
28 700 RPM. During this time, the data shows the throttle fluctuates between 19.6 % and 24.3 %

1 opening and the MAF fluctuates between 8.02 gps and 10.22 gps. After time stamp 17664, the
2 data shows the engine RPM was increased and then held steady at around 1850 RPM. During the
3 elevated engine RPM, the data shows the throttle fluctuates between 18.8 % and 23.9 % opening
4 and the MAF fluctuates between 7.94 gps and 10.21 gps.

5 43. The steady idle and steady elevated engine RPMs along with the improbable throttle
6 positions and MAF readings are not characteristic or expected for normal engine operation. The
7 throttle position and MAF readings are expected to be stable at idle and at the elevated engine
8 RPM, not fluctuate. Additionally, with the elevated engine RPM, the throttle position and the
9 MAF readings are expected to increase, not decrease to values lower than idle. The discrepancies
10 in the OIS Test Data prove the Data Acquisition Device was not connected as required to the
11 2001 Ford F350 SRW Super Duty being certified, causing the issuance of a fraudulent Smog
12 Check Certificate of Compliance.

13 **Clean Plug Number 2 – 2001 BMW 325 CI**

14 44. OIS Test data for Los Smoggers indicated that on December 28, 2024, a 2001 BMW
15 325 CI, VIN# WBABN33411JW50233, CA License 8RQB142, was tested and Smog
16 Certificate of Compliance #UI290451C was issued by Los Smoggers Smog Check under
17 Respondent Peralta's Smog Check Inspector License #EO 643740.

18 45. The Dynamic Data Charts for the 2001 BMW 325 CI shows that between time stamp
19 300 and 22522, the engine RPM is steady at around 700 RPM. During this time, the data shows
20 that the throttle rises from 2 % opening to 3.9 % opening and then drops to 3.1 % opening and the
21 MAF fluctuates between 3.41 gps and 4.84 gps. After time stamp 22522, the data shows the
22 engine RPM was increased and then held steady at around 1860 RPM. During the elevated engine
23 RPM, the data shows that the throttle drops from 5.1 % opening to 2.4 % opening and then rises
24 to 3.9 % opening and the MAF fluctuates between 2.73 gps and 4.67 gps.

25 46. The steady idle and steady elevated engine RPMs along with the improbable throttle
26 positions and MAF readings are not characteristic or expected for normal engine operation. The
27 throttle position and MAF readings are expected to be stable at idle and at the elevated engine
28 RPM, not drop or rise unexpectedly and/or fluctuate. Additionally, with the elevated engine

1 RPM, the throttle position and the MAF readings are expected to increase, not decrease to values
2 lower than idle. The discrepancies in the OIS Test Data prove the Data Acquisition Device was
3 not connected as required to the 2001 BMW 325 CI being certified, causing the issuance of a
4 fraudulent Smog Check Certificate of Compliance.

5 **Clean Plug Number 3 – 2001 Ford F150 SVT Lightning**

6 47. OIS Test data for Los Smoggers indicated that on January 21, 2025, a 2001 Ford F150
7 SVT Lightning, VIN# 2FTZF07341CA47113, CA License 61687N3, was tested and Smog
8 Certificate of Compliance #UI979005C was issued by Los Smoggers Smog Check under
9 Respondent Peralta’s Smog Check Inspector License #EO 643740.

10 48. The Dynamic Data Charts for the 2001 Ford F150 SVT Lightning shows that between
11 time stamp 97 and 18378, the engine RPM is steady at around 575 RPM. During this time, the
12 data shows that the throttle fluctuates between 12.9 % opening and 16.9 % opening and the MAF
13 fluctuates between 3.13 gps and 4.98 gps. After time stamp 18378, the data shows the engine
14 RPM was increased and then held steady at around 1775 RPM. From the time the engine RPM
15 increases off idle to the higher RPMs, the data shows that the throttle fluctuates between 12.5 %
16 opening and 18 % opening and the MAF fluctuates between 2.89 gps to 5.05 gps.

17 49. The steady idle and steady elevated engine RPMs along with the improbable throttle
18 positions and MAF readings are not characteristic or expected for normal engine operation. The
19 throttle position and MAF readings are expected to be stable at idle and at the elevated engine
20 RPM, not fluctuate. Additionally, with the elevated engine RPM, the throttle position and the
21 MAF readings are expected to increase, not decrease to values lower than idle. The discrepancies
22 in the OIS Test Data prove the Data Acquisition Device was not connected as required to the
23 2001 Ford F150 SVT Lightning being certified, causing the issuance of a fraudulent Smog Check
24 Certificate of Compliance.

25 **Clean Plug Number 4 – 2000 Pontiac Firebird Formula**

26 50. OIS Test data for Los Smoggers indicated that on February 14, 2025, a 2000 Pontiac
27 Firebird Formula, VIN# 2G2FV22G5Y2143168, License Plate 4KKN700, was tested and Smog
28

1 Certificate of Compliance #JD328848C was issued by Los Smoggers Smog Check under
2 Respondent Peralta's Smog Check Inspector License #EO 643740.

3 51. The Dynamic Data Charts for the 2000 Pontiac Firebird Formula shows that between
4 time stamp 133 and 17684, the engine RPM is steady at around 675 RPM. During this time, the
5 data shows that the throttle fluctuates between 0.4 % opening and 5.1 % opening, the MAF
6 fluctuates between 5.33 gps and 7.17 gps, and the MAP fluctuates between 35 kPa and 46 kPa.
7 After time stamp 17684, the data shows the engine RPM was increased and then held steady at
8 around 1775 RPM. From the time the engine RPM increases off idle to the higher RPMs, the
9 data shows that the throttle fluctuates between 0.4 % opening and 5.1 % opening and the MAF
10 fluctuates between 5.34 gps and 7.62 gps, and the MAP fluctuates between 33 kPa and 42 kPa.

11 52. The steady idle and steady elevated engine RPMs along with the improbable throttle
12 positions, MAF and MAP readings are not characteristic or expected for normal engine operation.
13 The throttle position, MAF and MAP readings are expected to be stable at idle and at the elevated
14 engine RPM, not fluctuate. Additionally, with the elevated engine RPM, the throttle position and
15 the MAF readings are expected to increase, not decrease to values lower than idle. The
16 discrepancies in the OIS Test Data prove the Data Acquisition Device was not connected as
17 required to the 2000 Pontiac Firebird Formula being certified, causing the issuance of a fraudulent
18 Smog Check Certificate of Compliance.

19 **Clean Plug Number 5 – 2002 Subaru Impreza RS**

20 53. OIS Test data for Los Smoggers indicated that on March 6, 2025, a 2002 Subaru
21 Impreza RS, VIN# JF1GD67582G518087, no license plate, was tested and Smog Certificate of
22 Compliance #UK407604C was issued by Los Smoggers Smog Check under Respondent Peralta's
23 Smog Check Inspector License #EO 643740.

24 54. The Dynamic Data Charts for the 2002 Subaru Impreza RS shows that between time
25 stamp 283 and 19694, the engine RPM is steady at around 675 RPM. During this time, the data
26 shows the throttle rises from 1.2 % opening to 3.5 % opening and then gradually drops to 2 %
27 opening, the MAF gradually rises from 2.94 gps to 3.56 gps, and the MAP fluctuates between 34
28 kPa and 38 kPa. After time stamp 19694, the data shows the engine RPM was increased and held

1 above 1650 RPM. During the elevated engine RPM, the data shows the throttle fluctuates
2 between 0.4 % to 4.3 % opening, the MAF drops from 4.52 gps to 3.24 gps and then ultimately
3 rises to 3.84 gps, and the MAP fluctuates between 33 kPa and 46 kPa.

4 55. The steady idle and steady elevated engine RPMs along with the improbable throttle
5 positions, MAF and MAP readings are not characteristic or expected for normal engine operation.
6 The throttle position, MAF and MAP readings are expected to be stable at idle and at the elevated
7 engine RPM, not drop or rise unexpectedly and/or fluctuate. Additionally, with the elevated
8 engine RPM, the throttle position and MAF readings are expected to increase, not decrease to
9 values lower than idle. The MAP readings are expected to decrease, not increase to values higher
10 than idle. The discrepancies in the OIS Test Data prove the Data Acquisition Device was not
11 connected as required to the 2002 Subaru Impreza RS being certified, causing the issuance of a
12 fraudulent Smog Check Certificate of Compliance.

13 **Clean Plug Number 6 – 2003 Mitsubishi Lancer Evolution**

14 56. OIS Test data for Los Smoggers indicated that on April 30, 2025, a 2003 Mitsubishi
15 Lancer Evolution, VIN# JA3AH86F53U115437, CA License GOSU999, was tested and Smog
16 Certificate of Compliance #UM653230C was issued by Los Smoggers Smog Check under
17 Respondent Peralta's Smog Check Inspector License #EO 643740.

18 57. The Dynamic Data Charts for the 2003 Mitsubishi Lancer Evolution shows that
19 between time stamp 260 and 17437, the engine RPM is steady at around 660 RPM. During this
20 time, the data shows that the throttle varies between 0.8 % and 5.1 % opening and the MAF
21 fluctuates between 2.79 gps and 5.1 gps. After time stamp 17437, the engine RPM was increased
22 and then held steady around 1885 RPM. During this time, the data shows that the throttle varies
23 between 3.9 % to 5.5 % opening and the MAF varies between 2.91 gps and 4.36 gps.

24 58. The steady idle and steady elevated engine RPMs along with the improbable throttle
25 positions and MAF readings are not characteristic or expected for normal engine operation. The
26 throttle position and MAF readings are expected to be stable at idle and at the elevated engine
27 RPM, not vary abnormally and/or fluctuate. Additionally, with the elevated engine RPM, the
28 throttle position and MAF readings are expected to increase, not decrease to values lower than

1 idle. The discrepancies in the OIS Test Data prove the Data Acquisition Device was not
2 connected as required to the 2003 Mitsubishi Lancer Evolution being certified, causing the
3 issuance of a fraudulent Smog Check Certificate of Compliance.

4 **Clean Plug Number 7 – 2002 Porsche 911 Carrera 2**

5 59. OIS Test data for Los Smoggers indicated that on May 3, 2025, a 2002 Porsche 911
6 Carrera 2, VIN# WP0AA299X2S621638, no license plate, was tested and Smog Certificate of
7 Compliance #UM653247C was issued by Los Smoggers Smog Check under Respondent
8 Peralta's Smog Check Inspector License #EO 643740.

9 60. The Dynamic Data Charts for the 2002 Porsche 911 Carrera 2 shows that between
10 time stamp 262 and 17569, the engine RPM is steady at around 550 RPM. During this time, the
11 data shows that the throttle fluctuates between 0.4 % opening and 4.3 % opening and the MAF
12 varies between 2.84 gps and 4.87 gps. After time stamp 17569, the data shows the engine RPM
13 was increased and then held steady at around 1800 RPM. From the time the engine RPM
14 increases off idle to the higher RPMs, the data shows that the throttle fluctuates between 0 % and
15 5.5 % opening and the MAF fluctuates between 2.84 gps and 5 gps.

16 61. The steady idle and steady elevated engine RPMs along with the improbable throttle
17 positions and MAF readings are not characteristic or expected for normal engine operation. The
18 throttle position and MAF readings are expected to be stable at idle and at the elevated engine
19 RPM, not vary abnormally and/or fluctuate. Additionally, with the elevated engine RPM, the
20 throttle position and MAF readings are expected to increase, not decrease to values less than idle.
21 The discrepancies in the OIS Test Data prove the Data Acquisition Device was not connected as
22 required to the 2002 Porsche 911 Carrera 2 being certified, causing the issuance of a fraudulent
23 Smog Check Certificate of Compliance.

24 **Clean Plug Number 8 – 2003 Nissan 350Z Coupe**

25 62. OIS Test data for Los Smoggers indicated that on May 30, 2025, a 2003 Nissan 350Z
26 Coupe, VIN# JN1AZ34E73T015781, License Plate 7ZVA879, was tested and Smog Certificate
27 of Compliance #UO716978C was issued by Los Smoggers Smog Check under Respondent
28 Peralta's Smog Check Inspector License #EO 643740.

1 63. The Dynamic Data Charts for the 2003 Nissan 350Z Coupe shows that between time
2 stamp 337 and 19634, the engine RPM is steady at around 725 RPM. During this time, the data
3 shows that the throttle fluctuates between 0 % and 5.5 % opening and the MAF fluctuates
4 between 6.71 gps and 7.51 gps. After time stamp 19634, the engine RPM was increased and then
5 held at no less than 1647 RPM. During this time, the data shows that the throttle gradually drops
6 from 4.3 % to 0.4 % opening and ultimately rises to 5.1 % opening, the MAF fluctuates between
7 5.88 gps and 7.65 gps.

8 64. The steady idle and steady elevated engine RPMs along with the improbable throttle
9 positions and MAF readings are not characteristic or expected for normal engine operation. The
10 throttle position and MAF readings are expected to be stable at idle and at the elevated engine
11 RPM, not drop or rise unexpectedly and/or fluctuate. Additionally, with the elevated engine
12 RPM, the throttle position and MAF readings are expected to increase, not decrease to values
13 lower than idle. The discrepancies in the OIS Test Data prove the Data Acquisition Device was
14 not connected as required to the 2003 Nissan 350Z Coupe being certified, causing the issuance of
15 a fraudulent Smog Check Certificate of Compliance.

16 **Clean Plug Number 9 – 2002 Chevrolet Camaro Z28**

17 65. OIS Test data for Los Smoggers indicated that on May 31, 2025, a 2002 Chevrolet
18 Camaro Z28, VIN# 2G1FP22G322162677, CA License 8HEC229, was tested and Smog
19 Certificate of Compliance #UQ189451C was issued by Los Smoggers Smog Check under
20 Respondent Peralta's Smog Check Inspector License #EO 643740.

21 66. The Dynamic PID Charts for the 2002 Chevrolet Camaro Z28 shows that between
22 time stamp 155 and 21603, the engine RPM is steady at around 760 RPM. During this time, the
23 data shows that the throttle is fluctuating between 1.2 % and 5.5 % opening, the MAF is
24 fluctuating between 5.62 gps and 7.23 gps, and the MAP fluctuates between 16 kPa and 29 kPa.
25 After time stamp 21603, the engine RPM was increased and then held steady at around 1910
26 RPM. During this time, the date shows that the throttle fluctuates between 0.4 % and 5.5 %
27 opening, the MAF fluctuates between 5.56 gps, and 7.37 gps, and the MAP fluctuates between 17
28 kPa and 29 kPa.

1 67. The steady idle and steady elevated engine RPMs along with the improbable throttle
2 positions, MAF and MAP readings are not characteristic or expected for normal engine operation.
3 The throttle position, MAF and MAP readings are expected to be stable at idle and at the elevated
4 engine RPM, not fluctuate. Additionally, with the elevated engine RPM, the throttle position and
5 MAF readings are expected to increase, not decrease to values lower than idle. The MAP
6 readings are expected to decrease, not increase to values higher than idle. The discrepancies in
7 the OIS Test Data prove the Data Acquisition Device was not connected as required to the 2002
8 Chevrolet Camaro Z28 being certified, causing the issuance of a fraudulent Smog Check
9 Certificate of Compliance.

10 **Clean Plug Number 10 – 2005 Chevrolet Avalanche C1500**

11 68. OIS Test data for Los Smoggers indicated that on June 7, 2025, a 2005 Chevrolet
12 Avalanche C1500, VIN# 3GNEC12Z85G265502, CA License 17881Z3, was tested and Smog
13 Certificate of Compliance #UQ189455C was issued by Los Smoggers Smog Check under
14 Respondent Peralta's Smog Check Inspector License #EO 643740.

15 69. The Dynamic PID Charts for the 2005 Chevrolet Avalanche C1500 shows that
16 between time stamp 117 and 18753, the engine RPM is steady at around 700 RPM. During this
17 time, the data shows that the throttle is fixed at 11.8 % opening, the MAF is fixed at 5.96 gps, and
18 the MAP is fixed at 32 kPa. After time stamp 18753, the engine RPM was increased and then
19 held steady at around 1830 RPM. During this time, the data shows that the throttle gradually rises
20 from 7.1 % to 11.4 % opening then drops to 9.8 % opening and ultimately rises to 11.8 %
21 opening, the MAF fluctuates from 6.18 gps to 7.46 gps, and the MAP rises from 32 kPa to 46 kPa
22 and then ultimately drops to 34 kPa.

23 70. The steady idle and steady elevated engine RPMs along with the improbable throttle
24 positions, MAF and MAP readings are not characteristic or expected for normal engine operation.
25 The throttle position, MAF and MAP readings are expected to be stable at idle and at the elevated
26 engine RPM, not drop or rise unexpectedly and/or fluctuate. Additionally, with the elevated
27 engine RPM, the throttle position readings are expected to increase, not decrease to values lower
28 than idle. The MAP readings are expected to decrease, not increase to values higher than idle.

1 The discrepancies in the OIS Test Data prove the Data Acquisition Device was not connected as
2 required to the 2005 Chevrolet Avalanche C1500 being certified, causing the issuance of a
3 fraudulent Smog Check Certificate of Compliance.

4 **FIRST CAUSE FOR DISCIPLINE**

5 **(Untrue or Misleading Statements – Respondent Ramirez)**

6 71. Respondent Ramirez’s Automotive Repair Dealer Registration is subject to
7 disciplinary action under Business and Professions Code section 9884.7, subdivision (a)(1), in
8 that he made statements which were known to be untrue or misleading or, which by exercise of
9 reasonable care, should have been known to be untrue or misleading, by issuing electronic smog
10 certificates of compliance for the vehicles identified above certifying that those vehicles were in
11 compliance with applicable laws and regulations when, in fact, those vehicles had not been so
12 inspected. Complainant refers to, and by this reference incorporates, the allegations contained in
13 paragraphs 40 through 70, as though fully set forth here.

14 **SECOND CAUSE FOR DISCIPLINE**

15 **(Fraud – Respondent Ramirez)**

16 72. Respondent Ramirez’s Automotive Repair Dealer Registration is subject to
17 disciplinary action pursuant to Business and Professions Code section 9884.7, subdivision (a)(4),
18 in that he committed acts that constitute fraud by issuing electronic certificates of compliance to
19 the vehicles identified above without performing bone fide inspections of the emission control
20 devices and systems on those vehicles, thereby depriving the People of the State of California of
21 the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by
22 this reference incorporates, the allegations contained in paragraphs 40 through 70, above, as
23 though set forth fully herein.

24 **THIRD CAUSE FOR DISCIPLINE**

25 **(Material Violation of Automotive Repair Act – Respondent Ramirez)**

26 73. Respondent Ramirez’s Automotive Repair Dealer Registration is subject to
27 disciplinary action pursuant to Business and Professions Code section 9884.7, subdivision (a)(6),
28 in that he failed in a material respect to comply with the provisions of this chapter or regulations

1 adopted pursuant to it when he issued electronic certificates of compliance for the vehicles
2 identified above without performing bona fide inspections of the emission control devices and
3 systems on those vehicles, thereby depriving the People of the State of California of the
4 protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this
5 reference incorporates, the allegations contained in paragraphs 40 through 70, above, as though
6 set forth fully herein.

7 **FOURTH CAUSE FOR DISCIPLINE**

8 **(Violations of the Motor Vehicle Inspection Program – Respondent Ramirez)**

9 74. Respondent Ramirez’s Smog Check, Test Only, Station License is subject to
10 disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that he
11 failed to comply with the following sections of that Code:

12 a. **Section 44012:** Respondent failed to ensure that the emission control tests
13 were performed on the vehicles identified above in accordance with procedures prescribed by the
14 department.

15 b. **Section 44015, subdivision (b):** Respondent issued electronic smog
16 certificates of compliance to the vehicles identified above without properly testing and inspecting
17 those vehicles to determine if they were in compliance with Health & Safety Code section 44012.

18 Complainant refers to, and by this reference incorporates, the allegations contained in
19 paragraphs 40 through 70, above, as though set forth fully herein.

20 **FIFTH CAUSE FOR DISCIPLINE**

21 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)**

22 75. Respondent Ramirez’s Smog Check, Test Only, Station License is subject to
23 disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (c), in that he
24 failed to comply with provisions of California Code of Regulations, title 16, as follows:

25 a. **Section 3340.24, subdivision (c):** Respondent falsely or fraudulently issued
26 electronic smog certificates of compliance for the vehicles identified above.

27 ///

28 ///

1 **SEVENTH CAUSE FOR DISCIPLINE**

2 **(Violations of the Motor Vehicle Inspection Program – Respondent Peralta)**

3 77. Respondent Peralta’s Smog Check Inspector License is subject to disciplinary action
4 pursuant to Health & Safety Code section 44072.2, subdivision (a), in that he failed to comply
5 with the following sections of that code:

6 a. **Section 44012, subdivision (a):** Respondent failed to determine that all
7 emission control devices and systems required by law were installed and functioning correctly on
8 the vehicles identified above in accordance with test procedures prescribed by the Bureau.

9 b. **Section 44012, subdivision (f):** Respondent failed to perform emission control
10 tests on the vehicles identified above in accordance with procedures prescribed by the Bureau.

11 c. **Section 44032:** Respondent failed to perform tests of emission control devices
12 and systems of the vehicles identified above in accordance with Health & Safety Code section
13 44012.

14 d. **Section 44015, subdivision (b):** Respondent caused electronic smog
15 certificates of compliance to be issued for the subject vehicles identified above without ensuring
16 that they were properly tested and inspected to determine if they were in compliance with Health
17 & Safety Code section 44012.

18 e. **Section 44059:** Respondent willfully made false entries for the electronic
19 certificates of compliance by certifying that the vehicles identified above had been inspected as
20 required when, in fact, they had not.

21 Complainant refers to, and by this reference incorporates, the allegations contained in
22 paragraphs 40 through 70, above, as though set forth fully herein.

23 **EIGHTH CAUSE FOR DISCIPLINE**

24 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program –**
25 **Respondent Peralta)**

26 78. Respondent Peralta’s Smog Check Inspector License is subject to disciplinary action
27 pursuant to Health & Safety Code section 44072.2, subdivision (c), in that he failed to comply
28 with provisions of California Code of Regulations, title 16, as follows:

1 a. **Section 3340.24, subdivision (c)**: Respondent falsely or fraudulently issued
2 electronic smog certificates of compliance for the vehicles identified above.

3 b. **Section 3340.30, subdivision (a)**: Respondent failed to inspect and test the
4 vehicles identified above in accordance with Health & Safety Code sections 44012 and 44035,
5 and California Code of Regulations, title 16, section 3340.42.

6 c. **Section 3340.41, subdivision (c)**: Respondent knowingly entered false
7 information into the on-board diagnostic inspection system for the vehicles identified above.

8 d. **Section 3340.42**: Respondent failed to ensure that the smog inspections
9 conducted on the vehicles identified above were done in accordance with the Bureau's
10 specifications.

11 Complainant refers to, and by this reference incorporates, the allegations contained in
12 paragraphs 40 through 70, above, as though set forth fully herein.

13 **NINTH CAUSE FOR DISCIPLINE**

14 **(Dishonesty, Fraud or Deceit – Respondent Peralta)**

15 79. Respondent Peralta's Smog Check Inspector License is subject to disciplinary action
16 pursuant to Health & Safety Code section 44072.2, subdivision (d), in conjunction with Health &
17 Safety Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or
18 deceitful acts whereby another was injured by issuing electronic smog certificates of compliance
19 for the vehicles identified above without performing bona fide inspections of the emission control
20 devices and systems on those vehicles, thereby depriving the People of the State of California of
21 the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by
22 this reference incorporates, the allegations contained in paragraphs 40 through 70, above, as
23 though set forth fully herein.

24 **OTHER MATTERS**

25 80. Pursuant to Business and Professions Code section 9884.7, subdivision (c), the
26 Director may suspend, revoke, or place on probation the registration for all places of business
27 operated in this state by Respondent Ramirez, upon a finding that he has, or is, engaged in a
28 course of repeated and willful violations of the laws and regulations pertaining to an

1 automotive repair dealer.

2 81. Pursuant to Health & Safety Code section 44072.8, if Smog Check, Test Only,
3 Station License No. TC 305845, issued to Respondent Ramirez, is revoked or suspended, any
4 additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Safety Code in
5 the name of said licensee may be likewise revoked or suspended by the director.

6 82. Pursuant to Health & Safety Code section 44072.8, if Smog Check Inspector License
7 No. EO 643740, issued to Respondent Peralta, is revoked or suspended, any additional license
8 issued under Chapter 5 of Part 5 of Division 26 of the Health & Safety Code in the name of said
9 licensee may be likewise revoked or suspended by the director.

10 **PRAYER**

11 WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged,
12 and that following the hearing, the Director of the Department of Consumer Affairs issue a
13 decision:

14 1. Revoking or suspending Automotive Repair Dealer Registration Number ARD
15 305845, issued to David Gerardo Ramirez;

16 2. Revoking or suspending any other automotive repair dealer registration issued to
17 David Gerardo Ramirez;

18 3. Revoking or suspending Smog Check, Test-Only, Station License Number TC
19 305845, issued to David Gerardo Ramirez;

20 4. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
21 Division 26 of the Health & Safety Code in the name of David Gerardo Ramirez;

22 5. Revoking or suspending Smog Check Inspector License Number EO 643740, issued
23 to Zeferino Peralta Jr.;

24 6. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
25 Division 26 of the Health & Safety Code in the name of Zeferino Peralta Jr.;

26 7. Ordering David Gerardo Ramirez and Zeferino Peralta Jr. to pay the Bureau of
27 Automotive Repair the reasonable costs of the investigation and enforcement of this case,

28 ///

1 pursuant to Business and Professions Code section 125.3 and if placed on probation, the costs of
2 probation monitoring; and,

3 8. Taking such other and further action as deemed necessary and proper.
4

5 DATED: As of digital signature date

6 PATRICK DORAIS
7 Chief
8 Bureau of Automotive Repair
9 Department of Consumer Affairs
10 State of California
11 *Complainant*

12 LA2025604507
13 68022737
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28