

1 ROB BONTA
Attorney General of California
2 KAREN R. DENVIR
Supervising Deputy Attorney General
3 MALISSA N. SIEMANTEL
Deputy Attorney General
4 State Bar No. 240157
1300 I Street, Suite 125
5 Sacramento, CA 95814
Telephone: (916) 210-7555
6 Facsimile: (916) 324-5567
E-mail: Malissa.Siemantel@doj.ca.gov
7 *Attorneys for Complainant*

8
9 **BEFORE THE**
DEPARTMENT OF CONSUMER AFFAIRS
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 77/26-3819

13 **ROMITA AUTOMOTIVE SERVICE LLC**
DBA ROMITA AUTO SERVICE
14 **NESTOR ANGUIANO RODRIGUEZ,**
MEMBER
15 **MARIA RAMIREZ GONZALEZ,**
MEMBER
16 4909 E Dakota
Fresno, CA 93727

ACCUSATION

17 **Automotive Repair Dealer Registration No.**
18 **ARD 298711**
Smog Check, Test-and-Repair, Station
19 **License No. RC 298711,**

20 **and**

21 **NESTOR ANGUIANO RODRIGUEZ**
4755 E Grant
22 Fresno, CA 93702

23 **Smog Check Inspector License No.**
EO 154541
24 **Smog Check Repair Technician License No.**
EI 154541

25 Respondents.
26

27 ///

28 ///

1 **PARTIES**

2 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as
3 the Chief of the Bureau of Automotive Repair (Bureau), Department of Consumer Affairs.

4 **Automotive Repair Dealer Registration**

5 2. On or about December 22, 2020, the Bureau issued Automotive Repair Dealer
6 Registration Number ARD 298711 to Romita Automotive Service LLC, doing business as
7 Romita Auto Service, (Respondent Romita) with Nestor Anguiano Rodriguez (Respondent
8 Rodriguez) and Maria Ramirez Gonzalez (Respondent Gonzalez) as members. The Automotive
9 Repair Dealer Registration (registration) was in full force and effect at all times relevant to the
10 charges brought herein and will expire on December 31, 2026, unless renewed.

11 **Smog Check, Test-and-Repair, Station License**

12 3. On or about June 8, 2021, the Bureau issued Smog Check, Test-and-Repair, Station
13 License Number RC 298711 to Respondent Romita. The Smog Check, Test-and-Repair, Station
14 License (license) was in full force and effect at all times relevant to the charges brought herein
15 and will expire on December 31, 2026, unless renewed.

16 **Smog Check Inspector License**

17 4. On or about July 5, 2013, the Bureau issued Smog Check Inspector License Number
18 EO 154541 to Respondent Rodriguez. The Smog Check Inspector License was in full force and
19 effect at all times relevant to the charges brought herein and will expire on July 31, 2027, unless
20 renewed.

21 **Smog Check Repair Technician License**

22 5. On or about July 5, 2013, the Bureau issued Smog Check Repair Technician License
23 Number EI 154541 to Respondent Rodriguez. The Smog Check Repair Technician License was
24 in full force and effect at all times relevant to the charges brought herein and will expire on July
25 31, 2027, unless renewed.

26 ///

27 ///

28 ///

1 **JURISDICTION**

2 6. This Accusation is brought before the Bureau under the authority of the following
3 laws. All section references are to the Business and Professions Code (Code) unless otherwise
4 indicated.

5 7. Code section 118, subdivision (b), provides that the expiration of a license shall not
6 deprive the Bureau of jurisdiction to proceed with a disciplinary action during the period within
7 which the license may be renewed, restored, reissued or reinstated.

8 8. Code section 477 states:

9 As used in this division:

10 (a) "Board" includes "bureau," "commission," "committee," "department,"
11 "division," "examining committee," "program," and "agency."

12 (b) "License" includes certificate, registration or other means to engage in a
business or profession regulated by this code.

13 9. Code section 9884.13 provides, in pertinent part, that the expiration of a valid
14 registration shall not deprive the director or chief of jurisdiction to proceed with a disciplinary
15 proceeding against an automotive repair dealer or to render a decision invalidating a registration
16 temporarily or permanently.

17 **STATUTORY PROVISIONS**

18 10. Code section 9884.7 states, in pertinent part:

19 (a) The director, if the automotive repair dealer cannot show there was a bona
20 fide error, may deny, suspend, revoke, or place on probation the registration of an
21 automotive repair dealer for any of the following acts or omissions related to the
22 conduct of the business of the automotive repair dealer, which are done by the
automotive repair dealer or any automotive technician, employee, partner, officer, or
member of the automotive repair dealer:

23 (1) Making or authorizing in any manner or by any means whatever any
24 statement written or oral which is untrue or misleading, and which is known, or which
by the exercise of reasonable care should be known, to be untrue or misleading.

25 ...

26 (4) Any other conduct that constitutes fraud.

27 ...

28 (6) Failure in any material respect to comply with the provisions of this chapter
or regulations adopted pursuant to it.

1 ...
2 (7) Any willful departure from or disregard of accepted trade standards for good
3 and workmanlike repair in any material respect, which is prejudicial to another
4 without consent of the owner or the owner's duly authorized representative.

5 11. Code section 9884.8 states:

6 All work done by an automotive repair dealer, including all warranty work,
7 shall be recorded on an invoice and shall describe all service work done and parts
8 supplied. Service work and parts shall be listed separately on the invoice, which shall
9 also state separately the subtotal prices for service work and for parts, not including
10 sales tax, and shall state separately the sales tax, if any, applicable to each. If any
11 used, rebuilt, or reconditioned parts are supplied, the invoice shall clearly state that
12 fact. If a part of a component system is composed of new and used, rebuilt or
13 reconditioned parts, that invoice shall clearly state that fact. The invoice shall include
14 a statement indicating whether any crash parts are original equipment manufacturer
15 crash parts or nonoriginal equipment manufacturer aftermarket crash parts. One copy
16 of the invoice shall be given to the customer and one copy shall be retained by the
17 automotive repair dealer.

18 12. Code section 9884.9 states, in pertinent part:

19 (a) The automotive repair dealer shall give to the customer a written estimated
20 price for labor and parts necessary for a specific job, except as provided in
21 subdivision (e). No work shall be done and no charges shall accrue before
22 authorization to proceed is obtained from the customer. No charge shall be made for
23 work done or parts supplied in excess of the estimated price, or the posted price
24 specified in subdivision (e), without the oral or written consent of the customer that
25 shall be obtained at some time after it is determined that the estimated or posted price
26 is insufficient and before the work not estimated or posted is done or the parts not
27 estimated or posted are supplied. Written consent or authorization for an increase in
28 the original estimated or posted price may be provided by electronic mail or facsimile
transmission from the customer. The bureau may specify in regulation the procedures
to be followed by an automotive repair dealer if an authorization or consent for an
increase in the original estimated price is provided by electronic mail or facsimile
transmission. If that consent is oral, the dealer shall make a notation on the work
order of the date, time, name of person authorizing the additional repairs, and
telephone number called, if any, together with a specification of the additional parts
and labor and the total additional cost, and shall do either of the following:

29 ...
30 13. Code section 9884.11 states:

31 Each automotive repair dealer shall maintain any records that are required by
32 regulations adopted to carry out this chapter. Those records shall be open for
33 reasonable inspection by the chief or other law enforcement officials. All of those
34 records shall be maintained for at least three years.

35 ///

36 ///

14. Health and Safety (Health & Saf.) Code section 44072.2 states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

...

(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

...

REGULATORY PROVISIONS

15. California Code of Regulations, title 16 (CCR), section 3353.1 states, in pertinent part:

(a) No diagnosis or repair, including no-charge and warranty repairs, shall commence and no charges shall accrue without specific authorization from the customer. Any estimate or revised work order provided to the customer shall be authorized by the customer or the customer's designee in written, oral, or electronic form.

16. CCR section 3356 states, in pertinent part:

...

(c) The invoice shall separately list, describe and identify all of the following:

(1) All services and repairs performed, including any diagnosis or warranty repairs, and the prices for each.

(2) Each part supplied, in such a manner that the customer can understand what was purchased, and the price for each described part. The description of each part shall state whether the part was new, used, reconditioned, rebuilt, an OEM crash part, or a non-OEM aftermarket crash part. Part kits containing several components may be listed as a single part on the invoice and identified by brand name and corresponding part number or similar designation.

...

17. CCR section 3358 states, in pertinent part:

Pursuant to Section 9884.11 of the Business and Professions Code, each automotive repair dealer shall maintain, in either written or electronic form, legible copies of the following records for at least three years:

(a) All invoices relating to automotive repair including invoices received from other sources for parts and/or labor.

...

1 18. CCR section 3371, states:

2 No automotive repair dealer shall publish, utter, or make or cause to be
3 published, uttered, or made any false or misleading statement or advertisement which
4 is known to be false or misleading, or which by the exercise of reasonable care should
5 be known to be false or misleading. Advertisements and advertising signs shall
6 clearly show the name and address listed on the automotive repair dealer's State
7 registration certificate.

8 19. CCR section 3373, states:

9 No automotive repair dealer or individual in charge shall, in filling out an
10 estimate, invoice, or work order, or record required to be maintained by section
11 3340.15(e) of this chapter, withhold therefrom or insert therein any statement or
12 information which will cause any such document to be false or misleading, or where
13 the tendency or effect thereby would be to mislead or deceive customers, prospective
14 customers, or the public.

15 **COST RECOVERY**

16 20. Section 125.3 of the Code provides, in pertinent part, that the Board may request the
17 administrative law judge to direct a licensee found to have committed a violation or violations of
18 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
19 enforcement of the case, with failure of the licensee to comply subjecting the license to not being
20 renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be
21 included in a stipulated settlement.

22 **UNDERCOVER OPERATION**

23 21. On and between December 24, 2025, through February 6, 2026, Bureau
24 representative T.H. documented the condition of the fuel, ignition, and powertrain management
25 systems on the Bureau's 2007 Dodge. T.H. confirmed that the engine/powertrain were in good
26 working order and operating within the manufacturer's specifications. T.H. introduced an open
27 ground into the left upstream oxygen (O2) sensor heater circuit, which caused the engine to run
28 lean, created a misfire condition in the left bank (bank 1) cylinders, and illuminated the
Malfunction Indicator Lamp (MIL). The only repairs that the vehicle needed to correct the MIL
indicator were to properly diagnose and repair the open ground wire for the left upstream O2
sensor heater circuit and clear the stored Diagnostic Trouble Codes (DTC) from the Powertrain
Control Module (PCM) memory.

1 22. On or about February 23, 2026, Bureau representative H.P. called Respondent Romita
2 and spoke to a person who identified himself as Frank. H.P. requested to schedule an
3 appointment for a diagnosis of the check engine light (CEL) being on and a rough running issue
4 for the 2007 Dodge. Frank told H.P. that the diagnostic charge would be \$195.00. Frank
5 scheduled the appointment for February 26, 2026. H.P. told Frank that her boyfriend would be
6 delivering the 2007 Dodge.

7 23. On or about February 26, 2026, a Bureau undercover operator (operator) took the
8 2007 Dodge to Respondent Romita's facility and met with Frank. The operator told Frank that his
9 girlfriend, H.P., had made the appointment to have the CEL and the rough-running condition
10 diagnosed. Frank observed the rough-running condition and stated that the rough-running
11 condition was severe. Frank said the diagnosis would cost \$240.00. The operator told Frank that
12 he understood that Frank had told H.P. that the diagnosis would cost \$195.00. Frank agreed to
13 perform the diagnosis for \$195.00. Frank had the operator sign an estimate for the diagnosis and
14 gave the operator a copy.

15 24. On or about February 27, 2026, the operator called Frank for an update on the 2007
16 Dodge. Frank stated that the engine had low compression caused by the top end and that cylinder
17 #7 was low on compression. Frank stated he would prepare an estimate to remove the cylinder
18 heads and send them to a machine shop for testing.

19 25. On or about March 2, 2026, the operator called Respondent Romita and spoke to
20 Frank. Frank asked the operator to come to Respondent Romita's facility in person so he could
21 explain the repairs more clearly. The operator told Frank he could not because he was working
22 out of town. Frank stated to the operator that they needed to remove the cylinder heads and send
23 them to the machine shop for repairs and testing. Frank stated both cylinder heads needed repair
24 because what happened on one side would happen on the other side. Frank quoted the operator
25 \$2,700.00 for cylinder head repairs and warned the operator that additional issues might be
26 discovered due to the engine's mileage. The operator told Frank he would call him back after he
27 spoke with H.P.

28 ///

1 26. That same day, the operator called Frank and asked whether repairing the cylinder
2 heads would be cheaper than replacing the engine. Frank stated that the cylinder head repairs
3 were significantly cheaper. The operator approved the repairs for \$2,700.00.

4 27. On or about March 6, 2026, the operator called Frank for an update. Frank stated that
5 the technician needed more time to finalize his notes and that he would call the operator on the
6 following Monday, March 9.

7 28. On or about March 10, 2026, the operator contacted Respondent Romita and spoke to
8 a person who identified herself as Abby. Abby stated that Frank was no longer employed by
9 Respondent Romita and that a person named Christian would be taking over. Abby stated that
10 Christian needed some time to review the 2007 Dodge's status and would likely call later that
11 day.

12 29. That same day, the operator received a text message from Respondent Romita
13 requesting a return call. The operator called and spoke to Christian, who stated that they had
14 removed the cylinder heads and found them in good condition but discovered bent pushrods had
15 caused the low compression. Christian stated that a leak-down test on the cylinder heads showed
16 normal tests. Christian asked how old the spark plugs were. The operator told Christian he did
17 not know. Christian gave the operator two options: machine the existing cylinder heads or
18 purchase new ones. Christian stated the existing heads were in good condition and that
19 machining them would be sufficient. Christian quoted a price of \$3,558.43 to replace the
20 pushrods and head bolts and machine the cylinder heads. Christian gave another price of
21 \$3,933.54 to replace the pushrods and head bolts and replace the cylinder heads. Christian
22 recommended replacing all sixteen spark plugs for approximately \$186.00 in parts, noting the
23 operator would save about \$360.00 in labor since the cylinder heads were already removed. The
24 operator approved the machining option and declined the spark plug replacement. Christian
25 stated parts would take approximately three days to arrive and that the repairs were expected to be
26 completed by March 27, 2026.

27 30. On or about March 25, 2026, the operator called Respondent Romita and spoke to a
28 person who identified herself as Janice. Janice stated that Christian was not in, and that the

1 technician was still working on the 2007 Dodge and that he was trying his best to finish by March
2 27th.

3 31. On or about March 30, 2026, the operator called Respondent Romita. The operator
4 spoke to Christian who stated that the technician was “buttoning it up.” Christian stated he would
5 call the operator back in approximately twenty minutes.

6 32. That same day, Christian called the operator back. Christian stated that they had
7 additional recommendations. Christian stated that the spark plugs were included in the original
8 estimate. Christian stated that they had replaced the pushrods on Cylinder #7, replaced the head
9 gaskets, valve cover gaskets, and intake gaskets, filled and bled the cooling system, and changed
10 the oil. Christian stated that they had run the engine for approximately fifteen minutes and test-
11 driven it multiple times. The engine was operating normally; however, the CEL returned without
12 other symptoms. The DTC displayed was P0032 for an O2 sensor circuit. Christian
13 acknowledged that this code had been present during the initial diagnosis but was a secondary
14 issue. Christian stated that there were two issues with the 2007 Dodge. Christian told the
15 operator that the total invoice for the completed work was \$3,321.73, which included spark plugs.
16 Christian stated that an additional \$195.00 was required to diagnose DTC P0032, bringing the
17 total to \$3,516.73. The operator told Christian that he would call him back.

18 33. Later that day, the operator called Respondent Romita back and spoke with Christian.
19 The operator expressed concern that he had already paid for a diagnosis related to the CEL and
20 the cost continued to increase. Christian stated that the primary issue had been resolved and this
21 was a separate problem. Christian stated that if the problem turned out to be a simple wiring
22 repair, they would only charge the diagnostic fee. Otherwise, Christian would call with a new
23 estimate. The operator approved the \$195.00 diagnostic fee.

24 34. On or about April 2, 2026, the operator called Respondent Romita and spoke with
25 Christian. Christian stated that the technician had visually inspected the O2 sensor and saw no
26 obvious damage. The technician checked the power and ground circuits, confirmed the power
27 supply was good, and identified a bad ground wire. The technician repaired the ground wire,
28 retested and verified the CEL was off, and the 2007 Dodge was ready. Christian stated the cost

1 remained the same because the repair done was done with the diagnostic fee. The total invoice
2 amount was \$3,516.73. The operator told Christian he would pick up the 2007 Dodge the
3 following day.

4 35. On or about April 3, 2026, the operator returned to Respondent Romita's facility to
5 retrieve the 2007 Dodge. Christian provided the operator with two invoices. Christian asked the
6 operator to sign an estimate for the additional \$195.00 diagnostic fee that the operator had
7 approved on March 30, 2026. Christian stated that the repairs carried a two-year warranty.
8 Christian provided the operator with an envelope and said that it contained all the operator's
9 paperwork. The operator paid \$3,516.73.

10 36. Bureau representative T.H. subsequently re-inspected the 2007 Dodge. T.H.
11 observed that there were two exhaust system leaks where none had existed before the repairs.
12 T.H. found that Respondent Romita had failed to correctly install the catalytic converter pipes and
13 to secure exhaust system band clamps, and that there was damage to an exhaust flex pipe. The
14 mounting boss threads on the number one ignition coil were damaged which prevented the
15 ignition coil from being properly secured. The engine oil dipstick tube was not properly secured
16 to the right-side exhaust manifold. Proper attachment of the dipstick tube is necessary to ensure
17 correct crankcase sealing and system operation. The Engine Coolant Temperature (ECT) sensor
18 locking retainer had been broken. A foam pad located in the engine valley was missing.

19 37. Furthermore, in reviewing the invoice provided to the operator by Respondent
20 Romita, T.H.'s analysis revealed that Respondent Romita had failed to mention that DTC P0032
21 was stored in the PCM memory. The invoice stated that the check engine light was present for
22 DTC P0035, however this was recorded after Respondent Romita had performed unnecessary
23 engine repairs. Prior to the 2007 Dodge's release, DTC P0035 was not stored in the PCM
24 memory. The invoice stated the engine cylinder # 7 compression tested approximately 20 pounds
25 per square inch (psi) lower than a good cylinder. Respondent Romita did not provide engine
26 compression test results for all cylinders to confirm that cylinder # 7 was outside the
27 manufacturer's specifications and to justify further teardown of the left cylinder head for
28 inspection. Furthermore, the manufacture allowed a maximum of 25% variation between

1 cylinders. Respondent Romita's own test results confirmed that cylinder # 7 compression was
2 within specification, and a teardown of the left cylinder head and replacement of cylinder # 7
3 pushrods were not needed.

4 38. Additionally, T.H. found replacement of the spark plugs, repairs to the cylinder
5 heads, and new pushrods were not needed to correct the introduced malfunction. The invoice
6 stated a Multi Displacement System (MDS) solenoid was replaced, and T.H. found the MDS
7 solenoid on cylinder 1 was replaced. The MDS solenoids were in good working condition, not in
8 need of replacement, and not needed to correct the introduced malfunction. T.H. verified that the
9 left upstream O2 sensor had been replaced. This repair was not mentioned, listed on the invoice,
10 or needed to correct the introduced malfunction. T.H. verified that the ground wire had been
11 repaired as described on the invoice. This was the only repair needed to correct the introduced
12 malfunction. This diagnosis and repair was performed only after Respondent Romita had already
13 completed the unnecessary engine repairs.

14 39. T.H. found that the most serious deficiency was the extensive and unnecessary repairs
15 performed that included removing the cylinder heads, replacing the related parts, and completing
16 related labor – before Respondent Romita correctly diagnosed and repaired the introduced
17 malfunction. The only repair required to repair the 2007 Dodge's illuminated MIL, left upstream
18 O2 sensor heater circuit fault, engine misfire condition, and to restore normal vehicle operation
19 was to properly diagnose and repair the open ground wire for the left upstream O2 sensor heater
20 circuit, followed by clearing the stored DTCs from the PCM memory.

21 40. On or about May 27, 2026, Bureau representative J.B. made a field visit to
22 Respondent Romita's facility and met with Respondent Rodriguez and A.A., his daughter and
23 operations manager. Both identified the technician who worked on the 2007 Dodge as Roberto,
24 but stated he was too busy working on another vehicle to speak with J.B. about the work
25 performed on the 2007 Dodge. J.B. provided Respondent Rodriguez and A.A. with a records
26 request for all records related to the 2007 Dodge. Respondent Rodriguez and Abby agreed to
27 provide the records by May 29, 2026.

28 ///

1 41. On or about May 27, 2026, J.B. made a field visit to Ron's Machine Shop (RMS) and
2 met with S.Y., the owner. S.Y. stated that Respondent Romita sublet the machine work and valve
3 job on the 2007 Dodge. S.Y. stated that Respondent Romita had him perform a valve job to both
4 cylinder heads, checked the heads for cracks, performed a valve grind, and resurfaced the cylinder
5 heads.

6 42. On or about May 28, 2026, J.B. received records from Respondent Rodriguez.
7 Respondent Rodriguez did not provide their copy of the RMS invoice.

8 43. On or about June 2, 2026, J.B. called Respondent Rodriguez to discuss the repairs
9 performed on the 2007 Dodge. Respondent Rodriguez stated that he did not perform the work on
10 the 2007 Dodge but was involved in the testing and had firsthand knowledge of what had been
11 done with the 2007 Dodge.

12 44. J.B. found that Respondent Romita had performed extensive and unnecessary repairs,
13 which included removing both cylinder heads, replacing parts associated with the cylinder head
14 removal, and the extensive labor related to cylinder head removal before properly diagnosing the
15 root cause: an open ground circuit for the left upstream O2 sensor. The only repair needed to
16 resolve all symptoms was correcting the circuit fault and clearing the DTCs from the PCM
17 memory. Respondent Romita also replaced the spark plugs even after the replacement had been
18 declined by the operator. In addition, Respondent Romita placed an O2 sensor and the MDS
19 solenoid without notifying the operator or obtaining authorization. Respondent Romita generated
20 a false and misleading invoice and made false and misleading statements to justify the repairs.

21 45. Additionally, the records provided by Respondent Rodriguez in response to the
22 records request did not match the statements recorded on the records Respondent Romita
23 provided the operator. The operator's invoice reported results of the compression test of a 20-psi
24 variance in comparison to a known good cylinder, but the records Respondent Rodriguez
25 provided showed a variance of about 60-psi. The records Respondent Rodriguez provided
26 showed DTC P0032 was active, but the technician stated DTC P0032 was pending. The
27 introduced malfunction was an active circuit failure in the O2 sensor heater circuit, and it was
28 documented.

46. Bureau representative J.B. determined that Respondent had charged \$3,321.73 for parts and labor that were unnecessary.

FIRST CAUSE FOR DISCIPLINE

(False or Misleading Statements- Respondent Romita)

47. Respondent Romita's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in conjunction with CCR sections 3371 and 3373, in that Respondent Romita made or authorized statements which it knew or in the exercise of reasonable care should have known to be untrue or misleading, as set forth above in paragraphs 21 through 46, above.

SECOND CAUSE FOR DISCIPLINE

(Fraud - Respondent Romita)

48. Respondent Romita's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that Respondent Romita and Respondent Rodriguez fraudulently charged and accepted \$3,321.73 for parts and labor not necessary, as set forth in paragraphs 21 through 46, above.

THIRD CAUSE FOR DISCIPLINE

(Failure to Comply with the Automotive Repair Act - Respondent Romita)

49. Respondent Romita's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that Respondent Romita failed to materially comply with provisions of the Automobile Repair Act regarding the Bureau's 2007 Dodge, as set forth in paragraphs 21 through 46, above, and as follows:

a. **Section 3353.1, subdivision (a)**: Respondent Romita failed to obtain proper authorization from the operator before replacing the spark plugs.

b. **Section 3356, subdivision (c)(1)**: The final invoice did not record all repairs performed, including any diagnosis or warrant repairs, and the prices for each.

c. **Section 3356, subdivision (c)(2)**: The final invoice did not describe the parts supplied as new, used, reconditioned, or rebuilt.

///

1 **FOURTH CAUSE FOR DISCIPLINE**

2 **(Willful Departure from or Disregard of Accepted Trade Standards - Respondent Romita)**

3 50. Respondent Romita's registration is subject to disciplinary action pursuant to Code
4 section 9884.7, subdivision (a)(7), in that it willfully departed from or disregarded accepted trade
5 standards for good and workmanlike repair regarding the 2007 Dodge, as set forth in paragraphs
6 21 through 46, above, and as follows:

7 a. Respondent Romita damaged the mounting boss threads on number one
8 ignition coil which prevented the ignition coil from being properly secured.

9 b. Respondent Romita failed to properly secure the engine oil dipstick to the right-
10 side exhaust manifold.

11 c. Respondent Romita broke the Engine Coolant Temperature (ECT) sensor
12 locking retainer.

13 d. A foam pad located in the engine valley was missing.

14 **FIFTH CAUSE FOR DISCIPLINE**

15 **(Failure to Comply with Invoice Requirements - Respondent Romita)**

16 51. Respondent Romita's registration is subject to disciplinary action pursuant to Code
17 section 9884.8, in that it failed to comply with invoice requirements regarding the 2007 Dodge, as
18 set forth in paragraphs 21 through 46, above, and as follows:

19 a. Respondent Romita replaced an O2 Sensor without authorization and neither of
20 Respondent Romita's invoices documented this component or authorization.

21 b. Respondent Romita replaced the MDS solenoid without authorization.
22 Respondent Romita's invoice showed the authorization to replace the MDS solenoid was given
23 on March 10, 2026, when, in fact, authorization was not given.

24 **SIXTH CAUSE FOR DISCIPLINE**

25 **(Failure to Comply with Estimate and Authorization Requirements - Respondent Romita)**

26 52. Respondent Romita's registration is subject to disciplinary action pursuant to Code
27 section 9884.9, subdivision (a), in conjunction with CCR section 3354, subdivision (a)(2),
28 regarding estimate and authorization requirements when Respondent Romita failed to comply

1 with estimate and authorization requirements regarding the 2007 Dodge, as set forth in
2 paragraphs 21 through 46, above, and as follows:

3 a. Respondent Romita replaced an O2 Sensor without authorization and neither of
4 Respondent Romita's invoices documented this component or authorization.

5 b. Respondent Romita replaced the MDS solenoid without authorization.
6 Respondent Romita's invoice showed the authorization to replace the MDS solenoid was given
7 on March 10, 2026, when, in fact, authorization was not given.

8 c. Respondent Romita stated the spark plugs were in the original estimate and
9 were replaced after the operator declined this repair.

10 **SEVENTH CAUSE FOR DISCIPLINE**

11 **(Failure to Produce Maintenance and Repair Records - Respondent Romita)**

12 53. Respondent Romita's registration is subject to disciplinary action pursuant to Code
13 section 9884.11, in conjunction with CCR section 3358, subdivision (a), in that Respondent
14 Romita failed to provide a copy of the RMS invoice, as set forth in paragraph 42, above.

15 **EIGHTH CAUSE FOR DISCIPLINE**

16 **(Dishonesty, Fraud, Deceit - Respondent Romita)**

17 54. Respondent Romita's license is subject to disciplinary action pursuant to Health &
18 Saf. Code section 44072.2, subdivision (d), in that Respondent Romita and Respondent
19 Rodriguez committed dishonest, fraudulent, or deceitful acts whereby another was injured when it
20 charged and accepted \$3,321.73 for parts and labor not necessary, as set forth in paragraphs 21
21 through 46, above.

22 **NINTH CAUSE FOR DISCIPLINE**

23 **(Failure to Comply with Provisions of the Automotive Repair Act – Respondent Romita)**

24 55. Respondent Romita's registration is subject to disciplinary action pursuant to Code
25 section 9884.7, subdivision (a)(6), as set forth in paragraph 57, below, and when Respondent
26 continued to violate provisions of the Automotive Repair Act, as set forth in paragraphs 21
27 through 54, above, despite participating in a Proactive Conference and Office Conference where
28 Respondent Romita and Respondent Rodriguez were advised that compliance was necessary.

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28

2

3
4
5
6
7

8

9
10

11
12
13
14
15
16

17
18
19
20
21
22
23

24

25
26
27
28

59. Pursuant to Health and Safety Code section 44072.8, if Smog Check, Test-and-Repair, Station License Number RC 298711, issued to Romita Automotive Service LLC, doing business as Romita Auto Service, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the director.

60. Pursuant to Health and Safety Code section 44072.8, if Smog Check Inspector License No. EO 154541 and Smog Check Repair Technician License No. EI 154541, issued to Nestor Anguiano Rodriguez, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the director.

PRAYER

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of the Department of Consumer Affairs issue a decision:

1. Revoking or suspending Automotive Repair Dealer Registration Number ARD 298711, issued to Romita Automotive Service LLC, doing business as Romita Auto Service, with Nestor Anguiano Rodriguez and Maria Ramirez Gonzalez as members;

2. Revoking or suspending Smog Check, Test-and-Repair, Station License Number RC 298711, issued to Romita Automotive Service LLC, doing business as Romita Auto Service, with Nestor Anguiano Rodriguez and Maria Ramirez Gonzalez as members;

3. Revoking or suspending any other automotive repair dealer registration issued to Romita Automotive Service LLC, doing business as Romita Auto Service;

4. Revoking or suspending any other automotive repair dealer registration or license issued to Nestor Anguiano Rodriguez;

5. Revoking or suspending any other automotive repair dealer registration or license issued to Maria Ramirez Gonzalez.

6. Revoking or suspending Smog Check Inspector License Number EO 154541, issued to Nestor Anguiano Rodriguez;

7. Revoking or suspending Smog Check Repair Technician License Number EI 154541,
issued to Nestor Anguiano Rodriguez;

1 8. Revoking or suspending any additional licenses issued under chapter 5 of part 5 of
2 division 26 of the Health and Safety Code in the name of Nestor Anguiano Rodriguez;

3 9. Ordering Romita Automotive Service LLC, doing business as Romita Auto Service;
4 Nestor Anguiano Rodriguez; and Maria Ramirez Gonzalez to pay the Bureau of Automotive
5 Repair the reasonable costs of the investigation and enforcement of this case, pursuant to
6 Business and Professions Code section 125.3 and if placed on probation, the costs of probation
7 monitoring; and,

8 10. Taking such other and further action as deemed necessary and proper.

9
10 DATED: As of Digital Signature Date

Dorais,

Patrick@DCA

Digitally signed by Dorais,
Patrick@DCA

Date: 2026.09.10 15:38:33
-07'00'

PATRICK DORAIS

Chief

Bureau of Automotive Repair

Department of Consumer Affairs

State of California

Complainant

11
12
13
14
15 SA2026303634
16 45261148.docx
17
18
19
20
21
22
23
24
25
26
27
28