BEFORE THE DIRECTOR OF CONSUMER AFFAIRS BUREAU OF AUTOMOTIVE REPAIR STATE OF CALIFORNIA

In the Matter of the Accusation Against:

CHEVREM CORPORATION, DBA CLEAR BLUE TEST ONLY SMOG STATION

2850 Crow Canyon Road San Ramon, California 94583 FATIH TEKIN, PRESIDENT Automotive Repair Dealer Registration No. ARD 241700 Smog Check, Test Only Station License No. TC 241700,

HARPREET SINGH CHHINA

2680 Cherry Blossom Way Union City, California 94587 Advanced Emission Specialist Technician License No. EA 152180

CHEVREM CORPORATION, DBA CLEAR BLUE TEST ONLY SMOG STATION 2

3790 Hopyard Road Pleasanton, California 94588 FATIH TEKIN, PRESIDENT Automotive Repair Dealer Registration No. ARD 244942 Smog Check, Test Only Station License No. TC 244942,

CHRISTOPHER BRYAN HARRISON

143 Roxanne Court, #2 Walnut Creek, California 94597 Advanced Emission Specialist Technician License No. EA 151176

CHEVREM CORPORATION, DBA CLEAR BLUE TEST ONLY SMOG STATION 3

898 A Street
Hayward, California 94541
FATIH TEKIN, PRESIDENT
Automotive Repair Dealer Registration
No. ARD 248804
Smog Check Test Only Station License
No. TC 248804

Case No. 79/09-21

DECISION AND ORDER

[as to FATIH TEKIN and associated licenses only]

WINCHESTER SIBUMA ORDONEZ

2210 Grove Way Castro Valley, California 94546 Advanced Emission Specialist Technician License No. EA 144440

CHEVREM CORPORATION, DBA TEST ONLY SMOG STATION II

5200 Telegraph Avenue Oakland, California 94609 FATIH TEKIN, PRESIDENT Automotive Repair Dealer Registration No. ARD 236306 Smog Check, Test Only Station No. TC 236306

BRYON LEONARD SCHAUB

46410 Briarplace Fremont, California 94539 Advanced Emission Specialist Technician License No. EA 152893

NUSRET B. TOPCU

2427 Byron Street Berkeley, California 94702 Advanced Emission Specialist Technician License No. EA 147911

MATTHEW JARED PHELPS

916 Magnolia Drive Alameda, California 94502 Advanced Emission Specialist Technician License No. EA 151026

CHEVREM CORPORATION, DBA G I C SMOG STATION

690 Ygnacio Valley Road, #3 Walnut Creek, California 94596 FATIH TEKIN, PRESIDENT Automotive Repair Dealer Registration No. ARD 221700 Smog Check, Test Only Station License No. TC 221700

NUSRET B. TOPCU

2427 Byron Street
Berkeley, California 94702
Advanced Emission Specialist Technician
License No. EA 147911

Respondents.

The attached Stipulated Settlement and Disciplinary Order (as to FAITH TEKIN and associated licenses only] is hereby accepted and adopted as the Decision of the Director of the Department of Consumer Affairs in the above-entitled matter only as to respondent Chevrem Corporation, Fatih Tekin, President, relating to the following licenses:

dba Clear Blue Test Only Smog Station Automotive Repair Dealer Registration No. ARD 241700 Smog Check Test Only Station License No. TC 241700

dba Clear Blue Test Only Smog Station 2 Automotive Repair Dealer Registration No. ARD 244942 Smog Check Test Only Station License No. TC 244942

dba Clear Blue Test Only Smog Station 3 Automotive Repair Dealer Registration No. ARD 248804 Smog Check Test Only Station License No. TC 248804

dba Test Only Smog Station II Automotive Repair Dealer Registration No. ARD 236306 Smog Check Test Only Station License No. TC 236306

dba GIC Smog Station Automotive Repair Dealer Registration No. ARD 221700 Smog Check Test Only Station License No. TC 221700

The registrations/licenses shall be suspended as follows:

License No.	Suspension
Automotive Repair Dealer Registration No. ARD 241700	10 days
Smog Check Test Only Station License No. TC 241700	10 days
Automotive Repair Dealer Registration No. ARD 244942	5 days
Smog Check Test Only Station License No. TC 244942	5 days
Automotive Repair Dealer Registration No. ARD 248804	10 days
Smog Check Test Only Station License No. TC 248804	10 days
Automotive Repair Dealer Registration No. ARD 236306	10 days
Smog Check Test Only Station License No. TC 226306	10 days
Automotive Repair Dealer Registration No. ARD 221700	45 days
Smog Check Test Only Station License No. TC 221700	45 days

The suspension of the above registrations/licenses shall commence on the effective date of this Decision.

This Decision shall become effective	4/6/09
DATED: February 27, 2009	PATRICIA HARRIS Deputy Director, Board/Bureau Support Department of Consumer Affairs

1	EDMUND G. BROWN JR., Attorney General	
2	of the State of California WILBERT E. BENNETT	
3	Supervising Deputy Attorney General KIM M. SETTLES, State Bar No. 116945	
4	Deputy Attorney General 1515 Clay Street, 20 th Floor	
5	P.O. Box 70550 Oakland, CA 94612-0550	
6	Telephone: (510) 622-2138 Facsimile: (510) 622-2270	
7	Attorneys for Complainant	
8	BEFORE THE	
9	DEPARTMENT OF CONSUMER AFFAIRS FOR THE BUREAU OF AUTOMOTIVE REPAIR	
10	STATE OF CAL	IFORNIA
11	In the Matter of the Accusation Against:	Case No. 79/09-21
12	CHEVREM CORPORATION, DBA	CONTROL A PRED CEREBU ERAFRAGI AND
13	CLEAR BLUE TEST ONLY SMOG STATION	STIPULATED SETTLEMENT AND DISCIPLINARY ORDER
14	2850 Crow Canyon Road San Ramon, California 94583	
15	FATIH TEKIN, PRESIDENT Automotive Repair Dealer Registration	[as to FATIH TEKIN and associated
16	No. ARD 241700 Smog Check, Test Only Station License	licenses only]
17	No. TC 241700,	
18		
19	Union City, California 94587 Advanced Emission Specialist Technician	
20	License No. EA 152180	
21	CHEVREM CORPORATION, DBA CLEAR BLUE TEST ONLY SMOG	
22	STATION 2 3790 Hopyard Road	
23	Pleasanton, California 94588 FATIH TEKIN, PRESIDENT	
24	Automotive Repair Dealer Registration No. ARD 244942	
25	Smog Check, Test Only Station License No. TC 244942,	
26	CHRISTOPHER BRYAN HARRISON	
27	143 Roxanne Court, #2 Walnut Creek, California 94597	
28	Advanced Emission Specialist Technician License No. EA 151176	
ļ		

1	CHEVREM CORPORATION, DBA CLEAR BLUE TEST ONLY SMOG
2	STATION 3
3	898 A Street Hayward, California 94541
	FATIH TEKIN, PRESIDENT
4	Automotive Repair Dealer Registration No. ARD 248804
5	Smog Check Test Only Station License
6	No. TC 248804
j	WINCHESTER SIBUMA ORDONEZ
7	2210 Grove Way
8	Castro Valley, Čalifornia 94546 Advanced Emission Specialist Technician
	License No. EA 144440
9	CHEVREM CORPORATION, DBA
10	TEST ONLY SMOG STATION II
, ,	5200 Telegraph Avenue
11	Oakland, California 94609 FATIH TEKIN, PRESIDENT
12	Automotive Repair Dealer Registration
13	No. ARD 236306 Smog Check, Test Only Station
נו	No. TC 236306
14	PRIVANT FONT PROGRAMS
15	BRYON LEONARD SCHAUB 46410 Briarplace
`	Fremont, California 94539
16	Advanced Emission Specialist Technician License No. EA 152893
17	License No. EA 132873
10	NUSRET B. TOPCU
18	2427 Byron Street Berkeley, California 94702
19	Advanced Emission Specialist Technician
20	License No. EA 147911
	MATTHEW JARED PHELPS
21	916 Magnolia Drive
22	Alameda, California 94502 Advanced Emission Specialist Technician
	License No. EA 151026
23	CHEVREM CORPORATION, DBA
24	G I C SMOG STATION
25	690 Ygnacio Valley Road, #3 Walnut Creek, California 94596
	FATIH TEKIN, PRESIDENT
26	Automotive Repair Dealer Registration No. ARD 221700
27	Smog Check, Test Only Station License
30	No. TC 221700
, .	I 111

1	NUSRET B. TOPCU
2	2427 Byron Street Berkeley, California 94702
3	Advanced Emission Specialist Technician License No. EA 147911
4	Respondents.
5	
6	IT IS HEREBY STIPULATED AND AGREED by and between the parties to the
7	above-entitled proceedings that the following matters are true:
8	<u>PARTIES</u>
9	1. Sherry Mehl (Complainant) is the Chief of the Bureau of Automotive
10	Repair. She brought this action solely in his official capacity and is represented in this matter by
11	Edmund G. Brown Jr., Attorney General of the State of California, by Kim M. Settles, Deputy
12	Attorney General.
13	2. Respondent, FATIH TEKIN (Respondent) is represented by Merrill
14	Schwartz, whose address is 1999 Harrison Street, Suite 1520, Oakland, CA 94612-4703.
15	LICENSE HISTORY
16	RESPONDENT NO. 1
17	Automotive Repair Dealer Registration
18	3. On or about February 3, 2006, the Bureau issued Automotive Repair
19	Dealer Registration Number ARD 241700 ("registration") to CHEVREM CORPORATION,
20	doing business as CLEAR BLUE TEST ONLY SMOG STATION ("Respondent No. 1") with
21	FATIH TEKIN as president. The registration will expire on September 30, 2008, unless
22	renewed.
23	Smog Check, Test Only Station License
24	4. On or about February 16, 2006, the Bureau issued SMOG CHECK, TEST
25	ONLY STATION License Number TC 241700 to Respondent No. 1. The registration will expire
26	on September 30, 2008, unless renewed.
27	· · · · · · · · · · · · · · · · · · ·
28	

1	Advanced Emission Specialist Technician License
2	5. On or about December 21, 2006, the Bureau issued Advanced Emission
3	Specialist Technician License Number EA 152180 ("technician license") to HARPREET SINGF
4	CHHINA ("Respondent CHHINA"). The technician license will expire on June 30, 2010, unless
5	renewed.
6	RESPONDENT NO. 2
7	Automotive Repair Dealer Registration
8	6. On or about July 11, 2006, the Bureau issued Automotive Repair Dealer
9	Registration Number ARD 244942 ("registration") to CHEVREM CORPORATION, doing
10	business as CLEAR BLUE TEST ONLY SMOG STATION 2 ("Respondent No. 2") with FATII
11	TEKIN as president. The registration will expire on April 30, 2009, unless renewed.
ا 2	Smog Check, Test Only Station License
13	7. On or about November 20, 2006, the Bureau issued SMOG CHECK,
ا 4	TEST ONLY STATION License Number TC 244942 ("station license") to Respondent No. 2.
15	The registration will expire on April 30, 2009, unless renewed.
16	Advanced Emission Specialist Technician License
ا 17	8. On or about March 23, 2005, the Bureau issued Advanced Emission
18	Specialist Technician License Number EA 151176 ("technician license") to CHRISTOPHER
19	BRYAN HARRISON ("Respondent HARRISON"). The technician license will expire on
20	July 31, 2009, unless renewed.
21	RESPONDENT NO. 3
22	Automotive Repair Dealer Registration
23	9. On or about February 14, 2007, the Bureau issued Automotive Repair
24	Dealer Registration Number ARD 248804 ("registration") to CHEVREM CORPORATION,
25	doing business as CLEAR BLUE TEST ONLY SMOG STATION 3 ("Respondent No. 3") with
26	FATIH TEKIN as president. The registration will expire on January 31, 2009, unless renewed.
!	

TOPCU ("Respondent Topcu"). The technician license expired on October 31, 2007.

1 **Advanced Emission Specialist Technician License** 2 16. On or about February 18, 2005, the Bureau issued Advanced Emission 3 Specialist Technician License Number EA 151026 ("technician license") to MATTHEW JARED 4 PHELPS ("Respondent PHELPS"). The technician license will expire on December 31, 2008, 5 unless renewed. 6 **RESPONDENT NO. 5** 7 **Automotive Repair Dealer Registration** 8 17. On or about June 12, 2002, the Bureau issued Automotive Repair Dealer 9 Registration Number ARD 221700 ("registration") to CHEVREM CORPORATION, doing 10 business as G I C SMOG STATION ("Respondent No. 5") with FATIH TEKIN as president. 11 The registration will expire on May 31, 2009, unless renewed. 12 Smog Check, Test Only Station License 13 18. On or about June 21, 2002, the Bureau issued SMOG CHECK, TEST 14 ONLY STATION License Number TC 221700 ("station license") to Respondent No. 5. The 15 station license will expire on May 31, 2009, unless renewed. 16 Advanced Emission Specialist Technician License 17 19. On or about November 26, 2003, the Bureau issued Advanced Emission 18 Specialist Technician License Number EA 147911 ("technician license") to NUSRET B. TOPCU ("Respondent TOPCU"). The technician license will expire on October 31, 2008, 19 20 unless renewed. 21 **JURISDICTION** 22 20. Accusation No. 79/09-21 was filed before the Department of Consumer 23 Affairs (Director), for the Bureau of Automotive Repair (Bureau), and is currently pending 24 against Respondent. The Accusation and all other statutorily required documents were properly

28 //

incorporated herein by reference.

25

26

27

served on Respondent on September 24, 2008. Respondent timely filed his Notice of Defense

contesting the Accusation. A copy of Accusation No. 79/09-21 is attached as Exhibit A and

ADVISEMENT AND WAIVERS

- 21. Respondent has carefully read, and understands the charges and allegations in Accusation No. 79/09-21. Respondent has also carefully read, and understands the effects of this Stipulated Settlement and Disciplinary Order.
- 22. Respondent is fully aware of his legal rights in this matter, including the right to a hearing on the charges and allegations in the Accusation; the right to be represented by counsel at his own expense; the right to confront and cross-examine the witnesses against him; the right to present evidence and to testify on his own behalf; the right to the issuance of subpoenas to compel the attendance of witnesses and the production of documents; the right to reconsideration and court review of an adverse decision; and all other rights accorded by the California Administrative Procedure Act and other applicable laws.
- 23. Respondent voluntarily, knowingly, and intelligently waives and gives up each and every right set forth above.

CULPABILITY

- 24. Respondent admits the truth of every charge and allegation contained in Accusation No. 79/09-21.
- Respondent agrees that his Automotive Repair Dealer Registration

 Number ARD 241700, Smog Check Station License Number TC 241700, Automotive Repair

 Dealer Registration Number ARD 244942, Smog Check Station License Number TC 244942,

 Automotive Repair Dealer Registration Number 248804, Smog Check Station License Number

 TC 248804, Automotive Repair Dealer Registration Number ARD 236306, Smog Check Station

 License Number TC 236306, Automotive Repair Dealer Registration Number ARD 221700, and

 Smog Check Station License TC 221700, are subject to discipline and he agrees to be bound by

 the Director's imposition of discipline as set forth in the Disciplinary Order below.

CONTINGENCY

26. The parties understand and agree that facsimile copies of this Stipulated Settlement and Disciplinary Order, including facsimile signatures thereto, shall have the same force and effect as the originals.

۰.

- 28. The parties hereto stipulate that in the event that this Stipulated Settlement is not adopted by the Director, nothing herein recited shall be construed as a waiver of Respondent's right to a hearing or as an admission of the truth of any of the matters charged in the Accusation.
- 29. The parties acknowledge that based on the foregoing recitals, IT IS
 HEREBY STIPULATED AND AGREED that the Director of Consumer Affairs may issue the
 following Disciplinary Order:

DISCIPLINARY ORDER

IT IS HEREBY ORDERED that Automotive Repair Dealer Registration Number ARD 241700 and Smog Check Station License Number TC 241700 issued to Respondent FATIH TEKIN are revoked. However, the Automotive Repair Dealer Registration and Smog Check Station License revocations are stayed and Respondent is placed on probation for five (5) years on the following terms and conditions.

IT IS FURTHER ORDERED that Automotive Repair Dealer Registration

Number ARD 244942 and Smog Check Station License Number TC 244942 issued to

Respondent FATIH TEKIN are revoked. However, the Automotive Repair Dealer Registration

and Smog Check Station License revocations are stayed and Respondent is placed on probation

for five (5) years on the following terms and conditions.

IT IS FURTHER ORDERED that Automotive Repair Dealer Registration

Number ARD 248804 and Smog Check Station License Number TC 248804 issued to

Respondent FATIH TEKIN are revoked. However, the Automotive Repair Dealer Registration and Smog Check Station License revocations are stayed and Respondent is placed on probation for five (5) years on the following terms and conditions.

IT IS FURTHER ORDERED that Automotive Repair Dealer Registration

Number ARD 236306 and Smog Check Station License Number TC 236306 issued to

Respondent FATIH TEKIN are revoked. However, the Automotive Repair Dealer Registration and Smog Check Station License revocations are stayed and Respondent is placed on probation for five (5) years on the following terms and conditions.

IT IS FURTHER ORDERED that Automotive Repair Dealer Registration

Number ARD 221700 and Smog Check Station License Number TC 221700 issued to

Respondent FATIH TEKIN are revoked. However, the Automotive Repair Dealer Registration
and Smog Check Station License revocations are stayed and Respondent is placed on probation
for five (5) years on the following terms and conditions.

1. Actual Suspension. ARD Registration Number ARD 241700 and Smog Check Station License Number TC 241700 issued to Respondent, FATIH TEKIN, Owner, CHEVREM CORPORATION, d.b.a. CLEAR BLUE TEST ONLY SMOG STATION is suspended for ten (10) days.

ARD Registration Number 244942 and Smog Check Station License Number TC 244942 issued to Respondent, FATIH TEKIN, Owner, CHEVREM CORPORATION, d.b.a. CLEAR BLUE TEST ONLY SMOG STATION 2 is suspended for five (5) days.

ARD Registration Number 244804 and Smog Check Station License Number TC 248804 issued to Respondent, FATIH TEKIN, Owner, CHEVREM CORPORATION, d.b.a. CLEAR BLUE TEST ONLY SMOG STATION 3, issued to Respondent, FATIH TEKIN, Owner, CHEVREM CORPORATION, d.b.a. CLEAR BLUE TEST ONLY SMOG STATION 3 is suspended for ten (10) days.

ARD Registration Number ARD 236306 and Smog Check Station License Number TC 236306 issued to Respondent, FATIH TEKIN, Owner, CHEVREM CORPORATION, d.b.a. TEST ONLY SMOG STATION II is suspended for ten (10) days.

ARD Registration Number ARD 221700 and Smog Check Station License Number TC 221700 issued to Respondent, FATIH TEKIN, Owner, CHEVREM CORPORATION, d.b.a. GIC SMOG STATION is suspended for forty-five (45) days.

- 2. **Obey All Laws.** Comply with all statutes, regulations and rules governing automotive inspections, estimates and repairs.
- 3. **Post Sign.** Post a prominent sign, provided by the Bureau, indicating the beginning and ending dates of the above-referenced suspensions and indicating the reason for the suspension. The sign shall be conspicuously displayed in a location open to and frequented by customers and shall remain posted during the entire period of actual suspension.
- 4. **Reporting.** Respondent or Respondent's authorized representative must report in person or in writing as prescribed by the Bureau of Automotive Repair, on a schedule set by the Bureau, but no more frequently than each quarter, on the methods used and success achieved in maintaining compliance with the terms and conditions of probation.
- 5. **Report Financial Interest.** Within thirty (30) days of the effective date of this action, report any financial interest which any partners, officers, or owners of the Respondent facility may have in any other business required to be registered pursuant to Business and Professions Code section 9884.6.
- 6. **Jurisdiction.** If an accusation and/or petition to revoke probation is filed against Respondent during the term of probation, the Director of Consumer Affairs shall have continuing jurisdiction over this matter until the final decision on the accusation and/or petition to revoke probation, and the period of probation shall be extended until such decision.
- 7. **Violation of Probation.** Should the Director of Consumer Affairs determine that Respondent has failed to comply with the terms and conditions of probation, the Director may, after giving notice and opportunity to be heard, suspend or revoke Respondent's licenses.

1	8. Cost Recovery. Payment to the Bureau of the full amount of cost
2	recovery in the amount of \$25,000.00 shall be received no later that six (6) months of the
3	effective date of this decision. Failure to complete payment of cost recovery within this time
4	frame shall constitute a violation of probation which may subject Respondent's above-referenced
5	ARD Registrations and Smog Check Station Licenses to outright revocation; however, the
6	Director or the Director's Bureau of Automotive Repair designee may elect to continue probation
7	until such time as reimbursement of the entire cost recovery amount has been made to the
8	Bureau.
9	<u>ACCEPTANCE</u>
10	I have carefully read the Stipulated Settlement and Disciplinary Order. I
11	understand the stipulation and the effect it will have on my Automotive Repair Dealer
12	Registrations and Smog Check Station Licenses. I enter into this Stipulated Settlement and
13	Disciplinary Order voluntarily, knowingly, and intelligently, and agree to be bound by the
14	Decision and Order of the Director of Consumer Affairs.
15	DATED: 1.27.2009.
16	EATH TEKINUM CUM
17	Respondent
18	
19	I have read and fully discussed with Respondent FATIH TEKIN the terms and
20	conditions and other matters contained in the above Stipulated Settlement and Disciplinary
21	Order. I approve of its form.
22	DATED: 1-27-09
23	MERRILL SCHWARTZ, ESO.
24	Attorney for Respondent
25	
26	

1	ENDORSEMENT
2	The foregoing Stipulated Settlement and Disciplinary Order is hereby respectfully
3	submitted for consideration by the Director of Consumer Affairs.
4	
5	DATED: 1/28/09
6	EDMUND G. BROWN JR., Attorney General of the State of California
7	WILBERT E. BENNETT
8	Supervising Deputy Attorney General
9	
10	KIM M. Settles KIM M. SETTLES
11	Deputy Attorney General Attorneys for Complainant
12	Attorneys for Complamant
13	
14	03562110SF2008400135
15	90103830.wpd
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	

Exhibit A

Accusation No. 79/09-21

	· · · · · · · · · · · · · · · · · · ·	
1	EDMUND G. BROWN JR., Attorney General	
•	of the State of California WILBERT E. BENNETT	
2	Supervising Deputy Attorney General	
3	KIM M. SETTLES, State Bar No. 116945	•
	Deputy Attorney General	
4	1515 Clay Street, 20th Floor P.O. Box 70550	
5	Oakland, CA 94612-0550	
_3.	Telephone: (510) 622-2138	
6	Facsimile: (510) 622-2270	
7	Attorneys for Complainant	
8	BEFORE '	
	DEPARTMENT OF CON FOR THE BUREAU OF AU	
9	STATE OF CAL	
10		
	To the Method of the Acquestion Against	Case No. 79/09 21
11.	In the Matter of the Accusation Against:	Case No. 75755
12	CHEVREM CORPORATION, DBA	
10	CLEAR BLUE TEST ONLY SMOG	ACCUSATION
13	STATION 2850 Crow Canyon Road	[SMOG CHECK]
14	San Ramon, California 94583	
	FATIH TEKIN, PRESIDENT	
15	Automotive Repair Dealer Registration No. ARD 241700	
16	Smog Check, Test Only Station License	
	["] No. TC 241700,	
17	HARPREET SINGH CHHINA	
18	2680 Cherry Blossom Way	
·	Union City, California 94587	
19	Advanced Emission Specialist Technician	
20	License No. EA 152180	
	CHEVREM CORPORATION, DBA	
21	CLEAR BLUE TEST ONLY SMOG	
22	STATION 2 3790 Hopyard Road	
	Pleasanton, California 94588	
23	FATIH TEKIN, PRESIDENT	
- 24	Automotive Repair Dealer Registration No. ARD 244942	
- 27	Smog Check, Test Only Station License	
25	No. TC 244942,	
26	CHDICTODHED DOVAN HADDICON	
26	CHRISTOPHER BRYAN HARRISON 143 Roxanne Court, #2	
27	Walnut Creek, California 94597	
00	Advanced Emission Specialist Technician	
28	License No. EA 151176	

	,
1	CHEVREM CORPORATION, DBA CLEAR BLUE TEST ONLY SMOG
2	STATION 3 898 A Street
3	Hayward, California 94541
4	FATIH TEKIN, PRESIDENT Automotive Repair Dealer Registration
5	No. ARD 248804 Smog Check Test Only Station License
6	No. TC 248804
7	WINCHESTER SIBUMA ORDONEZ 2210 Grove Way
8	Castro Valley, California 94546 Advanced Emission Specialist Technician
9	License No. EA 144440
	CHEVREM CORPORATION, DBA TEST ONLY SMOG STATION II
10	5200 Telegraph Avenue
11	Oakland, California 94609 FATIH TEKIN, PRESIDENT
12	Automotive Repair Dealer Registration No. ARD 236306
13	Smog Check, Test Only Station No. TC 236306
14	BRYON LEONARD SCHAUB
15	46410 Briarplace Fremont, California 94539
16	Advanced Emission Specialist Technician License No. EA 152893
17	NUSRET B. TOPCU
18	2427 Byron Street
19	Berkeley, California 94702 Advanced Emission Specialist Technician
20	License No. EA 147911
21	MATTHEW JARED PHELPS 916 Magnolia Drive
22	Alameda, California 94502 Advanced Emission Specialist Technician
23	License No. EA 151026
24	CHEVREM CORPORATION, DBA G I C SMOG STATION
25	690 Ygnacio Valley Road, #3
	Walnut Creek, California 94596 FATIH TEKIN, PRESIDENT
26	Automotive Repair Dealer Registration No. ARD 221700
27	Smog Check, Test Only Station License No. TC 221700
28	///

1	NUSRET B. TOPCU 2427 Byron Street
2	Berkeley, California 94702 Advanced Emission Specialist Technician
3	License No. EA 147911
4	Respondents.
5	
6	Sherry Mehl ("Complainant") alleges:
7	<u>PARTIES</u>
.8	1. Complainant brings this Accusation solely in her official capacity as the
9	Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer Affairs.
10	<u>LICENSE HISTORY</u>
11	RESPONDENT NO. 1
12	Automotive Repair Dealer Registration
13	2. On or about February 3, 2006, the Bureau issued Automotive Repair
14	Dealer Registration Number ARD 241700 ("registration") to Chevrem Corporation, doing
15	business as Clear Blue Test Only Smog Station ("Respondent No. 1") with Fatih Tekin as
16	president. The registration will expire on September 30, 2008, unless renewed.
17	Smog Check, Test Only Station License
18	3. On or about February 16, 2006, the Bureau issued Smog Check, Test Only
19	Station License Number TC 241700 to Respondent No. 1. The registration will expire on
20	September 30, 2008, unless renewed.
21	Advanced Emission Specialist Technician License
22	4. On or about December 21, 2006, the Bureau issued Advanced Emission
23	Specialist Technician License Number EA 152180 ("technician license") to Harpreet Singh
24	Chhina ("Respondent Chhina"). The technician license will expire on June 30, 2010, unless
25	renewed.
26	///
27	///
28	

RESPONDENT NO. 2 Automotive Repair Dealer Registration

5. On or about July 11, 2006, the Bureau issued Automotive Repair Dealer Registration Number ARD 244942 ("registration") to Chevrem Corporation, doing business as Clear Blue Test Only Smog Station 2 ("Respondent No. 2") with Fatih Tekin as president. The registration will expire on April 30, 2009, unless renewed.

Smog Check, Test Only Station License

6. On or about November 20, 2006, the Bureau issued Smog Check, Test Only Station License Number TC 244942 ("station license") to Respondent No. 2. The registration will expire on April 30, 2009, unless renewed.

Advanced Emission Specialist Technician License

7. On or about March 23, 2005, the Bureau issued Advanced Emission Specialist Technician License Number EA 151176 ("technician license") to Christopher Bryan Harrison ("Respondent Harrison"). The technician license will expire on July 31, 2009, unless renewed.

RESPONDENT NO. 3

Automotive Repair Dealer Registration

8. On or about February 14, 2007, the Bureau issued Automotive Repair Dealer Registration Number ARD 248804 ("registration") to Chevrem Corporation, doing business as Clear Blue Test Only Smog Station 3 ("Respondent No. 3") with Fatih Tekin as president. The registration will expire on January 31, 2009, unless renewed.

Smog Check, Test Only Station License

9. On or about March 2, 2007, the Bureau issued Smog Check, Test Only Station License Number TC 248804 to Respondent No. 3. The station license will expire on January 31, 2009, unless renewed.

Advanced Emission Specialist Technician License

10. On or about May 13, 2002, the Bureau issued Advanced Emission

Specialist Technician License Number EA 144440 ("technician license") to Winchester Sibuma

Ordonez ("Respondent Ordonez"). The technician license will expire on October 31, 2010
unless renewed.
RESPONDENT NO. 4
Automotive Repair Dealer Registration
11. On or about February 9, 2005, the Bureau issued Automotive Repair
Dealer Registration Number ARD 236306 ("registration") to Chevrem Corporation, doing
business as Test Only Smog Station II ("Respondent No. 4") with Fatih Tekin as president. The
registration will expire on October 31, 2008, unless renewed.
Smog Check, Test Only Station License
12. On or about February 14, 2005, the Bureau issued Smog Check, Test Only
Station License Number TC 236306 ("station license") to Respondent No. 4. The station license
will expire on October 31, 2008, unless renewed.
Advanced Emission Specialist Technician License
13. On or about July 7, 2006, the Bureau issued Advanced Emission Specialist
Technician License Number EA 152893 ("technician license") to Bryan Leonard Schaub
("Respondent Schaub"). The technician license will expire on September 30, 2010, unless
renewed.
Advanced Emission Specialist Technician License
14. On or about November 26, 2003, the Bureau issued Advanced Emission
Specialist Technician License Number EA 147911 ("technician license") to Nusret B. Topcu
("Respondent Topcu"). The technician license expired on October 31, 2007.
Advanced Emission Specialist Technician License
15. On or about February 18, 2005, the Bureau issued Advanced Emission
Specialist Technician License Number EA 151026 ("technician license") to Matthew Jared
Phelps ("Respondent Phelps"). The technician license will expire on December 31, 2008, unless
renewed.
///
///

RESPONDENT NO. 5 Automotive Repair Dealer Registration

16. On or about June 12, 2002, the Bureau issued Automotive Repair Dealer Registration Number ARD 221700 ("registration") to Chevrem Corporation, doing business as GIC Smog Station ("Respondent No. 5") with Fatih Tekin as president. The registration will expire on May 31, 2009, unless renewed.

Smog Check, Test Only Station License

On or about June 21, 2002, the Bureau issued Smog Check, Test Only 17. Station License Number TC 221700 ("station license") to Respondent No. 5. The station license will expire on May 31, 2009, unless renewed.

Advanced Emission Specialist Technician License

On or about November 26, 2003, the Bureau issued Advanced Emission 18. Specialist Technician License Number EA 147911 ("technician license") to Nusret B. Topcu ("Respondent Topcu"). The technician license will expire on October 31, 2008, unless renewed.

STATUTORY PROVISIONS

- 19. Section 9884.7 of the Business and Professions Code ("Code") states, in pertinent part:
 - (a) The director, where the automotive repair dealer cannot show there was a bona fide error, may refuse to validate, or may invalidate temporarily or permanently, the registration of an automotive repair dealer for any of the following acts or omissions related to the conduct of the business of the automotive repair dealer, which are done by the automotive repair dealer or any automotive technician, employee, partner, officer, or member of the automotive repair dealer.
 - (1) Making or authorizing in any manner or by any means whatever any statement written or oral which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading.
 - (2) Causing or allowing a customer to sign any work order that does not state the repairs requested by the customer or the automobile's odometer reading at the time of repair.
 - (3) Failing or refusing to give to a customer a copy of any document requiring his or her signature, as soon as the customer signs the document.
 - (4) Any other conduct which constitutes fraud.

27

28

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

- (6) Failure in any material respect to comply with the provisions of this chapter [the Automotive Repair Act (Bus. & Prof. Code, 9880, et seq.)] or regulations adopted pursuant to it.
- (b) Except as provided for in subdivision (c), if an automotive repair dealer operates more than one place of business in this state, the director pursuant to subdivision (a) shall only invalidate temporarily or permanently the registration of the specific place of business which has violated any of the provisions of this chapter. This violation, or action by the director, shall not affect in any manner the right of the automotive repair dealer to operate his or her other places of business.
- (c) Notwithstanding subdivision (b), the director may invalidate temporarily or permanently, the registration for all places of business operated in this state by an automotive repair dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated and willful violations of this chapter, or regulations adopted pursuant to it.
 - 20. Code section 9884.9, subdivision (a), states:
- (a) The automotive repair dealer shall give to the customer a written estimated price for labor and parts necessary for a specific job. No work shall be done and no charges shall accrue before authorization to proceed is obtained from the customer. No charge shall be made for work done or parts supplied in excess of the estimated price without the oral or written consent of the customer that shall be obtained at some time after it is determined that the estimated price is insufficient and before the work not estimated is done or the parts not estimated are supplied. Written consent or authorization for an increase in the original estimated price may be provided by electronic mail or facsimile transmission from the customer. The bureau may specify in regulation the procedures to be followed by an automotive repair dealer if an authorization or consent for an increase in the original estimated price is provided by electronic mail or facsimile transmission. If that consent is oral, the dealer shall make a notation on the work order of the date, time, name of person authorizing the additional repairs and telephone number called, if any, together with a specification of the additional parts and labor and the total additional cost, and shall do either of the following:
- (1) Make a notation on the invoice of the same facts set forth in the notation on the work order.
- (2) Upon completion of the repairs, obtain the customer's signature or initials to an acknowledgment of notice and consent, if there is an oral consent of the customer to additional repairs, in the following language:

"I acknowledge notice and oral approval of an increase in the original estimated price.

(signature or initials)"

Nothing in this section shall be construed as requiring an automotive repair dealer to give a written estimated price if the dealer does not agree to perform the requested repair.

21. Code section 9884.13 provides, in pertinent part, that the expiration of a valid registration shall not deprive the director or chief of jurisdiction to proceed with a

states:

disciplinary proceeding against an automotive repair dealer or to render a decision invalidating a registration temporarily or permanently.

- 22. Code section 477 provides, in pertinent part, that "Board" includes "bureau," "commission," "committee," "department," "division," "examining committee," "program," and "agency." "License" includes certificate, registration or other means to engage in a business or profession regulated by the Code.
- 23. Section 44002 of the Health and Safety Code provides, in pertinent part, that the Director has all the powers and authority granted under the Automotive Repair Act for enforcing the Motor Vehicle Inspection Program.
 - 24. Section 44072.2 of the Health and Safety Code states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

- (a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health and Saf. Code, § 44000, et seq.)] and the regulations adopted pursuant to it, which related to the licensed activities.
- (c) Violates any of the regulations adopted by the director pursuant to this chapter.
- (d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.
- 25. Section 44072.6 of the Health and Safety Code provides, in pertinent part, that the expiration or suspension of a license by operation of law, or by order or decision of the Director of Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive the Director of jurisdiction to proceed with disciplinary action.
 - 26. Section 44072.8 of the Health and Safety Code states:

"When a license has been revoked or suspended following a hearing under this article, any additional license issued under this chapter in the name of the licensee may be likewise revoked or suspended by the director."

REGULATORY PROVISION

27. California Code of Regulations, title 16, section 3356, subdivision (a)(1),

27

28

(a) All invoices for service and repair work performed, and parts supplied, as provided for in Section 9884.8 of the Business and Professions Code,

(1) The invoice shall show the automotive repair dealer's registration number and the corresponding business name and address as shown in the

Code section 125.3 provides, in pertinent part, that a Board may request the administrative law judge to direct a licentiate found to have committed a violation or violations of the licensing act to pay a sum not to exceed the reasonable costs of the investigation

<u>UNDERCOVER OPERATION - JUNE 26, 2007</u>

On June 26, 2007, a Bureau undercover operator using the alias Ron Picard ("operator") drove a Bureau-documented 1992 Toyota, California License Plate No. 4S12688, to Respondent No. 1's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's air suction ("AS") system was missing. Respondent Chhina performed the smog inspection and issued electronic Certificate of Compliance No. MS616778, certifying that he had tested and inspected the 1992 Toyota and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's AS system was missing.

FIRST CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

Respondent No. 1's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about June 26, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MS616778 for the 1992 Toyota, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's AS system was missing.

SECOND CAUSE FOR DISCIPLINE

(Fraud)

31. Respondent No. 1's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about June 26, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MS616778 for the 1992 Toyota without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

THIRD CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 32. Respondent No. 1's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about June 26, 2007, regarding the 1992 Toyota, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No.1 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 1 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44015, subdivision (b)</u>: Respondent No. 1 issued electronic Certificate of Compliance No. MS616778 for the vehicle without properly testing and inspecting the vehicle to determine if it was in compliance with Health & Safety Code section 44012.
- d. <u>Section 44059:</u> Respondent No. 1 willfully made false entries for electronic Certificate of Compliance No. MS616778 by certifying that the vehicle had been inspected as required when, in fact, it had not.

26 | ///

27 | ///

28 | ///

20 | 21

///

///

FOURTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 33. Respondent No. 1's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (c), in that on or about June 26, 2007, regarding the 1992 Toyota, it failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. Section 3340.24, subdivision (c): Respondent No. 1 falsely or fraudulently issued electronic Certificate of Compliance No. MS616778 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's AS system was missing.
- b. <u>Section 3340.35, subdivision (c)</u>: Respondent No. 1 issued electronic Certificate of Compliance No. MS616778 for the vehicle even though the vehicle had not been inspected in accordance with section 3340.42.
- c. <u>Section 3340.42</u>: Respondent No. 1 failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

FIFTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

34. Respondent No. 1's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about June 26, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MS616778 for the 1992 Toyota without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

.

///

SIXTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 35. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about June 26, 2007, regarding the 1992 Toyota, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Chhina failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Chhina failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Chhina failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Chhina entered false information for electronic Certificate of Compliance No. MS616778 by certifying that the vehicle had been inspected as required when, in fact, it had not.

SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 36. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about June 26, 2007, regarding the 1992 Toyota, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Chhina falsely or fraudulently issued electronic Certificate of Compliance No. MS616778 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's AS system was missing.

11

12 13

14

15

16

17 18

19

21

20

22

23

24

25 26

27

28

- Ъ. Section 3340.30, subdivision (a): Respondent Chhina failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- Section 3340.41, subdivision (c): Respondent Chhina entered false c. information into the Emission Inspection System ("EIS") by entering "Pass" for the visual portion of the smog test when, in fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's AS system was missing.
- d. Section 3340.42: Respondent Chhina failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

EIGHTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

Respondent Chhina has subjected his technician license to disciplinary 37. action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about June 26, 2007, regarding the 1992 Toyota, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MS616778 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - JULY 25, 2007

38. On July 25, 2007, a Bureau undercover operator using the alias Steve Palmer ("operator") drove a Bureau-documented 1994 Toyota Camry, California License Plate No. 3FLD508, to Respondent No. 1's facility for a smog inspection. The vehicle could not pass the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications. Respondent Chhina performed the smog inspection and issued electronic Certificate of Compliance No. MU025610, certifying that he had tested and inspected the 1994 Toyota Camry and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.

Q

///

NINTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

39. Respondent No. 1's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about July 25, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MU025610 for the 1994 Toyota Camry, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.

TENTH CAUSE FOR DISCIPLINE

(Fraud)

40. Respondent No. 1's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about July 25, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MU025610 for the 1994 Toyota Camry without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

ELEVENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 41. Respondent No. 1's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about July 25, 2007, regarding the 1994 Toyota Camry, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 1 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.

pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about

Respondent No. 1's station license is subject to disciplinary action

27

28

43.

July 25, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MU025610 for the 1994 Toyota Camry without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

FOURTEENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 44. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about July 25, 2007, regarding the 1994 Toyota Camry, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Chhina failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Chhina failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Chhina failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent entered false information for electronic Certificate of Compliance No. MU025610 by certifying that the vehicle had been inspected as required when, in fact, it had not.

FIFTEENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

45. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about July 25, 2007, regarding the 1994 Toyota Camry, he violated the following sections of the California Code of Regulations, title 16:

- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Chhina falsely or fraudulently issued electronic Certificate of Compliance No. MU025610 for the vehicle, in that the vehicle could not pass the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.
- b. <u>Section 3340.30, subdivision (a):</u> Respondent Chhina failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c)</u>: Respondent Chhina entered false information into the EIS unit by entering "Pass" for the functional portion of the smog inspection when, in fact, the vehicle the vehicle could not have passed the functional portion of the inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.
- d. <u>Section 3340.42</u>: Respondent Chhina failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

SIXTEENTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

46. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about July 25, 2007, regarding the 1994 Toyota Camry, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MU025610 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - JULY 26, 2007

47. On July 26, 2007, a Bureau undercover operator using the alias

Steve Palmer ("operator") drove a Bureau-documented 1996 Ford Explorer, California License

Plate No. 3PZE600, to Respondent No. 1's facility for a smog inspection. The vehicle could not

pass a smog inspection because the vehicle's positive crankcase ventilation ("PCV") system was

missing. Respondent Chhina performed the smog inspection and issued electronic Certificate of

| //

Compliance No. MU025621, certifying that he had tested and inspected the 1996 Ford Explorer and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

SEVENTEENTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

48. Respondent No. 1's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about July 26, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MU025621 for the 1996 Ford Explorer, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

EIGHTEENTH CAUSE FOR DISCIPLINE (Fraud)

49. Respondent No. 1's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about July 26, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MU025621 for the 1996 Ford Explorer without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

NINETEENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

50. Respondent No. 1's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, it failed to comply with the following sections of that Code:

///

.

- ...

///

///

///

TWENTY-FIRST CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

52. Respondent No. 1's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about July 26, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MU025621 for the 1996 Ford Explorer without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

TWENTY-SECOND CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 53. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Chhina failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Chhina failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Chhina failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent entered false information for electronic Certificate of Compliance No. MU025621 by certifying that the vehicle had been inspected as required when, in fact, it had not.

TWENTY-THIRD CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations' Pursuant to the Motor Vehicle Inspection Program)

- 54. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Chhina falsely or fraudulently issued electronic Certificate of Compliance No. MU025621 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's PCV system was missing.
- b. <u>Section 3340.30, subdivision (a):</u> Respondent Chhina failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c):</u> Respondent Chhina entered false information into the EIS unit by entering "Pass" for the visual portion of the smog test when, in fact, the vehicle's PCV system was missing.
- d. <u>Section 3340.42</u>: Respondent Chhina failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

TWENTY-FOURTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

55. Respondent Chhina has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MU025621 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

.

11.

///

///

RESPONDENT NO. 2

UNDERCOVER OPERATION - SEPTEMBER 21, 2007

Joseph Cook ("operator") drove a Bureau-documented 1989 Ford Ranger, California License Plate No. 3Y13631, to Respondent No. 2's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's thermostatic air cleaner ("TAC") was missing. The operator was provided with a copy of the signed work order; however, the document did not contain the vehicle's current odometer reading. Respondent Harrison performed the smog inspection and issued electronic Certificate of Compliance No. MU744740, certifying that he had tested and inspected the 1989 Ford Ranger and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's TAC was missing.

TWENTY-FIFTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

57. Respondent No. 2's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about September 21, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MU744740 for the 1989 Ford Ranger, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's TAC was missing.

TWENTY-SIXTH CAUSE FOR DISCIPLINE

(Failure to Record Vehicle's Current Odometer Reading on the Work Order)

58. Respondent's registration is subject to discipline under Code section 9884.7, subdivision (a)(2), in that Respondent allowed the operator to sign the work order dated September 21, 2007, that did not contain the vehicle's current odometer reading.

•

28 -

TWENTY-SEVENTH CAUSE FOR DISCIPLINE

(Fraud)

to Code section 9884.7, subdivision (a)(4), in that on or about September 21, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MU744740 for the 1989 Ford Ranger without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

TWENTY-EIGHTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

60. Respondent is subject to discipline under Code section 9884.7, subdivision (a)(6), in that on or about September 21, 2007, Respondent failed to materially comply with California Code of Regulations, title 16, section 3356, subdivision (a)(1), by failing to set forth its business name as reflected on Bureau records.

TWENTY-NINTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 61. Respondent No. 2's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about September 21, 2007, regarding the 1989 Ford Ranger, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 2 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 2 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44015, subdivision (b)</u>: Respondent No. 2 issued electronic Certificate of Compliance No. MU744740 for the vehicle without properly testing and inspecting the vehicle to determine if it was in compliance with Health & Safety Code section 44012.

d. <u>Section 44059:</u> Respondent No. 2 willfully made false entries for electronic Certificate of Compliance No. MU744740 by certifying that the vehicle had been inspected as required when, in fact, it had not.

THIRTIETH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 62. Respondent No. 2's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (c), in that on or about September 21, 2007, regarding the 1989 Ford Ranger, it failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent No. 2 falsely or fraudulently issued electronic Certificate of Compliance No. MU744740 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's TAC was missing.
- b. <u>Section 3340.35, subdivision (c)</u>: Respondent No. 2 issued electronic Certificate of Compliance No. MU744740 for the vehicle even though the vehicle had not been inspected in accordance with section 3340.42.
- c. <u>Section 3340.42</u>: Respondent No. 2 failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

THIRTY-FIRST CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

63. Respondent No. 2's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about September 21, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MU744740 for the 1989 Ford Ranger without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

THIRTY-SECOND CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 64. Respondent Harrison has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about September 21, 2007, regarding the 1989 Ford Ranger, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Harrison failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Harrison failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Harrison failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent entered false information for electronic Certificate of Compliance No. MU744740 by certifying that the vehicle had been inspected as required when, in fact, it had not.

THIRTY-THIRD CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 65. Respondent Harrison has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about September 21, 2007, regarding the 1989 Ford Ranger, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Harrison falsely or fraudulently issued electronic Certificate of Compliance No. MU744740 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's TAC was missing.

5

8

7

9 10

11

12 13

14 15

16

17

18

19

20 21

22

23

24

25

26

27

28

- Ъ. Section 3340.30, subdivision (a): Respondent Harrison failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- Section 3340.41, subdivision (c): Respondent Harrison entered false c. information into the EIS unit by entering "N/A" for the visual inspection of the TAC indicating that the system was not applicable when, in fact, the TAC system is applicable but was missing from the vehicle.
- d. Section 3340.42: Respondent Harrison failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

THIRTY-FOURTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

66. Respondent Harrison has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about September 21, 2007, regarding the 1989 Ford Ranger, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MU744740 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - SEPTEMBER 21, 2007

67. On September 21, 2007, a Bureau undercover operator using the alias Joseph Cook ("operator") drove a Bureau-documented 1998 Ford E-150, California License Plate No. 5R77178, to Respondent No. 2's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's positive crankcase ventilation ("PCV") system was missing. Respondent Harrison performed the smog inspection and issued electronic Certificate of Compliance No. MU744743, certifying that he had tested and inspected the 1998 Ford E-150 and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

/

12...

///

THIRTY-FIFTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

68. Respondent No. 2's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about September 21, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MU744743 for the 1998 Ford E-150, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

THIRTY-SIXTH CAUSE FOR DISCIPLINE

(Fraud)

69. Respondent No. 2's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about September 21, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MU744743 for the 1998 Ford E-150 without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

THIRTY-SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

70. Respondent is subject to discipline under Code section 9884.7, subdivision (a)(6), in that on or about September 21, 2007, Respondent failed to materially comply with California Code of Regulations, title 16, section 3356, subdivision (a)(1), by failing to set forth its business name as reflected on Bureau records.

THIRTY-EIGHTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

71. Respondent No. 2's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about

inspected in accordance with section 3340.42.

27

c. <u>Section 3340.42</u>: Respondent No. 2 failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

FORTIETH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

73. Respondent No. 2's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about September 21, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MU744743 for the 1998 Ford E-150 without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

FORTY-FIRST CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 74. Respondent Harrison has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about September 21, 2007, regarding the 1998 Ford E-150, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Harrison failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Harrison failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Harrison failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent entered false information for electronic Certificate of Compliance No. MU744743 by certifying that the vehicle had been inspected as required when, in fact, it had not.

4

21 |

23.

///

FORTY-SECOND CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 75. Respondent Harrison has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about September 21, 2007, regarding the 1998 Ford E-150, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Harrison falsely or fraudulently issued electronic Certificate of Compliance No. MU744743 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's PCV system was missing.
- b. <u>Section 3340:30 subdivision (a):</u> Respondent Harrison failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c):</u> Respondent Harrison entered false information into the EIS unit by entering "Pass" for the visual portion of the smog test when, in fact, the vehicle's PCV system was missing.
- d. <u>Section 3340.42</u>: Respondent Harrison failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

FORTY-THIRD CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

76. Respondent Harrison has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about September 21, 2007, regarding the 1998 Ford E-150, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MU744743 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

RESPONDENT NO. 3

UNDERCOVER OPERATION - OCTOBER 24, 2007

On October 24, 2007, a Bureau undercover operator using the alias Bob Johnson ("operator") drove a Bureau-documented 1994 Toyota Camry, California License Plate No. 3FLD508, to Respondent No. 3's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications. The operator filled out and signed a work order but was not provided with a copy of the document. Respondent Ordonez performed the smog inspection and issued electronic Certificate of Compliance No. MW137423, certifying that he had tested and inspected the 1994 Toyota Camry and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.

FORTY-FOURTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

78. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about October 24, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MW137423 for the 1994 Toyota Camry, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specification.

FORTY-FIFTH CAUSE FOR DISCIPLINE

(Failure to Provide Copy of Document)

79. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(3), in that on or about October 24, 2007, it failed to provide the operator with a copy of the work order as soon as he signed the document.

8:

· 13

FORTY-SIXTH CAUSE FOR DISCIPLINE

(Fraud)

80. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about October 24, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MW137423 for the 1994 Toyota Camry without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

FORTY-SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Code)

Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that on or about October 24, 2007, it failed to comply with Code section 9884.9, subdivision (a), by failing to provide the operator with a written estimated price for parts and labor for a specific job.

FORTY-EIGHTH-CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 82. Respondent No. 3's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about October 24, 2007, regarding the 1994 Toyota Camry, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 3 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 3 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44015, subdivision (b)</u>: Respondent No. 3 issued electronic Certificate of Compliance No. MW137423 for the vehicle without properly testing and

28 | ///

3.

by issuing electronic Certificate of Compliance No. MW137423 for the 1994 Toyota Camry

without performing a bona fide inspection of the emission control devices and systems on the

27

fraudulently issued electronic Certificate of Compliance No. MW137423 for the vehicle, in that

27 |

the vehicle could not pass the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specification.

- b. <u>Section 3340.30, subdivision (a):</u> Respondent Ordonez failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c)</u>: Respondent Ordonez entered false information into the EIS unit by entering "Pass" for the ignition timing portion of the smog test when, in fact, the vehicle's ignition timing was adjusted beyond the manufacturer's specification.
- d. <u>Section 3340.42</u>: Respondent Ordonez failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

FIFTY-THIRD CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

87. Respondent Ordonez has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about October 24, 2007, regarding the 1994 Toyota Camry, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MW137423 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - OCTOBER 31, 2007

Robert ("operator") drove a Bureau-documented 1992 Toyota, California License Plate No. 4S12688, to Respondent No. 3's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's air suction ("AS") system was missing. The operator filled out and signed a work order but was not provided with a copy of the document. Respondent Ordonez performed the smog inspection and issued electronic Certificate of Compliance No. MW137444, certifying that he had tested and inspected the 1992 Toyota and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle

could not have passed the visual portion of the smog inspection because the vehicle's AS system was missing.

FIFTY-FOURTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

89. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about October 31, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MW137444 for the 1992 Toyota, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's AS system was missing.

EIETY-FIRTH CAUSE-FOR-DISGIPLINE

(Failure to Provide Copy of Document)

90. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(3), in that on or about October 31, 2007, it failed to provide the operator with a copy of the work order as soon as he signed the document.

FIFTY-SIXTH CAUSE FOR DISCIPLINE

(Fraud)

91. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about October 31, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MW137444 for the 1992 Toyota without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

FIFTY-SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Code)

92. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(6), in that on or about October 31, 2007, it failed to comply

with Code section 9884.9, subdivision (a), by failing to provide the operator with a written estimated price for parts and labor for a specific job.

, FIFTY-EIGHTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 93. Respondent No. 3's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about October 31, 2007, regarding the 1992 Toyota, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 3 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 3 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. Section 44015; subdivision (b): Respondent No. 3 issued electronic Certificate of Compliance No. MW137444 for the vehicle without properly testing and inspecting the vehicle to determine if it was in compliance with Health & Safety Code section 44012.
- d. <u>Section 44059:</u> Respondent No. 3 willfully made false entries for electronic Certificate of Compliance No. MW137444 by certifying that the vehicle had been inspected as required when, in fact, it had not.

FIFTY-NINTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

94. Respondent No. 3's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (c), in that on or about October 31, 2007, regarding the 1992 Toyota, it failed to comply with provisions of California Code of Regulations, title 16, as follows:

///

- a. <u>Section 3340.24, subdivision (c)</u>: Respondent No. 3 falsely or fraudulently issued electronic Certificate of Compliance No. MW137444 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's AS system was missing.
- b. <u>Section 3340.35, subdivision (c)</u>: Respondent No. 3 issued electronic Certificate of Compliance No. MW137444 for the vehicle even though the vehicle had not been inspected in accordance with section 3340.42.
- c. <u>Section 3340.42</u>: Respondent No. 3 failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

SIXTIETH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

95. Respondent No. 3's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about October 31, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MW137444 for the 1992 Toyota without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

SIXTY-FIRST CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 96. Respondent Ordonez has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about October 31, 2007, regarding the 1992 Toyota, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Ordonez failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Ordonez failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.

SIXTY-THIRD CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

98. Respondent Ordonez has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about October 31, 2007, regarding the 1992 Toyota, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No.

MW137444 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - NOVEMBER 5, 2007

99. On November 5, 2007, a Bureau undercover operator using the alias Robert ("operator") drove a Bureau-documented 1995 Chevrolet Astro Van, California License Plate No. 3NUD802, to Respondent No. 3's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's positive crankcase ventilation ("PCV") system was missing. The operator filled out and signed a work order but was not provided with a copy of the document. Respondent Ordonez performed the smog inspection and issued electronic Certificate of Compliance No. MW279311, certifying that he had tested and inspected the 1995 Chevrolet Astro Van and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

SIXTY-FOURTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

100. Respondent No. 3's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about November 5, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MW279311 for the 1995 Chevrolet Astro Van, certifying that the vehicle was in compliance with applicable laws

 \parallel ///

and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing. SIXTY-FIFTH CAUSE FOR DISCIPLINE 3 (Failure to Provide Copy of Document) 4 Respondent No. 3's registration is subject to disciplinary action pursuant 5 to Code section 9884.7, subdivision (a)(3), in that on or about November 5, 2007, it failed to 7 provide the operator with a copy of the work order as soon as he signed the document. SIXTY-SIXTH CAUSE FOR DISCIPLINE 8 (Fraud) 9 Respondent No. 3's registration is subject to disciplinary action pursuant 102. 10 to Code section 9884.7, subdivision (a)(4), in that on or about November 5, 2007, it committed 11 acts which constitute fraud by issuing electronic Certificate of Compliance No. MW279311 for 12 the 1995 Chevrolet Astro Van without performing a bona fide inspection of the emission control 13 devices and systems on the vehicle, thereby depriving the People of the State of California of the 14 protection afforded by the Motor Vehicle Inspection Program. 15 16 SIXTY-SEVENTH CAUSE FOR DISCIPLINE (Failure to Comply with Code) 17 18 103. Respondent No. 3's registration is subject to disciplinary action pursuant to 19 Code section 9884.7, subdivision (a)(6), in that on or about November 5, 2007, it failed to 20 comply with Code section 9884.9, subdivision (a), by failing to provide the operator with a written estimated price for parts and labor for a specific job. 21 22 SIXTY-EIGHTH CAUSE FOR DISCIPLINE 23 24 104.

(Violations of the Motor Vehicle Inspection Program)

104. Respondent No. 3's station license is subject to disciplinary action
pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about
November 5, 2007, regarding the 1995 Chevrolet Astro Van, it failed to comply with the
following sections of that Code:

///

f 21

///

///

SEVENTIETH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

106. Respondent No. 3's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about November 5, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MW279311 for the 1995 Chevrolet Astro Van without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

SEVENTY-FIRST CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 107. Respondent Ordonez has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about November 5, 2007, regarding the 1995 Chevrolet Astro Van, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Ordonez failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Ordonez failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Ordonez failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Ordonez willfully made false entries for electronic Certificate of Compliance No. MW279311 by certifying that the vehicle had been inspected as required when, in fact, it had not.

22 ;

25°

28 | ///

SEVENTY-SECOND CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 108. Respondent Ordonez has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about November 5, 2007, regarding the 1995 Chevrolet Astro Van, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Ordonez falsely or fraudulently issued electronic Certificate of Compliance No. MW279311 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's PCV system was missing.
- b. <u>Section 3340 30, subdivision (a):</u> Respondent Ordonez failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c):</u> Respondent Ordonez entered false information into the EIS unit by entering "Pass" for the PCV system when, in fact, the vehicle's PCV system was missing.
- d. <u>Section 3340.42</u>: Respondent Ordonez failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

SEVENTY-THIRD CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

109. Respondent Ordonez has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about November 5, 2007, regarding the 1995 Chevrolet Astro Van, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MW279311 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

, 8

RESPONDENT NO. 4

UNDERCOVER OPERATION - JUNE 26, 2007

Ron Picard ("operator") drove a Bureau documented 1992 Toyota, California License Plate No. 4S12688, to Respondent No. 4's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's air suction ("AS") system was missing. Respondent Schaub performed the smog inspection; however, Respondent Schaub's entries into the EIS unit included a "pass" for the visual inspection and a "fail" for the ignition timing, creating a false and misleading Vehicle Inspection Report ("VIR"). In fact, the vehicle should not have passed the visual inspection because the vehicle's AS system was missing and the vehicle's ignition timing should not have failed because the vehicle's ignition timing was within the manufacturer's specifications. No certificate of compliance was issued.

· SEVENTY-FOURTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

- 111. Respondent No. 4's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about June 26, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading as follow:
- a. Respondent No. 4 provided the operator with a VIR that was false and misleading, in that the VIR provided that the vehicle passed the visual inspection when, in fact, the vehicle could not have passed the visual inspection because the vehicle's AS system was missing.
- b. Respondent No. 4 provided the operator with a VIR that was false and misleading, in that the VIR provided that the vehicle failed the functional inspection due to the vehicle's ignition timing when, in fact, the vehicle's ignition timing was within the manufacturer's specifications.
- /// ///

SEVENTY-FIFTH CAUSE FOR DISCIPLINE 1 (Violations of the Motor Vehicle Inspection Program) 2 112. Respondent No. 4's station license is subject to disciplinary action 3 pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about June 26, 2007, regarding the 1992 Toyota, it failed to comply with the following sections of that 5 Code: 6 Section 44012, subdivision (a): Respondent No. 4 failed to determine that all emission control devices and systems required by law were installed and functioning 8 9 correctly in accordance with test procedures. Section 44012, subdivision (f): Respondent No. 4 failed to perform 10 emission control tests on the vehicle in accordance with procedures prescribed by the department. 11 Section 44059: 12 Respondent No. 4 willfully made false entries for the VIR by 13 indicating the vehicle passed the visual inspection when, in fact, the vehicle could not have 14 passed the visual inspection because the vehicle's AS system was missing. 15 Respondent No. 4 willfully made false entries for the VIR by 16 ii. indicating the vehicle failed the functional portion of the inspection due to the vehicle's ignition 17 18 timing when, in fact, the vehicle's ignition timing was within the manufacturer's specifications. 19 SEVENTY-SIXTH CAUSE FOR DISCIPLINE 20 (Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program) 21 22 113. 23

24

25

26

27

28

113. Respondent No. 4's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (c), in that on or about June 26, 2007, regarding the 1992 Toyota, it failed to comply with provisions of California Code of Regulations, title 16, section 3340.42 by failing to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

SEVENTY-SEVENTH CAUSE FOR DISCIPLINE 1 (Dishonesty, Fraud or Deceit) 2 Respondent No. 4's station license is subject to disciplinary action 114. 3 pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about 4 5 June 26, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured, thereby depriving the People of the State of California of the protection afforded by the Motor 6 7 Vehicle Inspection Program, as follows: Respondent No. 4 created a VIR that was false and misleading, in that the 8 9 VIR provided that the vehicle passed the visual inspection when, in fact, the vehicle could not have passed the visual inspection because the vehicle's AS system was missing. 10 Respondent No. 4 created a VIR that was false and misleading, in that the 11 **b**. VIR provided that the vehicle failed the functional inspection due to the vehicle's ignition timing 12 when, in fact, the vehicle's ignition timing was within the manufacturer's specifications. 13 SEVENTY-EIGHTH CAUSE FOR DISCIPLINE 14 15 (Violations of the Motor Vehicle Inspection Program) 16 115. Respondent Schaub has subjected his technician license to disciplinary 17 action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about 18 June 26, 2007, regarding the 1992 Toyota, he violated the following sections of that Code: 19 Section 44012, subdivision (a): Respondent Schaub failed to determine a. 20 that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures. 21 22 Section 44012, subdivision (f): Respondent Schaub failed to perform 23 emission control tests on the vehicle in accordance with procedures prescribed by the department. 24 Section 44032: Respondent Schaub failed to perform tests of the 25 emission control devices and systems on the vehicle in accordance with section 44012 of that

26

.27

28

Code.

///

EIGHTIETH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

3 5

1

2

- 6
- 7

8

- 10
- 11
- 12
- 13

14

15

16

17

18

19

20 21

22

23 24

25

26

27

28

- 117. Respondent Schaub has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about June 26, 2007, regarding the 1992 Toyota, he committed acts involving dishonesty, fraud or deceit whereby another was injured, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program, as follows:
- Respondent Schaub created a VIR that was false and misleading, in that the VIR provided that the vehicle passed the visual inspection when, in fact, the vehicle could not have passed the visual inspection because the vehicle's AS system was missing.
- Respondent Schaub created a VIR that was false and misleading, in that **b**. the VIR provided that the vehicle failed the functional inspection due to the vehicle's ignition timing when, in fact, the vehicle's ignition timing was within the manufacturer's specifications.

UNDERCOVER OPERATION - JUNE 27, 2007

118. On June 27, 2007, a Bureau undercover operator using the alias Bob Strom ("operator") drove a Bureau-documented 1995 Chevrolet Astro Van, California License Plate No. 3NUD802, to Respondent No. 4's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's PCV system was missing. Respondent Topcu performed the smog inspection and issued electronic Certificate of Compliance No. MS578192, certifying that he had tested and inspected the 1995 Chevrolet Astro Van and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

EIGHTY-FIRST CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

119. Respondent No. 4's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about June 27, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known

to be untrue or misleading by issuing electronic Certificate of Compliance No. MS578192 for the 1995 Chevrolet Astro Van, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

EIGHTY-SECOND CAUSE FOR DISCIPLINE

(Fraud)

120. Respondent No. 4's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about June 27, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MS578192 for the 1995 Chevrolet Astro Van without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle-Inspection Program.

EIGHTY-THIRD CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 121. Respondent No. 4's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about June 27, 2007, regarding the 1995 Chevrolet Astro Van, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 4 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. Section 44012, subdivision (f): Respondent No. 4 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44015, subdivision (b)</u>: Respondent No. 4 issued electronic Certificate of Compliance No. MS578192 for the vehicle without properly testing and inspecting the vehicle to determine if it was in compliance with Health & Safety Code section 44012.

28 | ///

///

d. <u>Section 44059:</u> Respondent No. 4 willfully made false entries for electronic Certificate of Compliance No. MS578192 by certifying that the vehicle had been inspected as required when, in fact, it had not.

EIGHTY-FOURTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 122. Respondent No. 4's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (c), in that on or about June 27, 2007, regarding the 1995 Chevrolet Astro Van, it failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent No. 4 falsely or fraudulently issued electronic Certificate of Compliance No. MS578192 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's PCV system was missing.
- b. <u>Section 3340.35, subdivision (c)</u>: Respondent No. 4 issued electronic Certificate of Compliance No. MS578192 for the vehicle even though the vehicle had not been inspected in accordance with section 3340.42.
- c. <u>Section 3340.42</u>: Respondent No. 4 failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

EIGHTY-FIFTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

123. Respondent No. 4's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about June 27, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. MS578192 for the 1995 Chevrolet Astro Van without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

///

EIGHTY-SIXTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 124. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about June 27, 2007, regarding the 1995 Chevrolet Astro Van, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Topcu failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Topcu failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Topcu failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Topcu entered false information for electronic Certificate of Compliance No. MS578192 by certifying that the vehicle had been inspected as required when, in fact, it had not.

EIGHTY-SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 125. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about June 27, 2007, regarding the 1995 Chevrolet Astro Van, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Topcu falsely or fraudulently issued electronic Certificate of Compliance No. MS578192 for the vehicle, in that the vehicle could not pass the visual portion of the smog inspection because the vehicle's PCV system was missing.

- b. <u>Section 3340.30, subdivision (a):</u> Respondent Topcu failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c):</u> Respondent Topcu entered false information into the EIS unit by entering "Pass" for the PCV system when, in fact, the vehicle's PCV system was missing.
- d. <u>Section 3340.42</u>: Respondent Topcu failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

EIGHTY-EIGHTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about June 27, 2007, regarding the 1995 Chevrolet Astro Van, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MS578192 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - JULY 26, 2007

Bob Strom ("operator") drove a Bureau-documented 1996 Ford Explorer, California License Plate No. 3PZE600, to Respondent No. 4's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's PCV system was missing. Respondent Phelps performed the smog inspection and issued electronic Certificate of Compliance No. MS960291, certifying that he had tested and inspected the 1996 Ford Explorer and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

26 | /

27 | ///

28 ///

EIGHTY-NINTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

128. Respondent No. 4's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about July 26, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MS960291 for the 1996 Ford Explorer, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

NINETIETH CAUSE FOR DISCIPLINE

(Fraud)

129. Respondent No. 4's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about July 26, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MS960291 for the 1996 Ford Explorer without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

NINETY-FIRST CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 130. Respondent No. 4's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 4 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 4 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.

. .

issuing electronic Certificate of Compliance No. MS960291 for the 1996 Ford Explorer without

performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

NINETY-FOURTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 133. Respondent Phelps has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Phelps failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Phelps failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Phelps failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Phelps willfully made false entries for electronic Certificate of Compliance No. MS960291 by certifying that the vehicle had been inspected as required when, in fact, it had not.

NINETY-FIFTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 134. Respondent Phelps has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about July 26, 2007, regarding the 1996 Ford Explorer, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Phelps falsely or fraudulently issued electronic Certificate of Compliance No. MS960291 for the vehicle, in that

performed the smog inspection and issued electronic Certificate of Compliance No. MU037023,

certifying that he had tested and inspected the 1996 Ford Explorer and that the vehicle was in

compliance with applicable laws and regulations. In fact, the vehicle could not have passed the

visual portion of the smog inspection because the vehicle's PCV system was missing.

25

26

27

NINETY-SEVENTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

137. Respondent No. 5's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about July 27, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MU037023 for the 1996 Ford Explorer, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the visual portion of the smog inspection because the vehicle's PCV system was missing.

NINETY-EIGHTH CAUSE FOR DISCIPLINE

(Fraud)

138. Respondent No. 5's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about July 27, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MU037023 for the 1996 Ford Explorer without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

NINETY-NINTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 139. Respondent No. 5's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about July 27, 2007, regarding the 1996 Ford Explorer, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 5 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 5 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.

performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

ONE HUNDRED SECOND CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 142. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about July 27, 2007, regarding the 1996 Ford Explorer, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Topcu failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Topcu failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Topcu failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Topcu willfully entered false information for electronic Certificate of Compliance No. MU037023 by certifying that the vehicle had been inspected as required when, in fact, it had not.

ONE HUNDRED THIRD CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 143. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about July 27, 2007, regarding the 1996 Ford Explorer, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Topcu falsely or fraudulently issued electronic Certificaté of Compliance No. MÚ037023 for the vehicle, in that

25

26

27

28

Section 3340.30, subdivision (a): Respondent Topcu failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012. Section 3340.41, subdivision (c): Respondent Topcu entered false information into the EIS unit by entering "Pass" for the PCV system when, in fact, the vehicle's Section 3340.42: Respondent Topcu failed to conduct the required smog ONE HUNDRED FOURTH CAUSE FOR DISCIPLINE Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about July 27, 2007, regarding the 1996 Ford Explorer, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MU037023 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the **UNDERCOVER OPERATION - AUGUST 2, 2007** On August 2, 2007, a Bureau undercover operator using the alias Joe R. Wong ("operator") drove a Bureau-documented 1992 Oldsmobile Bravada, California License Plate No. 3WGW652, to Respondent No. 5's facility for a smog inspection. The vehicle could not pass a smog inspection because of the vehicle's non-functional exhaust gas recirculation ("EGR") system. Respondent Topcu performed the smog inspection and issued electronic Certificate of Compliance No. MU098289, certifying that he had tested and inspected the 1992 Oldsmobile Bravada and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog

inspection because of the vehicle's non-functional EGR system.

12_.

ONE HUNDRED FIFTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

146. Respondent No. 5's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about August 2, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. MU098289 for the 1992 Oldsmobile Bravada, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog inspection because of the vehicle's non-functional EGR system.

ONE HUNDRED SIXTH CAUSE FOR DISCIPLINE

(Fraud)

147. Respondent No. 5's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(4), in that on or about August 2, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. MU098289 for the 1992 Oldsmobile Bravada without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

ONE HUNDRED SEVENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 148. Respondent No. 5's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about August 2, 2007, regarding the 1992 Oldsmobile Bravada, it failed to comply with the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent No. 5 failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent No. 5 failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.

by issuing electronic Certificate of Compliance No. MU098289 for the 1992 Oldsmobile

Bravada without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

ONE HUNDRED TENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 151. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about August 2, 2007, regarding the 1992 Oldsmobile Bravada, he violated the following sections of that Code:
- a. Section 44012, subdivision (a): Respondent Topcu failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Topcu failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Topcu failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Topcu willfully entered false information for electronic Certificate of Compliance No. MU098289 by certifying that the vehicle had been inspected as required when, in fact, it had not.

ONE HUNDRED ELEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 152. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about August 2, 2007, regarding the 1992 Oldsmobile Bravada, he violated the following sections of the California Code of Regulations, title 16:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent Topcu falsely or fraudulently issued electronic Certificate of Compliance No. MU098289 for the vehicle, in that

the vehicle could not pass the visual portion of the smog inspection because of the vehicle's non-functional EGR system.

- b. <u>Section 3340.30, subdivision (a):</u> Respondent Topcu failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c):</u> Respondent Topcu entered false information into the EIS unit by entering "Pass" for the functional inspection of the EGR system when, in fact, that system was non-functional.
- d. <u>Section 3340.42</u>: Respondent Topcu failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

ONE HUNDRED TWELFTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about August 2, 2007, regarding the 1992 Oldsmobile Bravada, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. MU098289 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

UNDERCOVER OPERATION - AUGUST 13, 2007

Joe Wong ("operator") drove a Bureau-documented 1994 Toyota Camry, California License Plate No. 3FLD508, to Respondent No. 5's facility for a smog inspection. The vehicle could not pass a smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications. Respondent Topcu performed the smog inspection and issued electronic Certificate of Compliance No. VJ442115, certifying that he had tested and inspected the 1994 Toyota Camry and that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog

inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.

ONE HUNDRED THIRTEENTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

155. Respondent No. 5's registration is subject to disciplinary action pursuant to Code section 9884.7, subdivision (a)(1), in that on or about August 13, 2007, it made or authorized statements which it knew or in the exercise of reasonable care it should have known to be untrue or misleading by issuing electronic Certificate of Compliance No. VJ442115 for the 1994 Toyota Camry, certifying that the vehicle was in compliance with applicable laws and regulations. In fact, the vehicle could not have passed the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.

ONE HUNDRED FOURTEENTH CAUSE FOR DISCIPLINE (Fraud)

to Code section 9884.7, subdivision (a)(4), in that on or about August 13, 2007, it committed acts which constitute fraud by issuing electronic Certificate of Compliance No. VJ442115 for the 1994 Toyota Camry without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

ONE HUNDRED FIFTEENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

157. Respondent No. 5's station license is subject to disciplinary action pursuant to Health & Safety Code section 44072.2, subdivision (a), in that on or about August 13, 2007, regarding the 1994 Toyota Camry, it failed to comply with the following sections of that Code:

27 ///

28 | ///

25:

26.

///

///

28.

ONE HUNDRED SEVENTEENTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

pursuant to Health & Safety Code section 44072.2, subdivision (d), in that on or about August 13, 2007, it committed dishonest, fraudulent or deceitful acts whereby another is injured by issuing electronic Certificate of Compliance No. VJ442115 for the 1994 Toyota Camry without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

ONE HUNDRED EIGHTEENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 160. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (a), in that on or about August 13, 2007, regarding the 1994 Toyota Camry, he violated the following sections of that Code:
- a. <u>Section 44012, subdivision (a):</u> Respondent Topcu failed to determine that all emission control devices and systems required by law were installed and functioning correctly in accordance with test procedures.
- b. <u>Section 44012, subdivision (f)</u>: Respondent Topcu failed to perform emission control tests on the vehicle in accordance with procedures prescribed by the department.
- c. <u>Section 44032:</u> Respondent Topcu failed to perform tests of the emission control devices and systems on the vehicle in accordance with section 44012 of that Code.
- d. <u>Section 44059:</u> Respondent Topcu willfully entered false information for electronic Certificate of Compliance No. VJ442115 for the vehicle by certifying that the vehicle had been inspected as required when, in fact, it had not.

ONE HUNDRED NINETEEN CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

7 8

22 |

161. Respondent Topcu has subjected his technician license to disciplinary action pursuant to Health and Safety Code section 44072.2, subdivision (c), in that on or about August 13, 2007, regarding the 1994 Toyota Camry, he violated the following sections of the California Code of Regulations, title 16:

- a. Section 3340.24, subdivision (c): Respondent Topcu falsely or fraudulently issued electronic Certificate of Compliance No. VJ442115 for the vehicle, in that the vehicle could not pass the functional portion of the smog inspection because the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.
- b. <u>Section 3340 30 subdivision (a):</u> Respondent Topcu failed to inspect and test the vehicle in accordance with Health and Safety Code section 44012.
- c. <u>Section 3340.41, subdivision (c)</u>: Respondent Topcu entered false information into the EIS unit by entering "Pass" for the functional portion of the smog inspection, when, in fact, the vehicle's ignition timing was adjusted beyond the manufacturer's specifications.
- d. <u>Section 3340.42</u>: Respondent Topcu failed to conduct the required smog tests on the vehicle in accordance with the Bureau's specifications.

ONE HUNDRED TWENTIETH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

action pursuant to Health and Safety Code section 44072.2, subdivision (d), in that on or about August 13, 2007, regarding the 1994 Toyota Camry, he committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing electronic Certificate of Compliance No. VJ442115 for that vehicle without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

PRIOR DISCIPLINE

2 RESPONDENT NO. 1

Issues Case No. 79/04-00 S, which became effective January 30, 2006, the Bureau issued Respondent's Automotive Repair Dealer Registration No. ARD 241700 on February 3, 2006, and Smog Check Test Only Station License No. TC 241700 on February 16, 2006. Automotive Repair Dealer Registration No. ARD 241700 and Smog Check Test Only Station License No. TC 241700 were immediately revoked; however, revocations were stayed, and the licenses were placed on probation with terms and conditions. Pursuant to the settlement, Respondent agreed to be bound by all of the terms and conditions set forth in the Decision and Order in Accusation No. 79/04-00, a related case brought against Respondent No. 5, as more particularly set forth in paragraph 167, below. The probation term ended December 6, 2007.

RESPONDENT NO. 2

Issues Case No. 79/04-00 S, which became effective June 30, 2006, the Bureau issued Respondent's Automotive Repair Dealer Registration No. ARD 244942 on July 11, 2006, and Smog Check Test Only Station License No. TC 244942 on November 20, 2006. Automotive Repair Dealer Registration No. ARD 244942 and Smog Check Test Only Station License No. TC 244942 were immediately revoked; however, revocations were stayed, and the licenses were placed on probation with terms and conditions. Pursuant to the settlement, Respondent agreed to be bound by all of the terms and conditions set forth in the Decision and Order in Accusation No. 79/04-00, a related case brought against Respondent No. 5, as more particularly set forth in paragraph 167, below. The probation term ended December 6, 2007.

RESPONDENT NO. 3

165. Pursuant to the Decision and Order, a stipulated settlement in Statement of Issues Case No. 79/04-00 S, which became effective February 8, 2007, the Bureau issued Respondent's Automotive Repair Dealer Registration No. ARD 248804 on February 14, 2007, and Smog Check Test Only Station License No. TC 248804 on March 2, 2007. Automotive

1 | I 2 | 7 3 | T 4 | t 5 | 7

Repair Dealer Registration No. ARD 248804 and Smog Check Test Only Station License No. TC 248804 were immediately revoked; however, revocations were stayed, and the licenses were placed on probation with terms and conditions. Pursuant to the settlement, Respondent agreed to be bound by all of the terms and conditions set forth in the Decision and Order in Accusation No. 79/04-00, a related case brought against Respondent No. 5, as more particularly set forth in paragraph 167, below. The probation term ended December 6, 2007.

RESPONDENT NO. 4

Issues Case No. 79/04-00 S, which became effective February 2, 2005, the Bureau issued
Respondent's Automotive Repair Dealer Registration No. ARD 236306 on February 9, 2005, and
Smog Check Test Only Station License No. TC 236306 on February 14, 2005. Automotive
Repair Dealer Registration No. ARD 236306 and Smog Check Test Only Station License No.
TC 236306 were immediately revoked; however, revocations were stayed, and the licenses were
placed on probation with terms and conditions. Pursuant to the settlement, Respondent agreed to
be bound by all of the terms and conditions set forth in the Decision and Order in Accusation No.
79/04-00, a related case brought against Respondent No. 5, as more particularly set forth in
paragraph 167, below. The probation term ended December 6, 2007.

RESPONDENT NO. 5

Accusation Case No. 79/04-00, Respondent's Automotive Repair Dealer Registration No. ARD 221700 and Smog Check Test Only Station License No. TC 221700 were revoked; however, revocation was stayed, and the licenses were placed on probation with terms and conditions. Further, Smog Check Test Only Station License No. TC 221700 was suspended for thirty (30) days. The probation term ended December 6, 2007.

OTHER MATTERS

168. Under Code section 9884.7, subdivision (c), the director may invalidate temporarily or permanently or refuse to validate, the registrations for all places of business operated in this state by Chevrem Corporation doing business as Clear Blue Test Only Smog

///

Station including, but not limited to Clear Blue Test Only Smog Station #3; Clear Blue Test Only Station 2; Test Only Smog Station II; and, G I C Smog Station, upon a finding that it has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.

- Station License Number TC 241700, issued to Chevrem Corporation doing business as Clear Blue Test Only Smog Station, is revoked or suspended, any additional license issued under this chapter in the name of said licensee including, but not limited to, TC 244942, issued to Chevrem Corporation, doing business as Clear Blue Test Only Smog Station 2; TC 248804, issued to Chevrem Corporation, doing business as Clear Blue Test Only Smog Station 3; TC 236306, issued to Chevrem Corporation, doing business as Test Only Smog Station II; and TC 221700, issued to Chevrem Corporation, doing business as G I C Smog Station, may be likewise revoked or suspended by the director.
- 170. Under Health and Safety Code section 44072.8, if Advanced Emission

 Specialist Technician License Number EA 152180, issued to Harpreet Singh Chhina, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the director.
- 171. Under Health and Safety Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 151176, issued to Christopher Bryan Harrison, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the director.
- 172. Under Health and Safety Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 144440, issued to Winchester Sibuma Ordonez, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the director.
- 173. Under Health and Safety Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 152893, issued to Bryon Leonard Schaub, is revoked

dealer registration issued to Chevrem Corporation;

26

27

or suspended, any additional license issued under this chapter in the name of said licensee may Under Health and Safety Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 147911, issued to Nusret B. Topcu, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be Under Health and Safety Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 151026, issued to Matthew Jared Phelps, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may WHEREFORE, Complainant requests that a hearing be held on the matters hereinalleged, and that following the hearing, the Director of Consumer Affairs issue a decision: Revoking or suspending Automotive Repair Dealer Registration Number ARD 241700, issued to Chevrem Corporation, doing business as Clear Blue Test Only Smog Revoking or suspending Automotive Repair Dealer Registration Number ARD 244942, issued to Chevrem Corporation, doing business as Clear Blue Test Only Smog Revoking or suspending Automotive Repair Dealer Registration Number ARD 248804, issued to Chevrem Corporation, doing business as Clear Blue Test Only Smog Revoking or suspending Automotive Repair Dealer Registration Number ARD 236306, issued to Chevrem Corporation, doing business as Test Only Smog Station II; Revoking or suspending Automotive Repair Dealer Registration Number ARD 221700, issued to Chevrem Corporation, doing business as G I C Smog Station; 6. Temporarily or permanently invalidating any other automotive repair

ClearBlue.Acc.wpd (8/18/08)