

1 ROB BONTA
Attorney General of California
2 ANDREW M. STEINHEIMER
Supervising Deputy Attorney General
3 BRENT O. JEX
Deputy Attorney General
4 State Bar No. 235261
1300 I Street, Suite 125
5 Sacramento, CA 95814
Telephone: (916) 210-7864
6 Facsimile: (916) 327-8643
E-mail: Brent.Jex@doj.ca.gov
7 *Attorneys for Complainant*

8 **BEFORE THE**
9 **DEPARTMENT OF CONSUMER AFFAIRS**
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 79/25-12387

13 **RAUL CASTORENA**
14 **DBA ALL SMOG EXPRESS**
2240 G Street
Merced, CA 95340

ACCUSATION

15 **Automotive Repair Dealer Registration No.**
16 **ARD 231921**
Smog Check, Test-Only, Station License No.
17 **TC 231921**

18 **RAUL CASTORENA**
2240 G Street
Merced, CA 95340

19 **Smog Check Repair Technician License No.**
20 **EI 130205**
Smog Check Inspector License No. EO
21 **130205**

22 **and**

23 **VINNY RAUL CASTORENA LOPEZ**
16321 West Gable Court
24 Delhi, CA 95315

25 **Smog Check Inspector License No. EO**
26 **635555**

27 Respondents.
28

PARTIES

1
2 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as
3 the Chief of the Bureau of Automotive Repair (Bureau), Department of Consumer Affairs.

4 **Raul Castorena dba All Smog Express**

5 2. In and around 2004, the Bureau issued Automotive Repair Dealership Registration
6 (registration) Number ARD 231921 to Raul Castorena (Respondent Castorena) doing business as
7 All Smog Express (Respondent All Smog Express). The registration was in full force and effect
8 at all times relevant to the charges brought herein and will expire on February 28, 2026, unless
9 renewed.

10 3. On or about February 9, 2008, the Bureau issued Smog Check, Test-Only, Station
11 License (station license) Number TC 231921 to Respondent All Smog Express. The station
12 license was in full force and effect at all times relevant to the charges brought herein and will
13 expire on February 28, 2026, unless renewed.

14 **Raul Castorena**

15 4. In and around 2002, the Bureau issued Advanced Emission Specialist Technician
16 (EA) license number 130205 to Respondent Castorena. The license was due to expire on July 31,
17 2012. Pursuant to California Code of Regulations, title 16, 3340.28, subdivision (e), the license
18 was renewed as Smog Check Repair Technician License (technician license) Number EI 130205
19 and Smog Check Inspector License (inspector license) Number EO 130205, effective July 24,
20 2012. The technician license expired on July 31, 2020, and has not been renewed. The inspector
21 license will expire on July 31, 2026, unless renewed.

22 **Vinny Raul Castorena Lopez**

23 5. On or about May 24, 2013, the Bureau issued Smog Check Inspector License Number
24 EO 635555 to Vinny Raul Castorena Lopez (Respondent Lopez). The inspector license was in
25 full force and effect at all times relevant to the charges brought herein and will expire on
26 October 31, 2027, unless renewed.

27 ///

28 ///

1 **LICENSE INFORMATION**

2 **Raul Castorena dba All Smog Express #2**

3 6. On or about August 6, 2018, the Bureau issued Automotive Repair Dealership
4 Registration Number ARD 291708 to Respondent Castorena doing business as All Smog Express
5 #2 (All Smog Express #2). The registration expires on August 31, 2026, unless renewed.

6 7. On or about September 20, 2018, the Bureau issued Smog Check, Test-Only, Station
7 License Number TC 291708 to All Smog Express #2. The station license expires on August 31,
8 2026, unless renewed.

9 **JURISDICTION**

10 8. This Accusation is brought before the Director of the Department of Consumer
11 Affairs (Director) for the Bureau under the authority of the following laws.

12 9. Code section 22 states:

13 Board," as used in any provision of this code, refers to the board in which the
14 administration of the provision is vested, and unless otherwise expressly provided,
15 shall include "bureau," "commission," "committee," "department," "division,"
"examining committee," "program," and "agency."

16 10. Code section 477 provides, in pertinent part, that Board includes bureau, commission,
17 committee, department, division, examining committee, program, and agency. License includes
18 certificate, registration, or other means to engage in a business or profession regulated by the
19 Code.

20 11. Code section 9884.7 provides that the Director may revoke an automotive dealer
21 registration.

22 12. Code section 9884.13 provides, in pertinent part, that the expiration of a valid
23 registration shall not deprive the director or chief of jurisdiction to proceed with a disciplinary
24 proceeding against an automotive repair dealer or to render a decision invalidating a registration
25 temporarily or permanently.

26 13. Health and Safety Code (Health & Saf. Code) section 44002 provides, in pertinent
27 part, that the Director has all the powers and authority granted under the Automotive Repair Act
28 for enforcing the Motor Vehicle Inspection Program.

1 14. Health & Saf. Code section 44072.4, states that "[t]he director may take disciplinary
2 action against any licensee after a hearing as provided in this article by any of the following:

3 (a) Imposing probation upon terms and conditions to be set forth by the director.

4 (b) Suspending the license.

5 (c) Revoking the license.

6 15. Health & Saf. Code section 44072.6 provides, in pertinent part, that the expiration or
7 suspension of a license by operation of law, or by order or decision of the Director of Consumer
8 Affairs, or a court of law, or the voluntary surrender of the license shall not deprive the Director
9 of jurisdiction to proceed with disciplinary action.

10 16. Health & Saf. Code section 44072.8 states that when a license has been revoked or
11 suspended following a hearing under this article, any additional licenses issued under this chapter
12 in the name of the license may be likewise revoked or suspended by the director.

13 **STATUTORY PROVISIONS**

14 17. Code section 9884.7 states, in pertinent part:

15 (a) The director, if the automotive repair dealer cannot show there was a bona
16 fide error, may deny, suspend, revoke, or place on probation the registration of an
17 automotive repair dealer for any of the following acts or omissions related to the
18 conduct of the business of the automotive repair dealer, which are done by the
19 automotive repair dealer or any automotive technician, employee, partner, officer, or
20 member of the automotive repair dealer:

21 (1) Making or authorizing in any manner or by any means whatever any
22 statement written or oral which is untrue or misleading, and which is known, or which
23 by the exercise of reasonable care should be known, to be untrue or misleading.

24 . . .

25 (4) Any other conduct that constitutes fraud.

26 . . .

27 (6) Failure in any material respect to comply with the provisions of this chapter
28 or regulations adopted pursuant to it.

....

18. Code section 9889.22 states:

The willful making of any false statement or entry with regard to a material
matter in any oath, affidavit, certificate of compliance or noncompliance, or
application form which is required by this chapter or Chapter 5 (commencing with

1 Section 44000) of Part 5 of Division 26 of the Health and Safety Code constitutes
2 perjury and is punishable as provided in the Penal Code.

3 19. Health & Saf. Code section 44012 states, in pertinent part:

4 The test at the smog check stations shall be performed in accordance with
5 procedures prescribed by the department, pursuant to Section 44013, shall require, at
6 a minimum, loaded mode dynamometer testing in enhanced areas, and two-speed
7 testing in all other program areas, and shall ensure all of the following:

8 (a) Emission control systems required by state and federal law are reducing
9 excess emissions in accordance with the standards adopted pursuant to subdivisions
10 (a) and (c) of Section 44013.

11 . . .

12 (f) A visual or functional check is made of emission control devices specified
13 by the department, including the catalytic converter in those instances in which the
14 department determines it to be necessary to meet the findings of Section 44001. The
15 visual or functional check shall be performed in accordance with procedures
16 prescribed by the department.

17

18 20. Health & Saf. Code section 44015, subdivision (b), provides that a certificate of
19 compliance shall be used if a vehicle meets the requirements of Health & Saf. Code section
20 44012.

21 21. Health & Saf. Code section 44024.5, subdivision (a) states:

22 The department shall compile and maintain statistical and emissions profiles
23 and data from motor vehicles that are subject to the motor vehicle inspection
24 program. The department may use data from any source, including remote sensing
25 data, in use data, and other motor vehicle inspection program data, to develop and
26 confirm the validity of the profiles, to evaluate the program, and to assess the
27 performance of smog check stations. The department shall undertake these
28 requirements directly or seek a qualified vendor for these services.

22 22. Health & Saf. Code section 44032 provides that qualified technicians shall perform
23 tests of emissions control devices and systems in accordance with Health & Saf. Code section
24 44012.

25 23. Health & Saf. Code section 44037 states, in pertinent part:

26 The department shall compile and maintain records, using the sampling
27 methodology necessary to ensure their scientific validity and reliability, of tests and
28 repairs performed by qualified smog check technicians at licensed smog check
stations pursuant to this chapter on all of the following information:

1 (1)The motor vehicle identification information and the test data collected at the
2 station.

3 ...

4 (5)Data received and compiled through the use of the centralized computer
5 database and computer network to be established pursuant to Section 44037.1, and
6 any other information determined to be essential by the department for program
7 enhancement to achieve greater efficiency, consumer protection, cost-effectiveness,
8 convenience, or emission reductions.

9

10 24. Health & Saf. Code section 44037.1 states, in pertinent part:

11 (a) On or before January 1, 1995, the department shall design and establish the
12 equipment necessary to operate a centralized computer data base and computer
13 network that is readily accessible by all licensed smog check technicians on a real
14 time basis.

15 (b) The centralized computer data base and network shall be designed with all
16 of the following capabilities:

17 ...

18 (2) To provide smog check technicians and the department with information as
19 to the date and result of prior smog check tests performed on each vehicle to
20 discourage vehicle owners from shopping for certificates of compliance and to permit
21 the department to identify smog check stations for further investigation as potential
22 violators of this chapter.

23 (3) To provide the department with data on the failure rates and repair
24 effectiveness for vehicles of each make and model year on a statewide basis, and by
25 smog check station and technician, to facilitate identification of smog check stations
26 and technicians as potential violators of this chapter.

27 ...

28 (8) To be compatible with the department's recordkeeping and compilation
requirements established by Section 44037.

...

(c) After January 1, 1995, each smog check station shall transmit vehicle data
emission test results to the department's centralized data base. Each smog check
station shall also transmit vehicle data and emission measurements made before and
after repair. The department shall establish, by regulation, the form, manner, and
frequency of the data transmittals.

....

25. Health & Saf. Code section 44059 states:

The willful making of any false statement or entry with regard to a material
matter in any oath, affidavit, certificate of compliance or noncompliance, or
application form which is required by this chapter or Chapter 20.3 (commencing with

1 Section 9880) of Division 3 of the Business and Professions Code, constitutes perjury
2 and is punishable as provided in the Penal Code.

3 26. Health & Saf. Code section 44072.2 states, in pertinent part:

4 The director may suspend, revoke, or take other disciplinary action against a
5 license as provided in this article if the licensee, or any partner, officer, or director
thereof, does any of the following:

6 (a) Violates any section of this chapter [the Motor Vehicle Inspection Program
7 (Health and Saf. Code, § 44000, et seq.)] and the regulations adopted pursuant to it,
which related to the licensed activities.

8 . . .

9 (d) Commits any act involving dishonesty, fraud, or deceit whereby another is
10 injured.

11

12 REGULATORY PROVISIONS

13 27. California Code of Regulations, title 16 (CCR), section 3340.17, subdivision (c),
14 states, "Vehicle data and test results from the OBD Inspection System (OIS) shall be transmitted
15 to the bureau's centralized database."

16 28. CCR, section 3340.30 states, in pertinent part:

17 A smog check technician shall comply with the following requirements at all
18 times while licensed.

19 (a) A licensed technician shall inspect, test and repair vehicles in accordance
20 with section 44012 of the Health and Safety Code, section 44035 of the Health and
Safety Code, and section 3340.42 of this article. . . .

21 29. CCR, section 3340.35, subdivision (c) states:

22 A licensed station shall issue a certificate of compliance or noncompliance to
23 the owner or operator of any vehicle that has been inspected in accordance with the
24 procedures specified in section 3340.42 of this article and has all the required
emission control equipment and devices installed and functioning correctly. . .

25 30. CCR, section 3340.41, subdivision (c) states:

26 No person shall enter any vehicle identification information or emission control
27 system identification data for any vehicle other than the one being tested into the EIS
or OIS. Nor shall any person enter into the EIS or OIS any false information about
28 the vehicle being tested.

///

1 31. CCR, section 3340.42 states, in pertinent part:

2 Smog check inspection methods are prescribed in the Smog Check Manual,
3 referenced by section 3340.45.

4 (a) All vehicles subject to a smog check inspection, shall receive one of the
5 following test methods:

6 . . .

7 (3) An OBD-focused test, shall be the test method used to inspect gasoline-
8 powered vehicles 2000 model-year and newer, and diesel-powered vehicles 1998
9 model-year and newer. The OBD test failure criteria are specified in section
10 3340.42.2.

11

12 32. CCR section 3371 states:

13 No dealer shall publish, utter, or make or cause to be published, uttered, or
14 made any false or misleading statement or advertisement which is known to be false
15 or misleading, or which by the exercise of reasonable care should be known to be
16 false or misleading. Advertisements and advertising signs shall clearly show the
17 following:

18 (a) Firm Name and Address. The dealer's firm name and address as they
19 appear on the State registration certificate as an automotive repair dealer; and

20 (b) Telephone Number. If a telephone number appears in an advertisement or
21 on an advertising sign, this number shall be the same number as that listed for the
22 dealer's firm name and address in the telephone directory, or in the telephone
23 company records if such number is assigned to the dealer subsequent to the
24 publication of such telephone directory.

25 33. CCR, section 3373 states:

26 No automotive repair dealer or individual in charge shall, in filling out an
27 estimate, invoice, or work order, or record required to be maintained by section
28 3340.15(f) of this chapter, withhold therefrom or insert therein any statement or
information which will cause any such document to be false or misleading, or where
the tendency or effect thereby would be to mislead or deceive customers, prospective
customers, or the public.

29 COST RECOVERY

30 34. Code section 125.3 provides, in pertinent part, that a Board may request the
31 administrative law judge to direct a licentiate found to have committed a violation or violations of
32 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
33 enforcement of the case.

1 **UPDATED SMOG CHECK PROGRAM – ON BOARD DIAGNOSTIC SYSTEM**

2 35. On or about March 9, 2015, California's Smog Check Program was updated to keep
3 pace with ever-advancing technology. The program update requires the use of an On-Board
4 Diagnostic Inspection System (BAR-OIS). BAR-OIS is the smog check equipment required in all
5 areas of the State when inspecting most model-year 2000 and newer gasoline and hybrid vehicles
6 and most 1998 and newer diesel vehicles. The system consists of a certified Data Acquisition Device
7 (DAD), computer, bar code scanner, and printer.

8 36. The DAD is an On-Board Diagnostic (OBD) scan tool that, when requested by the
9 California BAR-OIS software, retrieves OBD data from the vehicle. The DAD connects between
10 the BAR-OIS computer and the vehicle's diagnostic link connector. The bar code scanner is used
11 to input technician information, the vehicle identification number, and the Department of Motor
12 Vehicle (DMV) renewal information. The vehicle identification number (VIN) that is physically
13 present on all vehicles is required to be programmed into the vehicle's On-Board Diagnostics —
14 Generation II (OBD II) on 2005 and newer vehicles, and on many occasions was programmed
15 into the OBD II computer in earlier model-years. The electronically programmed VIN is referred
16 to as the "eVIN", is captured by the Bureau during a smog check inspection and should match the
17 physical VIN on the vehicle. The printer is used to provide a vehicle inspection report, which
18 shows the inspection results and the Smog Check Certificate of Compliance Number for passing
19 vehicles. Data retrieved and recorded during an OIS smog check includes the eVIN, the
20 communication protocol¹, and the number of Parameter Identifications (PID).²

21 37. Smog Check Inspectors are required to perform visual and functional tests to the
22 vehicle as outlined in the Smog Check Manual. The Smog Check Inspector must conduct a visual
23 inspection of the emission control components/devices to verify they are present and properly
24 connected. The Smog Check Inspector must perform a functional test of the malfunction

25 ¹ The OBD II communication protocol describes the specified communication "language"
26 used by the OBD II computer to communication to scan tools and other devices such as the BAR-
27 OIS. The communication protocol is programmed into the vehicle's on-board computer during
28 manufacture and does not change.

² PIDs are data points reported by the vehicle's on-board computer to a scan tool or BAR-
 OIS, such as engine speed, vehicle speed, engine temperature, etc. The PID count is the number
 of data points.

1 Indicator Lamp (MIL). The BAR-OIS prompts the Smog Check Inspector to start the vehicle's
2 engine and might ask them to raise the engine RPM. The BAR-OIS software makes the
3 determination whether the vehicle passes the inspection based on the results of the visual,
4 functional, and OBD II tests.

5 38. The EIS or BAR-OIS, dependent upon the test type, prints a VIR, which is a physical
6 record of the test results and shows the Smog Check Certificate of Compliance number that was
7 issued if the vehicle passed the Smog Check Inspection. The Smog Check Inspector must sign the
8 VIR to show that the inspection was performed within BAR guidelines. Licensed Smog Check
9 Inspectors are the only persons authorized by the BAR to perform official Smog Check
10 Inspections. They are issued a license and a personal access code which are used to gain access to
11 the EIS and used to set up a username and password within the BAR-OIS to perform Smog Check
12 Inspections. Beginning May 1, 2023, Smog Check inspectors must use a biometric palm scanner
13 instead of a password login for the BAR-OIS.

14 39. The Vehicle Identification Database (VID) contains vehicle registration data from
15 DMV, emission standards, vehicle Smog Check Inspection data, smog check station and inspector
16 information, and Smog Check Certificates of Compliance. The VID has an internal clock that is
17 set to Pacific Standard Time and records the time and date for each inspection. Each Smog Check
18 Certificate of Compliance has a unique control number so that it can be tracked to determine
19 which Smog Check Station purchased it and which vehicle it was issued to. The VID receives the
20 Smog Check Inspection results immediately following the inspection. BAR can access the VID to
21 view test data for Smog Check Inspections performed at any Smog Check Station. BAR can
22 search, retrieve, and print test records for all tested vehicles.

23 40. BAR has identified several means by which fraudulent Smog Check Certificates of
24 Compliance are issued to vehicles that will not pass a Smog Check Inspection or are not present
25 during the Smog Check Inspection. Some of these methods are known as "clean piping," "clean
26 gassing," and "clean plugging." Electronic defeat devices are used to simulate vehicles during the
27 BAR-OIS Smog Check Inspection. These devices mimic vehicle data for the purpose of
28 generating passing data to issue fraudulent Smog Check Certificates of Compliance. This method

1 is known as "clean plugging." Clean plugging is when another vehicle, an electronic defeat
2 device, and/or computer programming, is used to generate passing data readings to vehicles that
3 will not pass the inspection or are not present for testing.

4 **REVIEW OF BAR'S VEHICLE INFORMATION DATABASE DATA**

5 41. Bureau representative C.C. reviewed BAR'S VID for smog check inspections
6 performed at Respondent All Smog Express' facility. C.C. found smog check inspector
7 Respondent Lopez had performed smog check inspections on 10 vehicles that were improperly
8 inspected and were issued smog check certificates despite having different eVINs, different
9 communication protocols, and/or different PID counts. This meant that these vehicles were not
10 tested during the OBD II functional test, constituting clean-plugging, and resulting in the issuance
11 of fraudulent certificates of compliance for the vehicles.

12 **Vehicle 1**

13 42. The OIS test data showed that on February 4, 2025, Respondent Lopez performed a
14 smog check inspection on a 2006 Ford F-150 Supercrew (Vehicle 1), resulting in the issuance of
15 Smog Check Certificate of Compliance Number JD056003C. The OIS test data for Vehicle 1
16 showed that the eVIN recorded during the inspection did not match the physical VIN on the
17 vehicle and the PID count transmitted as 43/4. C.C. reviewed the Comparative OIS Test Data for
18 other 2006 Ford F-150 Supercrew vehicles and found that they transmit the correct eVIN and had
19 the expected PID count of 44. C.C. found that the PID count recorded during the inspection on
20 Vehicle 1 was not consistent with the PID count for the make and model of this vehicle by other
21 smog check stations. C.C. concluded that the DAD had not been connected to Vehicle 1 during
22 the smog check inspection performed by Respondent Lopez.

23 43. The OIS test data also showed that on September 26, 2020, Vehicle 1 had been tested
24 at another smog facility and passed inspection. C.C. found that the eVIN had been reported
25 correctly during the September 26, 2020, inspection, and that the PID count recorded was
26 consistent with the expected OIS Test Data and Similar Vehicle OIS Test Data for 2006 Ford F-
27 150 Supercrew vehicles.

28 ///

1 44. Further, C.C. researched the eVIN reported during the February 4, 2025, inspection
2 and found that it belonged to a 2014 GMC Savana 3500 Cutaway rental vehicle pursuant to a
3 CARFAX report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles
4 showed that the eVIN is reported correctly and the PID count was reported as expected. C.C.
5 found that the eVIN and PID count for the 2014 GMC Savana 3500 Cutaway vehicle matched
6 what had been reported for the February 4, 2025, inspection on Vehicle 1. C.C. concluded that
7 Respondent had used the 2014 GMC Savana 3500 Cutaway's properly functioning OBD II
8 system during the February 4, 2025, inspection on Vehicle 1, resulting in the issuance of a
9 fraudulent smog certificate of compliance for the vehicle.

10 **Vehicle 2**

11 45. The OIS test data showed that on February 5, 2025, Respondent Lopez performed a
12 smog check inspection on a 2007 Chevrolet Silverado C1500 (Vehicle 2), resulting in the
13 issuance of Smog Check Certificate of Compliance Number JD056004C. The OIS test data for
14 Vehicle 2 showed that the eVIN recorded during the inspection did not match the physical VIN
15 on the vehicle. C.C. reviewed the Comparative OIS Test Data for other Chevrolet Silverado
16 C1500 vehicles and found that they transmit the correct eVIN. C.C. concluded that the DAD had
17 not been connected to Vehicle 2 during the smog check inspection performed by Respondent
18 Lopez.

19 46. The OIS test data also showed that on February 3, 2021, Vehicle 2 had been tested at
20 another smog facility and passed inspection. C.C. found that the eVIN had been reported
21 correctly during the February 3, 2021, inspection.

22 47. Further, C.C. researched the eVIN reported during the February 5, 2025, inspection
23 and found that it belonged to a 2014 GMC Savana 3500 Cutaway rental vehicle pursuant to a
24 CARFAX report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles
25 showed that the eVIN is reported correctly. C.C. found that the eVIN for the 2014 GMC Savana
26 3500 Cutaway rental car matched what was reported for the February 5, 2025, inspection on
27 Vehicle 2. C.C. concluded that Respondent used the 2014 GMC Savana 3500 Cutaway's

28 ///

1 properly functioning OBD II system during the February 5, 2025, inspection on Vehicle 2,
2 resulting in the issuance of a fraudulent smog certificate of compliance for the vehicle.

3 **Vehicle 3**

4 48. The OIS test data showed that on February 28, 2025, Respondent Lopez performed a
5 smog check inspection on a 2002 Chevrolet Silverado C1500 (Vehicle 3), resulting in the
6 issuance of Smog Check Certificate of Compliance Number UK448356C. The OIS test data for
7 Vehicle 3 showed that the eVIN recorded during the inspection did not match the physical VIN
8 on the vehicle, the communication protocol was transmitted as ICAN11bt5 and the PID count was
9 43/4. C.C. reviewed the Comparative OIS Test Data for other 2002 Chevrolet Silverado C1500
10 vehicles and found that they transmit the correct eVIN and had the expected communication
11 protocol of JVPW and transmit a PID count of 22. C.C. found that the communication protocol
12 and PID count recorded during the inspection on Vehicle 3 were not consistent with the
13 communication protocol and PID count for the make and model of this vehicle by other smog
14 check stations. C.C. concluded that the DAD had not been connected to Vehicle 3 during the
15 smog check inspection performed by Respondent Lopez.

16 49. The OIS test data also showed that on February 1, 2021, Vehicle 3 had been tested at
17 another smog facility and passed inspection. C.C. found that the eVIN had been reported
18 correctly during the February 1, 2020, inspection, and that the communication protocol and PID
19 count recorded were consistent with the expected OIS Test Data and Similar Vehicle OIS Test
20 Data for 2002 Chevrolet Silverado C1500 vehicles.

21 50. Further, C.C. researched the eVIN reported during the February 28, 2025, inspection
22 and found that it belonged to a 2014 GMC Savana 3500 Cutaway vehicle pursuant to a CARFAX
23 report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles showed that
24 the eVIN is reported correctly and the communication protocol and PID count were reported as
25 expected. C.C. found that the eVIN, communication protocol and PID count for the 2014 GMC
26 Savana 3500 Cutaway vehicle matched what had been reported for the February 4, 2025,
27 inspection on Vehicle 1. C.C. concluded that Respondent had used the 2014 GMC Savana 3500

28 ///

1 Cutaway's properly functioning OBD II system during the February 28, 2025, inspection on
2 Vehicle 3, resulting in the issuance of a fraudulent smog certificate of compliance for the vehicle.

3 **Vehicle 4**

4 51. The OIS test data showed that on March 19, 2025, Respondent Lopez performed a
5 smog check inspection on a 2005 Honda Accord EX (Vehicle 4), resulting in the issuance of
6 Smog Check Certificate of Compliance Number JD699269C. The OIS test data for Vehicle 4
7 showed that the eVIN recorded during the inspection did not match the physical VIN on the
8 vehicle, the communication protocol transmitted as ICAN11bt5 and the PID count was 43/4.
9 C.C. reviewed the Comparative OIS Test Data for other 2005 Honda Accord EX vehicles and
10 found that they transmit the correct eVIN and had the expected communication protocol of 1914
11 and transmit a PID count of 24. C.C. found that the communication protocol and PID count
12 recorded during the inspection on Vehicle 4 were not consistent with the communication protocol
13 and PID count for the make and model of this vehicle by other smog check stations. C.C.
14 concluded that the DAD had not been connected to Vehicle 4 during the smog check inspection
15 performed by Respondent Lopez.

16 52. The OIS test data also showed that on April 6, 2020, Vehicle 4 had been tested at
17 another smog facility and passed inspection. C.C. found that the eVIN had been reported
18 correctly during the April 6, 2020, inspection, and that the communication protocol and PID
19 count recorded were consistent with the expected OIS Test Data and Similar Vehicle OIS Test
20 Data for 2005 Honda Accord EX vehicles.

21 53. Further, C.C. researched the eVIN reported during the February 28, 2025, inspection
22 and found that it belonged to a 2014 GMC Savana 3500 Cutaway vehicle pursuant to a CARFAX
23 report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles showed that
24 the eVIN is reported correctly and the communication protocol and PID count were reported as
25 expected. C.C. found that the eVIN, communication protocol and PID count for the 2014 GMC
26 Savana 3500 Cutaway vehicle matched what had been reported for the March 19, 2025,
27 inspection on Vehicle 4. C.C. concluded that Respondent had used the 2014 GMC Savana 3500

28 ///

1 Cutaway's properly functioning OBD II system during the March 19, 2025, inspection on
2 Vehicle 4, resulting in the issuance of a fraudulent smog certificate of compliance for the vehicle.

3 **Vehicle 5**

4 54. The OIS test data showed that on April 7, 2025, Respondent Lopez performed a smog
5 check inspection on a 2004 Chevrolet Silverado K2500 Heavy Duty (Vehicle 5), resulting in the
6 issuance of Smog Check Certificate of Compliance Number UM108984C. The OIS test data for
7 Vehicle 5 showed that the eVIN recorded during the inspection did not match the physical VIN
8 on the vehicle, the communication protocol transmitted as ICAN11bt5, and the PID count was
9 43/4. C.C. reviewed the Comparative OIS Test Data for other 2004 Chevrolet Silverado K2500
10 Heavy Duty vehicles and found that they transmit the correct eVIN and had the expected
11 communication protocol of JVPW and transmit a PID count of 22. C.C. found that the
12 communication protocol and PID count recorded during the inspection on Vehicle 5 were not
13 consistent with the communication protocol and PID count for the make and model of this vehicle
14 by other smog check stations. C.C. concluded that the DAD had not been connected to Vehicle 5
15 during the smog check inspection performed by Respondent Lopez.

16 55. The OIS test data also showed that on September 27, 2024, Vehicle 5 had been tested
17 at another smog facility and did not pass inspection. C.C. found that the eVIN had been reported
18 correctly during the September 27, 2024, inspection, and that the communication protocol and
19 PID count recorded were consistent with the expected OIS Test Data and Similar Vehicle OIS
20 Test Data for 2004 Chevrolet Silverado K2500 Heavy Duty vehicles.

21 56. Further, C.C. researched the eVIN reported during the April 7, 2025, inspection and
22 found that it belonged to a 2014 GMC Savana 3500 Cutaway vehicle pursuant to a CARFAX
23 report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles showed that
24 the eVIN is reported correctly and the communication protocol and PID count were reported as
25 expected. C.C. found that the eVIN, communication protocol and PID count for the 2014 GMC
26 Savana 3500 Cutaway vehicle matched what had been reported for the April 7, 2025, inspection
27 on Vehicle 5. C.C. concluded that Respondent had used the 2014 GMC Savana 3500 Cutaway's

28 ///

1 properly functioning OBD II system during the April 7, 2025, inspection on Vehicle 5, resulting
2 in the issuance of a fraudulent smog certificate of compliance for the vehicle.

3 **Vehicle 6**

4 57. The OIS test data showed that on April 8, 2025, Respondent Lopez performed a smog
5 check inspection on a 2006 Hummer H3 (Vehicle 6), resulting in the issuance of Smog Check
6 Certificate of Compliance Number UM108995C. The OIS test data for Vehicle 6 showed that the
7 eVIN recorded during the inspection did not match the physical VIN on the vehicle, the
8 communication protocol transmitted as ICAN11bt5 and the PID count was 43/4. C.C. reviewed
9 the Comparative OIS Test Data for other 2006 Hummer H3 vehicles and found that they transmit
10 the correct eVIN and had the expected communication protocol of JVPW and transmit a PID
11 count of 19. C.C. found that the communication protocol and PID count recorded during the
12 inspection on Vehicle 6 were not consistent with the communication protocol and PID count for
13 the make and model of this vehicle by other smog check stations. C.C. concluded that the DAD
14 had not been connected to Vehicle 6 during the smog check inspection performed by Respondent
15 Lopez.

16 58. The OIS test data also showed that on May 11, 2024, Vehicle 6 had been tested at
17 another smog facility and did not pass inspection. C.C. found that the eVIN had been reported
18 correctly during the May 11, 2024, inspection, and that the communication protocol and PID
19 count recorded were consistent with the expected OIS Test Data and Similar Vehicle OIS Test
20 Data for 2006 Hummer H3 vehicles.

21 59. Further, C.C. researched the eVIN reported during the April 8, 2025, inspection and
22 found that it belonged to a 2014 GMC Savana 3500 Cutaway vehicle pursuant to a CARFAX
23 report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles showed that
24 the eVIN is reported correctly and the communication protocol and PID count were reported as
25 expected. C.C. found that the eVIN, communication protocol and PID count for the 2014 GMC
26 Savana 3500 Cutaway vehicle matched what had been reported for the April 8, 2025, inspection
27 on Vehicle 6. C.C. concluded that Respondent had used the 2014 GMC Savana 3500 Cutaway's

28 ///

1 properly functioning OBD II system during the April 8, 2025, inspection on Vehicle 6, resulting
2 in the issuance of a fraudulent smog certificate of compliance for the vehicle.

3 **Vehicle 7**

4 60. The OIS test data showed that on April 22, 2025, Respondent Lopez performed a
5 smog check inspection on a 2014 Chevrolet Silverado C1500 LT (Vehicle 7), resulting in the
6 issuance of Smog Check Certificate of Compliance Number UM788899C. The OIS test data for
7 Vehicle 7 showed that the eVIN recorded during the inspection did not match the physical VIN
8 on the vehicle and the PID count transmitted as 43/4. C.C. reviewed the Comparative OIS Test
9 Data for other 2014 Chevrolet Silverado C1500 LT vehicles and found that they transmit the
10 correct eVIN and had the expected PID count of 49/4. C.C. found that the PID count recorded
11 during the inspection on Vehicle 7 was not consistent with the PID count for the make and model
12 of this vehicle by other smog check stations. C.C. concluded that the DAD had not been
13 connected to Vehicle 7 during the smog check inspection performed by Respondent Lopez.

14 61. The OIS test data also showed that on February 17, 2023, Vehicle 7 had been tested at
15 another smog facility and did not pass inspection. C.C. found that the eVIN had been reported
16 correctly during the February 17, 2023, inspection, and that the PID count recorded was
17 consistent with the expected OIS Test Data and Similar Vehicle OIS Test Data for 2014
18 Chevrolet Silverado C1500 LT vehicles.

19 62. Further, C.C. researched the eVIN reported during the April 22, 2025, inspection and
20 found that it belonged to a 2014 GMC Savana 3500 Cutaway rental vehicle pursuant to a
21 CARFAX report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles
22 showed that the eVIN is reported correctly and the PID count was reported as expected. C.C.
23 found that the eVIN and PID count for the 2014 GMC Savana 3500 Cutaway vehicle matched
24 what had been reported for the April 22, 2025, inspection on Vehicle 7. C.C. concluded that
25 Respondent had used the 2014 GMC Savana 3500 Cutaway's properly functioning OBD II
26 system during the April 22, 2025, inspection on Vehicle 7, resulting in the issuance of a
27 fraudulent smog certificate of compliance for the vehicle.

28 ///

Vehicle 8

63. The OIS test data showed that on June 18, 2025, Respondent Lopez performed a smog check inspection on a 2017 Chevrolet Corvette Stingray (Vehicle 8), resulting in the issuance of Smog Check Certificate of Compliance Number UQ698215C. The OIS test data for Vehicle 8 showed that the eVIN recorded during the inspection did not match the physical VIN on the vehicle and the PID count transmitted as 43/4. C.C. reviewed the Comparative OIS Test Data for other 2017 Chevrolet Corvette Stingray vehicles and found that they transmit the correct eVIN and had the expected PID count of 50/4/4. C.C. found that the PID count recorded during the inspection on Vehicle 8 was not consistent with the PID count for the make and model of this vehicle by other smog check stations. C.C. concluded that the DAD had not been connected to Vehicle 8 during the smog check inspection performed by Respondent Lopez.

64. Further, C.C. researched the eVIN reported during the inspection and found that it belonged to a 2014 GMC Savana 3500 Cutaway vehicle pursuant to a CARFAX report. Similar vehicle OIS test data for 2014 GMC Savana 3500 Cutaway vehicles showed that the eVIN is reported correctly and the PID count was reported as expected. C.C. found that the eVIN and PID count for the 2014 GMC Savana 3500 Cutaway vehicle matched what had been reported during the inspection on Vehicle 8. C.C. concluded that Respondent had used the 2014 GMC Savana 3500 Cutaway's properly functioning OBD II system during the inspection on Vehicle 8, resulting in the issuance of a fraudulent smog certificate of compliance for the vehicle.

Vehicle 9

65. The OIS test data showed that on June 17, 2025, Respondent Lopez performed a smog check inspection on a 2012 Ford Mustang GT (Vehicle 9), resulting in the issuance of Smog Check Certificate of Compliance Number UQ698205C. The OIS test data for Vehicle 9 showed that the eVIN recorded during the inspection did not match the physical VIN on the vehicle and the PID count transmitted as 43. C.C. reviewed the Comparative OIS Test Data for other 2012 Ford Mustang GT vehicles and found that they transmit the correct eVIN and had the expected PID count of 42. C.C. found that the PID count recorded during the inspection on Vehicle 9 was not consistent with the PID count for the make and model of this vehicle by other

1 smog check stations. C.C. concluded that the DAD had not been connected to Vehicle 9 during
2 the smog check inspection performed by Respondent Lopez.

3 66. The OIS test data also showed that on April 4, 2023, Vehicle 9 had been tested at
4 another smog facility and passed inspection. C.C. found that the eVIN had been reported correctly
5 during the April 4, 2023, inspection, and that the eVIN, the communication protocol and PID
6 count recorded were consistent with the expected OIS Test Data and Similar Vehicle OIS Test
7 Data for 2012 Ford Mustang GT vehicles.

8 67. Further, C.C. researched the eVIN reported during the inspection and found that it
9 belonged to a 2011 Ford Econoline Super Duty Van Cutaway commercial vehicle pursuant to a
10 CARFAX report. Similar vehicle OIS test data for 2011 Ford Econoline Super Duty Van
11 Cutaway vehicles showed that the eVIN is reported correctly and the PID count was reported as
12 expected. C.C. found that the eVIN and PID count for the 2011 Ford Econoline Super Duty Van
13 Cutaway commercial vehicle matched what had been reported during the inspection on Vehicle 9.
14 C.C. concluded that Respondent had used the 2011 Econoline Super Duty Van Cutaway's
15 properly functioning OBD II system during the inspection on Vehicle 9, resulting in the issuance
16 of a fraudulent smog certificate of compliance for the vehicle.

17 **Vehicle 10**

18 68. The OIS test data showed that on June 20, 2025, Respondent Lopez performed a
19 smog check inspection on a 2007 Chevrolet Tahoe K1500 (Vehicle 10), resulting in the issuance
20 of Smog Check Certificate of Compliance Number UQ698230C. The OIS test data for Vehicle
21 10 showed that the eVIN recorded during the inspection did not match the physical VIN on the
22 vehicle and the PID count transmitted as 43. C.C. reviewed the Comparative OIS Test Data for
23 other 2007 Chevrolet Tahoe K1500 vehicles and found that they transmit the correct eVIN and
24 had the expected PID count of 43/7 or 44/7. C.C. found that the PID count recorded during the
25 inspection on Vehicle 10 was not consistent with the PID count for the make and model of this
26 vehicle by other smog check stations. C.C. concluded that the DAD had not been connected to
27 Vehicle 10 during the smog check inspection performed by Respondent Lopez.

28 ///

69. The OIS test data also showed that on May 28, 2025, Vehicle 10 was tested at another smog facility and did not pass inspection. C.C. found that the eVIN had been reported correctly during the May 28, 2025, inspection, and that the PID count recorded was consistent with the expected OIS Test Data and Similar Vehicle OIS Test Data for 2007 Chevrolet Tahoe K1500 vehicles.

70. Further, C.C. researched the eVIN reported during the June 20, 2025, inspection and found that it belonged to a 2011 Ford Econoline Super Duty Van Cutaway commercial vehicle pursuant to a CARFAX report. Similar vehicle OIS test data for 2011 Ford Econoline Super Duty Van Cutaway vehicles showed that the eVIN is reported correctly and the PID count was reported as expected. C.C. found that the eVIN and PID count for the 2011 Ford Econoline Super Duty Van Cutaway commercial vehicle matched what had been reported for the June 20, 2025, inspection on Vehicle 10. C.C. concluded that Respondent had used the 2011 Econoline Super Duty Van Cutaway's properly functioning OBD II system during the June 20, 2025, inspection on Vehicle 10, resulting in the issuance of a fraudulent smog certificate of compliance for the vehicle.

FIRST CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements - Automotive Repair Dealer Registration)

71. Respondent All Smog Express' registration is subject to disciplinary action under Code section 9884.7, subdivision (a)(1), in conjunction with Code section 9889.22, in that it made or authorized statements which Respondent All Smog Express knew, or in the exercise of reasonable care should have known to be true or misleading. Specifically, Respondent All Smog Express certified that Vehicles 1 through 10, identified above in paragraphs 42 through 70, passed inspection and were in compliance with applicable laws and regulations. In fact, Respondent All Smog Express conducted smog check inspections on vehicles using clean-plugging methods, in that it substituted different vehicles during the inspection in order to issue smog certificates of compliance for the vehicles and did not test or inspect the vehicles as required by Health & Saf. Code section 44012.

///

1 **SECOND CAUSE FOR DISCIPLINE**

2 **(Fraud - Automotive Repair Dealer Registration)**

3 72. Respondent All Smog Express' registration is subject to disciplinary action under
4 Code section 9884.7, subdivision (a)(4), in that Respondent All Smog Express committed acts
5 which constitute fraud by using smog check certificates of compliance for Vehicles 1 through 10
6 identified in paragraphs 42 through 70, without ensuring that bona fide inspections were
7 performed of the emission control devices and systems on the vehicles, thereby depriving the
8 People of the State of California of the protection afforded by the Motor Vehicle Inspection
9 Program.

10 **THIRD CAUSE FOR DISCIPLINE**

11 **(Unfair Business Practice - Automotive Repair Dealer Registration)**

12 73. Respondent All Smog Express' registration is subject to disciplinary action under
13 Code section 9884.7, subdivision (a)(6), in that it utilized unfair business practices when
14 Respondent Lopez issued electronic smog check certificates of compliance for Vehicles 1
15 through 10, identified in paragraphs 42 through 70, above.

16 **FOURTH CAUSE FOR DISCIPLINE**

17 **(Violations of the Motor Vehicle Inspection Program - Smog Check Station License)**

18 74. Respondent All Smog Express' station license is subject to disciplinary action under
19 Health & Saf. Code section 44072.2, subdivision (a), in that regarding Vehicles 1 through 10,
20 identified in paragraphs 42 through 70, Respondent All Smog Express failed to comply with
21 provisions of the Health & Saf. Code, as follows:

- 22 a. **Section 44012:** Respondent All Smog Express' failed to ensure that the
23 emission control tests were performed on the vehicles in accordance with procedures prescribed
24 by the department.
- 25 b. **Section 44015:** Respondent All Smog Express issued electronic smog check
26 certificates of compliance for the vehicles without ensuring that the vehicles were properly tested
27 and inspected to determine they were in compliance with Health & Saf. Code section 44012.

28 ///

1 **FIFTH CAUSE FOR DISCIPLINE**

2 **(Violations of Regulations Pursuant to the Motor Vehicle Inspection Program - Smog Check**
3 **Station License)**

4 75. Respondent All Smog Express' station license is subject to disciplinary action under
5 Code section 44072.2, subdivision (c), in that regarding Vehicles 1 through 10, identified in
6 paragraphs 42 through 70, it failed to comply with provisions of the CCR, as follow:

7 a. **Section 3340.35, subdivision (c):** Respondent All Smog Express failed to
8 inspect and test the vehicles in accordance with the procedures specified in CCR, section 3340.42,
9 and failed to ensure that the vehicles had all the required emission control equipment and devices
10 installed and functioning properly.

11 b. **Section 3373:** Respondent All Smog Express made or authorized documents
12 which it knew or which by exercise of reasonable care should have known to be untrue or
13 misleading, when it issued fraudulent smog check certificates of compliance for Vehicles 1
14 through 10.

15 **SIXTH CAUSE FOR DISCIPLINE**

16 **(Dishonesty, Fraud or Deceit – Smog Check Station License)**

17 76. Respondent All Smog Express' station license is subject to disciplinary action under
18 Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health & Saf. Code
19 section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts
20 whereby another was injured by using false information for electronic smog check certificates of
21 compliance issued for Vehicles 1 through 10, identified in paragraphs 42 through 70, thereby
22 failing to perform bona fide inspections of the emission control device and systems on the
23 vehicles and depriving the People of the State of California of the protection afforded by the
24 Motor Vehicle Inspection Program.

25 **SEVENTH CAUSE FOR DISCIPLINE**

26 **(Dishonesty, Fraud or Deceit – Castorena's Smog Check Repair Technician License)**

27 77. Respondent Castorena's technician license is subject to disciplinary action under
28 Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health and Saf. Code

1 section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts
2 whereby another was injured by issuing electronic smog check certificates of compliance for
3 Vehicles 1 through 10, identified in paragraphs 42 through 70, without ensuring a bona fide
4 inspection was performed of the emission control devices and systems on the vehicles, thereby
5 depriving the People of the State of California of the protection afforded by the Motor Vehicle
6 Inspection Program.

7 **EIGHTH CAUSE FOR DISCIPLINE**

8 **(Dishonesty, Fraud or Deceit –Castorena’s Smog Check Inspector License)**

9 78. Respondent Castorena’s inspector license is subject to disciplinary action under
10 Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health and Saf. Code
11 section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts
12 whereby another was injured by issuing electronic smog check certificates of compliance for
13 Vehicles 1 through 10, identified in paragraphs 42 through 70, without ensuring a bona fide
14 inspection was performed of the emission control devices and systems on the vehicles, thereby
15 depriving the People of the State of California of the protection afforded by the Motor Vehicle
16 Inspection Program.

17 **NINTH CAUSE FOR DISCIPLINE**

18 **(Violations of the Motor Vehicle Inspection Program – Lopez’ Smog Check Inspector** 19 **License)**

20 79. Respondent Lopez’ smog check inspector license is subject to disciplinary action
21 under Health & Saf. Code section 44072.2, subdivision (a), in that he violated section 44032 of
22 that Code. Specifically, Respondent Lopez failed to perform the emission control tests on
23 Vehicles 1 through 10, identified in paragraphs 42 through 70, in accordance with procedures
24 prescribed by the department.

25 **TENTH CAUSE FOR DISCIPLINE**

26 **(Failure to Comply with Regulations – Lopez’ Smog Check Inspector License)**

27 80. Respondent Lopez’ smog check inspector license is subject to disciplinary action
28 under Health & Saf. Code section 44072.2, subdivision (c), in that regarding Vehicles 1 through

1 10, identified in paragraphs 42 through 70, he failed to comply with provisions of the CCR, as
2 follow:

3 a. **Section 3340.30, subdivision (a):** Respondent Lopez failed to inspect and test
4 the vehicles in accordance with Health & Saf. Code sections 44012 and 4035, and CCR section
5 3340.42.

6 b. **Section 3340.42:** Respondent Lopez failed to conduct the required smog check
7 tests on vehicles in accordance with the Bureau's specifications.

8 **ELEVENTH CAUSE FOR DISCIPLINE**

9 **(Dishonesty, Fraud or Deceit – Lopez' Smog Check Inspector License)**

10 81. Respondent Lopez' smog check inspector's license is subject to disciplinary action
11 under Health & Saf. Code section 44072.2, subdivision (d), in conjunction with Health & Saf.
12 Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful
13 acts whereby another was injured by using false information for electronic smog check
14 certificates of compliance issued for Vehicles 1 through 10, identified in paragraphs 42 through
15 70, thereby failing to perform bona fide inspections of the emission control device and systems on
16 the vehicles and depriving the People of the State of California of the protection afforded by the
17 Motor Vehicle Inspection Program.

18 **OTHER MATTERS**

19 82. Pursuant to Code section 9884.7, subdivision (c), the Director may suspend, revoke,
20 or place on probation the registration for all places of business operated in this state by
21 Respondent Castorena upon a finding that Respondent Castorena has, or is, engaged in a course
22 of repeated and willful violations of the laws and regulations pertaining to an automotive repair
23 dealer.

24 83. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Station License
25 Number TC 231921, issued to Respondent All Smog Express, is revoked or suspended, any
26 additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Saf. Code in
27 the name of said licensee may be likewise revoked or suspended by the Director.

28 ///

84. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Repair Technician License Number EI 130205 and Smog Check Inspector License Number EO 130205, issued to Respondent Castorena, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health and Safety Code in the name of said licensee may be likewise revoked or suspended by the Director.

85. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Inspector License Number EO 635555, issued to Respondent Lopez, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health and Safety Code in the name of said licensee may be likewise revoked or suspended by the Director.

MATTERS IN AGGRAVATION

86. To determine the degree of discipline, if any, to be imposed on Respondent, Complainant alleges, as follows:

All Smog Express

a. On or about May 30, 2008, the Bureau issued Citation Number C08-1052 to Respondent All Smog Express against registration number ARD 231921 and station license number TC 231921 for violations of Health & Saf. Code section 44012, subdivision (f) (failure to perform a visual/functional check of emission control devices) and CCR section 3340.35, subdivision (c) (issuing a certificate of compliance to a vehicle improperly tested). Respondent All Smog Express issued a certificate of compliance to a Bureau vehicle with a missing PCV. The Bureau issued a civil penalty of \$500.00. Respondent All Smog Express complied with the citation on July 7, 2008.

b. On or about October 27, 2008, the Bureau issued Citation Number C09-0460 to Respondent All Smog Express against registration number ARD 231921 and station license number TC 231921 for violations of Health & Saf. Code section 44012, subdivision (f) (failure to perform a visual/functional check of emission control devices) and CCR section 3340.35, subdivision (c) (issuing a certificate of compliance to a vehicle improperly tested). Respondent All Smog Express issued a certificate of compliance to a Bureau vehicle with a missing Pulse Air Reed Valve assembly, failed to perform the required timing check, and misidentified the Air

1 Injection as a pump system. The Bureau issued a civil penalty of \$1,000.00. Respondent All
2 Smog Express complied with the citation on November 24, 2008.

3 c. On or about August 2, 2010, a Bureau representative held a Proactive
4 Conference with Respondent All Smog Express. The conference was held due to a station
5 inspection and review of records that found aborted smog tests, ASM bypasses, not performing
6 required fuel evaporative and ignition timing tests and failure to record additional authorization.
7 Respondent All Smog Express was informed that the conference was held in an attempt to obtain
8 future compliance and to make Respondent All Smog Express aware of the seriousness of the
9 Bureau's warnings in their efforts to obtain compliance. Respondent All Smog Express was
10 advised to follow all laws and regulations of the Automotive Repair Act. Respondent All Smog
11 Express was also advised that future violations of the Automotive Repair Act could result in
12 disciplinary action, which could jeopardize registration number ARD 231921 and station license
13 number TC 231921.

14 d. On or about May 19, 2011, a Bureau representative held a Proactive Conference
15 with Respondent All Smog Express. The conference was held to discuss the facility not
16 performing complete smog inspections as required by the Health & Saf. Code, Business and
17 Professions Code and the California Code of Regulations. Respondent All Smog Express was
18 informed that the conference was held in an attempt to obtain future compliance and to make
19 Respondent All Smog Express aware of the seriousness of the Bureau's warnings in their efforts
20 to obtain compliance. Respondent All Smog Express was advised to follow all laws and
21 regulations of the Automotive Repair Act. Respondent All Smog Express was also advised that
22 future violations of the Automotive Repair Act could result in disciplinary action, which could
23 jeopardize registration number ARD 231921, station license number TC 231921 and Advanced
24 Emission Specialist License Number EA 130205.

25 e. On or about December 16, 2014, a Bureau representative held a Proactive
26 Conference with Respondent All Smog Express. The conference was held to discuss the
27 allowance of an unlicensed technician to perform smog inspection test at its facility in violation of
28 Health & Saf. Code sections 44014, subdivision (a) (testing and repair) and 44032 (test and

1 repairs to be performed by a licensed technician at a licensed station). Respondent All Smog
2 Express was informed that the conference was held in an attempt to obtain future compliance and
3 to make Respondent All Smog Express aware of the seriousness of the Bureau's warnings in their
4 efforts to obtain compliance. Respondent All Smog Express was advised to follow all laws and
5 regulations of the Automotive Repair Act. Respondent All Smog Express was also advised that
6 future violations of the Automotive Repair Act could result in disciplinary action, which could
7 jeopardize registration number ARD 231921, station license number TC 231921.

8 All Smog Express #2

9 f. On or about July 21, 2023, the Bureau issued Citation Number C2023-875 to
10 All Express Smog #2 against registration number ARD 291708 and station license number TC
11 291708 for violating Health & Saf. Code section 44012, subdivision (f) (failure to perform a
12 visual/functional check of emission control devices) and issued an Order of Abatement. All
13 Smog Express #2 issued a certificate of compliance to a vehicle using the BAR-97 when an OIS
14 test was required. The Bureau issued a civil penalty of \$1,000.00. All Smog Express #2
15 complied with the citation on August 4, 2023.

16 Raul Castorena

17 g. On or about May 30, 2008, the Bureau issued Citation Number M08-1053 to
18 Respondent Castorena against former Advanced Emission Specialist License Number EA 130205
19 for violating Health & Saf. Code section 44032 (qualified technicians shall perform tests of
20 emission control systems and devices in accordance with section 44012 of that Code and CCR,
21 section 3340.30, subdivision (a) (qualified technicians shall inspect, test and repair vehicles in
22 accordance with sections 44012 and 44035 of Health & Saf. Code and CCR, section 3340.42) and
23 issued an Order of Abatement. Respondent Castorena issued a certificate of compliance to a
24 Bureau vehicle with a missing PCV. Respondent Castorena was required to attend an 8-hour
25 BAR Certified Smog Check Citation training course. Respondent Castorena complied with the
26 citation on July 3, 2008.

27 h. On or about July 21, 2023, the Bureau issued Citation Number M2023-876 to
28 Respondent Castorena against Smog Check Inspector License Number EO 130205 for violating

1 Health & Saf. Code section 44032 (qualified technicians shall perform tests of emission control
2 systems and devices in accordance with section 44012 of that Code). Respondent Castorena
3 issued a certificate of compliance to a vehicle using the BAR-97 when an OIS test was required.
4 Respondent Castorena was required to attend an 8-hour BAR Certified Smog Check Citation
5 training course. Respondent Castorena complied with the citation on August 5, 2003.

6 Vinny Castorena Lopez

7 i. On or August 14, 2019, a Bureau representative held a Proactive Conference
8 with Respondent Lopez. The conference was held to educate Respondent Lopez regarding the
9 Automotive Repair Act and discussed a violation of Health & Saf. Code section 44012,
10 subdivision (f) (failure to perform a visual/functional check of emission control devices).
11 Respondent Lopez was provided a presentation request to educate employees, a Write it Right
12 brochure, and the Bureau's website where he could download a copy of laws and regulations.

13 PRAYER

14 WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged,
15 and that following the hearing, the Director issue a decision:

- 16 1. Revoking or suspending Automotive Repair Dealers Registration Number ARD
17 231921, issued to Raul Castorena doing business as All Smog Express;
- 18 2. Revoking or suspending Smog Check, Test-Only, Station License Number TC
19 231921, issued to Raul Castorena doing business as All Smog Express;
- 20 3. Revoking or suspending Smog Check Repair Technician License Number EI 130205,
21 issued to Raul Castorena;
- 22 4. Revoking or suspending Smog Check Inspector License Number EO 130205, issued
23 to Raul Castorena;
- 24 5. Revoking or suspending any other automotive repair dealer registrations issued to
25 Raul Castorena;
- 26 6. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
27 Division 26 of the Health and Safety Code in the name of Raul Castorena;

1 7. Revoking or suspending Smog Check Inspector License Number EO 635555, issued
2 to Vinny Raul Castorena Lopez;

3 8. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
4 Division 26 of the Health and Safety Code in the name of Vinny Raul Castorena Lopez;

5 9. Ordering Respondent All Smog Express, Respondent Castorena and Respondent
6 Lopez to pay the Bureau the reasonable costs of the investigation and enforcement of this case,
7 pursuant to Code section 125.3 and if placed on probation, the costs of probation monitoring; and,

8 10. Taking such other and further action as deemed necessary and proper.

9
10 DATED: As of Digital Signature Date__

Dorais,
Patrick@DCA

Digitally signed by Dorais,
Patrick@DCA
Date: 2026.01.26 10:00:05
-08'00'

PATRICK DORAIS
Chief
Bureau of Automotive Repair
Department of Consumer Affairs
State of California
Complainant