

**BEFORE THE DIRECTOR
DEPARTMENT OF CONSUMER AFFAIRS
BUREAU OF AUTOMOTIVE REPAIR
STATE OF CALIFORNIA**

In the Matter of the Accusation Against:

**ARCH'S AUTOMOTIVE, INC.,
dba ARCH'S AUTOMOTIVE SERVICE
BRENDAN CLIFTON BROOKS, PRESIDENT
KEVIN MARC MALTESE, SECRETARY**

Grass Valley, California 95945
Automotive Repair Dealer Registration
No. ARD 238380
Smog Check Station License No. RC 238380

and

RICKY LEE ALLEN MCDANIEL

Nevada City, California 95959
Advanced Emission Specialist Technician
License No. EA 632021,

and

SANDRA MARIE SANDELIUS

Marysville, CA 95901
Advanced Emission Specialist Technician
License No. EA 153369,

Respondents.

Case No. 79/12-79

OAH No. 2012070456

DECISION

The attached Proposed Decision of the Administrative Law Judge is hereby accepted and adopted by the Director of Consumer Affairs as the Decision in the above-entitled matter only as to respondent Ricky Lee Allen McDaniel, Advanced Emission Specialist Technician License No. EA 632021, except that, pursuant to Government Code section 11517(c)(2)(C), the typographical error in the Proposed Decision is corrected as follows:

Page 1, caption: "Smog Check Station License No. RC 238830" is corrected to read "Smog Check Station License No. RC 238380."

This Decision shall become effective March 24, 2014.

DATED: FEB 13 2014



DONALD CHANG
Assistant Chief Counsel
Department of Consumer Affairs

BEFORE THE
DEPARTMENT OF CONSUMER AFFAIRS
FOR THE BUREAU OF AUTOMOTIVE REPAIR
STATE OF CALIFORNIA

In the Matter of the Accusation Against:

ARCH'S AUTOMOTIVE, INC.,
dba ARCH'S AUTOMOTIVE SERVICE
BRENDAN CLIFTON BROOKS,
PRESIDENT
KEVIN MARC MALTESE, SECRETARY

Grass Valley, California 95945
Automotive Repair Dealer Registration
No. ARD 238380
Smog Check Station License No. RC 238830

and

RICKY LEE ALLEN MCDANIEL

Nevada City, California 95959
Advanced Emission Specialist Technician
License No. EA 632021,

and

SANDRA MARIE SANDELIUS

Marysville, CA 95901
Advanced Emission Specialist Technician
License No. EA 153369,

Respondents.

Case No. 79/12-79

OAH No. 2012070456

PROPOSED DECISION

Administrative Law Judge Danette C. Brown, Office of Administrative Hearings, State of California, heard this matter in Sacramento, California, on March 12 and 13, and December 10, 2013.

Sterling A. Smith, Deputy Attorney General, represented complainant Sherry Mehl, in her official capacity as Chief of the Bureau of Automotive Repair (Bureau), Department of Consumer Affairs.

Attorney William D. Ferreira represented respondent Ricky Lee Allen McDaniel, who was present throughout the hearing.¹

Evidence was received, the record was closed, and the matter was submitted for decision on December 10, 2013.

SUMMARY

Complainant seeks to discipline respondent's license on the grounds that he did not perform a proper smog inspection of the Bureau's undercover vehicle. The Bureau's procedures require the smog technician to conduct a visual inspection of the vehicle's emissions control systems and visually verify that all required emission control devices are properly installed. It is undisputed that respondent performed a visual inspection of the Bureau's undercover vehicle's emissions control systems. Complainant contends, however, that respondent did not perform a proper visual inspection because he incorrectly concluded that the positive crankcase ventilation hose was damaged and the evaporative service port was not properly connected. But the accuracy of his conclusions is irrelevant. Therefore, no cause exists to discipline respondent's license.

FACTUAL FINDINGS

1. Complainant issued the First Amended Accusation against respondent on March 8, 2013.

2. On April 28, 2010, the Bureau issued Advanced Emission Specialist (EA) Technician license EA 632021 to respondent.² Respondent's license will expire on December 31, 2015, unless renewed.

¹ During hearing, this matter settled as to respondents Arch's Automotive, Inc., dba Arch's Automotive Service; Brendan Brooks, President; Kevin Maltese, Secretary; and Sandra Marie Sandelius. Therefore, this Proposed Decision pertains only to respondent Ricky Lee Allen McDaniel.

² Effective August 1, 2012, California Code of Regulations, title 16, sections 3340.28, 3340.29, and 3340.30 were amended to implement a license restructure from the Advanced Emission Specialist Technician (EA) license and Basic Area (EB) Technician license to Smog Check Inspector (EO) license and/or Smog Check Repair

3. The Bureau has the responsibility of monitoring the performance of smog check stations and smog check technicians and ensuring that they are properly performing their duties under the smog control laws of the State of California. To monitor compliance with the State's Emissions Inspection Program, commonly referred to as the Smog Check Program, the Bureau conducts undercover operations at various licensed smog check stations.

4. The California Emissions Inspection Test requires the licensed technician to: (1) visually inspect the vehicle's emission components to ensure that they are present, properly connected, and in good working condition; (2) functionally test or inspect the vehicle's gas cap, the malfunction indicator light (MIL), if equipped, the ignition timing, if adjustable, and, depending on the test required, the exhaust gas recirculation (EGR) system; and (3) conduct a tailpipe emissions test.

5. The vehicle must pass all visual and functional tests, as well as the tailpipe emissions test, before an Emission Inspection Certificate of Compliance (Certificate of Compliance) can be issued by the technician, verifying that the vehicle passed the smog inspection.

Undercover Operation

6. The Bureau's undercover operation occurred on July 13, 2011, at Arch's Automotive Service (Arch's Automotive). Respondent performed a smog check on the Bureau's 1998 Ford Explorer (Explorer).

7. The Explorer was first taken to the Bureau's Documentation Lab, where Bureau employee Joseph Gibson conducted a Two Speed Idle (TSI) California Emissions Test to ensure that the vehicle passed the test. He did not perform any alterations to the vehicle.

8. On July 13, 2011, Jeff Hammer, a Bureau undercover agent, took the vehicle to Arch's Automotive, requested a smog inspection, and obtained an estimate for the inspection. He remained on site during the inspection. At the end of the inspection, respondent gave Mr. Hammer a work order receipt documenting payment for the smog inspection in the amount of \$61.75 and a Vehicle Inspection Report (VIR) certifying under penalty of perjury that the vehicle failed visual inspection due to a faulty positive crankcase ventilation (PCV) hose and the fuel evaporative port appeared to be "hooked up wrong."

9. Mr. Hammer returned the vehicle to the Documentation Lab, where it was secured. On July 22, 2011, Mr. Gibson performed a TSI California Emissions Test, which the vehicle passed. Mr. Gibson obtained a printout of the test results

Technician (EI) license. Complainant amended the accusation on the record to reflect that respondent's EA license is now referred to as an EO license.

showing "Overall Test Results – PASS." The "PASS" result indicated that the vehicle met all requirements for issuance of a certificate of compliance.

10. Mr. Gibson then inspected the VIR report respondent had previously provided Mr. Hammer. He noticed that the visual inspection results of the VIR stated "Fail" for the PCV system and "Modified" for the fuel evaporative controls. The PCV system on the Explorer consists of a PCV valve mounted in the left engine valve cover, a hose connecting the PCV valve to a vacuum source at the engine intake manifold, and a tube connecting the engine crankcase to filtered fresh air. The PCV system controls engine crankcase vapor emissions by using engine vacuum to pull fresh air through the engine crankcase, picking up engine vapors through the PCV valve into the intake manifold to be burned in the engine with the air/fuel mixture.

11. Mr. Gibson examined the PCV hose and valve. The hose is a pre-formed rubber hose marked with the Ford oval logo and a part number. The hose was not collapsed, split, cut, or damaged. Mr. Gibson found that the PCV hose was identical in all respects to a new hose obtained from a Ford dealer parts department. The PCV hose was not modified or damaged, and, in Mr. Gibson's opinion, should not have caused the Explorer to fail a properly performed smog check visual inspection.

12. Mr. Gibson also noticed the handwritten note on the VIR stating, "Evap service port looks like its hook up [*sic*] wrong." The evaporative emissions service port is a component of the vehicle's fuel evaporative control system. It is a service access valve, similar in appearance and operation to a tire valve stem. The service port is used by a technician to monitor pressure in the vehicle's fuel evaporative system during diagnosis and repair of the fuel evaporative system. The Explorer's port is connected to the end of a hose routed to the evaporative canister purge valve. The purge valve is located under the vehicle's battery. The service port hose and valve is routed from the purge valve, under the battery, to the battery ground cable wire harness, adjacent to the radiator filler cap. The hose and service port are secured to the wire harness with a metal clip. The service port and hose, and their location, are illustrated in the ALLDATA computerized vehicle repair information database. Mr. Gibson determined that the service port and hose were correct for the Explorer, properly installed, not modified or damaged, and should not have caused the Explorer to fail a properly performed smog check visual inspection.

Respondent's Evidence

13. Respondent began his employment at Arch's Automotive in June 2010.

14. Respondent signed a sworn declaration dated March 11, 2013, wherein he stated that he performed the smog inspection on the Explorer on July 13, 2011, at Arch's Automotive. Respondent's declaration stated, "The hose was unusually soft to the touch and would collapse when the vehicle's engine was revved." In his

professional opinion, respondent felt the hose was sufficiently faulty to cause the vehicle "not to pass the smog inspection." At the time of the smog inspection, respondent consulted Kevin Maltese, another licensed Advanced Emission Specialist Technician employed by Arch Automotive, for a second opinion. Mr. Maltese agreed with respondent's assessment.

15. Respondent testified that when he sees a collapsing hose, he is supposed to "fail" it. He asserted that a hose can collapse after being driven for 50 miles to an elevation of 2,500 feet on a hot day. His boss agreed that the hose was collapsing, and that respondent should "fail" the vehicle. It was respondent's "call" to fail the PCV hose due to the visual inspection. He did so, and did not issue a certificate of compliance.

16. Respondent also observed during his visual inspection that the evaporative service port was not properly connected. Respondent testified that he thought it was unusual that the evaporative service port was clipped to the negative battery cable. To determine the proper wiring location, respondent checked the underhood emissions label and the schematic diagram with ALLDATA. Respondent testified that the underhood label and ALLDATA were "not much help with the proper location of the [evaporative service port] hose." Respondent consulted with his supervisor Mr. Maltese for a second opinion. Mr. Maltese agreed with respondent's visual observation, in that the connection of the evaporative service port "raised a red flag." Respondent failed the fuel evaporative controls based upon his visual inspection.

17. Respondent is no longer employed at Arch's Automotive. His employment terminated in May 2012. Respondent is currently employed as a smog technician at a star-certified station in Roseville. The station is certified by the Bureau to conduct smog check and gross polluter inspections.

18. Respondent does not have a history of prior citations or discipline by the Bureau.

Evidentiary Discussion

19. Complainant asserts that the PCV hose was not damaged, and the fuel evaporative port was connected properly. Complainant further asserts that had respondent conducted a visual inspection in accordance with the Bureau's procedures and verified that the emission control devices were properly installed, the Explorer would have passed the smog check inspection. However, the evidence established that respondent conducted a visual inspection of the Explorer's PCV valve and hose and determined that the PCV hose was collapsed and therefore damaged. While respondent's conclusions differed from Mr. Gibson's testimony that the PCV hose was not damaged or collapsed, those differences do not negate the fact that respondent performed the visual inspection. The evidence did not establish that

respondent failed to perform his visual inspection of the PCV valve and hose in accordance with the procedures prescribed by the Bureau. (Health & Saf. Code, § 44012, subd. (f), Cal. Code Regs., tit. 16, § 3340.30, subd. (a).)

20. The evidence further established that respondent performed a visual inspection of the fuel evaporative service port and determined that it was not connected properly after verifying that the fuel evaporative emission controls were properly installed. (Cal. Code Regs., tit. 16, § 3340.42, subd. (e)(1).) The evidence did not establish that respondent failed to perform a visual inspection of the fuel evaporative emission controls in accordance with the procedures prescribed by the Bureau. (Health & Saf. Code, § 44012, subd. (f).)

Costs

21. The Bureau submitted a certified copy of the actual costs of investigation of this matter. The Bureau incurred a total of \$6,556.35 in investigative costs. Specific components of costs were \$6,362.85 for Bureau staff investigative services and \$193.50 for undercover runs. Similarly, the attorney general certified his prosecution costs of \$7,027.50 for legal services, including case evaluation and preparation, and paralegal work. The total amount of costs of investigation and prosecution of this matter is \$13,583.85.

LEGAL CONCLUSIONS

Burden of Proof

1. The Bureau bears the burden of proving, by a preponderance of the evidence, that the facts alleged in its Accusation are true and that the requested discipline against respondent's license should be imposed.

Statutes and Regulations

2. Qualified smog check technicians shall perform tests of emission control devices and systems in accordance with section Health and Safety Code section 44012. (Health & Saf. Code, § 44032.) Pursuant to Health and Safety Code section 44012, the test at the smog check stations "shall be performed in accordance with procedures prescribed by the department," which shall ensure, *inter alia*, "a visual or functional check ... made of emission control devices specified by the department, including the catalytic converter in those instances in which the department determines it to be necessary to meet the findings of Health and Safety Code section 44001. The visual or functional check shall be performed in accordance with procedures prescribed by the department." (Health & Saf. Code, § 44012, subd. (f).)

3. A smog check station's license or a qualified smog check technician's qualification may be suspended or revoked by the department, after a hearing, for failure to meet or maintain the standards prescribed for qualification, equipment, performance, or conduct. (Health & Saf. Code, § 44035, subd. (a).)

4. The director may suspend, revoke, or take other disciplinary action against a license if the licensee violates any statute or regulation relating to the Program. (Health & Saf. Code, § 44072.2, subds. (a), (c).)

5. A smog check technician shall inspect, test and repair vehicles, as applicable, in accordance with Health and Safety Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42. (Cal. Code Regs., tit. 16, § 3340.30, subd. (a).)

6. Smog check technicians are required conduct to a visual inspection of the vehicle's emissions control systems. During the visual inspection, the technician shall verify that emission control devices, including but not limited to: crankcase emissions controls, including positive crankcase ventilation; and fuel evaporative emission controls, are properly installed on the vehicle. (Cal. Code Regs., tit. 16, § 3340.42, subd. (e).)

Cause for Discipline

7. By reason of Findings 6, 14 through 16, 19, and 20, cause does not exist to discipline respondent's Smog Check Inspector License No. EO 632021, for violating Health and Safety Code section 44012, subdivision (f), in that the evidence did not establish that respondent failed to perform a visual inspection of the emission control systems and devices on the Explorer in accordance with the procedures prescribed by the Bureau.

8. By reason of Findings 6, 14 through 16, 19, and 20, cause does not exist to discipline respondent's Smog Check Inspector License No. EO 632021, for violating Health and Safety Code section 44072.2, subdivision (c), in conjunction with California Code of Regulations, title 16, section 3340.30, subdivision (a), in that the evidence did not establish that respondent failed to inspect and test the Explorer in accordance with Health and Safety Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.

9. By reason of Findings 6, 14 through 16, 19, and 20, cause does not exist to discipline respondent's Smog Check Inspector License No. EO 632021 for violating Health and Safety Code section 44072.2, subdivision (c), in conjunction with California Code of Regulations, title 16, section 3340.42, in that the evidence did not establish that respondent failed to perform visual inspections of the PCV valve and hose and the fuel evaporative emission controls for proper installation on the vehicle.


Costs

10. As set forth in Legal Conclusions 7 through 9, cause does not exist to discipline respondent's license. Therefore, costs shall not be awarded to the Bureau.

ORDER

The Accusation against respondent Ricky Lee Allen McDaniel, is hereby DISMISSED, by reason of Legal Conclusions 7 through 9.

DATED: January 23, 2014.



DANETTE C. BROWN
Administrative Law Judge
Office of Administrative Hearings

1 KAMALA D. HARRIS
Attorney General of California
2 JANICE K. LACHMAN
Supervising Deputy Attorney General
3 STERLING A. SMITH
Deputy Attorney General
4 State Bar No. 84287
1300 I Street, Suite 125
5 P.O. Box 944255
Sacramento, CA 94244-2550
6 Telephone: (916) 445-0378
Facsimile: (916) 327-8643
7 *Attorneys for Complainant*

8 BEFORE THE
9 DEPARTMENT OF CONSUMER AFFAIRS
FOR THE BUREAU OF AUTOMOTIVE REPAIR
10 STATE OF CALIFORNIA

11 In the Matter of the First Amended Accusation
12 Against:

13 ARCH'S AUTOMOTIVE, INC.,
dba ARCH'S AUTOMOTIVE SERVICE
14 BRENDAN CLIFTON BROOKS, PRESIDENT
KEVIN MARC MALTESE, SECRETARY
15 1355 East Main Street
Grass Valley, CA 95945

16 Automotive Repair Dealer Reg. No. ARD 238380
17 Smog Check Station License No. RC 238380,

18 RICKY LEE ALLEN MCDANIEL
11433 Banner Mountain Trail
19 Nevada City, CA 95959

20 Advanced Emission Specialist Technician
21 License No. EA 632021,

22 and

23 SANDRA MARIE SANDELIUS
2012 Covilaud Street, #4
24 Marysville, CA 95901

25 Smog Check Inspector License No. EO 153369
(formerly Advanced Emission Specialist
26 Technician License No. EA 153369)

27 Respondents.

28 ///

Case No. 79/12-79

OAH No. 2012070456

FIRST AMENDED ACCUSATION

(Smog Check)

1 renewed, pursuant to Respondent's election, as Smog Check Inspector License No. EO 153369,
2 effective October 31, 2012.¹ Respondent's smog check inspector license will expire on October
3 31, 2014, unless renewed.

4 JURISDICTION

5 6. Business and Professions Code ("Bus. & Prof. Code") section 9884.7 provides that
6 the Director may revoke an automotive repair dealer registration.

7 7. Bus. & Prof. Code section 9884.13 provides, in pertinent part, that the expiration of a
8 valid registration shall not deprive the Director of jurisdiction to proceed with a disciplinary
9 proceeding against an automotive repair dealer or to render a decision temporarily or permanently
10 invalidating (suspending or revoking) a registration.

11 8. Health and Safety Code ("Health & Saf. Code") section 44002 provides, in pertinent
12 part, that the Director has all the powers and authority granted under the Automotive Repair Act
13 for enforcing the Motor Vehicle Inspection Program.

14 9. Health & Saf. Code section 44072.6 provides, in pertinent part, that the expiration or
15 suspension of a license by operation of law, or by order or decision of the Director of Consumer
16 Affairs, or a court of law, or the voluntary surrender of the license shall not deprive the Director
17 of jurisdiction to proceed with disciplinary action.

18 10. Health & Saf. Code section 44072.8 states that when a license has been revoked or
19 suspended following a hearing under this article, any additional license issued under this chapter
20 in the name of the licensee may be likewise revoked or suspended by the director.

21 11. California Code of Regulations, title 16, section 3340.28, subdivision (e), states that
22 "[u]pon renewal of an unexpired Basic Area Technician license or an Advanced Emission
23 Specialist Technician license issued prior to the effective date of this regulation, the licensee may
24 apply to renew as a Smog Check Inspector, Smog Check Repair Technician, or both.

25 ///

26 ~~Effective August 1, 2012, California Code of Regulations, title 16, sections 3340.28,~~
27 ~~3340.29, and 3340.30 were amended to implement a license restructure from the Advanced~~
28 ~~Emission Specialist Technician (EA) license and Basic Area (EB) Technician license to Smog~~
~~Check Inspector (EO) license and/or Smog Check Repair Technician (EI) license.~~

STATUTORY PROVISIONS

12. Bus. & Prof. Code section 9884.7 states, in pertinent part:

(a) The director, where the automotive repair dealer cannot show there was a bona fide error, may deny, suspend, revoke, or place on probation the registration of an automotive repair dealer for any of the following acts or omissions related to the conduct of the business of the automotive repair dealer, which are done by the automotive repair dealer or any automotive technician, employee, partner, officer, or member of the automotive repair dealer.

(1) Making or authorizing in any manner or by any means whatever any statement written or oral which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading.

(c) Notwithstanding subdivision (b), the director may suspend, revoke, or place on probation the registration for all places of business operated in this state by an automotive repair dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated and willful violations of this chapter, or regulations adopted pursuant to it.

13. Bus. & Prof. Code section 22, subdivision (a), states:

"Board" as used in any provision of this Code, refers to the board in which the administration of the provision is vested, and unless otherwise expressly provided, shall include "bureau," "commission," "committee," "department," "division," "examining committee," "program," and "agency."

14. Bus. & Prof. Code section 477, subdivision (b), states, in pertinent part, that a "license" includes "registration" and "certificate."

15. Health & Saf. Code section 44072.2 states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

(a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health and Saf. Code § 44000, et seq.)] and the regulations adopted pursuant to it, which related to the licensed activities.

(c) Violates any of the regulations adopted by the director pursuant to this chapter...

///

///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

2
3
4
5

6

7
8
9
0
1
2
3
4
5
6

17
18
19
20

21

22

21
24
27
27

22

1 the PCV system on the Bureau's 1998 Ford Explorer had failed the visual inspection. In fact, the
2 PCV system was fitted with the correct parts, was not damaged, was properly installed on the
3 vehicle, and should have passed the visual inspection.

4 b. Respondent Arch's Automotive's technician, Respondent McDaniel, certified under
5 penalty of perjury on the VIR that the information listed on the VIR was true and correct, and that
6 the fuel evaporative controls on the Bureau's 1998 Ford Explorer were modified and had failed
7 the visual inspection. In fact, the fuel evaporative system was fitted with the correct parts, was
8 not damaged, was properly installed on the vehicle, and should have passed the visual inspection.

9 c. Respondent Arch's Automotive's technician, Respondent McDaniel, represented on
10 the VIR that "Evap service port looks like its hook up wrong". In fact, the evaporative emissions
11 service port and hose were correct for the vehicle, were properly installed, were not modified or
12 damaged, and should have passed the visual inspection.

13 SECOND CAUSE FOR DISCIPLINE

14 (Violations of the Motor Vehicle Inspection Program)

15 20. Respondent Arch's Automotive's smog check station license is subject to disciplinary
16 action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed
17 to comply with section 44012, subdivision (f), of that Code, as follows: Respondent failed to
18 ensure that the visual inspection of the emission control systems and devices on the Bureau's
19 1998 Ford Explorer was performed in accordance with procedures prescribed by the department.

20 THIRD CAUSE FOR DISCIPLINE

21 (Failure to Comply with Regulations Pursuant
22 to the Motor Vehicle Inspection Program)

23 21. Respondent Arch's Automotive's smog check station license is subject to disciplinary
24 action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed
25 to comply with California Code of Regulations, title 16, section 3340.42, as follows: Respondent
26 failed to ensure that the required smog tests were conducted on the Bureau's 1998 Ford Explorer
27 in accordance with the Bureau's specifications.

28 ///

1 FOURTH CAUSE FOR DISCIPLINE

2 (Violations of the Motor Vehicle Inspection Program)

3 22. Respondent McDaniel's technician license is subject to disciplinary action pursuant to
4 Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed to comply with
5 section 44012, subdivision (f), of that Code, as follows: Respondent failed to perform the visual
6 inspection of the emission control systems and devices on the Bureau's 1998 Ford Explorer in
7 accordance with procedures prescribed by the department.

8 FIFTH CAUSE FOR DISCIPLINE

9 (Failure to Comply with Regulations Pursuant
10 to the Motor Vehicle Inspection Program)

11 23. Respondent McDaniel's technician license is subject to disciplinary action pursuant to
12 Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed to comply with
13 provisions of California Code of Regulations, title 16, as follows:

14 a. Section 3340.30, subdivision (a): Respondent failed to inspect and test the Bureau's
15 1998 Ford Explorer in accordance with Health & Saf. Code sections 44012 and 44035, and
16 California Code of Regulations, title 16, section 3340.42.

17 b. Section 3340.42: Respondent failed to conduct the required smog tests on the
18 Bureau's 1998 Ford Explorer in accordance with the Bureau's specifications.

19 UNDERCOVER OPERATION #2: 1990 PLYMOUTH SUNDANCE

20 24. On July 13, 2011, a representative of the Bureau, acting in an undercover capacity,
21 ("operator"), took the Bureau's 1990 Plymouth Sundance to Respondent Arch's Automotive's
22 facility and requested a smog inspection. All of the required emission control devices and
23 systems on the Bureau-documented vehicle were present, properly connected, and in good
24 working condition. The operator signed and received a copy of a written estimate. After the
25 inspection was completed, the operator paid the facility \$61.75 and received copies of an invoice
26 and VIR. The VIR indicated that Respondent Sandelius performed the smog inspection on the
27 vehicle. The VIR also indicated that the vehicle's ignition timing was defective and had failed
28 the functional check, resulting in the vehicle's failure of the overall inspection.

25. On July 18, 2011, the Bureau inspected the vehicle. The Bureau found that the ignition timing was adjusted to factory specifications and that the facility had improperly failed the vehicle for the ignition timing, as set forth below.

SIXTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

26. Respondent Arch's Automotive's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized a statement which it knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows: Respondent Arch's Automotive's technician, Respondent Sandelius, certified under penalty of perjury on the VIR that the information listed on the VIR was true and correct, that the ignition timing on the Bureau's 1990 Plymouth Sundance was set to 6 degrees After Top Dead Center and was defective, and that the vehicle failed the functional check portion of the smog inspection. In fact, the ignition timing on the vehicle was set to factory specifications, 12 degrees Before Top Dead Center, was not defective, and should have passed the functional check.

SEVENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

27. Respondent Arch's Automotive's smog check station license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed to comply with section 44012, subdivision (f), of that Code, as follows: Respondent failed to ensure that the functional check of the emission control systems and devices on the Bureau's 1990 Plymouth Sundance was performed in accordance with procedures prescribed by the department.

EIGHTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant

to the Motor Vehicle Inspection Program)

28. Respondent Arch's Automotive's smog check station license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed

1 to comply with California Code of Regulations, title 16, section 3340.42; as follows: Respondent
2 failed to ensure that the required smog tests were conducted on the Bureau's 1990 Plymouth
3 Sundance in accordance with the Bureau's specifications.

4 NINTH CAUSE FOR DISCIPLINE

5 (Violations of the Motor Vehicle Inspection Program)

6 29. Respondent Sandelius' smog check inspector license is subject to disciplinary action
7 pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed to
8 comply with section 44012, subdivision (f), of that Code, as follows: Respondent failed to
9 perform the functional check of the emission control systems and devices on the Bureau's 1990
10 Plymouth Sundance in accordance with procedures prescribed by the department.

11 TENTH CAUSE FOR DISCIPLINE

12 (Failure to Comply with Regulations Pursuant
13 to the Motor Vehicle Inspection Program)

14 30. Respondent Sandelius' smog check inspector license is subject to disciplinary action
15 pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed to
16 comply with provisions of California Code of Regulations, title 16, as follows:

17 a. Section 3340.30, subdivision (a): Respondent failed to inspect and test the Bureau's
18 1990 Plymouth Sundance in accordance with Health & Saf. Code sections 44012 and 44035, and
19 California Code of Regulations, title 16, section 3340.42.

20 b. Section 3340.42: Respondent failed to conduct the required smog tests on the
21 Bureau's 1990 Plymouth Sundance in accordance with the Bureau's specifications:

22 MATTERS IN AGGRAVATION

23 31. To determine the degree of discipline, if any, to be imposed on Respondents Arch's
24 Automotive and Sandelius, Complainant alleges as follows:

25 Respondent Arch's Automotive

26 a. On or about March 2, 2009, the Bureau issued Citation No. C09-1015 against
27 Respondent for violations of Health & Saf. Code section 44012, subdivision (f) (failure to
28 perform a visual/functional check of emission control devices according to procedures prescribed

1 by the department); and California Code of Regulations, title 16, section ("Regulation") 3340.35,
2 subdivision (c) (issuing a certificate of compliance to a vehicle that was improperly tested). On
3 February 9, 2009, Respondent had issued a certificate of compliance to a Bureau undercover
4 vehicle with a missing PCV system. The Bureau assessed civil penalties totaling \$500 against
5 Respondent for the violations. Respondent paid the fine on March 25, 2009.

6 b. On or about May 6, 2009, the Bureau issued Citation No. C09-1279 against
7 Respondent for violations of Health & Saf. Code section 44012, subdivision (f) (failure to
8 perform a visual/functional check of emission control devices according to procedures prescribed
9 by the department); and Regulation 3340.35, subdivision (c) (issuing a certificate of compliance
10 to a vehicle that was improperly tested). On April 23, 2009, Respondent had issued a certificate
11 of compliance to a Bureau undercover vehicle with a missing fuel evaporative storage system
12 canister. The Bureau assessed civil penalties totaling \$1,000 against Respondent for the
13 violations. Respondent paid the fine on May 28, 2009.

14 Respondent Sandelius

15 c. On or about May 6, 2009, the Bureau issued Citation No. M09-1280 against
16 Respondent for violations of Health & Saf. Code section 44032 (qualified technicians shall
17 perform tests of emission control systems and devices in accordance with Health & Saf. Code
18 section 44012); and Regulation 3340.30, subdivision (a) (qualified technicians shall inspect, test
19 and repair vehicles in accordance with Health & Saf. Code sections 44012 and 44035 and
20 Regulation 3340.42). On or about April 23, 2009, Respondent issued a certificate of compliance
21 to a Bureau undercover vehicle with a missing fuel evaporative storage system canister.
22 Respondent was directed to complete an 8 hour training course and to submit proof of completion
23 to the Bureau within 30 days from receipt of the citation. Respondent completed the training on
24 May 21, 2009.

25 OTHER MATTERS

26 ~~32. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the Director may~~
27 suspend, revoke, or place on probation the registration for all places of business operated in this
28 state by Respondent Arch's Automotive, Inc., doing business as Arch's Automotive Service,

1 upon a finding that Respondent has, or is, engaged in a course of repeated and willful violations
2 of the laws and regulations pertaining to an automotive repair dealer:

3 33. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Station License
4 Number RC 238380, issued to Respondent Arch's Automotive, Inc., doing business as Arch's
5 Automotive Service, is revoked or suspended, any additional license issued under this chapter in
6 the name of said licensee may be likewise revoked or suspended by the Director.

7 34. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission Specialist
8 Technician License Number EA 632021, issued to Respondent Ricky Lee Allen McDaniel, is
9 revoked or suspended, any additional license issued under this chapter in the name of said
10 licensee may be likewise revoked or suspended by the Director.

11 35. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Inspector License
12 Number EO 153369, issued to Respondent Sandra Marie Sandelius, is revoked or suspended, any
13 additional license issued under this chapter in the name of said licensee may be likewise revoked
14 or suspended by the Director.

15 PRAYER

16 WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged,
17 and that following the hearing, the Director of Consumer Affairs issue a decision:

18 1. Revoking or suspending Automotive Repair Dealer Registration Number ARD
19 238380, issued to Arch's Automotive, Inc., doing business as Arch's Automotive Service;

20 2. Revoking or suspending any other automotive repair dealer registration issued to
21 Arch's Automotive, Inc.;

22 3. Revoking or suspending Smog Check Station License Number RC 238380, issued to
23 Arch's Automotive, Inc., doing business as Arch's Automotive Service;

24 4. Revoking or suspending any additional license issued under Chapter 5 of the Health
25 and Safety Code in the name of Arch's Automotive, Inc.;

26 ~~5. Revoking or suspending Advanced Emission Specialist Technician License Number~~
27 ~~EA 632021, issued to Ricky Lee Allen McDaniel;~~

28 ///

6. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name of Ricky Lee Allen McDaniel;

7. Revoking or suspending Smog Check Inspector License Number EO 153369, issued to Sandra Marie Sandelius;

8. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name of Sandra Marie Sandelius;

9. Ordering Arch's Automotive, Inc., doing business as Arch's Automotive Service, Ricky Lee Allen McDaniel, and Sandra Marie Sandelius to pay the Director of Consumer Affairs the reasonable costs of the investigation and enforcement of this case, pursuant to Business and Professions Code section 125.3;

10. Taking such other and further action as deemed necessary and proper.

DATED:

3/8/2013

Brian Newman Deputy Chief

JOHN WALLAUCH (BRIAN NEWMAN)
Chief
Bureau of Automotive Repair
Department of Consumer Affairs
State of California
Complainant

SA2011102824