

BEFORE THE DIRECTOR
DEPARTMENT OF CONSUMER AFFAIRS
BUREAU OF AUTOMOTIVE REPAIR
STATE OF CALIFORNIA

In the Matter of the Accusation Against:

**MOTHER LODE MOTORS, INC.,
dba MOTHER LODE MOTORS
NATHAN H. FLAKE, PRESIDENT
STANLEY M. FLAKE,
SECRETARY/TREASURER**
13411 Mono Way
Sonora, California 95370-5338

Automotive Repair Dealer Registration
No. ARD 77998

Case No. 77/14-52

OAH No. 2014040764

Respondent.

DECISION

The attached Stipulated Settlement and Disciplinary Order is hereby accepted and adopted as the Decision of the Director of the Department of Consumer Affairs in the above-entitled matter.

This Decision shall become effective April 1, 2015.

DATED: March 6, 2015



TAMARA COLSON
Assistant General Counsel
Department of Consumer Affairs

1 KAMALA D. HARRIS
Attorney General of California
2 KENT D. HARRIS
Supervising Deputy Attorney General
3 PHILLIP L. ARTHUR
Deputy Attorney General
4 State Bar No. 238339
1300 I Street, Suite 125
5 P.O. Box 944255
Sacramento, CA 94244-2550
6 Telephone: (916) 322-0032
Facsimile: (916) 327-8643
7 E-mail: Phillip.Arthur@doj.ca.gov
Attorneys for Complainant

8
9 **BEFORE THE**
DEPARTMENT OF CONSUMER AFFAIRS
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 77/14-52

13 **MOTHER LODE MOTORS, INC.,**
dba MOTHER LODE MOTORS
14 **NATHAN H. FLAKE, PRESIDENT**
STANLEY M. FLAKE,
15 **SECRETARY/TREASURER**
13411 Mono Way
16 Sonora, California 95370-5338

OAH No. 2014040764

**STIPULATED SETTLEMENT AND
DISCIPLINARY ORDER**

17 **Automotive Repair Dealer Registration No.**
18 **ARD 77998**

19 Respondent.

20
21 IT IS HEREBY STIPULATED AND AGREED by and between the parties to the above-
22 entitled proceedings that the following matters are true:

23 PARTIES

24 1. Patrick Dorais ("Complainant") is the Chief of the Bureau of Automotive Repair. He
25 brought this action solely in his official capacity and is represented in this matter by Kamala D.
26 Harris, Attorney General of the State of California, by Phillip L. Arthur, Deputy Attorney
27 General.

28 ///

1 court review of an adverse decision; and all other rights accorded by the California
2 Administrative Procedure Act and other applicable laws.

3 8. Respondent voluntarily, knowingly, and intelligently waives and gives up each and
4 every right set forth above.

5 CULPABILITY

6 9. Respondent admits the truth of each and every charge and allegation in Accusation
7 No. 77/14-52.

8 10. Respondent agrees that its Automotive Repair Dealer Registration is subject to
9 discipline and agrees to be bound by the Director's probationary terms as set forth in the
10 Disciplinary Order below.

11 CONTINGENCY

12 11. This stipulation shall be subject to approval by the Director of Consumer Affairs or
13 the Director's designee. Respondent understands and agrees that counsel for Complainant and the
14 staff of the Bureau of Automotive Repair may communicate directly with the Director and staff of
15 the Department of Consumer Affairs regarding this stipulation and settlement, without notice to
16 or participation by Respondent or its counsel. By signing the stipulation, Respondent understands
17 and agrees that it may not withdraw its agreement or seek to rescind the stipulation prior to the
18 time the Director considers and acts upon it. If the Director fails to adopt this stipulation as the
19 Decision and Order, the Stipulated Settlement and Disciplinary Order shall be of no force or
20 effect, except for this paragraph, it shall be inadmissible in any legal action between the parties,
21 and the Director shall not be disqualified from further action by having considered this matter.

22 12. The parties understand and agree that Portable Document Format (PDF), electronic,
23 and facsimile copies of this Stipulated Settlement and Disciplinary Order, including Portable
24 Document Format (PDF), electronic, and facsimile signatures thereto, shall have the same force
25 and effect as the originals.

26 13. This Stipulated Settlement and Disciplinary Order is intended by the parties to be an
27 integrated writing representing the complete, final, and exclusive embodiment of their agreement.
28 It supersedes any and all prior or contemporaneous agreements, understandings, discussions,

1 negotiations, and commitments (written or oral). This Stipulated Settlement and Disciplinary
2 Order may not be altered, amended, modified, supplemented, or otherwise changed except by a
3 writing executed by an authorized representative of each of the parties.

4 14. In consideration of the foregoing admissions and stipulations, the parties agree that
5 the Director may, without further notice or formal proceeding, issue and enter the following
6 Disciplinary Order:

7 **DISCIPLINARY ORDER**

8 IT IS HEREBY ORDERED that Automotive Repair Dealer Registration No. ARD 77998
9 issued to Mother Lode Motors Inc., doing business as Mother Lode Motors, with Nathan H. Flake
10 as president and Stanley M. Flake as secretary/treasurer (Respondent) is revoked. However, the
11 revocation is stayed and Respondent is placed on probation for five (5) years on the following
12 terms and conditions.

13 1. **Actual Suspension.** Automotive Repair Dealer Registration No. ARD 77998 issued
14 to Respondent is suspended for three (3) days, to begin on the effective date of the decision.

15 2. **Obey All Laws.** Comply with all statutes, regulations, and rules governing
16 automotive inspections, estimates, and repairs.

17 3. **Post Sign.** Post a prominent sign, provided by the Bureau, indicating the beginning
18 and ending dates of the suspension and indicating the reason for the suspension. The sign shall be
19 conspicuously displayed in a location open to and frequented by customers and shall remain
20 posted during the entire period of actual suspension.

21 4. **Reporting.** Respondent or Respondent's authorized representative must report in
22 person or in writing as prescribed by the Bureau of Automotive Repair, on a schedule set by the
23 Bureau, but no more frequently than each quarter, on the methods used and success achieved in
24 maintaining compliance with the terms and conditions of probation.

25 5. **Report Financial Interest.** Within 30 days of the effective date of this action, report
26 any financial interest which any partners, officers, or owners of the Respondent facility may have
27 in any other business required to be registered pursuant to Section 9884.6 of the Business and
28 Professions Code.

1 6. **Random Inspections.** Provide Bureau representatives unrestricted access to inspect
2 all vehicles (including parts) undergoing repairs, up to and including the point of completion.

3 7. **Jurisdiction.** If an accusation is filed against Respondent during the term of
4 probation, the Director of Consumer Affairs shall have continuing jurisdiction over this matter
5 until the final decision on the accusation, and the period of probation shall be extended until such
6 decision.

7 8. **Violation of Probation.** Should the Director of Consumer Affairs determine that
8 Respondent has failed to comply with the terms and conditions of probation, the Department may,
9 after giving notice and opportunity to be heard revoke Respondent's Automotive Repair Dealer
10 Registration.

11 9. **False and Misleading Advertising.** If the accusation involves false and misleading
12 advertising, during the period of probation, Respondent shall submit any proposed advertising
13 copy, whether revised or new, to the Bureau at least thirty (30) days prior to its use.

14 10. **Cost Recovery.** Respondent shall reimburse the amount of \$15,250.19, representing
15 the Bureau's costs for investigation and prosecution of this action. Payment to the Bureau of the
16 full amount of cost recovery shall be made in forty-eight (48) consecutive equal monthly
17 installments with the first payment due no later than 30 days after the effective date of the
18 decision and the last payment due no later than 12 months before probation terminates. Failure to
19 complete payment of cost recovery within this time frame shall constitute a violation of probation
20 which may subject Respondent's Automotive Repair Dealer Registration to outright revocation;
21 however, the Director or the Director's Bureau of Automotive Repair designee may elect to
22 continue probation until such time as reimbursement of the entire cost recovery amount has been
23 made to the Bureau.

24 ///

25 ///

26 ///

27 ///

28 ///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28


ENDORSEMENT

The foregoing Stipulated Settlement and Disciplinary Order is hereby respectfully submitted for consideration by the Director of Consumer Affairs.

Dated: 1/29/15

Respectfully submitted,

KAMALA D. HARRIS
Attorney General of California
KENT D. HARRIS
Supervising Deputy Attorney General



PHILLIP L. ARTHUR
Deputy Attorney General
Attorneys for Complainant

SA2013113953
11709616.doc

Exhibit A

Accusation No. 77/14-52

1 KAMALA D. HARRIS
Attorney General of California
2 KENT D. HARRIS
Supervising Deputy Attorney General
3 PHILLIP L. ARTHUR
Deputy Attorney General
4 State Bar No. 238339
1300 I Street, Suite 125
5 P.O. Box 944255
Sacramento, CA 94244-2550
6 Telephone: (916) 322-0032
Facsimile: (916) 327-8643
7 *Attorneys for Complainant*

8 **BEFORE THE**
9 **DEPARTMENT OF CONSUMER AFFAIRS**
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. **77/14-52**

13 **MOTHER LODGE MOTORS INC.,**
14 **dba MOTHER LODGE MOTORS**
15 **NATHAN H. FLAKE, PRESIDENT**
16 **STANLEY M. FLAKE, SECRETARY/**
17 **TREASURER**

ACCUSATION

18 13411 Mono Way
19 Sonora, California 95370-5338

20 **Automotive Repair Dealer Registration**
21 **No. ARD 77998**

22 Respondent.

23 Patrick Dorais ("Complainant") alleges:

24 **PARTIES**

25 1. Complainant brings this Accusation solely in his official capacity as the Chief of the
26 Bureau of Automotive Repair ("Bureau"), Department of Consumer Affairs.

27 2. In or around 1980, the Director of Consumer Affairs ("Director") issued Automotive
28 Repair Dealer Registration Number ARD 77998 to Mother Lode Motors Inc. ("Respondent"),
doing business as Mother Lode Motors, with Nathan H. Flake as president and Stanley M. Flake
as secretary/treasurer. The Automotive Repair Dealer Registration was in full force and effect

///

1 at all times relevant to the charges brought herein and will expire on April 30, 2015, unless.
2 renewed.

3 STATUTORY AND REGULATORY PROVISIONS

4 3. Business and Professions Code ("Code") section 9884.13 provides, in pertinent part,
5 that the expiration of a valid registration shall not deprive the Director or chief of jurisdiction to
6 proceed with a disciplinary proceeding against an automotive repair dealer or to render a decision
7 invalidating a registration temporarily or permanently.

8 4. Code section 9884.7 states, in pertinent part:

9 (a) The director, where the automotive repair dealer cannot show there was a
10 bona fide error, may deny, suspend, revoke, or place on probation the registration of
11 an automotive repair dealer for any of the following acts or omissions related to the
12 conduct of the business of the automotive repair dealer, which are done by the
13 automotive repair dealer or any automotive technician, employee, partner, officer, or
14 member of the automotive repair dealer.

15 (1) Making or authorizing in any manner or by any means whatever any
16 statement written or oral which is untrue or misleading, and which is known, or
17 which by the exercise of reasonable care should be known, to be untrue or
18 misleading.

19 ...
20 (5) Conduct constituting gross negligence.

21 (6) Failure in any material respect to comply with the provisions of this
22 chapter or regulations adopted pursuant to it.

23 (7) Any willful departure from or disregard of accepted trade standards for
24 good and workmanlike repair in any material respect, which is prejudicial to another
25 without consent of the owner or his or her duly authorized representative.

26 ...
27 (b) Except as provided for in subdivision (c), if an automotive repair dealer
28 operates more than one place of business in this state, the director pursuant to
subdivision (a) shall only suspend, revoke, or place on probation the registration of
the specific place of business which has violated any of the provisions of this
chapter. This violation, or action by the director, shall not affect in any manner the
right of the automotive repair dealer to operate his or her other places of business.

(c) Notwithstanding subdivision (b), the director may suspend, revoke, or
place on probation the registration for all places of business operated in this state by
an automotive repair dealer upon a finding that the automotive repair dealer has, or
is, engaged in a course of repeated and willful violations of this chapter, or
regulations adopted pursuant to it.

///

1 5. Code section 477 provides, in pertinent part, that "Board" includes "bureau,"
2 "commission," "committee," "department," "division," "examining committee," "program," and
3 "agency." "License" includes certificate, registration or other means to engage in a business or
4 profession regulated by the Code.

5 6. Code section 9884.8 states:

6 All work done by an automotive repair dealer, including all warranty work,
7 shall be recorded on an invoice and shall describe all service work done and parts
8 supplied. Service work and parts shall be listed separately on the invoice, which
9 shall also state separately the subtotal prices for service work and for parts, not
10 including sales tax, and shall state separately the sales tax, if any, applicable to each.
11 If any used, rebuilt, or reconditioned parts are supplied, the invoice shall clearly state
12 that fact. If a part of a component system is composed of new and used, rebuilt or
13 reconditioned parts, that invoice shall clearly state that fact. The invoice shall
14 include a statement indicating whether any crash parts are original equipment
15 manufacturer crash parts or nonoriginal equipment manufacturer aftermarket crash
16 parts. One copy of the invoice shall be given to the customer and one copy shall be
17 retained by the automotive repair dealer.

18 7. Code section 9884.9, subdivision (a), states:

19 The automotive repair dealer shall give to the customer a written estimated
20 price for labor and parts necessary for a specific job. No work shall be done and no
21 charges shall accrue before authorization to proceed is obtained from the customer.
22 No charge shall be made for work done or parts supplied in excess of the estimated
23 price without the oral or written consent of the customer that shall be obtained at
24 some time after it is determined that the estimated price is insufficient and before the
25 work not estimated is done or the parts not estimated are supplied. Written consent
26 or authorization for an increase in the original estimated price may be provided by
27 electronic mail or facsimile transmission from the customer. The bureau may specify
28 in regulation the procedures to be followed by an automotive repair dealer if an
authorization or consent for an increase in the original estimated price is provided by
electronic mail or facsimile transmission. If that consent is oral, the dealer shall
make a notation on the work order of the date, time, name of person authorizing the
additional repairs, and telephone number called, if any, together with a specification
of the additional parts and labor and the total additional cost, and shall do either of
the following:

(1) Make a notation on the invoice of the same facts set forth in the notation
on the work order.

(2) Upon completion of the repairs, obtain the customer's signature or initials
to an acknowledgment of notice and consent, if there is an oral consent of the
customer to additional repairs, in the following language:

"I acknowledge notice and oral approval of an increase in the original
estimated price.

(signature or initials)"

1 Nothing in this section shall be construed as requiring an automotive repair
2 dealer to give a written estimated price if the dealer does not agree to perform the
requested repair.

3 8. California Code of Regulations, title 16 ("Regulation"), section 3366, subdivision (a)
4 states:

5 Except as provided in subsection (b) of this section, any automotive repair
6 dealer that advertises or performs, directly or through a sublet contractor, automotive
7 air conditioning work and uses the words service, inspection, diagnosis, top off,
8 performance check or any expression or term of like meaning in any form of
advertising or on a written estimate or invoice shall include and perform all of the
following procedures as part of that air conditioning work:

9 (1) Exposed hoses, tubing and connections are examined for damage or leaks;

10 (2) The compressor and clutch, when accessible, are examined for damage,
missing bolts, missing hardware, broken housing and leaks;

11 (3) The compressor is rotated to determine if it is seized or locked up;

12 (4) Service ports are examined for missing caps, damaged threads and
conformance with labeling;

13 (5) The condenser coil is examined for damage, restrictions or leaks;

14 (6) The expansion device, if accessible, is examined for physical damage or
15 leaks;

16 (7) The accumulator receiver dryer and in-line filter have been checked for
17 damage, missing or loose hardware or leaks;

18 (8) The drive belt system has been checked for damaged or missing pulleys or
19 tensioners and for proper belt routing, tension, alignment, excessive wear or
cracking;

20 (9) The fan clutch has been examined for leakage, bearing wear and proper
operation;

21 (10) The cooling fan has been checked for bent or missing blades;

22 (11) Accessible electrical connections have been examined for loose, burnt,
23 broken or corroded parts;

24 (12) The refrigerant in use has been identified and checked for contamination;

25 (13) The system has been checked for leakage at a minimum of 50-PSI
system pressure;

26 (14) The compressor clutch, blower motor and air control doors have been
27 checked for proper operation;

28 (15) High and low side system operating pressures, as applicable, have been
measured and recorded on the final invoice; and,

1 (16) The center air distribution outlet temperature has been measured and
2 recorded on the final invoice.

3 9. Regulation, section 3371, states, in pertinent part:

4 No dealer shall publish, utter, or make or cause to be published, uttered, or
5 made any false or misleading statement or advertisement which is known to be false
6 or misleading, or which by the exercise of reasonable care should be known to be
7 false or misleading. . . .

8 **COST RECOVERY**

9 10. Code section 125.3 provides, in pertinent part, that a Board may request the
10 administrative law judge to direct a licentiate found to have committed a violation or violations of
11 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
12 enforcement of the case.

13 **UNDERCOVER OPERATION #1**

14 11. On or about August 14, 2013, at approximately 1030 hours, a Bureau undercover
15 [REDACTED] using an alias (the "operator") took a Bureau-documented 2006 Chevrolet to
16 Respondent's facility and asked "Jeff," Respondent's employee, for the \$49 A/C (air
17 conditioning) service advertised by Respondent. Jeff prepared an estimate to service the air
18 conditioning system for \$110, which included Freon.

19 12. A few hours later that same day, Jeff told the operator that the A/C was
20 malfunctioning and needed to be diagnosed. Jeff increased the estimate to \$213, which the
21 operator verbally authorized. Approximately one hour later, Jeff told the operator on the
22 telephone that the compressor showed an internal and catastrophic failure. Jeff recommended a
23 new compressor, dryer, expansion valve, and flushing the A/C system, for a total cost of around
24 \$1,050, which the operator verbally authorized.

25 13. On or about August 15, 2013, Jeff informed the operator that the vehicle was being
26 torn down and total repairs would not cost more than \$1,561.05.

27 14. On or about August 16, 2013, the operator retrieved the vehicle and paid Respondent
28 \$1,525.55, the total amount of Respondent's final invoice, # [REDACTED]

///

1 THIRD CAUSE FOR DISCIPLINE

2 (Failure to Comply with the Automotive Repair Act)

3 18. Respondent's registration is subject to discipline under Code section 9884.7,
4 subdivision (a)(6), in that, as regards the Bureau's 2006 Chevrolet, Respondent failed to
5 materially comply with that Code, as follows:

6 a. Section 9884.8: Respondent failed to describe on Invoice # [REDACTED] all work done.

7 b. Code Section 9884.9, Subdivision (a):

8 i. Respondent failed to obtain the operator's authorization to replace the A/C
9 compressor relay.

10 ii. Respondent increased the estimate from that previously authorized by the
11 operator without the operator's consent.

12 iii. Respondent failed to document on final invoice [REDACTED] the operator's
13 authorization to perform diagnostics on the A/C system.

14 UNDERCOVER OPERATION #2

15 19. On or about September 12, 2013, at approximately 1045 hours, a Bureau undercover
16 operator using an alias (the "operator") took a Bureau-documented 1997 Chevrolet to
17 Respondent's facility and asked Jeff for the \$49 A/C service that Respondent advertised. Jeff
18 prepared an estimate to service the A/C system for \$110, which included Freon. A few hours
19 later, Jeff told the operator on the telephone that the compressor would not come on and that a
20 diagnostic procedure would increase the estimate to \$152, which the operator verbally approved.
21 Jeff later told the operator that a broken wire was found and repaired. Invoice [REDACTED] which
22 included \$103 for the diagnostic procedure, totaled \$152, which the operator paid.

23 20. On or about September 18, 2013, the Bureau inspected the 1997 Chevrolet using
24 invoice [REDACTED] provided by Respondent for comparison. The Bureau determined that
25 Respondent improperly repaired the broken ground wire by bypassing the in-line diode circuit in
26 the connector. The A/C diode circuit controls voltage spikes generated by the A/C electrical
27 system and is an essential component.

28 ///

1 **FOURTH CAUSE FOR DISCIPLINE**

2 (False Advertising)

3 21. Respondent's registration is subject to discipline under Code section 9884.7,
4 subdivision (a)(6), as regards the Bureau's 1997 Chevrolet, in that Respondent failed to comply
5 with Regulation section 3371 by publishing, uttering, or making, or causing to be published,
6 uttered, or made false or misleading statements or advertisements which are known to be false or
7 misleading, or which by the exercise of reasonable care should be known to be false or
8 misleading. Specifically, Respondent advertised a \$49 A/C Service, but charged the operator to
9 diagnose a failure in the A/C system caused by a broken ground wire at the electrical connector.
10 An inspection of electrical connections is required when performing an A/C service, as set forth
11 in paragraph 22, subparagraph (a), below.

12 **FIFTH CAUSE FOR DISCIPLINE**

13 (Departure from Trade Standards)

14 22. Respondent's registration is subject to discipline under Code section 9884.7,
15 subdivision (a)(7), as regards the Bureau's 1997 Chevrolet, in that Respondent willfully departed
16 from or disregarded accepted trade standards for good and workmanlike repair without the
17 consent of the owner or the owner's duly authorized representative, as follows:

18 a. Respondent failed to include in its \$49 A/C service the inspection of electrical
19 connections for loose, burnt, broken or corroded parts, as required by Regulation, section 3366,
20 subdivision (a)(11).

21 b. Respondent failed to record on invoice [REDACTED] the high and low side system
22 operating pressures as required by Regulation, section 3366, subdivision (a)(15).

23 c. Respondent failed to record on invoice [REDACTED] the center air distribution outlet
24 temperature as required by Regulation, section 3366, subdivision (a)(16).

25 **SIXTH CAUSE FOR DISCIPLINE**

26 (Conduct Constituting Gross Negligence)

27 23. Respondent's registration is subject to discipline under Code section 9884.7,
28 subdivision (a)(5), as regards the Bureau's 1997 Chevrolet, in that Respondent committed an act

1 constituting gross negligence when Respondent's employee removed and then failed to properly
2 connect the A/C diode circuit in the connector.

3 **UNDERCOVER OPERATION #3**

4 24. On or about September 17, 2013, at approximately 1020 hours, a Bureau undercover
5 operator using an alias (the "operator") took a Bureau-documented 2000 Toyota to Respondent's
6 facility and asked Jeff for the \$49 A/C service that Respondent advertised. Jeff prepared an
7 estimate to service the A/C system for \$110, and told the operator that the total could change
8 depending on the amount of Freon used. A few hours later, Jeff telephoned the operator and
9 stated that the Freon was filled because it was low and the A/C condenser fan and A/C
10 compressor were not coming on. The operator verbally approved a revised estimate of \$157 for a
11 diagnostic procedure.

12 25. A few hours later that same day, Jeff told the operator that the pressure switch on the
13 dryer needed to be replaced, and increased the estimate to \$341, which the operator authorized.

14 26. On or about September 19, 2013, the operator retrieved the 2000 Toyota. He
15 received invoice #96019 in the amount of \$325.86 for the repairs, which included a charge of
16 \$103 for a diagnostic service. The operator paid Respondent \$325.86.

17 27. On or about October 1, 2013, the Bureau inspected the 2000 Toyota using invoice
18 [REDACTED] provided by Respondent for comparison. The Bureau determined that replacement of the
19 A/C pressure switch and charging the A/C system were unnecessary. Repair of the wiring
20 harness connector at the pressure switch was the only necessary repair.

21 **SEVENTH CAUSE FOR DISCIPLINE**

22 (Untrue or Misleading Statements)

23 28. Respondent is subject to discipline under Code section 9884.7, subdivision (a)(1), in
24 that, as regards the Bureau's 2000 Toyota, Respondent made or allowed statements on its behalf
25 which it knew or which by exercise of reasonable care should have known to be untrue or
26 misleading. Specifically, Respondent and/or Respondent's employees falsely represented to a
27 Bureau operator that the pressure switch on the dryer was shorted out and the A/C system needed

28 ///

1 to be recharged, when neither was true. Further, Respondent represented on invoice [REDACTED] that
2 such repairs were necessary.

3 **EIGHTH CAUSE FOR DISCIPLINE**

4 (False Advertising)

5 29. Respondent's registration is subject to discipline under Code section 9884.7,
6 subdivision (a)(6), as regards the Bureau's 2000 Toyota, in that Respondent failed to comply with
7 Regulation, section 3371, by publishing, uttering, or making, or causing to be published, uttered,
8 or made false or misleading statements or advertisements which are known to be false or
9 misleading, or which by the exercise of reasonable care should be known to be false or
10 misleading. Specifically, Respondent advertised a \$49 A/C Service, but charged the operator to
11 diagnose a failure in the A/C system caused by faulty wiring of the harness connector at the
12 pressure switch. An inspection of electrical connections is required when performing an A/C
13 service, as set forth in paragraph 30, subparagraph (a), below.

14 **NINTH CAUSE FOR DISCIPLINE**

15 (Departure from Trade Standards)

16 30. Respondent's registration is subject to discipline under Code section 9884.7,
17 subdivision (a)(7), as regards the Bureau's 2000 Toyota, in that Respondent willfully departed
18 from or disregarded accepted trade standards for good and workmanlike repair without the
19 consent of the owner or the owner's duly authorized representative, as follows:

20 a. Respondent failed to include in its \$49 A/C service the inspection of electrical
21 connections for loose, burnt, broken or corroded parts, as required by Regulation, section 3366,
22 subdivision-(a)(11).

23 b. Respondent failed to record on invoice [REDACTED] the high and low side system
24 operating pressures as required by Regulation, section 3366, subdivision (a)(15).

25 ///

26 ///

27 ///

28 ///

1 TENTH CAUSE FOR DISCIPLINE

2 (Failure to Comply with the Automotive Repair Act)

3 31. Respondent's registration is subject to discipline under Code section 9884.7,
4 subdivision (a)(6), in that Respondent failed to materially comply with Code Section 9884.8 by
5 failing to describe all work performed on the Bureau's 2000 Toyota:

6 OTHER MATTERS

7 32. Pursuant to Code section 9884.7, subdivision (c), the Director may suspend, revoke,
8 or place on probation the registration for all places of business operated in this state by
9 Respondent Mother Lode Motors Inc., dba Mother Lode Motors, upon a finding that Respondent
10 has, or is, engaged in a course of repeated and willful violations of the laws and regulations
11 pertaining to an automotive repair dealer.

12 PRAYER

13 **WHEREFORE**, Complainant requests that a hearing be held on the matters herein alleged,
14 and that following the hearing, the Director of Consumer Affairs issue a decision:

- 15 1. Revoking or suspending Automotive Repair Dealer Registration Number
- 16 ARD 77998, issued to Mother Lode Motors Inc., dba Mother Lode Motors;
- 17 2. Revoking or suspending any other automotive repair dealer registration issued to
- 18 Mother Lode Motors Inc., dba Mother Lode Motors;
- 19 3. Ordering Mother Lode Motors Inc., dba Mother Lode Motors, to pay the Director of
- 20 Consumer Affairs the reasonable costs of the investigation and enforcement of this case, pursuant
- 21 to Business and Professions Code section 125.3; and,
- 22 4. Taking such other and further action as deemed necessary and proper.

23
24 DATED: March 20, 2014



25 PATRICK DORAIS
26 Chief
27 Bureau of Automotive Repair
28 Department of Consumer Affairs
State of California
Complainant

SA2013113953
11259978.doc