

1 KAMALA D. HARRIS
Attorney General of California
2 LINDA K. SCHNEIDER
Supervising Deputy Attorney General
3 LORETTA A. WEST
Deputy Attorney General
4 State Bar No. 149294
110 West "A" Street, Suite 1100
5 San Diego, CA 92101
P.O. Box 85266
6 San Diego, CA 92186-5266
Telephone: (619) 645-2107
7 Facsimile: (619) 645-2061
Attorneys for Complainant

8
9 **BEFORE THE**
DEPARTMENT OF CONSUMER AFFAIRS
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 7912-18

13 **A & Z SMOG TEST ONLY**
14 **5070 Etiwanda Avenue, Unit B**
Mira Loma, CA 91752
15 **Mailing Address:**
P.O. Box 70435
16 **Riverside, CA 92513**
ABE I. RABADI, OWNER
17 **Automotive Repair Dealer Registration Number No.**
ARD 261018
18 **Smog Check Test Only Station License No. TC 261018,**

ACCUSATION
SMOG CHECK

19 **CARLOS EDUARDO LEON MONDRAGON**
20 **10541 Arlington Avenue**
Riverside, CA 92505
21 **Advanced Emission Specialist Technician License No. EA**
631695,

22 **MICHAEL S. FLORES**
23 **4296 Sepulveda Avenue #215**
San Bernardino, CA 92404
24 **Advanced Emission Specialist Technician License No. EA**
632244,

25 **SAMER GEORGE ZAIT**
26 **206 Euclid Avenue, #206**
Long Beach, CA 90803
27 **Advanced Emission Specialist Technician License No. EA**
152388

28 Respondents.

1 Complainant alleges:

2 **PARTIES**

3 1. Sherry Mehl (“Complainant”) brings this Accusation solely in her official capacity as
4 the Chief of the Bureau of Automotive Repair (“Bureau”), Department of Consumer Affairs.

5 **Automotive Repair Dealer Registration**

6 2. On or about March 2, 2010, the Bureau issued Automotive Repair Dealer Registration
7 Number Number ARD 261018 (“registration”) to Abe I. Rabadi (“Respondent A & Z Smog”)
8 doing business as A & Z Smog Test Only. The registration was in full force and effect at all
9 times relevant to the charges brought herein and will expire on February 29, 2012, unless
10 renewed.

11 **Smog Check Test Only Station License**

12 3. On or about April 22, 2010, the Bureau issued Smog Check Test Only Station
13 License Number TC 261018 (“station license”) to Respondent A & Z Smog. The station license
14 was in full force and effect at all times relevant to the charges brought herein and will expire on
15 February 29, 2012, unless renewed.

16 **Advanced Emission Specialist Technician License**

17 4. On or about January 25, 2010, the Bureau issued Advanced Emission Specialist
18 Technician License Number EA 631695 (“technician license”) to Carlos Eduardo Leon
19 Mondragon (“Respondent Mondragon”). The technician license was in full force and effect at all
20 times relevant to the charges brought herein and will expire on October 31, 2011, unless renewed.

21 **Advanced Emission Specialist Technician License**

22 5. On or about July 6, 2010, the Bureau issued Advanced Emission Specialist
23 Technician License Number EA 632244 (“technician license”) to Michael S. Flores (“Respondent
24 Flores”). The technician license was in full force and effect at all times relevant to the charges
25 brought herein and will expire on January 31, 2012, unless renewed.

26 ///

27 ///

28 ///

1 authorizing the additional repairs and telephone number called, if any, together with a
2 specification of the additional parts and labor and the total additional cost, and shall
3 do either of the following:

4 (1) Make a notation on the invoice of the same facts set forth in the
5 notation on the work order .

6 (2) Upon completion of the repairs, obtain the customer's signature or
7 initials to an acknowledgment of notice and consent, if there is an oral consent of the
8 customer to additional repairs, in the following language:

9 "I acknowledge notice and oral approval of an increase in the original
10 estimated price.

11 _____
12 (signature or initials)"

13 9. Code section 9884.13 provides, in pertinent part, that the expiration of a valid
14 registration shall not deprive the director or chief of jurisdiction to proceed with a disciplinary
15 proceeding against an automotive repair dealer or to render a decision invalidating a registration
16 temporarily or permanently.

17 10. Code section 477 provides, in pertinent part, that "Board" includes "bureau,"
18 "commission," "committee," "department," "division," "examining committee," "program," and
19 "agency." "License" includes certificate, registration or other means to engage in a business or
20 profession regulated by the Code.

21 11. Section 44002 of the Health and Safety Code provides, in pertinent part, that the
22 Director has all the powers and authority granted under the Automotive Repair Act for enforcing
23 the Motor Vehicle Inspection Program.

24 12. Section 44072.2 of the Health and Safety Code states, in pertinent part:

25 The director may suspend, revoke, or take other disciplinary action
26 against a license as provided in this article if the licensee, or any partner, officer, or
27 director thereof, does any of the following:

28 (a) Violates any section of this chapter [the Motor Vehicle Inspection
Program (Health and Saf. Code, § 44000, et seq.)] and the regulations adopted
pursuant to it, which related to the licensed activities.

(c) Violates any of the regulations adopted by the director pursuant to
this chapter.

(d) Commits any act involving dishonesty, fraud, or deceit whereby
another is injured.

1 (f) Aids or abets unlicensed persons to evade the provisions of this
chapter.

2 13. Section 44072.6 of the Health and Safety Code provides, in pertinent part, that the
3 expiration or suspension of a license by operation of law, or by order or decision of the Director
4 of Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive
5 the Director of jurisdiction to proceed with disciplinary action.

6 14. Section 44072.8 of the Health and Safety Code states:

7 When a license has been revoked or suspended following a hearing under
8 this article, any additional license issued under this chapter in the name of the
licensee may be likewise revoked or suspended by the director.

9 **COST RECOVERY**

10 15. Code section 125.3 provides, in pertinent part, that a Board may request the
11 administrative law judge to direct a licensee found to have committed a violation or violations of
12 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
13 enforcement of the case.

14 **UNDERCOVER OPERATION NO. 1 – JANUARY 6, 2011**

15 16. On or about January 6, 2011, a Bureau undercover operator (“operator”) drove a
16 Bureau-documented 1997 Ford Taurus to Respondent A & Z Smog’s facility and requested a
17 smog inspection. The operator spoke with Respondent Zait and told him that his cousin Ramon
18 recommended the shop. The operator provided Respondent Zait with the paperwork for a
19 previously failed smog inspection and the vehicle registration. The operator asked Respondent
20 Zait if he could help him. Respondent Zait stated he could for \$100. The operator authorized the
21 smog inspection; however, he was not provided with a written estimate prior to the inspection.
22 Respondent Mondragon performed the smog inspection with the assistance of Respondent Zait,
23 who drove the vehicle onto the dynamometer and entered information into the Emission
24 Inspection System (“EIS”). That inspection resulted in the issuance of electronic Certificate of
25 Compliance No. WR350520, certifying that Respondent Mondragon had tested and inspected that
26 vehicle and that the vehicle was in compliance with applicable laws and regulations. In fact,
27 Respondent Mondragon and Respondent Zait performed the smog inspection using the clean
28

1 piping method¹ by using the tail pipe emissions of a vehicle other than the vehicle being certified
2 in order to issue the electronic certificate of compliance. After the inspection was completed, the
3 operator paid Respondent Zait \$100 and was provided with a Vehicle Inspection Report (“VIR”)
4 and two copies of an unnumbered invoice.

5 **FIRST CAUSE FOR DISCIPLINE**

6 **(Misleading Statements)**

7 17. Respondent A & Z Smog has subjected his registration to discipline under Code
8 section 9884.7, subdivision (a)(1), in that on or about January 6, 2011, he made statements which
9 he knew or which by exercise of reasonable care he should have known were untrue or
10 misleading when he issued electronic Certificate of Compliance No. WR350520 for the 1997
11 Ford Taurus, certifying that the vehicle was in compliance with applicable laws and regulations
12 when, in fact, the vehicle had been clean piped.

13 **SECOND CAUSE FOR DISCIPLINE**

14 **(Fraud)**

15 18. Respondent A & Z Smog has subjected his registration to discipline under Code
16 section 9884.7, subdivision (a)(4), in that on or about January 6, 2011, he committed acts which
17 constitute fraud by issuing electronic Certificate of Compliance No. WR350520 for the 1997 Ford
18 Taurus without performing a bona fide inspection of the emission control devices and systems on
19 that vehicle, thereby depriving the People of the State of California of the protection afforded by
20 the Motor Vehicle Inspection Program.

21 **THIRD CAUSE FOR DISCIPLINE**

22 **(Failure to Provide a Written Estimate)**

23 19. Respondent A & Z Smog has subjected his registration to discipline under Code
24 section 9884.7, subdivision (a)(6), in that on or about January 6, 2011, he failed to comply with
25

26 ¹ “Clean piping” is sampling the (clean) tailpipe emissions and/or the RPM readings of
27 another vehicle for the purpose of illegally issuing smog certifications to vehicles that are not in
28 compliance or are not present in the smog check area during the time of the certification.

1 section 9884.9, subdivision (a). Respondent failed to provide the operator with a written
2 estimated price for a specific job regarding the smog inspection.

3 **FOURTH CAUSE FOR DISCIPLINE**

4 **(Violation of the Motor Vehicle Inspection Program)**

5 20. Respondent A & Z Smog has subjected his station license to discipline under Health
6 and Safety Code section 44072.2, subdivision (a), in that on or about January 6, 2011, regarding
7 the 1997 Ford Taurus, he violated sections of that Code, as follows:

8 a. **Section 44012, subdivision (a):** Respondent A & Z Smog failed to determine that all
9 emission control devices and systems required by law were installed and functioning correctly in
10 accordance with test procedures.

11 b. **Section 44012, subdivision (f):** Respondent A & Z Smog failed to perform emission
12 control tests on that vehicle in accordance with procedures prescribed by the department.

13 c. **Section 44014, subdivision (a):** Respondent A & Z Smog allowed Respondent Zait
14 to participate in the inspection of that vehicle when Zait's technician license was expired.

15 d. **Section 44015, subdivision (b):** Respondent A & Z Smog issued electronic
16 Certificate of Compliance No. WR350520 without properly testing and inspecting that vehicle to
17 determine if it was in compliance with section 44012 of that Code.

18 e. **Section 44059:** Respondent A & Z Smog willfully made false entries for electronic
19 Certificate of Compliance No. WR350520 by certifying that the vehicle had been inspected as
20 required when, in fact, it had not.

21 **FIFTH CAUSE FOR DISCIPLINE**

22 **(Violations of Regulations Pursuant to the Motor Vehicle Inspection Program)**

23 21. Respondent A & Z Smog has subjected his station license to discipline under Health
24 and Safety Code section 44072.2, subdivision (c), in that on or about January 6, 2011, regarding
25 the 1997 Ford Taurus, he violated sections of the California Code of Regulations, title 16, as
26 follows:

27 a. **Section 3340.24, subdivision (c):** Respondent A & Z Smog falsely or fraudulently
28 issued electronic Certificate of Compliance No. WR350520 without performing a bona fide

1 inspection of the emission control devices and systems on that vehicle as required by Health and
2 Safety Code section 44012.

3 b. **Section 3340.35, subdivision (c):** Respondent A& Z Smog issued electronic
4 Certificate of Compliance No. WR350520 even though that vehicle had not been inspected in
5 accordance with section 3340.42 of that Code.

6 c. **Section 3340.42:** Respondent A & Z Smog failed to conduct the required smog tests
7 and inspections on that vehicle in accordance with the Bureau's specifications.

8 **SIXTH CAUSE FOR DISCIPLINE**

9 **(Dishonesty, Fraud or Deceit)**

10 22. Respondent A & Z Smog has subjected his station license to discipline under Health
11 and Safety Code section 44072.2, subdivision (d), in that on or about January 6, 2011, regarding
12 the 1997 Ford Taurus, he committed acts involving dishonesty, fraud or deceit whereby another
13 was injured by issuing electronic Certificate of Compliance No. WR350520 for that vehicle
14 without performing a bona fide inspection of the emission control devices and systems on the
15 vehicle, thereby depriving the People of the State of California of the protection afforded by the
16 Motor Vehicle Inspection Program.

17 **SEVENTH CAUSE FOR DISCIPLINE**

18 **(Aiding and Abetting Unlicensed Activity)**

19 23. Respondent A & Z Smog has subjected his station license to discipline under Health
20 and Safety Code section 44072.2, subdivision (f), in that on or about January 6, 2011, regarding
21 the 1997 Ford Taurus, he aided and abetted Respondent Zait to evade the provisions of this
22 chapter by allowing him to participate in the smog inspection on that vehicle when Zait's
23 technician license was expired.

24 **EIGHTH CAUSE FOR DISCIPLINE**

25 **(Violations of the Motor Vehicle Inspection Program)**

26 24. Respondent Mondragon has subjected his technician license to discipline under
27 Health and Safety Code section 44072.2, subdivision (a), in that on or about January 6, 2011,
28 regarding the 1997 Ford Taurus, he violated sections of that Code, as follows:

1 a. **Section 44012, subdivision (a):** Respondent Mondragon failed to determine that all
2 emission control devices and systems required by law were installed and functioning correctly in
3 accordance with test procedures.

4 b. **Section 44012, subdivision (f):** Respondent Mondragon failed to perform emission
5 control tests on that vehicle in accordance with procedures prescribed by the department.

6 c. **Section 44014, subdivision (a):** Respondent Mondragon allowed Respondent Zait to
7 participate in the inspection of the vehicle when Zait's technician license was expired.

8 d. **Section 44032:** Respondent Mondragon failed to perform tests of the emission
9 control devices and systems on that vehicle in accordance with section 44012 of that Code, in that
10 the vehicle had been clean piped.

11 e. **Section 44059:** Respondent Mondragon willfully made false entries for electronic
12 Certificate of Compliance No. WR350520 by certifying that the vehicle had been inspected as
13 required when, in fact, it had not.

14 **NINTH CAUSE FOR DISCIPLINE**

15 **(Violations of Regulations Pursuant to the Motor Vehicle Inspection Program)**

16 25. Respondent Mondragon has subjected his technician license to discipline under
17 Health and Safety Code section 44072.2, subdivision (c), in that on or about January 6, 2011,
18 regarding the 1997 Ford Taurus, he violated sections of the California Code of Regulations, title
19 16, as follows:

20 a. **Section 3340.24, subdivision (c):** Respondent Mondragon falsely or fraudulently
21 issued electronic Certificate of Compliance No. WR350520 without performing a bona fide
22 inspection of the emission control devices and systems on that vehicle as required by Health and
23 Safety Code section 44012.

24 b. **Section 3340.30, subdivision (a):** Respondent Mondragon failed to inspect and test
25 that vehicle in accordance with Health and Safety Code section 44012.

26 c. **Section 3340.42:** Respondent Mondragon failed to conduct the required smog tests
27 and inspections on that vehicle in accordance with the Bureau's specifications.

28

1 TENTH CAUSE FOR DISCIPLINE

2 (Dishonesty, Fraud or Deceit)

3 26. Respondent Mondragon has subjected his technician license to discipline under
4 Health and Safety Code section 44072.2, subdivision (d), in that on or about January 6, 2011, he
5 committed acts involving dishonesty, fraud or deceit whereby another was injured by issuing
6 electronic Certificate of Compliance No. WR350520 for the 1997 Ford Taurus without
7 performing a bona fide inspection of the emission control devices and systems on that vehicle,
8 thereby depriving the People of the State of California of the protection afforded by the Motor
9 Vehicle Inspection Program.

10 ELEVENTH CAUSE FOR DISCIPLINE

11 (Aiding and Abetting Unlicensed Activity)

12 27. Respondent Mondragon has subjected his technician license to discipline under
13 Health and Safety Code section 44072.2, subdivision (f), in that on or about January 6, 2011,
14 regarding the 1997 Ford Taurus, he aided and abetted Respondent Zait to evade the provisions of
15 this chapter by allowing him to participate in the smog inspection on that vehicle when Zait's
16 technician license was expired.

17 TWELFTH CAUSE FOR DISCIPLINE

18 (Violations of the Motor Vehicle Inspection Program)

19 28. Respondent Zait has subjected his technician license to discipline under Health and
20 Safety Code section 44072.2, subdivision (a), in that on or about January 6, 2011, regarding the
21 1997 Ford Taurus, he violated sections of that Code, as follows:

22 a. **Section 44012, subdivision (a):** Respondent Zait failed to determine that all
23 emission control devices and systems required by law were installed and functioning correctly in
24 accordance with test procedures.

25 b. **Section 44012, subdivision (f):** Respondent Zait failed to perform emission control
26 tests on that vehicle in accordance with procedures prescribed by the department.

27 c. **Section 44014, subdivision (a):** Respondent Zait participated in the smog inspection
28 on that vehicle when his technician license was expired.

1 d. **Section 44032:** Respondent Zait failed to perform tests of the emission control
2 devices and systems on that vehicle in accordance with section 44012 of that Code, in that the
3 vehicle had been clean piped.

4 **THIRTEENTH CAUSE FOR DISCIPLINE**

5 **(Violations of Regulations Pursuant to the Motor Vehicle Inspection Program)**

6 29. Respondent Zait has subjected his technician license to discipline under Health and
7 Safety Code section 44072.2, subdivision (c), in that on or about January 6, 2011, regarding the
8 1997 Ford Taurus, he violated sections of the California Code of Regulations, title 16, as follows:

9 a. **Section 3340.30, subdivision (a):** Respondent Zait failed to inspect and test that
10 vehicle in accordance with Health and Safety Code section 44012.

11 b. **Section 3340.41, subdivision (c):** Respondent Zait entered false information into the
12 EIS for electronic Certificate of Compliance No. WR350520 by entering vehicle emission control
13 information for a vehicle other than the vehicle being certified.

14 c. **Section 3340.42:** Respondent Zait failed to conduct the required smog tests and
15 inspections on that vehicle in accordance with the Bureau's specifications.

16 **UNDERCOVER OPERATION NO. 2 – MARCH 8, 2011**

17 30. On or about March 8, 2011, the Bureau planned to perform a second undercover
18 operation at Respondent A & Z Smog's facility. The undercover operator drove the vehicle to
19 Respondent A & Z Smog for a smog inspection. The operator spoke with Respondent Zait. The
20 operator provided Respondent Zait with a VIR from a previously failed smog inspection.
21 Respondent Zait informed the operator that the smog inspection would cost \$100 but that the
22 vehicle would have to be inspected at another of his facilities because he had too many vehicles.
23 The operator paid Respondent Zait \$100 and drove the vehicle to Amigo Smog's facility also
24 located in Mira Loma, California, where the smog inspection was performed.

25 **UNDERCOVER OPERATION NO. 3 – APRIL 22, 2011**

26 31. On or about April 22, 2011, a Bureau undercover operator ("operator") drove a
27 Bureau-documented 1986 Chevrolet Monte Carlo to Respondent A & Z Smog's facility and
28 requested a smog inspection. The vehicle could not pass a smog inspection due to excessive

1 tailpipe emissions. Further, the vehicle had a faulty bulb in the malfunction indicator light socket
2 that would further keep the vehicle from passing the MIL functional check. The operator spoke
3 with a Middle Eastern male, who asked the operator if the vehicle was alright. The operator told
4 him he did not know. The operator then spoke with another male named Roberto, who wanted to
5 know whether or not the vehicle had been tested at another facility. The operator told him no.
6 Robert then informed the operator that the smog inspection would cost \$100. Roberto also stated
7 to the operator: "Trust me, it will be okay". The operator paid Roberto \$100 but did not receive
8 any paperwork. While the vehicle was being tested, the operator asked Roberto if he was the
9 owner of the facility. Roberto said he was not, but pointed to a middle-eastern male, later
10 identified as Respondent Zait, and told the operator that he was the owner. After the inspection
11 was completed, Roberto provided the operator with the pink and yellow copies of an unnumbered
12 invoice that indicated the operator paid \$40 for the smog inspection, and a VIR. The paperwork
13 had been filled out and signed; however, not by the operator. The VIR indicated that Respondent
14 Flores performed the smog inspection; however, another licensed technician, Samer Ibrahim
15 Alhsinat, drove the undercover vehicle onto the dynamometer. Respondent Flores issued
16 electronic Certificate of Compliance No. WV075817, certifying that he had tested and inspected
17 that vehicle and that the vehicle was in compliance with applicable laws and regulations. In fact,
18 the smog inspection was performed using the clean piping method by using the tail pipe
19 emissions of a vehicle other than the vehicle being certified in order to issue the electronic
20 certificate of compliance. The Bureau also discovered that a low pressure fuel evaporative
21 functional test had not been performed.

22 **FOURTEENTH CAUSE FOR DISCIPLINE**

23 **(Misleading Statements)**

24 32. Respondent A & Z Smog has subjected his registration to discipline under Code
25 section 9884.7, subdivision (a)(1), in that on or about April 22, 2011, he made statements which
26 he knew or which by exercise of reasonable care he should have known were untrue or
27 misleading when he issued electronic Certificate of Compliance No. WV075817 for the 1986
28

1 Chevrolet Monte Carlo, certifying that the vehicle was in compliance with applicable laws and
2 regulations when, in fact, the vehicle had been clean piped.

3 **FIFTEENTH CAUSE FOR DISCIPLINE**

4 **(Fraud)**

5 33. Respondent A & Z Smog has subjected his registration to discipline under Code
6 section 9884.7, subdivision (a)(4), in that on or about April 22, 2011, he committed acts which
7 constitute fraud by issuing electronic Certificate of Compliance No. WV075817 for the 1986
8 Chevrolet Monte Carlo without performing a bona fide inspection of the emission control devices
9 and systems on that vehicle, thereby depriving the People of the State of California of the
10 protection afforded by the Motor Vehicle Inspection Program.

11 **SIXTEENTH CAUSE FOR DISCIPLINE**

12 **(Failure to Provide a Written Estimate)**

13 34. Respondent A & Z Smog has subjected his registration to discipline under Code
14 section 9884.7, subdivision (a)(6), in that on or about April 22, 2011, he failed to comply with
15 section 9884.9, subdivision (a). Respondent A & Z Smog failed to provide the operator with a
16 written estimated price for a specific job regarding the smog inspection.

17 **SEVENTEENTH CAUSE FOR DISCIPLINE**

18 **(Violation of the Motor Vehicle Inspection Program)**

19 35. Respondent A & Z Smog has subjected his station license to discipline under Health
20 and Safety Code section 44072.2, subdivision (a), in that on or about April 22, 2011, regarding
21 the 1986 Chevrolet Monte Carlo, he violated sections of that Code, as follows:

22 a. **Section 44012, subdivision (a):** Respondent A & Z Smog failed to determine that all
23 emission control devices and systems required by law were installed and functioning correctly in
24 accordance with test procedures.

25 b. **Section 44012, subdivision (f):** Respondent A & Z Smog failed to perform emission
26 control tests on that vehicle in accordance with procedures prescribed by the department.

27 ///

28 ///

1 c. **Section 44015, subdivision (b):** Respondent A & Z Smog issued electronic
2 Certificate of Compliance No. WV075817 without properly testing and inspecting that vehicle to
3 determine if it was in compliance with section 44012 of that Code.

4 d. **Section 44059:** Respondent A & Z Smog willfully made false entries for electronic
5 Certificate of Compliance No. WV075817 by certifying that the vehicle had been inspected as
6 required when, in fact, it had not.

7 **EIGHTEENTH CAUSE FOR DISCIPLINE**

8 **(Violations of Regulations Pursuant to the Motor Vehicle Inspection Program)**

9 36. Respondent A & Z Smog has subjected his station license to discipline under Health
10 and Safety Code section 44072.2, subdivision (c), in that on or about April 22, 2011, regarding
11 the 1986 Chevrolet Monte Carlo, he violated sections of the California Code of Regulations, title
12 16, as follows:

13 a. **Section 3340.24, subdivision (c):** Respondent A & Z Smog falsely or fraudulently
14 issued electronic Certificate of Compliance No. WV075817 without performing a bona fide
15 inspection of the emission control devices and systems on that vehicle as required by Health and
16 Safety Code section 44012.

17 b. **Section 3340.35, subdivision (c):** Respondent A & Z Smog issued electronic
18 Certificate of Compliance No. WV075817 even though that vehicle had not been inspected in
19 accordance with section 3340.42 of that Code.

20 c. **Section 3340.42:** Respondent A & Z Smog failed to conduct the required smog tests
21 and inspections on that vehicle in accordance with the Bureau's specifications.

22 **NINETEENTH CAUSE FOR DISCIPLINE**

23 **(Dishonesty, Fraud or Deceit)**

24 37. Respondent A & Z Smog has subjected his station license to discipline under Health
25 and Safety Code section 44072.2, subdivision (d), in that on or about April 22, 2011, regarding
26 the 1986 Chevrolet Monte Carlo, he committed acts involving dishonesty, fraud or deceit
27 whereby another was injured by issuing electronic Certificate of Compliance No. WV075817 for
28 that vehicle without performing a bona fide inspection of the emission control devices and

1 systems on the vehicle, thereby depriving the People of the State of California of the protection
2 afforded by the Motor Vehicle Inspection Program.

3 **TWENTIETH CAUSE FOR DISCIPLINE**

4 **(Violations of the Motor Vehicle Inspection Program)**

5 38. Respondent Flores has subjected his technician license to discipline under Health and
6 Safety Code section 44072.2, subdivision (a), in that on or about April 22, 2011, regarding the
7 1986 Chevrolet Monte Carlo, he violated sections of that Code, as follows:

8 a. **Section 44012, subdivision (a):** Respondent Flores failed to determine that all
9 emission control devices and systems required by law were installed and functioning correctly in
10 accordance with test procedures.

11 b. **Section 44012, subdivision (f):** Respondent Flores failed to perform emission
12 control tests on that vehicle in accordance with procedures prescribed by the department.

13 c. **Section 44032:** Respondent Flores failed to perform tests of the emission control
14 devices and systems on that vehicle in accordance with section 44012 of that Code, in that the
15 vehicle had been clean piped.

16 d. **Section 44059:** Respondent Flores willfully made false entries for electronic
17 Certificate of Compliance No. WV075817 by certifying that the vehicle had been inspected as
18 required when, in fact, it had not.

19 **TWENTY-FIRST CAUSE FOR DISCIPLINE**

20 **(Violations of Regulations Pursuant to the Motor Vehicle Inspection Program)**

21 39. Respondent Flores has subjected his technician license to discipline under Health and
22 Safety Code section 44072.2, subdivision (c), in that on or about April 22, 2011, regarding the
23 1986 Chevrolet Monte Carlo, he violated sections of the California Code of Regulations, title 16,
24 as follows:

25 a. **Section 3340.24, subdivision (c):** Respondent Flores falsely or fraudulently issued
26 electronic Certificate of Compliance No. WV075817 without performing a bona fide inspection
27 of the emission control devices and systems on that vehicle as required by Health and Safety
28 Code section 44012.

1 compliance), both misdemeanors. As a result of this conviction, the Court sentenced Respondent
2 Zait to summary probation for a period of 36 months; to the custody of the Riverside County
3 Sheriff for a term of 120 days, with 20 days credit for time served; and, fines totaling \$330.
4 Respondent Zait was still on probation in the criminal matter when the allegations set forth in
5 paragraphs 28 and 29 occurred.

6 **OTHER MATTERS**

7 42. Pursuant to Code section 9884.7, subdivision (c), the Director may refuse to validate,
8 or may invalidate temporarily or permanently, the registrations for all places of business operated
9 in this state by Abe I. Rabadi upon a finding that he has, or is, engaged in a course of repeated
10 and willful violations of the laws and regulations pertaining to an automotive repair dealer.

11 43. Pursuant to Health & Safety Code section 44072.8, if Smog Check Test Only Station
12 License Number TC 261018, issued to Abe I. Rabadi doing business as A & Z Smog Test Only,
13 is revoked or suspended, any additional license issued under this chapter in the name of said
14 licensee may be likewise revoked or suspended by the director.

15 44. Pursuant to Health & Safety Code section 44072.8, if Advanced Emission Specialist
16 Technician License Number EA 631695, issued to Carlos Eduardo Leon Mondragon, is revoked
17 or suspended, any additional license issued under this chapter in the name of said licensee may be
18 likewise revoked or suspended by the director.

19 45. Pursuant to Health & Safety Code section 44072.8, if Advanced Emission Specialist
20 Technician License Number EA 632244, issued to Michael S. Flores, is revoked or suspended,
21 any additional license issued under this chapter in the name of said licensee may be likewise
22 revoked or suspended by the director.

23 46. Pursuant to Health & Safety Code section 44072.8, if Advanced Emission Specialist
24 Technician License Number EA 152388, issued to Samer George Zait, is revoked or suspended,
25 any additional license issued under this chapter in the name of said licensee may be likewise
26 revoked or suspended by the director.

27 ///

28 ///

PRAYER

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of Consumer Affairs issue a decision:

1. Revoking, suspending or placing on probation Automotive Repair Dealer Registration Number ARD 261018, issued to Abe I. Rabadi doing business as A & Z Smog Test Only;

2. Revoking, suspending or placing on probation any other automotive repair dealer registration issued to Abe I. Rabadi;

3. Revoking or suspending Smog Check Test Only Station License Number TC 261018, issued to Abe I. Rabadi doing business as A & Z Smog Test Only;

4. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name Abe I. Rabadi;

5. Revoking or suspending Advanced Emission Specialist Technician License Number EA 631695, issued to Carlos Eduardo Leon Mondragon;

6. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name of Carlos Eduardo Leon Mondragon;

7. Revoking or suspending Advanced Emission Specialist Technician License Number EA 632244, issued to Michael S. Flores;

8. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name of Michael S. Flores;

9. Revoking or suspending Advanced Emission Specialist Technician License Number EA 152388, issued to Samer George Zait;

10. Revoking or suspending any additional license issued under Chapter 5 of the Health and Safety Code in the name of Samer George Zait;

///

///

///

///


///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

11. Ordering Abe I. Rabadi, Carlos Eduardo Leon Mondragon, Michael S. Flores and Samer George Zait to pay the Bureau of Automotive Repair the reasonable costs of the investigation and enforcement of this case, pursuant to Business and Professions Code section 125.3; and,

12. Taking such other and further action as deemed necessary and proper.

DATED: 8/7/11


SHERRY MEHL
Chief
Bureau of Automotive Repair
Department of Consumer Affairs
State of California
Complainant

SD2011800889
10732153.doc