

**BEFORE THE DIRECTOR  
DEPARTMENT OF CONSUMER AFFAIRS  
BUREAU OF AUTOMOTIVE REPAIR  
STATE OF CALIFORNIA**

In the Matter of Accusation Against:

**FASTER AUTO SERVICE, INC. D.B.A.  
FASTER AUTO SERVICE,  
HAYATULLAH HAMIDI, PRESIDENT,  
SECRETARY & TREASURER  
2655 Monument Blvd., Unit J  
Concord, CA 94520  
Automotive Repair Dealer Registration No. ARD  
260665  
Smog Check Station License No. RC 260665  
Lamp Station License No. LS 260665, A  
Brake Station License No. BS 260665, C**

**HAYATULLAH HAMIDI  
881 San Simeon Drive  
Concord, CA 94518  
Smog Check Inspector License No. EO 138584  
Smog Check Repair Technician No. EI 138584  
(Formerly Advanced Emission Specialist  
Technician License No. EA 138584)  
Brake Adjuster License No. BA 138584, C  
Lamp Adjuster License No. LA 138584, A**

Case No. 77/13-10

OAH No. 2013010572

Respondents.


**DECISION**

The attached Stipulated Settlement and Disciplinary Order is hereby accepted and adopted as the Decision of the Director of the Department of Consumer Affairs in the above-entitled matter. The following typographical errors are noted:

1. Page 3, line 20: The expiration date of BA 138584, C, should be changed from "December 31, 2015" to "December 31, 2014".
2. Page 3, line 25: The expiration date of LA 138584, A, should be changed from "December 31, 2014" to "December 31, 2015".

This Decision shall become effective 7/17/13.

DATED: June 26, 2013

  
\_\_\_\_\_  
DORÉATHEA JOHNSON  
Deputy Director, Legal Affairs  
Department of Consumer Affairs

1 KAMALA D. HARRIS  
Attorney General of California  
2 JOSHUA A. ROOM  
Supervising Deputy Attorney General  
3 ROSAILDA PEREZ  
Deputy Attorney General  
4 State Bar No. 284646  
455 Golden Gate Avenue, Suite 11000  
5 San Francisco, CA 94102-7004  
Telephone: (415) 703-1618  
6 Facsimile: (415) 703-5480  
*Attorneys for Complainant*

7  
8 **BEFORE THE**  
9 **DEPARTMENT OF CONSUMER AFFAIRS**  
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**  
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 77/13-10

13 **FASTER AUTO SERVICE, INC. D.B.A.**  
14 **FASTER AUTO SERVICE,**  
15 **HAYATULLAH HAMIDI, PRESIDENT,**  
16 **SECRETARY & TREASURER**  
2655 Monument Blvd., Unit J  
Concord, CA 94520  
**Automotive Repair Dealer Registration No.**  
17 **ARD 260665**  
**Smog Check Station License No. RC 260665**  
18 **Lamp Station License No. LS 260665, A**  
**Brake Station License No. BS 260665, C**

OAH No. 2013010572  
**STIPULATED SETTLEMENT AND**  
**DISCIPLINARY ORDER**

19 **HAYATULLAH HAMIDI**  
881 San Simeon Drive  
Concord, CA 94518  
20 **Smog Check Inspector License No. EO**  
21 **138584**  
**Smog Check Repair Technician No. EI**  
22 **138584**  
**(Formerly Advanced Emission Specialist**  
23 **Technician License No. EA 138584)**  
**Brake Adjuster License No. BA 138584, C**  
24 **Lamp Adjuster License No. LA 138584, A**

25 Respondents.

26 In the interest of a prompt and speedy settlement of this matter, consistent with the public  
27 interest and the responsibilities of the Director of Consumer Affairs and the Bureau of  
28 Automotive Repair the parties hereby agree to the following Stipulated Settlement and

1 Disciplinary Order which will be submitted to the Director for the Director's approval and  
2 adoption as the final disposition of the Accusation.

3 PARTIES

4 1. John Wallauch (Complainant) is the Chief of the Bureau of Automotive Repair. He  
5 brought this action solely in his official capacity and is represented in this matter by Kamala D.  
6 Harris, Attorney General of the State of California, by Rosailda Perez, Deputy Attorney General.

7 2. Respondents Faster Auto Service, Inc. d.b.a. Faster Auto Service, Hayatullah Hamidi,  
8 President, and Hayatullah Hamidi (collectively Respondents), are represented in this proceeding  
9 by attorney William Ferreira, whose address is: 582 Market Street Suite 1608, San Francisco, CA  
10 94104.

11 **Automotive Repair Dealer Registration**

12 1. On or about February 3, 2010, the Bureau of Automotive Repair issued Automotive  
13 Repair Dealer Registration Number ARD 260665 to Faster Auto Service, Inc. d.b.a. Faster Auto  
14 Service, Hayatullah Hamidi - President, Secretary, and Treasurer (Respondent Facility). The  
15 Automotive Repair Dealer Registration was in full force and effect at all times relevant to the  
16 charges brought herein and will expire on January 31, 2014, unless renewed.

17 **Smog Check Station License**

18 2. On or about February 8, 2010, the Bureau of Automotive Repair issued Smog Check  
19 Station License Number RC 260665 to Respondent Facility. The Smog Check Station License  
20 was in full force and effect at all times relevant to the charges brought herein and will expire on  
21 January 31, 2014, unless renewed.

22 **Lamp Station License**

23 3. On or about February 11, 2010, the Bureau of Automotive Repair issued Lamp  
24 Station License LS 260665, A, to Respondent Facility. The Lamp Station License was in full  
25 force and effect at all times relevant to the charges brought herein and will expire on January 31,  
26 2014, unless renewed.

27 ///

28 ///



1 (Director), for the Bureau of Automotive Repair (Bureau), and is currently pending against  
2 Respondents. The Accusation and all other statutorily required documents were properly served  
3 on Respondents on September 26, 2012. Respondents timely filed their Notices of Defense  
4 contesting the Accusation.

5 4. A copy of Accusation No. 77/13-10 is attached as exhibit A and incorporated herein  
6 by reference.

#### 7 ADVISEMENT AND WAIVERS

8 5. Respondents have carefully read, fully discussed with counsel, and understand the  
9 charges and allegations in Accusation No. 77/13-10. Respondents have also carefully read, fully  
10 discussed with counsel, and understand the effects of this Stipulated Settlement and Disciplinary  
11 Order.

12 6. Respondents are fully aware of their legal rights in this matter, including the right to a  
13 hearing on the charges and allegations in the Accusation; the right to be represented by counsel at  
14 their own expense; the right to confront and cross-examine the witnesses against them; the right  
15 to present evidence and to testify on its own behalf; the right to the issuance of subpoenas to  
16 compel the attendance of witnesses and the production of documents; the right to reconsideration  
17 and court review of an adverse decision; and all other rights accorded by the California  
18 Administrative Procedure Act and other applicable laws.

19 7. Respondents voluntarily, knowingly, and intelligently waive and give up each and  
20 every right set forth above.

#### 21 CULPABILITY

22 8. Respondents admit the truth of each and every charge and allegation in Accusation  
23 No. 77/13-10.

24 9. Respondents agree that their Registration and Licenses are subject to discipline and  
25 they agree to be bound by the Director's orders and probationary terms as set forth in the  
26 Disciplinary Order below.

#### 27 CONTINGENCY

28 10. This stipulation shall be subject to approval by the Director of Consumer Affairs or

1 the Director's designee. Respondents understand and agree that counsel for Complainant and the  
2 staff of the Bureau of Automotive Repair may communicate directly with the Director and staff of  
3 the Department of Consumer Affairs regarding this stipulation and settlement, without notice to  
4 or participation by Respondents or their counsel. By signing the stipulation, Respondents  
5 understand and agree that they may not withdraw its agreement or seek to rescind the stipulation  
6 prior to the time the Director considers and acts upon it. If the Director fails to adopt this  
7 stipulation as the Decision and Order, the Stipulated Settlement and Disciplinary Order shall be of  
8 no force or effect, except for this paragraph, it shall be inadmissible in any legal action between  
9 the parties, and the Director shall not be disqualified from further action by having considered  
10 this matter.

11 11. The parties understand and agree that facsimile copies of this Stipulated Settlement  
12 and Disciplinary Order, including facsimile signatures thereto, shall have the same force and  
13 effect as the originals.

14 12. This Stipulated Settlement and Disciplinary Order is intended by the parties to be an  
15 integrated writing representing the complete, final, and exclusive embodiment of their agreement.  
16 It supersedes any and all prior or contemporaneous agreements, understandings, discussions,  
17 negotiations, and commitments (written or oral). This Stipulated Settlement and Disciplinary  
18 Order may not be altered, amended, modified, supplemented, or otherwise changed except by a  
19 writing executed by an authorized representative of each of the parties.

20 13. In consideration of the foregoing admissions and stipulations, the parties agree that  
21 the Director may, without further notice or formal proceeding, issue and enter the following  
22 Disciplinary Order:

23 **DISCIPLINARY ORDER**

24 IT IS HEREBY ORDERED that the following Registration and Licenses are revoked:

25 Registration/Licenses issued to Respondent Facility:

- 26 • Automotive Repair Dealer Registration No. ARD 260665
- 27 • Smog Check Station License No. RC 260665
- 28 • Lamp Station License No. LS 260665, A

- Brake Station License No. BS 260665, C

Licenses issued to Respondent Hamidi:

- Smog Check Inspector (EO) License No. 138584
- Smog Check Repair Technician (EI) License No. 138584
- Brake Adjuster (BA) License No License No. 138584
- Lamp Adjuster (LA) License No. 138584

However, the revocation of the following Registration and Licenses are stayed and that Registration and those Licenses are placed on probation for three (3) years with the terms and conditions listed below:

Registration/Licenses issued to Respondent Facility:

- Automotive Repair Dealer Registration No. ARD 260665
- Smog Check Station License No. RC 260665

Licenses issued to Respondent Hamidi:

- Smog Check Inspector (EO) License No. 138584
- Smog Check Repair Technician (EI) License No. 138584

**TERMS AND CONDITIONS**

1. **Obey All Laws.** Comply with all statutes, regulations and rules governing automotive inspections, estimates and repairs.


2. **Reporting.** Respondents or Respondents' authorized representative must report in person or in writing as prescribed by the Bureau of Automotive Repair, on a schedule set by the Bureau, but no more frequently than each quarter, on the methods used and success achieved in maintaining compliance with the terms and conditions of probation.

3. **Report Financial Interest.** Within 30 days of the effective date of this action, report any financial interest which any partners, officers, or owners of the Respondent facility may have in any other business required to be registered pursuant to Section 9884.6 of the Business and Professions Code.

4. **Random Inspections.** Provide Bureau representatives unrestricted access to inspect all vehicles (including parts) undergoing repairs, up to and including the point of completion.



1 I have carefully read the above Stipulated Settlement and Disciplinary Order and have fully  
2 discussed it with my attorney, William Ferreira. I understand the stipulation and the effect it will  
3 have on my Smog Check Inspector License, Smog Check Repair Technician License, Lamp  
4 Adjuster License, and Brake Adjuster License. I enter into this Stipulated Settlement and  
5 Disciplinary Order voluntarily, knowingly, and intelligently, and agree to be bound by the  
6 Decision and Order of the Director of Consumer Affairs.

7  
8 DATED: 6-3-13   
9 HAYATULLAH HAMIDI  
10 Respondent

11 I have read and fully discussed with Respondent Facility and Respondent Hamidi the terms  
12 and conditions and other matters contained in the above Stipulated Settlement and Disciplinary  
13 Order. I approve its form and content.

14  
15 DATED: 6-3-2013   
16 WILLIAM FERREIRA  
17 Attorney for Respondent

18 ENDORSEMENT

19 The foregoing Stipulated Settlement and Disciplinary Order is hereby respectfully  
20 submitted for consideration by the Director of Consumer Affairs.

21 Dated: 4/3/13

22 Respectfully submitted,  
23 KAMALA D. HARRIS  
24 Attorney General of California  
25 JOSHUA A. ROOM  
26 Supervising Deputy Attorney General

27   
28 ROSALDA PEREZ  
29 Deputy Attorney General  
30 Attorneys for Complainant

**Exhibit A**

**Accusation No. 77/13-10**

1 KAMALA D. HARRIS  
Attorney General of California  
2 FRANK H. PACOE  
Supervising Deputy Attorney General  
3 BRETT A. KINGSBURY  
Deputy Attorney General  
4 State Bar No. 243744  
455 Golden Gate Avenue, Suite 11000  
5 San Francisco, CA 94102-7004  
Telephone: (415) 703-1192  
6 Facsimile: (415) 703-5480  
*Attorneys for Complainant*

7  
8 **BEFORE THE**  
9 **DEPARTMENT OF CONSUMER AFFAIRS**  
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**  
11 **STATE OF CALIFORNIA**

11 In the Matter of the Accusation Against:  
12 **FASTER AUTO SERVICE, INC. D.B.A.**  
13 **FASTER AUTO SERVICE,**  
14 **HAYATULLAH HAMIDI, PRESIDENT,**  
15 **SECRETARY & TREASURER**  
2655 Monument Blvd., Unit J  
14 Concord, CA 94520  
**Automotive Repair Dealer Registration No.**  
15 **ARD 260665**  
**Smog Check Station License No. RC 260665**  
16 **Lamp Station License No. LS 260665, A**  
**Brake Station License No. BS 260665, C**  
17  
18 **HAYATULLAH HAMIDI**  
881 San Simeon Drive  
18 Concord, CA 94518  
19 **Smog Check Inspector License No. EO**  
**138584**  
20 **Smog Check Check Repair Technician No.**  
**EI 138584**  
21 **(Formerly Advanced Emission Specialist**  
**Technician License No. EA 138584)**  
22 **Brake Adjuster License No. BA 138584, C**  
**Lamp Adjuster License No. LA 138584, A**  
23  
24 Respondents.

Case No. 77/13-10

**AMENDED ACCUSATION**

25 Complainant alleges:

26 **PARTIES**

27 1. John Wallauch (Complainant) brings this Amended Accusation solely in his official  
28 capacity as the Chief of the Bureau of Automotive Repair, Department of Consumer Affairs.

1           **Automotive Repair Dealer Registration**

2           2.     On or about February 3, 2010, the Bureau of Automotive Repair issued Automotive  
3 Repair Dealer Registration Number ARD 260665 to Hayatullah Hamidi - President, Secretary,  
4 and Treasurer, Faster Auto Service, Inc. d.b.a. Faster Auto Service (Respondent Shop). The  
5 Automotive Repair Dealer Registration was in full force and effect at all times relevant to the  
6 charges brought herein and will expire on January 31, 2013, unless renewed.

7           **Smog Check Station License**

8           3.     On or about February 8, 2010, the Bureau of Automotive Repair issued Smog Check  
9 Station License Number RC 260665 to Respondent Shop. The Smog Check Station License was  
10 in full force and effect at all times relevant to the charges brought herein and will expire on  
11 January 31, 2013, unless renewed.

12           **Lamp Station License**

13           4.     On or about February 11, 2010, the Bureau of Automotive Repair issued Lamp  
14 Station License LS 260665, A, to Respondent Shop. The Lamp Station License was in full force  
15 and effect at all times relevant to the charges brought herein and will expire on January 31, 2013,  
16 unless renewed.

17           **Brake Station License**

18           5.     On or about February 10, 2010, the Bureau of Automotive Repair issued Brake  
19 Station License No. BS 260665, C, to Respondent Shop. The Brake Station License was in full  
20 force and effect at all times relevant to the charges brought herein and will expire on January 31,  
21 2013, unless renewed.

22           **Advanced Emission Specialist Technician License**

23           6.     In 2003, the Bureau of Automotive Repair issued Advanced Emission Specialist  
24 Technician License Number EA 138584 to Hayatullah Hamidi (Respondent Hamidi). The  
25 Advanced Emission Specialist Technician License was in full force and effect at all times  
26 relevant to the charges brought herein and expired on December 31, 2012. Pursuant to California  
27 Code of Regulations, title 16, section 3340.28, subdivision (e), said license was renewed,  
28 pursuant to Respondent's election, as Smog Check Inspector License No. EO 138584 and Smog

1 Check Repair Technician License No. EI 138584, effective December 31, 2012.<sup>1</sup> Respondent's  
2 Smog Check Inspector license and Smog Check Repair Technician license will expire on  
3 December 31, 2014.

4 **Brake Adjuster License**

5 7. In 1998, the Bureau of Automotive Repair issued Brake Adjuster License number BA  
6 138584, C, to Respondent Hamidi. The license was in full force and effect at all times relevant to  
7 the charges brought herein and will expire on December 31, 2014, unless renewed.

8 **Lamp Adjuster License**

9 8. In 1999, the Bureau of Automotive Repair issued Lamp Adjuster License number LA  
10 138584, A, to Respondent Hamidi. The license was in full force and effect at all times relevant to  
11 the charges brought herein and will expire on December 31, 2015, unless renewed.

12 **JURISDICTION**

13 9. This Accusation is brought before the Director of Consumer Affairs (Director) for the  
14 Bureau of Automotive Repair, under the authority of the following laws. All section references  
15 are to the Business and Professions Code unless otherwise indicated.

16 10. Section 118, subdivision (b), of the Code provides that the suspension, expiration,  
17 surrender, or cancellation of a license shall not deprive the Director of jurisdiction to proceed  
18 with a disciplinary action during the period within which the license may be renewed, restored,  
19 reissued or reinstated.

20 11. Section 477 of the Code provides, in pertinent part, that "Board" includes "bureau,"  
21 "commission," "committee," "department," "division," "examining committee," "program," and  
22 "agency." "License" includes certificate, registration or other means to engage in a business or  
23 profession regulated by the Code.

24 12. Section 9884.7 of the Code provides that the Director may revoke an automotive  
25 repair dealer registration.

26 <sup>1</sup> Effective August 1, 2012, California Code of Regulations, title 16, sections 3340.28,  
27 3340.29, and 3340.30 were amended to implement a license restructure from the Advanced  
28 Emissions Specialist Technician (EA) license and Basic Area (EB) Technician license to Smog  
Check Inspector (EO) license and/or Smog Check Repair Technician (EI) license.

1           13. Section 9884.13 of the Code provides, in pertinent part, that the expiration of a valid  
2 registration shall not deprive the Director of jurisdiction to proceed with a disciplinary proceeding  
3 against an automotive repair dealer or to render a decision invalidating a registration temporarily  
4 or permanently.

5           14. Section 9889.1 of the Code provides, in pertinent part, that the Director may suspend  
6 or revoke any license issued under Articles 5 and 6 (commencing with section 9887.1) of the  
7 Automotive Repair Act.

8           15. Section 9889.7 of the Code provides, in pertinent part, that the expiration or  
9 suspension of a license by operation of law or by order or decision of the Director or a court of  
10 law, or the voluntary surrender of a license, shall not deprive the Director of jurisdiction to  
11 proceed with any disciplinary proceedings.

12           16. Section 44002 of the Health and Safety Code provides, in pertinent part, that the  
13 Director has all the powers and authority granted under the Automotive Repair Act for enforcing  
14 the Motor Vehicle Inspection Program.

15           17. Section 44072 of the Health and Safety Code provides that the Director may suspend  
16 or revoke any license issued pursuant to the Motor Vehicle Inspection Program.

17           18. Section 44072.6 of the Health and Safety Code provides, in pertinent part, that the  
18 expiration or suspension of a license by operation of law, or by order or decision of the Director  
19 of Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive  
20 the Director of jurisdiction to proceed with disciplinary action.

21           19. Section 44072.8 of the Health and Safety Code states that when a licensee has been  
22 revoked or suspended following a hearing under this article, any additional licenses issued under  
23 this chapter in the name of the licensee may be likewise revoked or suspended by the director.

24           20. California Code of Regulations, title 16, section 3340.28, subdivision (e), states that  
25 [u]pon renewal of an unexpired Basic Area Technician license or an Advanced Emissions  
26 Specialist Technician license issued prior to the effective date of this regulation, the licensee may  
27 apply to renew as a Smog Check Inspector, Smog Check Repair Technician, or both.

28           ///



1           Upon denial of registration, the director shall notify the applicant thereof, in writing, by  
2 personal service or mail addressed to the address of the applicant set forth in the application, and  
3 the applicant shall be given a hearing under Section 9884.12 if, within 30 days thereafter, he or  
4 she files with the bureau a written request for hearing, otherwise the denial is deemed affirmed.

5           "(b) Except as provided for in subdivision (c), if an automotive repair dealer operates more  
6 than one place of business in this state, the director pursuant to subdivision (a) shall only suspend,  
7 revoke, or place on probation the registration of the specific place of business which has violated  
8 any of the provisions of this chapter. This violation, or action by the director, shall not affect in  
9 any manner the right of the automotive repair dealer to operate his or her other places of business.

10           "(c) Notwithstanding subdivision (b), the director may suspend, revoke, or place on  
11 probation the registration for all places of business operated in this state by an automotive repair  
12 dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated  
13 and willful violations of this chapter, or regulations adopted pursuant to it."

14           22. Section 9884.8 of the Code provides:

15           "All work done by an automotive repair dealer, including all warranty work, shall be  
16 recorded on an invoice and shall describe all service work done and parts supplied. Service work  
17 and parts shall be listed separately on the invoice, which shall also state separately the subtotal  
18 prices for service work and for parts, not including sales tax, and shall state separately the sales  
19 tax, if any, applicable to each. If any used, rebuilt, or reconditioned parts are supplied, the invoice  
20 shall clearly state that fact. If a part of a component system is composed of new and used, rebuilt  
21 or reconditioned parts, that invoice shall clearly state that fact. The invoice shall include a  
22 statement indicating whether any crash parts are original equipment manufacturer crash parts or  
23 nonoriginal equipment manufacturer aftermarket crash parts. One copy of the invoice shall be  
24 given to the customer and one copy shall be retained by the automotive repair dealer."

25           23. Section 9884.9 of the Code states:

26           "(a) The automotive repair dealer shall give to the customer a written estimated price for  
27 labor and parts necessary for a specific job. No work shall be done and no charges shall accrue  
28 before authorization to proceed is obtained from the customer. No charge shall be made for work

1 done or parts supplied in excess of the estimated price without the oral or written consent of the  
2 customer that shall be obtained at some time after it is determined that the estimated price is  
3 insufficient and before the work not estimated is done or the parts not estimated are supplied.  
4 Written consent or authorization for an increase in the original estimated price may be provided  
5 by electronic mail or facsimile transmission from the customer. The bureau may specify in  
6 regulation the procedures to be followed by an automotive repair dealer if an authorization or  
7 consent for an increase in the original estimated price is provided by electronic mail or facsimile  
8 transmission. If that consent is oral, the dealer shall make a notation on the work order of the date,  
9 time, name of person authorizing the additional repairs and telephone number called, if any,  
10 together with a specification of the additional parts and labor and the total additional cost, and  
11 shall do either of the following:

12       "(1) Make a notation on the invoice of the same facts set forth in the notation on the work  
13 order.

14       "(2) Upon completion of the repairs, obtain the customer's signature or initials to an  
15 acknowledgment of notice and consent, if there is an oral consent of the customer to additional  
16 repairs, in the following language:

17       "I acknowledge notice and oral approval of an increase in the original estimated price.

18  
19       \_\_\_\_\_

19       (signature or initials)"

20       "Nothing in this section shall be construed as requiring an automotive repair dealer to give a  
21 written estimated price if the dealer does not agree to perform the requested repair.

22       "(b) The automotive repair dealer shall include with the written estimated price a statement  
23 of any automotive repair service that, if required to be done, will be done by someone other than  
24 the dealer or his or her employees. No service shall be done by other than the dealer or his or her  
25 employees without the consent of the customer, unless the customer cannot reasonably be  
26 notified. The dealer shall be responsible, in any case, for any service in the same manner as if the  
27 dealer or his or her employees had done the service.

28       ///

1           "(c) In addition to subdivisions (a) and (b), an automotive repair dealer, when doing auto  
2 body or collision repairs, shall provide an itemized written estimate for all parts and labor to the  
3 customer. The estimate shall describe labor and parts separately and shall identify each part,  
4 indicating whether the replacement part is new, used, rebuilt, or reconditioned. Each crash part  
5 shall be identified on the written estimate and the written estimate shall indicate whether the crash  
6 part is an original equipment manufacturer crash part or a nonoriginal equipment manufacturer  
7 aftermarket crash part.

8           "(d) A customer may designate another person to authorize work or parts supplied in  
9 excess of the estimated price, if the designation is made in writing at the time that the initial  
10 authorization to proceed is signed by the customer. The bureau may specify in regulation the  
11 form and content of a designation and the procedures to be followed by the automotive repair  
12 dealer in recording the designation. For the purposes of this section, a designee shall not be the  
13 automotive repair dealer providing repair services or an insurer involved in a claim that includes  
14 the motor vehicle being repaired, or an employee or agent or a person acting on behalf of the  
15 dealer or insurer."

16           24. Section 9889.3 of the Code states, in pertinent part:

17           "The director may suspend, revoke, or take other disciplinary action against a license as  
18 provided in this article [Article 7 (commencing with section 9889.1) of the Automotive Repair  
19 Act] if the licensee or any partner, officer, or director thereof:

20           "(a) Violates any section of the Business and Professions Code which relates to his or her  
21 licensed activities.

22           "(b) Is convicted of any crime substantially related to the qualifications, functions and  
23 duties of the licenseholder in question.

24           "(c) Violates any of the regulations promulgated by the director pursuant to this chapter  
25 [the Automotive Repair Act].

26           "(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

27           "(e) Has misrepresented a material fact in obtaining a license.

28           "(f) Aids or abets an unlicensed person to evade the provisions of this chapter.

1           “(g) Fails to make and keep records showing his or her transactions as a licensee, or fails to  
2 have the records available for inspection by the director or his or her duly authorized  
3 representative for a period of not less than three years after completion of any transaction to  
4 which the records refer, or refuses to comply with a written request of the director to make the  
5 record available for inspection.

6           “(h) Violates or attempts to violate the provisions of this chapter relating to the particular  
7 activity for which he or she is licensed.

8           “(i) Is convicted of a violation of Section 551 of the Penal Code.”

9           25. Section 44072.2 of the Health and Safety Code states, in pertinent part:

10           “The director may suspend, revoke, or take other disciplinary action against a license as  
11 provided in this article if the licensee, or any partner, officer, or director thereof, does any of the  
12 following:

13           “....

14           “(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

15           “....”

16           26. Section 3305(a) of the California Code of Regulations provides:

17           “(a) All adjusting, inspecting, servicing, and repairing of brake systems and lamp systems  
18 for the purpose of issuing any certificate of compliance or adjustment shall be performed in  
19 official stations, by official adjusters, in accordance with the following, in descending order of  
20 precedence, as applicable:

21           “(1) Vehicle Manufacturers' current standards, specifications and recommended procedures,  
22 as published in the manufacturers' vehicle service and repair manuals.

23           “(2) Current standards, specifications, procedures, directives, manuals, bulletins and  
24 instructions issued by vehicle and equipment or device manufacturers.

25           “(3) Standards, specifications and recommended procedures found in current industry-  
26 standard reference manuals and periodicals published by nationally recognized repair information  
27 providers.

28           ///



1 The noncompliant rear brake drums were still oversized. Both license plate bulbs had been  
2 replaced.

3 **FIRST CAUSE FOR DISCIPLINE**

4 **(Untrue Statements)**

5 32. Respondent Shop's registration is subject to disciplinary action under section  
6 9884.7(a)(1) of the Code in that Respondent Hamidi made or authorized statements which he  
7 knew or in the exercise of reasonable care should have known to be untrue or misleading, as  
8 follows:

- 9 i) Respondent Hamidi certified under penalty of perjury on Brake Certificate Number  
10 BC [REDACTED] that the drums and rotors on the Bureau's 1995 Honda Civic were in  
11 satisfactory condition. In fact, both front rotors were impermissibly undersized and  
12 both rear brake drums were oversized and beyond permissible size.
- 13 ii) Respondent Hamidi certified under penalty of perjury on Brake Certificate Number  
14 BC [REDACTED] that he had performed the applicable inspection, adjustment, or repair on  
15 the drums and rotors of the Bureau's 1995 Honda Civic when in fact he had not.
- 16 iii) Respondent Hamidi certified under penalty of perjury on Lamp Certificate Number  
17 LC [REDACTED] that he had performed the applicable inspection and adjustment of the  
18 headlights of the Bureau's 1995 Honda Civic when in fact he had not.

19 **SECOND CAUSE FOR DISCIPLINE**

20 **(Acts Constituting Fraud)**

21 33. Respondent Shop's registration is subject to disciplinary action pursuant to section  
22 9884.7(a)(4) in that Respondent Hamidi committed acts constituting fraud, as follows:

- 23 i) Respondent Hamidi issued Brake Certificate Number BC [REDACTED] and Lamp  
24 Certificate Number LC [REDACTED] for the the Bureau's 1995 Honda Civic without  
25 ensuring that bona fide inspections were performed of the vehicle's lamps and brakes.
- 26 ii) Respondent Hamidi obtained payment from the operator for performing, in  
27 compliance with the Bureau regulations and/or the Vehicle Code, the applicable  
28 inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

1995 Honda Civic. In fact, the applicable inspections, adjustments, or repairs were not performed.

**THIRD CAUSE FOR DISCIPLINE**

**(Violations of Regulations)**

34. Respondent Shop's registration is subject to disciplinary action under section 9884.7(a)(6) in that Respondent failed to comply with the California Code of Regulations, title 16, in the following material respect:

- i) **Section 3305(a):** Respondent failed to have a licensed adjuster perform the inspection/ adjustment of the brake system and inspection/ adjustment of the lighting system on the Bureau's 1995 Honda Civic in accordance with the specifications, instructions, and directives issued by the Bureau and the vehicle manufacturer.

**FOURTH CAUSE FOR DISCIPLINE**

**(No Estimate)**

35. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.9(a) of the Code in that Respondent failed to give the operator a written estimated price for labor and necessary parts prior to performing the work.

**FIFTH CAUSE FOR DISCIPLINE**

**(No Repair Authorization)**

36. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.9(a) of the Code in that Respondent replaced light bulbs on the Bureau's 1995 Honda Civic without first obtaining authorization from the operator.

**SIXTH CAUSE FOR DISCIPLINE**

**(Deficient Invoice)**

37. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.8 of the Code in that the invoice supplied to the operator with respect to the 1995 Honda Civic did not include all parts supplied. Specifically, the invoice failed to include any statement about the lightbulbs that had been replaced.

///

1 **SEVENTH CAUSE FOR DISCIPLINE**

2 **(Fraud)**

3 38. Respondent Shop's Smog Check Station License is subject to disciplinary action  
4 under section 44072.2(d) of the California Health and Safety Code in that Respondent committed  
5 an act involving dishonesty, fraud, or deceit whereby another was injured. The circumstances are  
6 described above in the Second Cause for Discipline and "Undercover Operation #1: 1995 Honda  
7 Civic."

8 **EIGHTH CAUSE FOR DISCIPLINE**

9 **(Violations of Bus. & Prof. Code)**

10 39. Respondent Shop's Brake Station and Lamp Station licenses are subject to  
11 disciplinary action under sections 9889.3(a) & (h) of the Code in that Respondent violated various  
12 sections of Business and Professions Code Chapter 20.3. The circumstances are described above  
13 in the First through Sixth Causes for Discipline and "Undercover Operation #1: 1995 Honda  
14 Civic."

15 **NINTH CAUSE FOR DISCIPLINE**

16 **(Dishonesty)**

17 40. Respondent Shop's Brake Station and Lamp Station licenses are subject to  
18 disciplinary action under section 9889.3(d) of the Code in that Respondent committed an act  
19 involving dishonesty, fraud, or deceit whereby another was injured. The circumstances are  
20 described above in the Second Cause for Discipline and "Undercover Operation #1: 1995 Honda  
21 Civic."

22 **TENTH CAUSE FOR DISCIPLINE**

23 **(Violation of Regulation)**

24 41. Respondent Shop's Brake Station and Lamp Station licenses are subject to  
25 disciplinary action under section 9889.3(c) of the Code in that Respondent Shop violated a  
26 regulation promulgated pursuant to chapter 20.3 of the Business and Professions Code. The  
27 circumstances are described above in the Third Cause for Discipline and "Undercover Operation  
28 #1: 1995 Honda Civic."

1 **ELEVENTH CAUSE FOR DISCIPLINE**

2 **(Fraud)**

3 42. Respondent Hamidi's Smog Check Inspector License and Smog Check Repair  
4 Technician License are subject to disciplinary action under section 44072.2(d) of the California  
5 Health & Safety Code in that Respondent Hamidi committed an act involving dishonesty, fraud,  
6 or deceit whereby another was injured. Specifically, Respondent obtained payment from the  
7 operator, and issued brake and lamp certificates, for performing the applicable inspections,  
8 adjustments, or repairs of the brake and lighting systems on the Bureau's 1995 Honda Civic. In  
9 fact, the applicable inspections, adjustments, or repairs were not performed.

10 **TWELFTH CAUSE FOR DISCIPLINE**

11 **(Fraud)**

12 43. Respondent Hamidi's Brake Adjuster and Lamp Adjuster licenses are subject to  
13 disciplinary action under section 9889.3(d) of the Code in that Respondent Hamidi committed an  
14 act involving dishonesty, fraud, or deceit whereby another was injured. Specifically, Respondent  
15 obtained payment from the operator, and issued brake and lamp certificates, for performing the  
16 applicable inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's  
17 1995 Honda Civic. In fact, the applicable inspections, adjustments, or repairs were not  
18 performed.

19 **THIRTEENTH CAUSE FOR DISCIPLINE**

20 **(Violation of Regulations)**

21 44. Respondent Hamidi's Brake Adjuster and Lamp Adjuster licenses are subject to  
22 disciplinary action under section 9889.3(c) of the Code in that Respondent Hamidi violated a  
23 regulation promulgated pursuant to chapter 20.5 of the Business & Professions Code, specifically:

- 24 i) **Section 3305(a):** Respondent Hamidi failed to perform the inspection/ adjustment of  
25 the brake system and inspection/ adjustment of the lighting system on the Bureau's  
26 1995 Honda Civic in accordance with the specifications, instructions, and directives  
27 issued by the Bureau and the vehicle manufacturer.

28 ///



- 1 i) Respondent Hamidi certified under penalty of perjury on Brake Certificate Number  
2 BC [REDACTED] that the drums and rotors on the Bureau's 1994 Ford Thunderbird were in  
3 satisfactory condition. In fact, the driver's side front disc brake rotor had been  
4 machined to a thickness that is below the factory minimum specification, and the  
5 driver's side rear brake drum had been machined to a diameter larger than the factory  
6 maximum specification.
- 7 ii) Respondent Hamidi certified under penalty of perjury on Brake Certificate Number  
8 BC [REDACTED] that he had performed the applicable inspection, adjustment, or repair on  
9 the drums and rotors of the Bureau's 1994 Ford Thunderbird when in fact he had not.
- 10 iii) Respondent Hamidi certified under penalty of perjury on Lamp Certificate Number  
11 LC [REDACTED] that he had performed the applicable inspection and adjustment of the  
12 headlights of the Bureau's 1994 Ford Thunderbird when in fact he had not.

13 **FIFTEENTH CAUSE FOR DISCIPLINE**

14 **(Acts Constituting Fraud)**

15 50. Respondent Shop's registration is subject to disciplinary action pursuant to section  
16 9884.7(a)(4) of the Code in that Respondent Hamidi committed acts constituting fraud, as  
17 follows:

- 18 i) Respondent Hamidi issued Brake Certificate Number BC [REDACTED] and Lamp  
19 Certificate Number LC [REDACTED] for the Bureau's 1994 Ford Thunderbird without  
20 ensuring that bona fide inspections were performed of the vehicle's lamps and brakes.
- 21 ii) Respondent Hamidi obtained payment from the operator for performing, in  
22 compliance with Bureau regulations and/or the Vehicle Code, the applicable  
23 inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's  
24 1994 Ford Thunderbird. In fact, the applicable inspections, adjustments, or repairs  
25 were not performed in compliance with the Bureau regulations or the Vehicle Code.

26 ///

27 ///

28 ///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**SIXTEENTH CAUSE FOR DISCIPLINE**

**(Violations of Regulations)**

51. Respondent Shop's registration is subject to disciplinary action under section 9884.7(a)(6) in that Respondent failed to comply with the California Code of Regulations, title 16, in the following material respect:

- i) Section 3305(a): Respondent failed to have a licensed adjuster perform the inspection/ adjustment of the brake system and inspection/ adjustment of the lighting system on the Bureau's 1994 Ford Thunderbird in accordance with the specifications, instructions, and directives issued by the Bureau and the vehicle manufacturer.

**SEVENTEENTH CAUSE FOR DISCIPLINE**

**(No Estimate)**

52. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.9(a) of the Code in that Respondent failed to give the operator a written estimated price for labor and necessary parts prior to performing the work.

**EIGHTEENTH CAUSE FOR DISCIPLINE**

**(No Repair Authorization)**

53. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.9(a) of the Code in that Respondent replaced a lightbulb on the Bureau's 1994 Ford Thunderbird without first obtaining authorization from the operator.

**NINETEENTH CAUSE FOR DISCIPLINE**

**(Deficient Invoice)**

54. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.8 of the Code in that the invoice provided to the operator with respect to the 1994 Ford Thunderbird did not include all parts supplied. Specifically, the invoice failed to include any statement about the lightbulb that had been replaced.

///  
///  
///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**TWENTIETH CAUSE FOR DISCIPLINE**

**(Fraud)**

55. Respondent Shop's Smog Check Station License is subject to disciplinary action under section 44072.2(d) of the California Health and Safety Code in that Respondent committed an act involving dishonesty, fraud, or deceit whereby another was injured. The circumstances are described above in the Fifteenth Cause for Discipline and "Undercover Operation #2:1994 Ford Thunderbird."

**TWENTY-FIRST CAUSE FOR DISCIPLINE**

**(Violations of Bus. & Prof. Code)**

56. Respondent Shop's Brake Station and Lamp Station licenses are subject to disciplinary action under section 9889.3(a) of the Code in that Respondent violated various sections of Business and Professions Code Chapter 20.3. The circumstances are described above in the Fourteenth through Nineteenth Cause for Discipline and "Undercover Operation #2:1994 Ford Thunderbird."

**TWENTY-SECOND CAUSE FOR DISCIPLINE**

**(Dishonesty)**

57. Respondent Shop's Brake Station and Lamp Station licenses are subject to disciplinary action under section 9889.3(d) of the Code in that Respondent committed an act involving dishonesty, fraud, or deceit whereby another was injured. The circumstances are described above in the Fifteenth Cause for Discipline and "Undercover Operation #2:1994 Ford Thunderbird."

**TWENTY-THIRD CAUSE FOR DISCIPLINE**

**(Violation of Regulations)**

58. Respondent Shop's Brake Station and Lamp Station licenses are subject to disciplinary action under 9889.3(c) of the Code in that Respondent Shop violated a regulation promulgated pursuant to chapter 20.3 of the Business and Professions Code. The circumstances are described above in the Sixteenth Cause for Discipline.

///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**TWENTY-FOURTH CAUSE FOR DISCIPLINE**

**(Fraud)**

59. Respondent Hamidi's Smog Check Inspector License and Smog Check Repair Technician License are subject to disciplinary action under section 44072.2(d) of the California Health and Safety Code in that Respondent Hamidi committed an act involving dishonesty, fraud, or deceit whereby another was injured. Specifically, Respondent obtained payment from the operator, and issued brake and lamp certificates, for performing the applicable inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's 1994 Ford Thunderbird. In fact, the applicable inspections, adjustments, or repairs were not performed.

**TWENTY-FIFTH CAUSE FOR DISCIPLINE**

**(Fraud)**

60. Respondent Hamidi's Brake Adjuster and Lamp Adjuster licenses are subject to disciplinary action under section 9889.3(d) of the Code in that Respondent Hamidi committed an act involving dishonesty, fraud, or deceit whereby another was injured. Specifically, Respondent obtained payment from the operator, and issued brake and lamp certificates, for performing the applicable inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's 1994 Ford Thunderbird. In fact, the applicable inspections, adjustments, or repairs were not performed.

**TWENTY-SIXTH CAUSE FOR DISCIPLINE**

**(Violation of Regulations)**

61. Respondent Hamidi's Brake Adjuster and Lamp Adjuster licenses are subject to disciplinary action under section 9889.3(c) of the Code in that Respondent Hamidi violated a regulation promulgated pursuant to chapter 20.3 of the Business & Professions Code, specifically:

- i) **Section 3305(a):** Respondent failed to perform the inspection/ adjustment of the brake system and inspection/ adjustment of the lighting system on the Bureau's 1994 Ford Thunderbird in accordance with the specifications, instructions, and directives issued by the Bureau and the vehicle manufacturer.

///



- 1 ii) Respondent Hamidi certified under penalty of perjury on Brake Certificate Number  
2 BC [REDACTED] that he had performed the applicable inspection, adjustment, or repair on  
3 the drums and rotors of the Bureau's 1985 Oldsmobile Cutlass when in fact he had not.  
4 iii) Respondent Hamidi certified under penalty of perjury on Lamp Certificate Number  
5 LC [REDACTED] that he had performed the applicable inspection and adjustment of the  
6 headlights of the Bureau's 1985 Oldsmobile Cutlass when in fact he had not.

7 **TWENTY-EIGHTH CAUSE FOR DISCIPLINE**

8 **(Acts Constituting Fraud)**

9 67. Respondent Shop's registration is subject to disciplinary action pursuant to section  
10 9884.7(a)(4) of the Code in that Respondent Hamidi committed acts constituting fraud, as  
11 follows:

- 12 i) Respondent Hamidi issued Brake Certificate Number BC [REDACTED] and Lamp  
13 Certificate Number LC [REDACTED] for the Bureau's 1985 Oldsmobile Cutlass without  
14 ensuring that bona fide inspections were performed of the vehicle's lamps and brakes.  
15 ii) Respondent Hamidi obtained payment from the operator for performing, in  
16 compliance with Bureau regulations and/or the Vehicle Code, the applicable  
17 inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's  
18 1985 Oldsmobile Cutlass. In fact, the applicable inspections, adjustments, or repairs  
19 were not performed in compliance with the Bureau regulations or the Vehicle Code.

20 **TWENTY-NINTH CAUSE FOR DISCIPLINE**

21 **(Violations of Regulations)**

22 68. Respondent Shop's registration is subject to disciplinary action under section  
23 9884.7(a)(6) in that Respondent failed to comply with the California Code of Regulations, title  
24 16, in the following material respect:

- 25 i) **Section 3305(a):** Respondent failed to have a licensed adjuster perform the inspection/  
26 adjustment of the brake system and inspection/ adjustment of the lighting system on  
27 the Bureau's 1985 Oldsmobile Cutlass in accordance with the specifications,  
28 instructions, and directives issued by the Bureau and the vehicle manufacturer.

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**THIRTIETH CAUSE FOR DISCIPLINE**

**(No Estimate)**

69. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.9(a) of the Code in that Respondent failed to give the operator a written estimated price for labor and parts necessary prior to performing the work.

**THIRTY-FIRST CAUSE FOR DISCIPLINE**

**(No Repair Authorization)**

70. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.9(a) of the Code in that Respondent replaced a side marker bulb on the Bureau's 1985 Oldsmobile Cutlass without first obtaining authorization from the operator.

**THIRTY-SECOND CAUSE FOR DISCIPLINE**

**(Deficient Invoice)**

71. Respondent Shop's registration is subject to disciplinary action under sections 9884.7(a)(6) and 9884.8 of the Code in that the invoice provided to the operator with respect to the 1985 Oldsmobile Cutlass did not include all parts supplied. Specifically, the invoice failed to include any statement about the side marker bulb that had been replaced.

**THIRTY-THIRD CAUSE FOR DISCIPLINE**

**(Fraud)**

72. Respondent Shop's Smog Check Station License is subject to disciplinary action under section 44072.2(d) of the California Health and Safety Code in that Respondent committed an act involving dishonesty, fraud, or deceit whereby another was injured. The circumstances are described above in the Twenty-Eighth Cause for Discipline and "Undercover Operation #3:1985 Oldsmobile Cutlass."

**THIRTY-FOURTH CAUSE FOR DISCIPLINE**

**(Violations of Bus. & Prof. Code)**

73. Respondent Shop's Brake Station and Lamp Station licenses are subject to disciplinary action under section 9889.3(a) of the Code in that Respondent violated various sections of Business and Professions Code Chapter 20.3. The circumstances are described above

1 in the Twenty-Seventh through Thirty-Second Cause for Discipline and "Undercover Operation  
2 #3:1985 Oldsmobile Cutlass."

3 **THIRTY-FIFTH CAUSE FOR DISCIPLINE**

4 **(Dishonesty)**

5 74. Respondent Shop's Brake Station and Lamp Station licenses are subject to  
6 disciplinary action under section 9889.3(d) of the Code in that Respondent committed an act  
7 involving dishonesty, fraud, or deceit whereby another was injured. The circumstances are  
8 described above in the Twenty-Eighth Cause for Discipline and "Undercover Operation #3:1985  
9 Oldsmobile Cutlass."

10 **THIRTY-SIXTH CAUSE FOR DISCIPLINE**

11 **(Violation of Regulations)**

12 75. Respondent Shop's Brake Station and Lamp Station licenses are subject to  
13 disciplinary action under 9889.3(c) of the Code in that Respondent Shop violated a regulation  
14 promulgated pursuant to chapter 20.3 of the Business and Professions Code. The circumstances  
15 are described above in the Twenty-Ninth Cause for Discipline and "Undercover Operation  
16 #3:1985 Oldsmobile Cutlass."

17 **THIRTY-SEVENTH CAUSE FOR DISCIPLINE**

18 **(Fraud)**

19 76. Respondent Hamidi's Smog Check Inspector License and Smog Check Repair  
20 Technician License are subject to disciplinary action under section 44072.2(d) of the California  
21 Health and Safety Code in that Respondent Hamidi committed an act involving dishonesty, fraud,  
22 or deceit whereby another was injured. Specifically, Respondent obtained payment from the  
23 operator and issued brake and lamp certificates for performing the applicable inspections,  
24 adjustments, or repairs of the brake and lighting systems on the Bureau's 1985 Oldsmobile  
25 Cutlass. In fact, the applicable inspections, adjustments, or repairs were not performed.

26 ///

27 ///

28 ///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**THIRTY-EIGHTH CAUSE FOR DISCIPLINE**

**(Fraud)**

77. Respondent Hamidi's Brake Adjuster and Lamp Adjuster licenses are subject to disciplinary action under section 9889.3(d) of the Code in that Respondent Hamidi committed an act involving dishonesty, fraud, or deceit whereby another was injured. Specifically, Respondent obtained payment from the operator and issued brake and lamp certificates for performing the applicable inspections, adjustments, or repairs of the brake and lighting systems on the Bureau's 1985 Oldsmobile Cutlass. In fact, the applicable inspections, adjustments, or repairs were not performed.

**THIRTY-NINTH CAUSE FOR DISCIPLINE**

**(Violation of Regulations)**

78. Respondent Hamidi's Brake Adjuster and Lamp Adjuster licenses are subject to disciplinary action under section 9889.3(c) of the Code in that Respondent Hamidi violated a regulation promulgated pursuant to chapter 20.3 of the Business & Professions Code, specifically:

- i) **Section 3305(a):** Respondent failed to perform the inspection/ adjustment of the brake system and inspection/ adjustment of the lighting system on the Bureau's 1985 Oldsmobile Cutlass in accordance with the specifications, instructions, and directives issued by the Bureau and the vehicle manufacturer.

**OTHER MATTERS**

79. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the Director may suspend, revoke or place on probation the registration for all places of business operated in this state by Respondent Hamidi, owner of Respondent Shop, upon a finding that Respondent Hamidi has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.

80. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Station License RC260665, issued to Respondent Hamidi, owner of Respondent Shop, is revoked or suspended, any additional license issued under Chapter 5 of the Health & Saf. Code in the name of said licensee may be likewise revoked or suspended by the Director.



- 1           1.    Revoking or suspending Automotive Repair Dealer Registration Number ARD
- 2 260665, issued to Hayatullah Hamidi - President, Secretary, and Treasurer, Faster Auto Service,
- 3 Inc. d.b.a. Faster Auto Service (Respondent Shop);
- 4           2.    Revoking or suspending Smog Check Station License Number RC 260665, issued to
- 5 Respondent Shop;
- 6           3.    Revoking or suspending Lamp Station License Number LS 260665, A, issued to
- 7 Respondent Shop;
- 8           4.    Revoking or suspending Brake Station License Number BS 260665, C, issued to
- 9 Respondent Shop;
- 10          5.    Revoking or suspending Smog Check Inspector License Number EO 138584, issued
- 11 to Hayatullah Hamidi (Respondent Hamidi);
- 12          6.    Revoking or suspending Smog Check Repair Technician License Number EI 138584,
- 13 issued to Hayatullah Hamidi (Respondent Hamidi);
- 14          7.    Revoking or suspending Brake Adjuster License Number BA 138584, C, issued to
- 15 Respondent Hamidi;
- 16          8.    Revoking or suspending Lamp Adjuster License Number LA 138584, A, issued to
- 17 Respondent Hamidi;
- 18          9.    Ordering Respondent Shop and Respondent Hamidi to pay the Bureau of Automotive
- 19 Repair the reasonable costs of the investigation and enforcement of this case, pursuant to
- 20 Business and Professions Code section 125.3;
- 21          10.   Taking such other and further action as deemed necessary and proper.

22  
23  
24 DATED: April 22, 2013

  
JOHN WALLAUCH  
Chief  
Bureau of Automotive Repair  
Department of Consumer Affairs  
State of California  
*Complainant*

25  
26  
27  
28 SF2012401848