

1 KAMALA D. HARRIS  
Attorney General of California  
2 GREGORY J. SALUTE  
Supervising Deputy Attorney General  
3 ADRIAN R. CONTRERAS  
Deputy Attorney General  
4 State Bar No. 267200  
110 West "A" Street, Suite 1100  
5 San Diego, CA 92101  
P.O. Box 85266  
6 San Diego, CA 92186-5266  
Telephone: (619) 645-2634  
7 Facsimile: (619) 645-2061  
E-mail: Adrian.Contreras@doj.ca.gov  
8 *Attorneys for Complainant*

9 **BEFORE THE**  
**DEPARTMENT OF CONSUMER AFFAIRS**  
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**  
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:  
13 **JAMES GILBERT RICHARDS,**  
**PARTNER,**  
14 **MOHAMMED R. AZAD, PARTNER,**  
**DOING BUSINESS AS 7 TO 7 SMOG AND**  
15 **AUTO REPAIR**  
3716 Spruce Street  
Riverside, CA 92501  
16  
Automotive Repair Dealer Registration No.  
17 **ARD 266532**  
18 Smog Check Station License No. **RC 266532**  
19 Lamp Station License No. **LS 266532**  
20 Brake Station License No. **BS 266532,**  
21 **JAMES GILBERT RICHARDS**  
3716 Spruce Street  
22 Riverside, CA 92501  
23 Smog Check Inspector License No. **EO**  
630900 and Smog Check Repair Technician  
24 License No. **EI 630900** (formerly Advanced  
Emission Specialist Technician License No.  
25 **EA 630900**)  
26 Lamp Adjuster License No. **LA 630900**  
27 Brake Adjuster License No. **BA 630900**

Case No. *79/15-110*  
**ACCUSATION**  
*Smog Check*

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**MOHAMMAD RAHIM AZAD**  
12305 Puma Ct.  
Moreno Valley, CA 92555  
Smog Check Inspector License No. EO 636435  
Lamp Adjuster License No. LA 636435  
Brake Adjuster License No. BA 636435,

**JOSE FRANCISCO LEAL**  
13860 Pheasant Knoll Ln.  
Moreno Valley, CA 92553  
Smog Check Inspector License No. EO 637039

**STEPHEN BLACKSHEAR**  
800 E. Washington #730  
Colton, CA 92324  
Advanced Emission Specialist Technician License No. EA 634692 (to be redesignated upon renewal as EO 634692 and/or EI 634692)

Respondents.

Complainant alleges:

**PARTIES**

1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as the Chief of the Bureau of Automotive Repair, Department of Consumer Affairs.
2. On or about September 9, 2011, the Bureau of Automotive Repair issued Automotive Repair Dealer Registration Number ARD 266532 to James Gilbert Richards, Partner, Mohammad Rahim Azad, Partner, doing business as 7 to 7 Smog and Auto Repair (collectively 7 to 7 Smog). The Automotive Repair Dealer Registration was in full force and effect at all times relevant to the charges brought herein and will expire on September 30, 2015, unless renewed.
3. On or about September 22, 2011, the Bureau of Automotive Repair issued Smog Check Station License Number RC 266532 to 7 to 7 Smog. The Smog Check Station License

1 was in full force and effect at all times relevant to the charges brought herein and will expire on  
2 September 30, 2015, unless renewed.

3 4. On or about September 22, 2011, the Bureau of Automotive Repair issued Lamp  
4 Station License No. 266532 to 7 to 7 Smog. The Lamp Station License was in full force and  
5 effect at all times relevant to the charges brought herein and will expire on September 30, 2015,  
6 unless renewed.

7 5. On or about September 22, 2011, the Bureau of Automotive Repair issued Brake  
8 Station License No. 266532 to 7 to 7 Smog. The Brake Station License was in full force and  
9 effect at all times relevant to the charges brought herein and will expire on September 30, 2015,  
10 unless renewed.

11 6. On or about March 19, 2009, Advanced Emission Specialist Technician License EA  
12 630900 was issued to James Gilbert Richards (Richards). Upon timely renewal, and Richards's  
13 election, the license was renewed on July 9, 2013, as Smog Check Repair Technician EI 630900  
14 and Smog Check Inspector License EO 630900.<sup>1</sup> The Smog Check Repair Technician License  
15 and Smog Check Inspector License were in full force and effect at all times relevant to the  
16 charges brought herein and will expire on June 30, 2015, unless renewed.

17 7. On or about March 11, 2010, the Bureau of Automotive Repair issued Lamp Adjuster  
18 License No. LA 630900 to Richards. The Lamp Adjuster License was in full force and effect at  
19 all times relevant to the charges brought herein and will expire on June 30, 2017, unless renewed.

20 8. On or about January 11, 2010, the Bureau of Automotive Repair issued Brake  
21 Adjuster License No. BA 630900 to Richards. The Brake Adjuster License was in full force and  
22 effect at all times relevant to the charges brought herein and will expire on June 30, 2017, unless  
23 renewed.

24 9. On or about January 10, 2014, the Bureau of Automotive Repair issued Smog Check  
25 Inspector No. EO 636435 to Mohammad Rahim Azad (Azad). The Smog Check Inspector was in

26 <sup>1</sup> Effective August 1, 2012, California Code of Regulations, title 16, sections 3340.28,  
27 3340.29, and 3340.30 were amended to implement a license restructure from the Advanced  
28 Emission Specialist Technician (EA) license and Basic Area (EB) Technician license to Smog  
Check Inspector (EO) license and/or Smog Check Repair Technician (EI) license.

1 full force and effect at all times relevant to the charges brought herein and will expire on February  
2 29, 2016, unless renewed.

3 10. On or about April 25, 2014, the Bureau of Automotive Repair issued Lamp Adjuster  
4 License No. LA 636435 to Azad. The Lamp Adjuster License was in full force and effect at all  
5 times relevant to the charges brought herein and will expire on February 28, 2018, unless  
6 renewed.

7 11. On or about January 17, 2014, the Bureau of Automotive Repair Brake Adjuster  
8 License No. BA 636435 to Azad. The Brake Adjuster License was in full force and effect at all  
9 times relevant to the charges brought herein and will expire on February 28, 2017, unless  
10 renewed.

11 12. On or about June 27, 2014, the Bureau of Automotive Repair issued Smog Check  
12 Inspector Number EO 637039 to Jose Francisco Leal (Leal). The Smog Check Inspector was in  
13 full force and effect at all times relevant to the charges brought herein and will expire on  
14 December 31, 2015, unless renewed.

15 13. On or about August 24, 2012, the Bureau of Automotive Repair issued Advanced  
16 Emission Specialist Technician No. EA 634692 to Stephen Blackshear (Blackshear). The  
17 Advanced Emission Specialist Technician License expired on October 31, 2014, and has not been  
18 renewed. Upon timely renewal of the license, it will be redesignated as EO 634692 and/or EI  
19 634692.

#### 20 JURISDICTION

21 14. This Accusation is brought before the Director of Consumer Affairs (Director) for the  
22 Bureau of Automotive Repair, under the authority of the following laws. All references are to the  
23 Business and Professions Code unless otherwise stated.

24 15. Section 118, subdivision (b), of the Code provides that the suspension, expiration,  
25 surrender, or cancellation of a license shall not deprive the Director of jurisdiction to proceed with  
26 a disciplinary action during the period within which the license may be renewed, restored,  
27 reissued or reinstated.

28

1           16. Section 9884.13 of the Code provides, in pertinent part, that the expiration of a valid  
2 registration shall not deprive the director or chief of jurisdiction to proceed with a disciplinary  
3 proceeding against an automotive repair dealer or to render a decision invalidating a registration  
4 temporarily or permanently.

5           17. Section 9884.20 of the Code states:

6           “All accusations against automotive repair dealers shall be filed within three years after the  
7 performance of the act or omission alleged as the ground for disciplinary action, except that with  
8 respect to an accusation alleging fraud or misrepresentation as a ground for disciplinary action,  
9 the accusation may be filed within two years after the discovery, by the bureau, of the alleged  
10 facts constituting the fraud or misrepresentation.”

11           18. Section 9884.22 of the Code states:

12           “(a) Notwithstanding any other provision of law, the director may revoke, suspend, or deny  
13 at any time any registration required by this article on any of the grounds for disciplinary action  
14 provided in this article. The proceedings under this article shall be conducted in accordance with  
15 Chapter 5 (commencing with Section 11500) of Part 1 of Division 3 of Title 2 of the Government  
16 Code, and the director shall have all the powers granted therein.

17           “ . . . ”

18           19. Section 9889.5 of the Code states:

19           “The director may take disciplinary action against any licensee after a hearing as provided  
20 in this article by any of the following:

21           “(a) Imposing probation upon terms and conditions to be set forth by the director.

22           “(b) Suspending the license.

23           “(c) Revoking the license.”

24           20. Section 9889.7 of the Code states:

25           “The expiration or suspension of a license by operation of law or by order or decision of the  
26 director or a court of law, or the voluntary surrender of a license by a licensee shall not deprive  
27 the director of jurisdiction to proceed with any investigation of or action or disciplinary  
28 proceedings against such licensee, or to render a decision suspending or revoking such license.”

1           21. Section 9889.8 of the Code states:

2           “All accusations against licensees shall be filed within three years after the act or omission  
3 alleged as the ground for disciplinary action, except that with respect to an accusation alleging a  
4 violation of subdivision (d) of Section 9889.3, the accusation may be filed within two years after  
5 the discovery by the bureau of the alleged facts constituting the fraud or misrepresentation  
6 prohibited by that section.”

7           22. Section 44002 of the Health and Safety Code provides, in pertinent part, that the  
8 Director has all the powers and authority granted under the Automotive Repair Act for enforcing  
9 the Motor Vehicle Inspection Program.

10          23. Section 44072.4 of the Health and Safety Code states:

11          “The director may take disciplinary action against any licensee after a hearing as provided  
12 in this article by any of the following:

13           “(a) Imposing probation upon terms and conditions to be set forth by the director.

14           “(b) Suspending the license.

15           “(c) Revoking the license.”

16          24. Section 44072.6 of the Health and Safety Code provides, in pertinent part, that the  
17 expiration or suspension of a license by operation of law, or by order or decision of the Director  
18 of Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive  
19 the Director of jurisdiction to proceed with disciplinary action.

20          25. Section 44072.7 of the Health and Safety Code states:

21          “All accusations against licensees shall be filed within three years after the act or omission  
22 alleged as the ground for disciplinary action, except that with respect to an accusation alleging a  
23 violation of subdivision (d) of Section 44072.2, the accusation may be filed within two years after  
24 the discovery by the bureau of the alleged facts constituting the fraud or misrepresentation  
25 prohibited by that section.”

26          ///

27          ///

28          ///



1           “(4) Any other conduct that constitutes fraud.

2           “... .

3           “(6) Failure in any material respect to comply with the provisions of this chapter or  
4 regulations adopted pursuant to it.

5           “... .

6           “(c) Notwithstanding subdivision (b), the director may suspend, revoke, or place on  
7 probation the registration for all places of business operated in this state by an automotive repair  
8 dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated  
9 and willful violations of this chapter, or regulations adopted pursuant to it.”

10          30. Section 9884.11 of the Code states:

11           “Each automotive repair dealer shall maintain any records that are required by regulations  
12 adopted to carry out this chapter. Those records shall be open for reasonable inspection by the  
13 chief or other law enforcement officials. All of those records shall be maintained for at least three  
14 years.”

15          31. Section 9889.3 of the Code states:

16           “The director may suspend, revoke, or take other disciplinary action against a license as  
17 provided in this article if the licensee or any partner, officer, or director thereof:

18           “(a) Violates any section of the Business and Professions Code that relates to his or her  
19 licensed activities.

20           “... .

21           “(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

22           “... .”

23          32. Section 9889.9 of the Code states:

24           “When any license has been revoked or suspended following a hearing under the provisions  
25 of this article, any additional license issued under Articles 5 and 6 of this chapter in the name of  
26 the licensee may be likewise revoked or suspended by the director.”

27          ///

28          ///

1           33. Section 44072.2 of the Health and Safety Code states:

2           "The director may suspend, revoke, or take other disciplinary action against a license as  
3 provided in this article if the licensee, or any partner, officer, or director thereof, does any of the  
4 following:

5           "(a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health  
6 and Saf. Code, § 44000, et seq.)] and the regulations adopted pursuant to it, which related to the  
7 licensed activities.

8           ". . .

9           "(d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.

10          ". . .

11          "(g) Fails to make and keep records showing his or her transactions as a licensee, or fails to  
12 have those records available for inspection by the director or his or her duly authorized  
13 representative for a period of not less than three years after completion of any transaction to which  
14 the records refer, or refuses to comply with a written request of the director to make the records  
15 available for inspection.

16          ". . . ."

17           34. Section 44072.10 of the Health and Safety Code states:

18           "(a) Notwithstanding Sections 44072 and 44072.4, the director, or the director's designee,  
19 pending a hearing conducted pursuant to subdivision (e), may temporarily suspend any smog  
20 check station or technician's license issued under this chapter, for a period not to exceed 60 days,  
21 if the department determines that the licensee's conduct would endanger the public health, safety,  
22 or welfare before the matter could be heard pursuant to subdivision (e), based upon reasonable  
23 evidence of any of the following:

24           "(1) Fraud.

25           "(2) Tampering.

26           "(3) Intentional or willful violation of this chapter or any regulation, standard, or procedure  
27 of the department implementing this chapter.

28

1 “(4) A pattern or regular practice of violating this chapter or any regulation, standard, or  
2 procedure of the department implementing this chapter.

3 “. . .

4 “(c) The department shall revoke the license of any smog check technician or station  
5 licensee who fraudulently certifies vehicles or participates in the fraudulent inspection of vehicles.  
6 A fraudulent inspection includes, but is not limited to, all of the following:

7 “(1) Clean piping, as defined by the department.

8 “(2) Tampering with a vehicle emission control system or test analyzer system.

9 “(3) Tampering with a vehicle in a manner that would cause the vehicle to falsely pass or  
10 falsely fail an inspection.

11 “(4) Intentional or willful violation of this chapter or any regulation, standard, or procedure  
12 of the department implementing this chapter.”

### 13 REGULATORY PROVISIONS

14 35. California Code of Regulations, title 16, section 3340.15, states:

15 "A smog check station shall meet the following requirements for licensure and shall comply  
16 with these requirements at all times while licensed.

17 “. . .

18 “(e) The station shall make, keep secure, and have available for inspection on request of the  
19 bureau, or its representative, legible records showing the station's transactions as a licensee for a  
20 period of not less than three years after completion of any transaction to which the records refer.

21 All records shall be open for reasonable inspection and/or reproduction by the bureau or its  
22 representative. Station records required to be maintained shall include copies of:

23 “(1) All certificates of compliance and certificates of noncompliance in stock and/or issued,

24 “(2) Repair orders relating to the inspection and repair activities, and

25 “(3) Vehicle inspection reports generated either manually or by the emissions inspection  
26 system.

27 “The above listed station records shall be maintained in such a manner that the records for  
28 each transaction are kept together, so as to facilitate access to those records by the bureau or its

1 representative. In this regard, the second copy of an issued certificate shall be attached to the final  
2 invoice record.

3 “. . . .”

4 36. California Code of Regulations, title 16, section 3356, states:

5 “(a) All invoices for service and repair work performed, and parts supplied, as provided for  
6 in Section 9884.8 of the Business and Professions Code, shall comply with the following:

7 “(1) The invoice shall show the automotive repair dealer's registration number and the  
8 corresponding business name and address as shown in the Bureau's records. If the automotive  
9 repair dealer's telephone number is shown, it shall comply with the requirements of subsection (b)  
10 of Section 3371 of this chapter.

11 “(2) The invoice shall separately list, describe and identify all of the following:

12 “(A) All service and repair work performed, including all diagnostic and warranty work,  
13 and the price for each described service and repair.

14 “(B) Each part supplied, in such a manner that the customer can understand what was  
15 purchased, and the price for each described part. The description of each part shall state whether  
16 the part was new, used, reconditioned, rebuilt, or an OEM crash part, or a non-OEM aftermarket  
17 crash part.

18 “(C) The subtotal price for all service and repair work performed.

19 “(D) The subtotal price for all parts supplied, not including sales tax.

20 “(E) The applicable sales tax, if any.

21 “(b) If a customer is to be charged for a part, that part shall be specifically listed as an item  
22 in the invoice, as provided in subparagraph (B) of paragraph (2) of subsection (a) above. If that-  
23 item is not listed in the invoice, it shall not be regarded as a part, and a separate charge may not be  
24 made for it.

25 “(c) Separate billing in an invoice for items generically noted as shop supplies,  
26 miscellaneous parts, or the like, is prohibited.



1 renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be  
2 included in a stipulated settlement.

### 3 CLEAN PLUGGING

4 40. At all times alleged in this Accusation, Richards, Azad, Leal, and Blackshear were  
5 acting in the course and within the scope of a technician, employee, partner, officer, owner, or  
6 member of 7 to 7 Smog.

7 41. In August 2014, the Bureau initiated an investigation of 7 to 7 Smog's smog check  
8 station based on a review of information from the Bureau's Vehicle Information Database to  
9 determine if 7 to 7 Smog or their employees had engaged in fraudulent smog check inspections.

10 42. During a Bureau representative's review of 7 to 7 Smog's certified test results in the  
11 Vehicle Information Database for inspections purportedly performed between April 2 and  
12 December 20, 2014, 11 vehicles identified below had Diagnostic Trouble Codes stored in the  
13 Powertrain Control Module that did not apply to those vehicles for the On Board Diagnostics,  
14 generation II (OBD II) test.<sup>2</sup> The Vehicle Information Database showed that 7 to 7 Smog and  
15 their smog check technicians inspected these vehicles using a method known as "clean  
16 plugging."<sup>3</sup> This resulted in the issuance of fraudulent certificates of compliance for the vehicles  
17 as follows:

---

18 <sup>2</sup> The OBD II is a functional test and is performed on most 1996 and newer vehicles. The  
19 technician is required to connect a test cable from the BAR-97 analyzer to a diagnostic link  
20 connector, which is located in the vehicle's passenger compartment. Through the diagnostic link  
21 connector, the BAR-97 analyzer retrieves information from the vehicle's on-board computer about  
22 the status of the readiness indicators, trouble codes, and the malfunction indicator light. The  
23 readiness indicators tell whether or not the OBD II system has run its self-tests on the vehicle's  
24 emission and engine control systems to completion. If a readiness monitor is not set, it means that  
25 particular system has not been tested. A trouble code results when the vehicle fails one of these  
26 self-tests and identifies the system and/or component which failed. If the trouble code is  
27 persistent, the on-board computer will command the malfunction indicator light to turn on. The  
28 vehicle will fail the OBD II functional test if more than the allowable number of readiness  
monitors have not been set, a trouble code has been set, or the malfunction indicator light has  
been commanded on. It will also fail if the on-board computer will not communicate with the  
BAR 97 through the diagnostic link connector. If the vehicle fails any of the applicable visual or  
functional tests, it will fail the overall inspection.

<sup>3</sup> Clean plugging is the use of the OBD II readiness monitor status and stored code status  
of a passing vehicle for the purpose of illegally issuing a smog certificate to another vehicle that is  
not in compliance due to the noncompliant vehicle's failure to complete the minimum number of  
self tests, known as monitors, or due to the presence of a stored code that indicates an emission  
(continued...)

1 a. Clean Plug 1 – Volvo S40

2 The BAR97 Test Detail from the Vehicle Information Database shows that on April 2,  
3 2014, from 1434 hours to 1441 hours, 7 to 7 Smog and Richards performed a smog check  
4 inspection on a 2003 Volvo S40, VIN #YV1VS27533F973625 (hereafter “Volvo”). The Volvo  
5 was issued Certificate of Compliance #YD826628C. The BAR97 Test Detail shows that  
6 Diagnostic Trouble Code P1238 was stored in the Powertrain Control Module memory of the  
7 Volvo during the time of certification. However, Diagnostic Trouble Code P1238 does not apply  
8 to the Volvo.

9 b. Clean Plug 2 – Toyota Sienna

10 The BAR97 Test Detail from the Vehicle Information Database shows that on April 2,  
11 2014, from 1726 hours to 1739 hours, 7 to 7 Smog and Azad performed a smog check inspection  
12 on a 2002 Toyota Sienna, VIN #4T3ZF13CX2U467801 (hereafter “Sienna”). The Sienna was  
13 issued Certificate of Compliance #YD826631C. The BAR97 Test Detail shows that Diagnostic  
14 Trouble Code P1238 was stored in the Powertrain Control Module memory of the Sienna during  
15 the time of certification. However, Diagnostic Trouble Code P1238 does not apply to the Sienna.

16 c. Clean Plug 3 – Jeep Grand Cherokee

17 The BAR97 Test Detail from the Vehicle Information Database shows that on July 3, 2014,  
18 from 1947 hours to 1957 hours, 7 to 7 Smog and Blackshear performed a smog check inspection  
19 on a 1997 Jeep Grand Cherokee, CA License #5PKP051 (hereafter “Grand Cherokee”). The  
20 Grand Cherokee was issued Certificate of Compliance #YH454313C. The BAR97 Test Detail  
21 shows that Diagnostic Trouble Code P0756 was stored in the Powertrain Control Module memory  
22 of the Grand Cherokee during the time of certification. However, Diagnostic Trouble Code  
23 P0756 does not apply to the Grand Cherokee.

24 \_\_\_\_\_  
25 (...continued)  
26 control system or component failure. Clean plugging occurs during the inspection of a vehicle  
27 that has an OBD II system. To “clean plug” a vehicle, the smog technician enters information  
28 into the Emissions Inspection System for the vehicle the technician wishes to certify and then  
plugs the OBD II system connection from the Emissions Inspection System into another vehicle  
that has a properly functioning OBD II system, rather than plugging the connection into the  
vehicle that was originally identified for testing.

1 d. Clean Plug 4 – Volkswagen Jetta

2 The BAR97 Test Detail from the Vehicle Information Database shows that on July 10,  
3 2014, from 1734 hours to 1748 hours, 7 to 7 Smog and Blackshear performed a smog check  
4 inspection on a 2000 Volkswagen Jetta, VIN #3VWSA29M5YM013470 (hereafter “Jetta”). The  
5 Jetta was issued Certificate of Compliance #YH565002C. The BAR97 Test Detail shows that  
6 Diagnostic Trouble Code P0756 was stored in the Powertrain Control Module memory of the  
7 Jetta during the time of certification. However, Diagnostic Trouble Code P0756 does not apply to  
8 the Jetta.

9 e. Clean Plug 5 – Nissan Frontier

10 The BAR97 Test Detail from the Vehicle Information Database shows that on July 12,  
11 2014, from 1255 hours to 1305 hours, 7 to 7 Smog and Leal performed a smog check inspection  
12 on a 2006 Nissan Frontier, CA License #8D77854 (hereafter “Frontier”). The Frontier was issued  
13 Certificate of Compliance #YH565027C. The BAR97 Test Detail shows that Diagnostic Trouble  
14 Code P0756 was stored in the Powertrain Control Module memory of the Frontier during the time  
15 of certification. However, Diagnostic Trouble Code P0756 does not apply to the Frontier.

16 f. Clean Plug 6 – Subaru Impreza

17 The BAR97 Test Detail from the Vehicle Information Database shows that on July 14,  
18 2014, from 1727 hours to 1734 hours, 7 to 7 Smog and Leal performed a smog check inspection  
19 on a 2006 Subaru Impreza, VIN #JF1GD79666G512791 (hereafter “Impreza”). The Impreza was  
20 issued Certificate of Compliance #YH608456C. The BAR97 Test Detail shows that Diagnostic  
21 Trouble Code P0756 was stored in the Powertrain Control Module memory of the Impreza during  
22 the time of certification. However, Diagnostic Trouble Code P0756 does not apply to the  
23 Impreza.

24 g. Clean Plug 7 –Kia Rio

25 The BAR97 Test Detail from the Vehicle Information Database shows that on October 7,  
26 2014, from 1916 hours to 1921 hours, 7 to 7 Smog and Leal performed a smog check inspection  
27 on a 2005 Kia Rio, VIN #KNADC125X56372289 (hereafter “Rio”). The Rio was issued  
28 Certificate of Compliance #YL063719C. The BAR97 Test Detail shows that Diagnostic Trouble

1 Code P1155 was stored in the Powertrain Control Module memory of the Rio during the time of  
2 certification. However, Diagnostic Trouble Code P1155 does not apply to the Rio.

3 h. Clean Plug 8 – Saturn LW

4 The BAR97 Test Detail from the Vehicle Information Database shows that on October 24,  
5 2014, from 1620 hours to 1635 hours, 7 to 7 Smog and Leal performed a smog check inspection  
6 on a 2000 Saturn LW, VIN #1G8JW82R7YY669757 (hereafter “LW”). The LW was issued  
7 Certificate of Compliance #YL353306C. The BAR97 Test Detail shows that Diagnostic Trouble  
8 Code P1258 was stored in the Powertrain Control Module memory of the LW during the time of  
9 certification. However, Diagnostic Trouble Code P1258 does not apply to the LW.

10 i. Clean Plug 9 – Nissan 200SX

11 The BAR97 Test Detail from the Vehicle Information Database shows that on December  
12 20, 2014, from 1414 hours to 1422 hours, 7 to 7 Smog and Leal performed a smog check  
13 inspection on a 1998 Nissan 200SX, VIN #1N4AB42D0WC513736 (hereafter “200SX”). The  
14 200SX was issued Certificate of Compliance #YN072164C. The BAR97 Test Detail shows that  
15 Diagnostic Trouble Code P0012 was stored in the Powertrain Control Module memory of the  
16 200SX during the time of certification. However, Diagnostic Trouble Code P0012 does not apply  
17 to the 200SX.

18 j. Clean Plug 10 – Jeep Wrangler

19 The BAR97 Test Detail from the Vehicle Information Database shows that on December  
20 20, 2014, from 1716 hours to 1724 hours, 7 to 7 Smog and Leal performed a smog check  
21 inspection on a 2004 Jeep Wrangler, VIN #1J4FA49S84P794238 (hereafter “Wrangler”). The  
22 Wrangler was issued Certificate of Compliance #YN072166C. The BAR97 Test Detail shows  
23 that Diagnostic Trouble Code P0012 was stored in the Powertrain Control Module memory of the  
24 Wrangler during the time of certification. However, Diagnostic Trouble Code P0012 does not  
25 apply to the Wrangler.

26 k. Clean Plug 11 – Nissan Altima

27 The BAR97 Test Detail from the Vehicle Information Database shows that on December  
28 20, 2014, from 1734 hours to 1748 hours, 7 to 7 Smog and Leal performed a smog check

1 inspection on a 2001 Nissan Altima, CA License #6ELY131 (hereafter "Altima"). The Altima  
 2 was issued Certificate of Compliance #YN072167C. The BAR97 Test Detail shows that  
 3 Diagnostic Trouble Code P0012 was stored in the Powertrain Control Module memory of the  
 4 Altima during the time of certification. However, Diagnostic Trouble Code P0012 does not apply  
 5 to the Altima.

6 The following chart summarizes the fraudulent Certificates of Compliance issued by 7 to 7  
 7 Smog, Richards, Azad, Leal, and Blackshear by clean plugging:

	Time of Certification as Recorded in Vehicle Information Database	Vehicle Certified	Unsupported Diagnostic Trouble Code
1	April 2, 2014, from 1434 hours to 1441 hours	2003 Volvo S40 VIN #YV1VS27533F973625 Certificate of Compliance #YD826628C	P1238
2	April 2, 2014, from 1726 hours to 1739 hours	2002 Toyota Sienna VIN #4T3ZF13CX2U467801 Certificate of Compliance #YD826631C	P1238
3	July 3, 2014, from 1947 hours to 1957 hours	1997 Jeep Grand Cherokee CA License #5PKP051 Certificate of Compliance #YH454313C	P0756
4	July 10, 2014, from 1734 hours to 1748 hours	2000 Volkswagen Jetta VIN #3VWSA29M5YM013470 Certificate of Compliance #YH565002C	P0756
5	July 12, 2014, from 1255	2006 Nissan Frontier	P0756

1		hours to 1305 hours	CA License #8D77854	
2			Certificate of Compliance	
3			#YH565027C	
4	6	July 14, 2014, from 1727	2006 Subaru Impreza	P0756
5		hours to 1734 hours	VIN #JF1GD79666G512791	
6			Certificate of Compliance	
7			#YH608456C	
8	7	October 7, 2014, from 1916	2005 Kia Rio	P1155
9		hours to 1921 hours	VIN #KNADC125X56372289	
10			Certificate of Compliance	
11			#YL063719C	
12	8	October 24, 2014, from	2000 Saturn LW	P1258
13		1620 hours to 1635 hours	VIN #1G8JW82R7YY669757	
14			Certificate of Compliance	
15			#YL353306C	
16	9	December 20, 2014, from	1998 Nissan 200SX	P0012
17		1414 hours to 1422 hours	VIN #1N4AB42D0WC513736	
18			Certificate of Compliance	
19			#YN072164C	
20	10	December 20, 2014, from	2004 Jeep Wrangler	P0012
21		1716 hours to 1724 hours	VIN #1J4FA49S84P794238	
22			Certificate of Compliance	
23			#YN072166C	
24	11	December 20, 2014, from	2001 Nissan Altima	P0012
25		1734 hours to 1748 hours	CA License #6ELY131	
26			Certificate of Compliance	
27			#YN072167C	
28	///			

1 **FIRST CAUSE FOR DISCIPLINE**

2 **(Untrue or Misleading Statement)**

3 43. Complainant re-alleges and incorporates by reference the allegations set forth above  
4 in paragraphs 40-42.

5 44. 7 to 7 Smog's Registration is subject to disciplinary action under section 9884.7,  
6 subdivision (a)(1), and 7 to 7 Smog's Lamp Station License and Brake Station License are subject  
7 to discipline under Code section 9889.3, subdivision (a), in that 7 to 7 Smog made or authorized  
8 statements which 7 to 7 Smog knew or in the exercise of reasonable care should have known to be  
9 untrue or misleading.

10 45. 7 to 7 Smog certified that 7 to 7 Smog inspected the vehicle(s) described in  
11 paragraphs 40-42, when in fact the vehicle(s) were not inspected.

12 **SECOND CAUSE FOR DISCIPLINE**

13 **(Violations of Motor Vehicle Inspection Program)**

14 46. Complainant re-alleges and incorporates by reference the allegations set forth above  
15 in paragraphs 40-45.

16 47. 7 to 7 Smog's Smog Check Station License is subject to disciplinary action under  
17 Health and Safety Code sections 44072.10, subdivisions (a) and (c) and 44072.2, subdivision (a),  
18 in that 7 to 7 Smog failed to comply with the following sections of that Code:

19 a. **Section 44012**: failed to perform the tests of the emission control systems and devices  
20 on the vehicle(s) in paragraphs 40-45 in accordance with procedures prescribed by the  
21 Department.

22 b. **Section 44015**: issued a certificate of compliance for the vehicle(s) in paragraphs 40-  
23 45 without properly testing and inspecting them to determine if they were in compliance with  
24 Health & Safety Code section 44012.

25 c. **Section 44035**: failed to meet or maintain the standards prescribed for qualification,  
26 equipment, performance, or conduct by failing to properly perform a smog inspection on the  
27 vehicle(s) in paragraphs 40-45 or certifying that such test(s) had been performed, when in fact  
28 they were never performed.

1 **THIRD CAUSE FOR DISCIPLINE**

2 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)**

3 48. Complainant re-alleges and incorporates by reference the allegations set forth above  
4 in paragraphs 40-47.

5 49. 7 to 7 Smog's Smog Check Station License is subject to disciplinary action under  
6 Health and Safety Code sections 44072.10, subdivisions (a) and (c) and 44072.2, subdivision (a),  
7 in that 7 to 7 Smog failed to comply with the following sections of Title 16, California Code of  
8 Regulations:

9 a. **Section 3340.35, subdivision (c)**: failed to inspect and test the vehicle(s) in  
10 paragraphs 40-47 in accordance with the procedures specified in section 3340.42 of the  
11 Regulations and failed to ensure that the vehicle(s) had all the required emission control  
12 equipment and devices installed and functioning correctly.

13 b. **Section 3340.41, subdivision (c)**: knowingly entered into the Emissions Inspection  
14 System false information about the vehicle(s) in paragraphs 40-47, providing result(s) for smog  
15 inspection(s) which were not actually performed.

16 c. **Section 3340.42**: failed to conduct the required smog tests on the vehicle(s) in  
17 paragraphs 40-47 in accordance with the Bureau's specifications.

18 **FOURTH CAUSE FOR DISCIPLINE**

19 **(Dishonesty, Fraud, or Deceit)**

20 50. Complainant re-alleges and incorporates by reference the allegations set forth above  
21 in paragraphs 40-49.

22 51. 7 to 7 Smog's Registration is subject to disciplinary action under Code section  
23 9884.7, subdivision (a)(4), 7 to 7 Smog's Smog Check Station License is subject to disciplinary  
24 action under Health and Safety Code sections 44072.10, subdivision (a) and (c) and 44072.2,  
25 subdivision (d), and 7 to 7 Smog's Lamp Station License and Brake Station License are subject to  
26 disciplinary action under Code section 9889.3, subdivisions (a) and (d), in that 7 to 7 Smog  
27 committed dishonest, fraudulent, or deceitful acts whereby another is injured by issuing a smog  
28 certificate of compliance for the vehicle(s) in paragraphs 40-49 without performing bona fide

1 inspections of the emission control devices and systems on the vehicle(s), thereby depriving the  
2 People of the State of California of the protection afforded by the Motor Vehicle Inspection  
3 Program.

4 **FIFTH CAUSE FOR DISCIPLINE**

5 **(Failure to Produce Records)**

6 52. Complainant re-alleges and incorporates by reference the allegations set forth above  
7 in paragraphs 40-51.

8 53. 7 to 7 Smog's Registration is subject to disciplinary action under Code section  
9 9884.7, subdivision (a)(6), in conjunction with Code section 9884.11 and California Code of  
10 Regulations, title 16, sections 3356 and 3358; and 7 to 7 Smog's Smog Check Station License is  
11 subject to disciplinary action under Health and Safety Code sections 44072.2, subdivision (g), for  
12 failure to produce records upon the Bureau's request in the following respect:

13 54. On September 19, 2014, a Bureau representative requested 7 to 7 Smog to produce all  
14 original vehicle inspection reports and invoices for all smog inspections 7 to 7 Smog performed  
15 from June 1 to August 31, 2014. The deadline to comply was September 24, 2014. On  
16 September 26, 2014, the Bureau representative received a box of test records from 7 to 7 Smog.  
17 The Bureau representative put the test records into chronological order and found about half of  
18 the requested records were missing. Testing records for clean plug #1-8 were missing. On  
19 October 17, 2014, the Bureau representative returned the records to 7 to 7 Smog. The Bureau  
20 representative informed 7 to 7 Smog of the missing records and of the requirement to have them  
21 available for inspection. 7 to 7 Smog stated they would look for any additional records. The  
22 Bureau representative never heard back from 7 to 7 Smog.

23 **SIXTH CAUSE FOR DISCIPLINE**

24 **(Violation of Motor Vehicle Inspection Program)**

25 55. Complainant re-alleges and incorporates by reference the allegations set forth above  
26 in paragraphs 40-54.

27 56. Richards's Smog Check Repair Technician License and Smog Check Inspector  
28 License are subject to disciplinary action under Health and Safety Code sections 44072.10,

1 subdivisions (a) and (c) and 44072.2, subdivision (a), in that Richards failed to comply with the  
2 following sections of that Code:

3 a. **Section 44012**: failed to perform the tests of the emission control systems and devices  
4 on the vehicle(s) in paragraphs 40-54 in accordance with procedures prescribed by the  
5 Department.

6 b. **Section 44015**: issued a certificate of compliance for the vehicle(s) in paragraphs 40-  
7 54 without properly testing and inspecting them to determine if they were in compliance with  
8 Health & Safety Code section 44012.

9 c. **Section 44035**: failed to meet or maintain the standards prescribed for qualification,  
10 equipment, performance, or conduct by failing to properly perform a smog inspection on the  
11 vehicle(s) in paragraphs 40-54 or certifying that such test(s) had been performed, when in fact  
12 they were never performed.

### 13 **SEVENTH CAUSE FOR DISCIPLINE**

#### 14 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)**

15 57. Complainant re-alleges and incorporates by reference the allegations set forth above  
16 in paragraphs 40-56.

17 58. Richards's Smog Check Repair Technician License and Smog Check Inspector  
18 License are subject to disciplinary action under Health and Safety Code sections 44072.10,  
19 subdivisions (a) and (c) and 44072.2, subdivision (a) in that Richards failed to comply with the  
20 following sections of Title 16, California Code of Regulations:

21 a. **Section 3340.35, subdivision (c)**: failed to inspect and test the vehicle(s) in  
22 paragraphs 40-56 in accordance with the procedures specified in section 3340.42 of the  
23 Regulations and failed to ensure that the vehicle(s) had all the required emission control  
24 equipment and devices installed and functioning correctly.

25 b. **Section 3340.41, subdivision (c)**: knowingly entered into the Emissions Inspection  
26 System false information about the vehicle(s) in paragraphs 40-56, providing result(s) for smog  
27 inspection(s) which were not actually performed.

28

1 c. **Section 3340.42**: failed to conduct the required smog tests on the vehicle(s) in  
2 paragraphs 40-56 in accordance with the Bureau's specifications.

3 **EIGHTH CAUSE FOR DISCIPLINE**

4 **(Dishonesty, Fraud, or Deceit)**

5 59. Complainant re-alleges and incorporates by reference the allegations set forth above  
6 in paragraphs 40-58.

7 60. Richards's Smog Check Repair Technician License and Smog Check Inspector  
8 License are subject to disciplinary action under Health and Safety Code sections 44072.10,  
9 subdivision (a) and (c) and 44072.2, subdivision (d), and his Lamp Adjuster License and Brake  
10 Adjuster License are subject to disciplinary action under Code section 9889.3, subdivision (d), in  
11 that Richards committed dishonest, fraudulent, or deceitful acts whereby another is injured by  
12 issuing a smog certificate of compliance for the vehicle(s) in paragraphs 40-58 without  
13 performing bona fide inspections of the emission control devices and systems on the vehicle(s),  
14 thereby depriving the People of the State of California of the protection afforded by the Motor  
15 Vehicle Inspection Program.

16 **NINTH CAUSE FOR DISCIPLINE**

17 **(Violation of Motor Vehicle Inspection Program)**

18 61. Complainant re-alleges and incorporates by reference the allegations set forth above  
19 in paragraphs 40-60.

20 62. Azad's Smog Check Inspector License is subject to disciplinary action under Health  
21 and Safety Code sections 44072.10, subdivisions (a) and (c) and 44072.2, subdivision (a), in that  
22 Azad failed to comply with the following sections of that Code:

23 a. **Section 44012**: failed to perform the tests of the emission control systems and devices  
24 on the vehicle(s) in paragraphs 40-60 in accordance with procedures prescribed by the  
25 Department.

26 b. **Section 44015**: issued a certificate of compliance for the vehicle(s) in paragraphs 40-  
27 60 without properly testing and inspecting them to determine if they were in compliance with  
28 Health & Safety Code section 44012.

1 c. **Section 44035:** failed to meet or maintain the standards prescribed for qualification,  
2 equipment, performance, or conduct by failing to properly perform a smog inspection on the  
3 vehicle(s) in paragraphs 40-60 or certifying that such test(s) had been performed, when in fact  
4 they were never performed.

5 **TENTH CAUSE FOR DISCIPLINE**

6 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)**

7 63. Complainant re-alleges and incorporates by reference the allegations set forth above  
8 in paragraphs 40-62.

9 64. Azad's Smog Check Inspector License is subject to disciplinary action under Health  
10 and Safety Code sections 44072.10, subdivisions (a) and (c) and 44072.2, subdivision (a) in that  
11 Azad failed to comply with the following sections of Title 16, California Code of Regulations:

12 a. **Section 3340.35, subdivision (c):** failed to inspect and test the vehicle(s) in  
13 paragraphs 40-62 in accordance with the procedures specified in section 3340.42 of the  
14 Regulations and failed to ensure that the vehicle(s) had all the required emission control  
15 equipment and devices installed and functioning correctly.

16 b. **Section 3340.41, subdivision (c):** knowingly entered into the Emissions Inspection  
17 System false information about the vehicle(s) in paragraphs 40-62, providing result(s) for smog  
18 inspection(s) which were not actually performed.

19 c. **Section 3340.42:** failed to conduct the required smog tests on the vehicle(s) in  
20 paragraphs 40-62 in accordance with the Bureau's specifications.

21 **ELEVENTH CAUSE FOR DISCIPLINE**

22 **(Dishonesty, Fraud, or Deceit)**

23 65. Complainant re-alleges and incorporates by reference the allegations set forth above  
24 in paragraphs 40-64.

25 66. Azad's Smog Check Inspector License is subject to disciplinary action under Health  
26 and Safety Code sections 44072.10, subdivision (a) and (c) and 44072.2, subdivision (d), and his  
27 Lamp Adjuster License and Brake Adjuster License are subject to disciplinary action under Code  
28 section 9889.3, subdivision (d), in that Azad committed dishonest, fraudulent, or deceitful acts

1 whereby another is injured by issuing a smog certificate of compliance for the vehicle(s) in  
2 paragraphs 40-64 without performing bona fide inspections of the emission control devices and  
3 systems on the vehicle(s), thereby depriving the People of the State of California of the protection  
4 afforded by the Motor Vehicle Inspection Program.

5 **TWELFTH CAUSE FOR DISCIPLINE**

6 **(Violation of Motor Vehicle Inspection Program)**

7 67. Complainant re-alleges and incorporates by reference the allegations set forth above  
8 in paragraphs 40-66.

9 68. Leal's Smog Check Inspector License is subject to disciplinary action under Health  
10 and Safety Code sections 44072.10, subdivisions (a) and (c) and 44072.2, subdivision (a), in that  
11 Leal failed to comply with the following sections of that Code:

12 a. **Section 44012**: failed to perform the tests of the emission control systems and devices  
13 on the vehicle(s) in paragraphs 40-66 in accordance with procedures prescribed by the  
14 Department.

15 b. **Section 44015**: issued a certificate of compliance for the vehicle(s) in paragraphs 40-  
16 66 without properly testing and inspecting them to determine if they were in compliance with  
17 Health & Safety Code section 44012.

18 c. **Section 44035**: failed to meet or maintain the standards prescribed for qualification,  
19 equipment, performance, or conduct by failing to properly perform a smog inspection on the  
20 vehicle(s) in paragraphs 40-66 or certifying that such test(s) had been performed, when in fact  
21 they were never performed.

22 **THIRTEENTH CAUSE FOR DISCIPLINE**

23 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)**

24 69. Complainant re-alleges and incorporates by reference the allegations set forth above  
25 in paragraphs 40-68.

26 70. Leal's Smog Check Inspector License is subject to disciplinary action under Health  
27 and Safety Code sections 44072.10, subdivisions (a) and (c) and 44072.2, subdivision (a) in that  
28 Leal failed to comply with the following sections of Title 16, California Code of Regulations:

1 a. **Section 3340.35, subdivision (c)**: failed to inspect and test the vehicle(s) in  
2 paragraphs 40-68 in accordance with the procedures specified in section 3340.42 of the  
3 Regulations and failed to ensure that the vehicle(s) had all the required emission control  
4 equipment and devices installed and functioning correctly.

5 b. **Section 3340.41, subdivision (c)**: knowingly entered into the Emissions Inspection  
6 System false information about the vehicle(s) in paragraphs 40-68, providing result(s) for smog  
7 inspection(s) which were not actually performed.

8 c. **Section 3340.42**: failed to conduct the required smog tests on the vehicle(s) in  
9 paragraphs 40-68 in accordance with the Bureau's specifications.

10 **FOURTEENTH CAUSE FOR DISCIPLINE**

11 **(Dishonesty, Fraud, or Deceit)**

12 71. Complainant re-alleges and incorporates by reference the allegations set forth above  
13 in paragraphs 40-70.

14 72. Leal's Smog Check Inspector License is subject to disciplinary action under Health  
15 and Safety Code sections 44072.10, subdivision (a) and (c) and 44072.2, subdivision (d), in that  
16 Leal committed dishonest, fraudulent, or deceitful acts whereby another is injured by issuing a  
17 smog certificate of compliance for the vehicle(s) in paragraphs 40-70 without performing bona  
18 fide inspections of the emission control devices and systems on the vehicle(s), thereby depriving  
19 the People of the State of California of the protection afforded by the Motor Vehicle Inspection  
20 Program.

21 **FIFTEENTH CAUSE FOR DISCIPLINE**

22 **(Violation of Motor Vehicle Inspection Program)**

23 73. Complainant re-alleges and incorporates by reference the allegations set forth above  
24 in paragraphs 40-72.

25 74. Blackshear's Advanced Emission Specialist Technician License is subject to  
26 disciplinary action under Health and Safety Code sections 44072.10, subdivisions (a) and (c) and  
27 44072.2, subdivision (a), in that Blackshear failed to comply with the following sections of that  
28 Code:

1 a. **Section 44012**: failed to perform the tests of the emission control systems and devices  
2 on the vehicle(s) in paragraphs 40-72 in accordance with procedures prescribed by the  
3 Department.

4 b. **Section 44015**: issued a certificate of compliance for the vehicle(s) in paragraphs 40-  
5 72 without properly testing and inspecting them to determine if they were in compliance with  
6 Health & Safety Code section 44012.

7 c. **Section 44035**: failed to meet or maintain the standards prescribed for qualification,  
8 equipment, performance, or conduct by failing to properly perform a smog inspection on the  
9 vehicle(s) in paragraphs 40-72 or certifying that such test(s) had been performed, when in fact  
10 they were never performed.

11 **SIXTEENTH CAUSE FOR DISCIPLINE**

12 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)**

13 75. Complainant re-alleges and incorporates by reference the allegations set forth above  
14 in paragraphs 40-74.

15 76. Blackshear's Advanced Emission Specialist Technician License is subject to  
16 disciplinary action under Health and Safety Code sections 44072.10, subdivisions (a) and (c) and  
17 44072.2, subdivision (a) in that Blackshear failed to comply with the following sections of Title  
18 16, California Code of Regulations:

19 a. **Section 3340.35, subdivision (c)**: failed to inspect and test the vehicle(s) in  
20 paragraphs 40-74 in accordance with the procedures specified in section 3340.42 of the  
21 Regulations and failed to ensure that the vehicle(s) had all the required emission control  
22 equipment and devices installed and functioning correctly.

23 b. **Section 3340.41, subdivision (c)**: knowingly entered into the Emissions Inspection  
24 System false information about the vehicle(s) in paragraphs 40-74, providing result(s) for smog  
25 inspection(s) which were not actually performed.

26 c. **Section 3340.42**: failed to conduct the required smog tests on the vehicle(s) in  
27 paragraphs 40-74 in accordance with the Bureau's specifications.

28 ///

1 **SEVENTEENTH CAUSE FOR DISCIPLINE**

2 **(Dishonesty, Fraud, or Deceit)**

3 77. Complainant re-alleges and incorporates by reference the allegations set forth above  
4 in paragraphs 40-76.

5 78. Blackshear's Advanced Emission Specialist Technician License is subject to  
6 disciplinary action under Health and Safety Code sections 44072.10, subdivision (a) and (c) and  
7 44072.2, subdivision (d), in that Blackshear committed dishonest, fraudulent, or deceitful acts  
8 whereby another is injured by issuing a smog certificate of compliance for the vehicle(s) in  
9 paragraphs 40-76 without performing bona fide inspections of the emission control devices and  
10 systems on the vehicle(s), thereby depriving the People of the State of California of the protection  
11 afforded by the Motor Vehicle Inspection Program.

12 **OTHER MATTERS**

13 79. Under Code section 9884.7, subdivision (c), the Director may suspend, revoke or  
14 place on probation the registration for all places of business operated in this State by 7 to 7 Smog  
15 upon a finding that 7 to 7 Smog has, or is, engaged in a course of repeated and willful violations  
16 of the laws and regulations pertaining to an automotive repair dealer.

17 80. Under Code section 9889.9, if a license is revoked or suspended following a hearing  
18 under Article 7 of the Automotive Repair Act, any additional license issued under Articles 5 and 6  
19 of Chapter 20.3 in the name of 7 to 7 Smog may be likewise revoked or suspended.

20 81. Under Code section 9889.9, if a license is revoked or suspended following a hearing  
21 under Article 7 of the Automotive Repair Act, any additional license issued under Articles 5 and 6  
22 of Chapter 20.3 in the name of Richards may be likewise revoked or suspended.

23 82. Under Code section 9889.9, if a license is revoked or suspended following a hearing  
24 under Article 7 of the Automotive Repair Act, any additional license issued under Articles 5 and 6  
25 of Chapter 20.3 in the name of Azad may be likewise revoked or suspended.

26 83. Under Health & Safety Code section 44072.8, if 7 to 7 Smog's Smog Check Station  
27 License is revoked or suspended, the Director may likewise revoke or suspend any additional  
28 license issued under Chapter 5 of the Health and Safety Code in the name of 7 to 7 Smog.



1           4.    Revoking or suspending Lamp Station License No. LS 266532, issued to James  
2 Gilbert Richards, Partner, Mohammad Rahim Azad, Partner, doing business as 7 to 7 Smog and  
3 Auto Repair;

4           5.    Revoking or suspending any additional license issued under Chapter 5 of the Health  
5 and Safety Code in the name of James Gilbert Richards, Partner, Mohammad Rahim Azad,  
6 Partner, doing business as 7 to 7 Smog and Auto Repair;

7           6.    Revoking or suspending the registration for all places of business operated in this  
8 State in the name of James Gilbert Richards, Partner, Mohammad Rahim Azad, Partner, doing  
9 business as 7 to 7 Smog and Auto Repair;

10          7.    Revoking or suspending any additional license issued under Articles 5 and 6 of  
11 Chapter 20.3 of the Code in the name of James Gilbert Richards, Partner, Mohammad Rahim  
12 Azad, Partner, doing business as 7 to 7 Smog and Auto Repair.

13          8.    Revoking or suspending Smog Check Repair Technician License No. EI 630900 and  
14 Smog Check Inspector License No. EO 630900 issued to James Gilbert Richards;

15          9.    Revoking or suspending Brake Adjuster License Number BA 630900, issued to James  
16 Gilbert Richards;

17          10.   Revoking or suspending Lamp Adjuster License Number LA 630900, issued to James  
18 Gilbert Richards;

19          11.   Revoking or suspending any additional license issued under Chapter 5 of the Health  
20 and Safety Code in the name of James Gilbert Richards;

21          12.   Revoking or suspending any additional license issued under Articles 5 and 6 of  
22 Chapter 20.3 of the Code in the name of James Gilbert Richards.

23          13.   Revoking or suspending Smog Check Inspector License No. EO 636435 issued to  
24 Mohammad Rahim Azad;

25          14.   Revoking or suspending Brake Adjuster License Number BA 636435, issued to  
26 Mohammad Rahim Azad;

27          15.   Revoking or suspending Lamp Adjuster License Number LA 636435, issued to  
28 Mohammad Rahim Azad;

1 16. Revoking or suspending any additional license issued under Chapter 5 of the Health  
2 and Safety Code in the name of Mohammad Rahim Azad;

3 17. Revoking or suspending any additional license issued under Articles 5 and 6 of  
4 Chapter 20.3 of the Code in the name of Mohammad Rahim Azad;

5 18. Revoking or suspending Smog Check Inspector License No. EO 637039 issued to  
6 Jose Francisco Leal;

7 19. Revoking or suspending any additional license issued under Chapter 5 of the Health  
8 and Safety Code in the name of Jose Francisco Leal;

9 20. Revoking or suspending Stephen Blackshear's smog technician license(s), currently  
10 designated as Advanced Emission Specialist Technician License Number EA 634692 and as  
11 redesignated upon his timely renewal as EO 634692 and/or EI 634692;

12 21. Revoking or suspending any additional license issued under Chapter 5 of the Health  
13 and Safety Code in the name of Stephen Blackshear;

14 22. Ordering James Gilbert Richards, Partner, Mohammad Rahim Azad, Partner, doing  
15 business as 7 to 7 Smog and Auto Repair; James Gilbert Richards; Mohammad Rahim Azad; Jose  
16 Francisco Leal; and Stephen Blackshear to pay the Bureau of Automotive Repair the reasonable  
17 costs of the investigation and enforcement of this case, pursuant to Business and Professions Code  
18 section 125.3; and

19 23. Taking such other and further action as deemed necessary and proper.  
20  
21

22  
23 DATED: April 21, 2015



PATRICK DORAIS  
Chief  
Bureau of Automotive Repair  
Department of Consumer Affairs  
State of California  
*Complainant*

24  
25  
26  
27  
28 SD2015700641  
71050455.doc