| 1  |  |  |  |
|----|--|--|--|
| Į. | Rob Bonta  |  |  |
| 2  | Attorney General of California NANCY A. KAISER                     |  |  |
| 3  | Supervising Deputy Attorney General MELISSA TYNER                  |  |  |
| 4  | Deputy Attorney General<br>State Bar No. 269649                    |  |  |
| 5  | 300 So. Spring Street, Suite 1702<br>Los Angeles, CA 90013         |  |  |
| 6  | Telephone: (213) 269-6314<br>Facsimile: (916) 731-2126             |  |  |
| 7  | E-mail: Melissa.Tyner@doj.ca.gov  Attorneys for Complainant        |  |  |
| 8  | 22   |  |  |
| 9  | BEFORE THE   |  |  |
| 10 | DEPARTMENT OF CONSUMER AFFAIRS FOR THE BUREAU OF AUTOMOTIVE REPAIR |  |  |
| 11 | STATE OF C.  | ALIFORNIA                                |  |
| 12 |  |  |  |
| 13 | In the Matter of the Accusation Against:                           | Case No. 79/21-10764                     |  |
| 14 | KEVIN GEOVANY SANDOVAL DBA   | Cuse 110. 19121 10704                    |  |
| 15 | CHEVY BOYS SMOG CHECK 8220 Foothill Blvd. Unit #5                  | ACCUSATION                               |  |
| 16 | Sunland, CA 91040  | ACCUSATION                               |  |
| 17 | Automotive Repair Dealer Registration No.<br>ARD 297756            |  |  |
| 18 | Smog Check, Test Only Station License No. TC 297756                |  |  |
| 19 | and  |  |  |
| 20 | KEVIN GEOVANY SANDOVAL<br>12020 Vanowen St., Apt. 12               |  |  |
| 21 | North Hollywood, CA 91605  |  |  |
| 22 | Smog Check Inspector License No.<br>EO 642853                      |  |  |
| 23 | EO 042033  |  |  |
| 24 | Respondent.  |  |  |
| 25 |  |  |  |
| 26 |  |  |  |
| 27 |  |  |  |
| 28 |  |  |  |
|    |  | 1 HEVY BOYS SMOG CHECK and KEVIN GEOVANY |  |

#### **PARTIES**

- 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as the Chief of the Bureau of Automotive Repair, Department of Consumer Affairs.
- 2. On or about August 6, 2020, the Bureau of Automotive Repair issued Automotive Repair Dealer Registration Number ARD 297756 to Kevin Geovany Sandoval dba Chevy Boys Smog Check (Respondent). The Automotive Repair Dealer Registration was in full force and effect at all times relevant to the charges brought herein and will expire on August 31, 2022, unless renewed.
- 3. On or about March 3, 2021, the Bureau of Automotive Repair issued Smog Check, Test Only Station License Number TC 297756 to Kevin Geovany Sandoval dba Chevy Boys Smog Check (Respondent). The Smog Check, Test Only Station License was in full force and effect at all times relevant to the charges brought herein and will expire on August 31, 2022, unless renewed.
- 4. On or about April 14, 2021, Kevin Geovany Sandoval dba Chevy Boys Smog Check a was certified as a STAR Station. This certification will remain unless the Automotive Repair Dealer Registration and/or Smog Check Station License is revoked, canceled, licenses become delinquent, or the certification is invalidated.
- 5. On or about January 19, 2021, the Bureau of Automotive Repair issued Smog Check Inspector License Number EO 642853 to Kevin Geovany Sandoval (Respondent). The Smog Check Inspector License was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2022, unless renewed.

#### **JURISDICTION**

- 6. Business and Professions Code (Bus. & Prof. Code) section 118, subdivision (b), provides that suspension, expiration, surrender, or cancellation of a license shall not deprive the Director of jurisdiction to proceed with a disciplinary action during the period within which the license may be renewed, restored, reissued or reinstated.
- 7. Bus. & Prof. Code section 9884.7 provides that the Director may revoke an automotive repair dealer registration.

|        | 8.      | Bus. & Prof. Code section 9884.13 provides, in pertinent part, that the expiration of a |
|--------|---------|---|
| valid  | registı | ration shall not deprive the Director of jurisdiction to proceed with a disciplinary    |
| proce  | eding   | against an automotive repair dealer or to render a decision temporarily or permanently  |
| invali | dating  | g (suspending or revoking) a registration.  |

- 9. Health and Safety Code (Health & Saf. Code) section 44002 provides, in pertinent part, that the Director has all the powers and authority granted under the Automotive Repair Act for enforcing the Motor Vehicle Inspection Program.
- 10. Health & Saf. Code section 44072.6 provides, in pertinent part, that the expiration or suspension of a license by operation of law, or by order or decision of the Director of Consumer Affairs, or a court of law, or the voluntary surrender of the license shall not deprive the Director of jurisdiction to proceed with disciplinary action.

#### **STATUTORY PROVISIONS**

#### 11. Section 9884.7 of the Code states:

- (a) The director, where the automotive repair dealer cannot show there was a bona fide error, may deny, suspend, revoke, or place on probation the registration of an automotive repair dealer for any of the following acts or omissions related to the conduct of the business of the automotive repair dealer, which are done by the automotive repair dealer or any automotive technician, employee, partner, officer, or member of the automotive repair dealer.
- (1) Making or authorizing in any manner or by any means whatever any statement written or oral which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading.

. . . .

(4) Any other conduct which constitutes fraud.

. . .

- (6) Failure in any material respect to comply with the provisions of this chapter or regulations adopted pursuant to it.
- 12. Bus. & Prof. Code section 477 provides, in pertinent part, that "Board" includes "bureau," "commission," "committee," "department," "division," "examining committee," "program," and "agency." "License" includes certificate, registration or other means to engage in a business or profession regulated by the Bus. & Prof. Code.

3456

## 8

9

7

10

11

12

13

26

2223

20

21

24

25

27

28

the tendency or effect thereby would be to mislead or deceive customers, prospective customers, or the public.

#### **COST RECOVERY**

25. Section 125.3 of the Code provides, in pertinent part, that the Board may request the administrative law judge to direct a licensee found to have committed a violation or violations of the licensing act to pay a sum not to exceed the reasonable costs of the investigation and enforcement of the case, with failure of the licensee to comply subjecting the license to not being renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be included in a stipulated settlement.

#### **FACTUAL ALLEGATIONS**

26. The Bureau has become aware of certain methods that some Smog Check stations and Smog Check inspectors use to fraudulently issue smog certificates to vehicles that may not or will not pass a Smog Check test on their own, or in some instances, are not even present during the time the test is performed. "Clean tanking" is one such method, during which the Low Pressure Fuel Evaporative Test (LPFET) is performed using the LPFET equipment calibration tank instead of connecting to the subject vehicle's fuel inlet to determine if there is a leak in the system. The LPFET tests the functionality of the vehicle's Evaporative Emissions Control (EVAP) system by introducing inert Nitrogen gas into the vehicle's fuel system, which includes the fuel tank, until it reaches a predetermined pressure and then holds that pressure for a specified period of time to confirm no leaks are present in the system. As part of this test, the LPFET equipment measures the "headspace volume" based upon the volume of gas needed to achieve a specified pressure as the Nitrogen gas is introduced into the vehicle's fuel tank, and records that data to the Vehicle Information Database (VID). The "headspace volume" is the volume of the vapor space in the fuel tank above the fuel level. This means a vehicle with a full tank of gas will have a smaller headspace volume than a vehicle with less fuel in the tank. The LPFET equipment must pass a calibration test every 3 days to verify its ability to properly measure the volume of Nitrogen gas introduced during a test and the pressure readings. In order to pass the calibration test, the amount of Nitrogen gas introduced to the calibration tank during the test must be within

the 1.5 to 2.5 gallon headspace volume range. If the LPFET equipment fails a calibration test, the LPFET tester is locked and the station is not able to perform the LPFET test until the unit passes.

- 27. On August 20, 2021, the Bureau conducted a review of Chevy Boys Smog
  Check's BAR-97 Smog Check inspection records from the VID for vehicles that received an
  LPFET test during the period of April 28, 2021 through July 31, 2021. The review showed a total
  of 23 LPFET tests passed. Of those 23 LPFET tests, 91.30% had a calculated headspace volume
  within the 1.5 to 2.5 gallon range, the same range the LPFET calibration tank is required to
  maintain, resulting in 21 possible fraudulent certifications issued by Chevy Boys Smog Check.
  VID data show that of certified vehicles statewide that received an LPFET test during the same
  period of time [109,717 inspections from 4,295 stations], just 16.04% reported a calculated
  headspace volume within the 1.5 to 2.5 gallon range. After adjusting for the statewide percentage
  of expected headspace volume results in this range, the data shows that Chevy Boys Smog Check
  issued 17 fraudulent certifications utilizing the clean tanking method.
- 28. Of the 23 vehicles certified by Chevy Boys Smog Check with passing LPFET inspections between April 28, 2021 through July 31, 2021. Respondent performed 23, with 91.30% reporting calculated headspace volumes within the 1.5 to 2.5 gallon range, resulting in 21 possible fraudulent certifications. After adjusting for the statewide percentage of expected headspace volume results in this range (16.04%) the data show that Respondent issued 17 fraudulent certifications utilizing the clean tanking method.

#### FIRST CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

29. Respondent's Automotive Repair Dealer Registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that between April 28, 2021 through July 31, 2021, Respondent made or authorized statements which it knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows: From April 28, 2021 through July 31, 2021, Respondent issued 17 fraudulent certificates of compliance to vehicles using the calibration tank or a tank other than the actual vehicles' fuel tank during the LPFET portion of the smog inspection. Complainant refers to, and by this reference

incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### SECOND CAUSE FOR DISCIPLINE

#### (Fraud)

30. Respondent's Automotive Repair Dealer Registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that he committed acts that constitute fraud by issuing electronic certificates of compliance for 17 vehicles, as described above in paragraph 28, without performing bone fide inspections of the emission control devices and systems on those vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28 above, as though set forth fully herein.

#### THIRD CAUSE FOR DISCIPLINE

#### (Material Violation of Automotive Repair Act)

31. Respondent's Automotive Repair Dealer Registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that he failed in a material respect to comply with the provisions of this chapter or regulations adopted pursuant to it when he issued electronic certificates of compliance for 17 vehicles, as described above in paragraph 28, without performing bona fide inspections of the emission control devices and systems on those vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

28

#### **FOURTH CAUSE FOR DISCIPLINE**

#### (Violations of the Motor Vehicle Inspection Program)

- 32. Respondent's Smog Check Test Only Station License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that he failed to comply with the following sections of that Code:
- a. <u>Section 44012</u>: Respondent failed to ensure that the emission control tests were performed on 17 vehicles, as described in paragraph 28 above, in accordance with procedures prescribed by the department.
- b. <u>Section 44015, subdivision (b)</u>: Respondent issued electronic smog certificates of compliance for 17 vehicles, as described in paragraph 28 above, without ensuring that the vehicles were properly tested and inspected to determine if they were in compliance with Health & Saf. Code section 44012.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### FIFTH CAUSE FOR DISCIPLINE

# (Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 33. Respondent's Smog Check Test Only Station License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that he failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent falsely or fraudulently issued electronic smog certificates of compliance for 17 vehicles as described in paragraph 28 above.
- b. <u>Section 3340.30, subdivision (a)</u>: Respondent failed to inspect and test 17 vehicles, as described in paragraph 28 above, in accordance with Health & Saf. Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
- c. <u>Section 3340.35, subdivision (c)</u>: Respondent issued electronic smog certificates of compliance for 17 vehicles, as described in paragraph 28 above, even though those vehicles had not been inspected in accordance with section 3340.42.

- d. <u>Section 3340.41, subdivision (c)</u>: Respondent knowingly entered false information into the emissions inspection system for 17 vehicles as described in paragraph 28 above.
- e. <u>Section 3340.42</u>: Respondent failed to ensure that the smog inspections conducted on 17 vehicles, as described in paragraph 28 above, were done in accordance with the Bureau's specifications.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### SIXTH CAUSE FOR DISCIPLINE

#### (Dishonesty, Fraud or Deceit)

34. Respondent's Smog Check Test Only Station License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), and Health & Saf. Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts whereby another was injured by issuing electronic smog certificates of compliance for 17 vehicles, as described in paragraph 28 above, without performing bona fide inspections of the emission control devices and systems on the vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### SEVENTH CAUSE FOR DISCIPLINE

#### (Violations of the Motor Vehicle Inspection Program)

- 35. Respondent's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that he failed to comply with the following sections of that code:
- a. <u>Section 44032</u>: Respondent failed to ensure that the emission control tests were performed on 17 vehicles, as described in paragraph 28 above, in accordance with Health & Saf. Code section 44012.
- b. <u>Section 44015, subdivision (b)</u>: Respondent issued electronic smog certificates of compliance for 17 vehicles, as described in paragraph 28 above, without ensuring that the

vehicles were properly tested and inspected to determine if they were in compliance with Health & Saf. Code section 44012.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### **EIGHTH CAUSE FOR DISCIPLINE**

### (Failure to Comply with Regulations Pursuant

#### to the Motor Vehicle Inspection Program)

- 36. Respondent's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that he failed to comply with provisions of California Code of Regulations, title 16, as follows:
- a. <u>Section 3340.24, subdivision (c)</u>: Respondent falsely or fraudulently issued electronic smog certificates of compliance for 17 vehicles as described in paragraph 28 above.
- b. <u>Section 3340.30, subdivision (a)</u>: Respondent failed to inspect and test 17 vehicles, as described in paragraph 28 above, in accordance with Health & Saf. Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
- c. <u>Section 3340.41, subdivision (c)</u>: Respondent knowingly entered false information into the emissions inspection system for 17 vehicles as described in paragraph 28 above.
- d. <u>Section 3340.42</u>: Respondent failed to ensure that the smog inspections conducted on 17 vehicles, as described in paragraph 28 above, were done in accordance with the Bureau's specifications.

Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### NINTH CAUSE FOR DISCIPLINE

#### (Dishonesty, Fraud or Deceit)

37. Respondent's Smog Check Inspector License is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), and Health & Saf. Code section 44072.10, subdivision (c), in that he committed dishonest, fraudulent, or deceitful acts whereby another was injured by issuing electronic smog certificates of compliance for 17 vehicles, as

described in paragraph 28 above, without performing bona fide inspections of the emission control devices and systems on the vehicles, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program. Complainant refers to, and by this reference incorporates, the allegations contained in paragraphs 26 through 28, above, as though set forth fully herein.

#### OTHER MATTERS

- 38. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the Director may suspend, revoke, or place on probation the registration for all places of business operated in this state by Respondent, upon a finding that he has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.
- 39. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Test Only Station License No. TC 297756, issued to Respondent, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Saf. Code in the name of said licensee may be likewise revoked or suspended by the Director.
- 40. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Inspector License No. EO 642853, issued to Respondent, is revoked or suspended, any additional license issued under Chapter 5 of Part 5 of Division 26 of the Health & Saf. Code in the name of said licensee may be likewise revoked or suspended by the Director.

#### **PRAYER**

WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged, and that following the hearing, the Director of the Department of Consumer Affairs issue a decision:

- Revoking or suspending Automotive Repair Dealer Registration Number ARD
   297756, issued to Kevin Geovany Sandoval dba Chevy Boys Smog Check;
- 2. Revoking or suspending Smog Check, Test Only Station License Number TC 297756, issued to Kevin Geovany Sandoval dba Chevy Boys Smog Check;
- 3. Revoking or suspending Smog Check Inspector License Number EO 642853, issued to Kevin Geovany Sandoval;

SANDOVAL) ACCUSATION